APPENDIX A

Public Opinion Survey Summary







North Fulton County CTP Telephone Survey Results

October 2009

Table of Contents

Introduction and Methodology	1
Driving Patterns	2
Possible Transportation Improvements	4
Walking and Biking	5
Public Transit	6
Future Measures	8



The Schapiro Group, Inc. 127 Peachtree Street, NE – Suite 1540 + Atlanta, GA 30303 404-584-5215 + 404-581-0058 fax

schapirogroup.com


Introduction and Methodology

The Schapiro Group (TSG), in consultation with the Atlanta Regional Commission and Kimley-Horn and Associates, interviewed 1,000 North Fulton County residents to explore usage of, attitudes toward, and perceptions of transportation options in their area. TSG sampled residential phone numbers within the six cities comprising North Fulton County (Alpharetta, Johns Creek, Milton, Mountain Park, Roswell, and Sandy Springs) to obtain telephone survey data during September and October 2009. The results were weighted and are demographically and geographically representative of the North Fulton County area. The margin of sampling error for the regionwide results is $\pm 3.1\%$.

Professional interviewers administered the survey instrument to respondents who reported living within one of these cities. TSG completed a proportionate number of surveys in each of the six cities – Alpharetta 18%, Johns Creek 19%, Milton 8%, Mountain Park 1%, Roswell 28%, and Sandy Springs 26%. The margin of sampling error for results within individual cities is greater than that of the region, depending on the size of the city. This report is based on analysis of regionwide data, rather than individual city data, though the results for cities with more than 100 respondents are reported when necessary.

Driving Patterns


A majority of North Fulton County residents are on major roads or highways in the area during morning and afternoon rush periods, while slightly less than half are on major roads during non-rush times.



The top reasons for being on the road during each of those times are:

- The morning rush, 6 a.m. to 9 a.m. commute to work (78%), take children to school or activities (13%), errands (5%)
- 9 a.m. to 4 p.m. errands (37%), commute to work (29%), part of job duties (12%), take children to school or activities (12%)
- The evening rush, 4 p.m. to 7 p.m. commute to work (58%), take children to school or activities (15%), errands (14%)
- After 7 p.m. entertainment or leisure (54%), errands (23%), take children to school or activities (10%), commute to work (9%)


Half of North Fulton County residents spend 20 minutes or more on the way to work each morning. Nearly one-third of residents do not commute to work.



Alpharetta drivers spend the most time commuting; Sandy Springs drivers spend the least.

Possible Transportation Improvements

All possible transportation improvements were viewed as "extremely high" or 'high" priorities by at least half of the area's residents.¹




- Repairing the roads (67% "extremely high" or "high") and developing more public transit options (66%) are the highest priorities in the area, followed by making it easier and safer to walk in the area (63%) and improving connections and making it easier to get to destinations in the North Fulton County area (63%).
- Improving safety for bicycles and reducing the number of cars from other areas ranked as the lowest priorities, though both were still considered "extremely high" or "high" priorities by most residents.
- Roswell is consistently the city most likely to indicate that an improvement is an "extremely high" priority.


¹ Exact wording of the tested transportation improvements: "Repairing the roads," "Developing more public transit options," "Making it easier and safer for people to walk to destinations around town," "Improving connections and making it easier to get to destinations in the North Fulton County area," "Improving accessibility options for individuals with disabilities," "Making travel times in your area more reliable, so that you usually know how long it will take to get to your destination," "Improving mobility options for residents who do not drive," "Improving safety for vehicles in the area," "Making it safer to ride bicycles in your area," and "Reducing the number of cars from other areas passing through town on the way to work."

Walking and Biking

More than one-third (37%) of residents walk to destinations around their community, most often for recreation. More than half of them (60%) walk to destinations at least once a week. Only 14% of residents bike to destinations in their area. Two-thirds of those residents bike for recreation and about one-third bike to parks. About half of cyclists (51%) bike to destinations once a week or more.



A majority of residents believe each of the tested locations needs more sidewalks and bicycle lanes in place.




Nearly three-quarters (73%) of residents indicate that they would walk or ride a bike more often if their destinations were closer to their homes. Almost as many (68%) say they would walk or bike more if the roads were more pedestrian- and bike-friendly.


Public Transit

A strong majority (67%) of North Fulton County residents believe public transit to be useful for most people in their area. Residents in Sandy Springs and younger residents are more likely to say public transit is "very useful," while Johns Creek residents are least likely to find it "very useful."


A majority (64%) of residents ride public transit only once a month or less.



Residents generally rate public transit unfavorably, particularly when it comes to matters of convenience. About 15% of residents did not have an opinion on the characteristics of public transit. Once again, Sandy Springs residents and younger residents almost always give the highest ratings for public transit. Johns Creek residents rate it the lowest.




Each public transit improvement option was considered an "extremely high" or "high" priority by most North Fulton County residents.




Younger residents are consistently more likely to say that any of the options are an "extremely high priority."

North Fulton County residents are overwhelmingly in favor of the state and/or nearby counties contributing to MARTA funding – only 13% oppose the idea.



Future Measures

Adding a new crossing over the Chattahoochee River also receives strong support, as 77% of residents favor the idea. Support is particularly strong among Johns Creek residents and commuters.





North Fulton County Survey Tables September 16 - October 6, 2009 N=1,000 North Fulton County Residents

	ng: The morning a.m. – 9 a.m.	Yes	No	Don't know/ Refused
	Total	56%	43%	0%
City	Alpharetta	63%	37%	0%
	Johns Creek	58%	42%	0%
	Roswell	52%	48%	0%
	Sandy Springs	56%	44%	0%
Gender	Male	62%	38%	0%
	Female	52%	48%	0%
Age	18-29	69%	31%	0%
	30-39	67%	33%	0%
	40-49	65%	35%	0%
	50-59	50%	50%	0%
	60 and over	24%	76%	0%
Commuter	Yes	73%	27%	0%
	No	20%	80%	0%

Which of th	a fallowing boat							
Which of the following best describes why you are						To take		
	lriving on major		Ac part			children		
	ghways in North	То	As part of my		For	to school		
	ounty during the	commute	job	For	entertainment	or	Something	Don't know/
	rush period?	to work		errands	or leisure	activities	else	Refused
morning	Total							
		78%	2%	5%	1%	13%	1%	1%
City	Alpharetta	87%	0%	3%	0%	7%	2%	0%
	Johns Creek	76%	1%	7%	1%	15%	1%	0%
	Roswell	74%	4%	4%	0%	17%	1%	0%
	Sandy Springs	79%	1%	5%	0%	12%	3%	0%
Gender	Male	85%	3%	4%	1%	6%	0%	1%
	Female	70%	1%	5%	0%	21%	3%	0%
Age	18-29	76%	0%	4%	0%	16%	4%	0%
	30-39	82%	2%	3%	0%	11%	1%	2%
	40-49	78%	1%	2%	0%	19%	0%	0%
	50-59	79%	3%	7%	0%	9%	2%	0%
	60 and over	62%	4%	17%	7%	5%	4%	0%
Commuter	Yes	87%	2%	1%	0%	9%	1%	0%
	No	9%	2%	30%	4%	43%	6%	5%



Drive du	Iring: The day			Don't know/
	a.m. and 4 p.m.	Yes	No	Refused
	Total	47%	52%	0%
City	Alpharetta	44%	56%	0%
	Johns Creek	52%	47%	1%
	Roswell	50%	50%	0%
	Sandy Springs	43%	56%	0%
Gender	Male	39%	61%	0%
	Female	55%	45%	0%
Age	18-29	39%	61%	0%
	30-39	45%	55%	0%
	40-49	48%	52%	0%
	50-59	45%	55%	0%
	60 and over	58%	42%	0%
Commuter	Yes	41%	59%	0%
	No	62%	38%	0%

	ne following best							
describes why you are						To take		
	lriving on major		As part			children		
	ghways in North	То	of my		For	to school		
	unty during the	commute	job	For	entertainment	or	Something	Don't know/
day betwe	en 9 am-4 pm?	to work	duties	errands	or leisure	activities	else	Refused
	Total	29%	12%	37%	7%	12%	3%	0%
City	Alpharetta	21%	12%	41%	12%	13%	1%	0%
	Johns Creek	29%	8%	43%	7%	13%	1%	0%
	Roswell	31%	15%	29%	8%	15%	3%	0%
	Sandy Springs	33%	13%	33%	5%	10%	5%	1%
Gender	Male	27%	23%	25%	10%	11%	4%	0%
	Female	30%	6%	44%	5%	13%	2%	0%
Age	18-29	50%	14%	14%	7%	14%	0%	0%
	30-39	35%	10%	26%	9%	18%	3%	0%
	40-49	29%	12%	38%	2%	16%	1%	1%
	50-59	21%	23%	38%	5%	10%	4%	0%
	60 and over	16%	6%	57%	13%	2%	5%	1%
Commuter	Yes	45%	17%	17%	6%	11%	3%	0%
	No	6%	5%	64%	8%	14%	2%	0%



	ng: The evening			Don't know/
rush, 4	p.m. – 7 p.m.	Yes	No	Refused
	Total	61%	39%	0%
City	Alpharetta	65%	35%	0%
	Johns Creek	61%	38%	1%
	Roswell	62%	38%	0%
	Sandy Springs	55%	45%	0%
Gender	Male	66%	34%	0%
	Female	56%	43%	0%
Age	18-29	67%	33%	0%
	30-39	66%	34%	0%
	40-49	70%	30%	0%
	50-59	54%	46%	0%
	60 and over	41%	59%	0%
Commuter	Yes	72%	28%	0%
	No	38%	62%	0%

describe	ne following best s why you are		A a a a a			To take		
	riving on major ghways in North	То	As part of my		For	children to school		
Fulton Co	unty during the rush period?	commute to work	job	For errands	entertainment or leisure	or activities	Something else	Don't know/ Refused
	Total	58%	3%	14%	9%	15%	1%	0%
City	Alpharetta	65%	4%	12%	5%	14%	0%	0%
	Johns Creek	62%	3%	11%	9%	15%	0%	0%
	Roswell	54%	4%	16%	9%	17%	0%	0%
	Sandy Springs	61%	3%	11%	7%	15%	3%	0%
Gender	Male	68%	4%	13%	6%	8%	1%	0%
	Female	47%	2%	15%	11%	23%	0%	1%
Age	18-29	58%	0%	13%	8%	21%	0%	0%
	30-39	57%	3%	11%	5%	21%	2%	1%
	40-49	65%	3%	10%	5%	17%	0%	0%
	50-59	61%	8%	17%	8%	5%	1%	0%
	60 and over	36%	5%	28%	26%	5%	1%	0%
Commuter	Yes	70%	3%	10%	4%	12%	1%	0%
	No	5%	3%	30%	28%	31%	1%	1%



	ng: The evening er 7 p.m.	Yes	No	Don't know/ Refused
	Total	40%	60%	0%
City	Alpharetta	33%	67%	0%
	Johns Creek	41%	58%	1%
	Roswell	41%	59%	0%
	Sandy Springs	42%	57%	0%
Gender	Male	45%	55%	0%
	Female	35%	65%	0%
Age	18-29	47%	53%	0%
	30-39	37%	63%	0%
	40-49	43%	57%	0%
	50-59	39%	61%	0%
	60 and over	31%	69%	0%
Commuter	Yes	43%	57%	0%
	No	34%	66%	0%

Which of th	o following boot							
Which of the following best describes why you are						To take		
	riving on major		As part			children		
	ghways in North	То	of my		For	to school		
	County in the	commute	job	For	entertainment	or	Something	Don't know/
	s after 7 pm?	to work	-		or leisure	activities	else	Refused
g	Total	9%						
City	Alpharetta							
City	· ·	9%	5%	18%	56%	11%	1%	0%
	Johns Creek	8%	3%	26%	55%	8%	0%	0%
	Roswell	10%	6%	15%	56%	10%	3%	0%
	Sandy Springs	10%	1%	25%	52%	8%	4%	1%
Gender	Male	8%	4%	25%	53%	8%	1%	0%
	Female	10%	2%	20%	54%	11%	3%	0%
Age	18-29	18%	0%	35%	35%	6%	6%	0%
	30-39	12%	0%	15%	67%	6%	0%	0%
	40-49	3%	4%	24%	48%	19%	2%	0%
	50-59	8%	8%	22%	54%	6%	1%	1%
	60 and over	5%	4%			7%	5%	
Commuter	Yes	11%	4%	25%	48%	10%	2%	0%
	No	1%	0%			10%	2%	



On average	e, how long does									
	to commute to									
work?	If you do not	Does not	Less						90	
commute	to work, just say	commute	than 10	10-19	20-29	30-44	45-59	60-89	minutes	Don't know/
	SO.	to work	minutes	minutes	minutes	minutes	minutes	minutes	or more	Refused
	Total	29%	5%	15%	16%	18%	10%	5%	1%	2%
City	Alpharetta	27%	4%	10%	12%	21%	14%	8%	2%	1%
	Johns Creek	30%	4%	14%	19%	17%	10%	6%	0%	0%
	Roswell	29%	4%	17%	14%	15%	13%	4%	0%	4%
	Sandy Springs	28%	9%	16%	22%	17%	2%	2%	1%	3%
Gender	Male	22%	5%	17%	16%	22%	11%	4%	1%	2%
	Female	36%	5%	13%	16%	14%	8%	5%	0%	2%
Age	18-29	11%	8%	11%	19%	28%	11%	8%	0%	3%
	30-39	22%	2%	16%	19%	16%	18%	5%	0%	2%
	40-49	24%	7%	16%	17%	23%	7%	4%	1%	0%
	50-59	32%	7%	15%	17%	15%	6%	5%	2%	1%
	60 and over	59%	4%	12%	9%	8%	3%	0%	0%	4%
Commuter	Yes	0%							1%	0%
	No	100%	0%	0%	0%	0%	0%	0%	0%	0%

improvem	transportation ents: Improving	Extremely		.	Not a	
safety for	vehicles in the	high	High	Somewhat		Don't know/
	area	priority	priority	high priority	at all	Refused
	Total	12%	45%	28%	12%	3%
City	Alpharetta	13%	41%	26%	18%	1%
	Johns Creek	10%	46%	31%	10%	4%
	Roswell	15%	49%	25%	11%	1%
	Sandy Springs	9%	44%	34%	10%	2%
Gender	Male	9%	42%	32%	13%	4%
	Female	14%	49%	24%	11%	2%
Age	18-29	11%	57%	26%	6%	0%
	30-39	11%	42%	31%	11%	3%
	40-49	12%	50%	25%	11%	2%
	50-59	9%	40%	31%	17%	3%
	60 and over	12%	43%	26%	14%	5%
Commuter	Yes	11%	46%	29%	12%	1%
	No	12%	43%	26%	13%	7%



	transportation					
	ents: Making it safer for people	Extremely			Not a	
	o destinations	Extremely	High	Somewhat		Don't know/
	und town	high priority		high priority	• •	Refused
	Total					
		18%	45%	27%	8%	1%
City	Alpharetta	18%	43%	26%	12%	0%
	Johns Creek	14%	43%	32%	8%	2%
	Roswell	22%	43%	27%	8%	1%
	Sandy Springs	17%	50%	24%	7%	2%
Gender	Male	13%	44%	31%	12%	1%
	Female	23%	46%	24%	6%	1%
Age	18-29	11%	57%	29%	3%	0%
	30-39	20%	49%	26%	6%	0%
	40-49	18%	45%	28%	8%	1%
	50-59	19%	36%	32%	12%	1%
	60 and over	20%	39%	23%	15%	3%
Commuter	Yes	17%	46%	28%	8%	0%
	No	20%	44%	25%	9%	3%

Possible transportation						
improvements: Making it safer to ride bicycles in your		Extremely		• • • •	Not a	D #1 /
safer to ride		•	High	Somewhat	priority	Don't know/
	area	priority	priority	high priority	at all	Refused
	Total	16%	36%	33%	13%	1%
City	Alpharetta	14%	39%	35%	11%	1%
	Johns Creek	15%	40%	34%	9%	2%
	Roswell	21%	34%	29%	16%	0%
	Sandy Springs	14%	33%	38%	13%	3%
Gender	Male	14%	34%	39%	12%	1%
	Female	18%	39%	28%	13%	1%
Age	18-29	19%	42%	36%	3%	0%
	30-39	18%	41%	31%	9%	0%
	40-49	14%	37%	37%	11%	1%
	50-59	18%	25%	38%	19%	1%
	60 and over	15%	35%	25%	21%	4%
Commuter	Yes	16%	37%	36%	11%	0%
	No	17%	35%	28%	16%	3%



	transportation					
improvements: Making						
	es in your area					
	ble, so that you				•• •	
	w how long it will				Not a	– <i>и и и</i>
	get to your	high	High	Somewhat	1	Don't know/
des	stination	priority	priority	high priority	at all	Refused
	Total	16%	43%	30%	10%	2%
City	Alpharetta	11%	48%	30%	11%	0%
	Johns Creek	16%	43%	30%	7%	4%
	Roswell	21%	43%	26%	8%	1%
	Sandy Springs	14%	39%	32%	12%	3%
Gender	Male	14%	46%	31%	7%	2%
	Female	18%	40%	29%	11%	2%
Age	18-29	25%	47%	28%	0%	0%
	30-39	18%	45%	25%	10%	1%
	40-49	11%	45%	34%	9%	2%
	50-59	17%	38%	35%	9%	1%
	60 and over	10%	37%	32%	17%	3%
Commuter	Yes	17%	44%	30%	8%	1%
	No	12%	41%	29%	15%	

Possible	transportation					
	Possible transportation improvements: Reducing					
	er of cars from	Extremely			Not a	
	passing through		High	Somewhat	priority	Don't know/
	he way to work	priority	•	high priority	at all	Refused
	Total	15%	-		16%	2%
City	Alpharetta	11%	39%	25%	24%	1%
	Johns Creek	12%	40%	28%	18%	3%
	Roswell	21%	37%	30%	11%	1%
	Sandy Springs	14%	37%	34%	12%	2%
Gender	Male	14%	39%	27%	19%	1%
	Female	17%	38%	30%	13%	2%
Age	18-29	17%	39%	31%	14%	0%
	30-39	17%	47%	25%	10%	1%
	40-49	15%	35%	32%	17%	2%
	50-59	14%	35%	31%	18%	1%
	60 and over	15%	33%	27%	21%	4%
Commuter	Yes	16%	39%	30%	14%	1%
	No	15%	37%	25%	20%	4%



Dessible	transportation					
	Possible transportation improvements: Improving					
	y options for	Extremely			Not a	
	n your area who	high	High	Somewhat	priority	Don't know/
	not drive	priority		high priority	atall	Refused
	Total	15%	42%	30%	12%	1%
City	Alpharetta	18%	36%	31%	15%	0%
	Johns Creek	11%	36%	36%	14%	3%
	Roswell	18%	43%	23%	15%	0%
	Sandy Springs	14%	44%	29%	9%	3%
Gender	Male	13%	39%	33%	13%	1%
	Female	17%	44%	26%	12%	2%
Age	18-29	17%	42%	33%	8%	0%
	30-39	20%	45%	23%	12%	0%
	40-49	10%	41%	33%	14%	1%
	50-59	12%	39%	35%	13%	1%
	60 and over	15%	39%	28%	14%	4%
Commuter	Yes	14%	44%	30%	13%	0%
	No	19%	38%	28%	12%	3%

		Extremely			Not a	
	ility options for	high	High	Somewhat	1	Don't know/
individuals	with disabilities	priority	priority	high priority	at all	Refused
	Total	17%	45%	27%	9%	1%
City	Alpharetta	18%	36%	31%	14%	1%
	Johns Creek	14%	41%	29%	13%	3%
	Roswell	21%	47%	24%	7%	1%
	Sandy Springs	14%	48%	29%	7%	2%
Gender	Male	15%	44%	30%	10%	1%
	Female	19%	46%	25%	8%	2%
Age	18-29	20%	46%	29%	6%	0%
	30-39	18%	53%	22%	8%	0%
	40-49	13%	39%	36%	10%	2%
	50-59	18%	43%	28%	11%	1%
	60 and over	19%	43%	23%	11%	3%
Commuter	Yes	16%	45%	29%	9%	1%
	No	20%	44%	24%	9%	3%



Possible	transportation	Extremely			Not a	
improveme	ents: Developing c transit options	high priority	High priority	Somewhat high priority	priority	Don't know/ Refused
	Total	28%	38%	22%	11%	1%
City	Alpharetta	26%	38%	23%	12%	1%
	Johns Creek	28%	34%	20%	16%	1%
	Roswell	32%	42%	16%	10%	0%
	Sandy Springs	25%	37%	25%	10%	2%
Gender	Male	24%	40%	22%	14%	1%
	Female	31%	36%	22%	10%	1%
Age	18-29	33%	31%	31%	6%	0%
	30-39	34%	41%	14%	11%	0%
	40-49	23%	39%	23%	15%	1%
	50-59	23%	36%	28%	12%	1%
	60 and over	24%	41%	18%	13%	3%
Commuter	Yes	29%	39%	22%	10%	0%
	No	24%	37%	20%	15%	3%

Possible transportation improvements: Repairing		Extremely high	High	Somewhat	Not a priority	Don't know/
	e roads	priority	priority	high priority	at all	Refused
	Total	21%				1%
City	Alpharetta	15%	55%	20%	10%	0%
	Johns Creek	22%	40%	23%	14%	1%
	Roswell	26%	44%	24%	6%	0%
	Sandy Springs	19%	46%	22%	11%	2%
Gender	Male	17%	46%	25%	11%	1%
	Female	25%	46%	20%	8%	1%
Age	18-29	14%	47%	25%	14%	0%
	30-39	22%	42%	24%	12%	0%
	40-49	23%	49%	21%	6%	0%
	50-59	19%	49%	23%	8%	1%
	60 and over	25%	44%	21%	7%	3%
Commuter	Yes	21%	47%	24%	8%	0%
	No	22%	45%	20%	10%	3%



Possible	transportation					
	improvements: Improving					
connection	ns and making it					
	et to destinations				Not a	
in the Nort	h Fulton County area	high priority	High priority	Somewhat high priority	priority at all	Don't know/ Refused
	Total	17%				1%
City	Alpharetta	13%	61%	20%	6%	1%
	Johns Creek	17%	47%	29%	5%	2%
	Roswell	24%	39%	31%	6%	0%
	Sandy Springs	14%	41%	34%	9%	2%
Gender	Male	15%	47%	32%	6%	1%
	Female	19%	45%	27%	7%	1%
Age	18-29	17%	42%	39%	3%	0%
	30-39	15%	51%	30%	3%	0%
	40-49	18%	50%	23%	8%	1%
	50-59	18%	44%	29%	8%	1%
	60 and over	17%	41%	28%	11%	3%
Commuter	Yes	18%	47%	29%	6%	0%
	No	13%	47%	28%	9%	3%

destina	Do you ever walk to destinations in your			Don't know/
con	nmunity?	Yes	No	Refused
	Total	37%	63%	1%
City	Alpharetta	39%	61%	0%
	Johns Creek	36%	63%	1%
	Roswell	33%	67%	0%
	Sandy Springs	40%	58%	2%
Gender	Male	36%	64%	0%
	Female	37%	62%	1%
Age	18-29	47%	53%	0%
	30-39	38%	62%	0%
	40-49	37%	63%	0%
	50-59	37%	63%	0%
	60 and over	30%	70%	0%
Commuter	Yes	38%	61%	0%
	No	35%	64%	0%



Destinatio	ns walk to most		
often: F	Yes	No	
	Total	60%	40%
City	Alpharetta	51%	49%
	Johns Creek	75%	25%
	Roswell	52%	48%
	Sandy Springs	68%	32%
Gender	Male	61%	39%
	Female	60%	40%
Age	18-29	59%	41%
	30-39	55%	45%
	40-49	61%	39%
	50-59	74%	26%
	60 and over	56%	44%
Commuter	Yes	65%	35%
	No	49%	51%

	ns walk to most		
ofte	Yes	No	
	Total	3%	97%
City	Alpharetta	2%	98%
	Johns Creek	2%	98%
	Roswell	0%	100%
	Sandy Springs	6%	94%
Gender	Male	2%	98%
	Female	3%	97%
Age	18-29	0%	100%
	30-39	5%	95%
	40-49	1%	99%
	50-59	4%	96%
	60 and over	1%	99%
Commuter	Yes	2%	98%
	No	3%	97%



Destinatio	ns walk to most		
often:	Yes	No	
	Total	11%	89%
City	Alpharetta	11%	89%
	Johns Creek	5%	95%
	Roswell	13%	87%
	Sandy Springs	11%	89%
Gender	Male	7%	93%
	Female	14%	86%
Age	18-29	12%	88%
	30-39	8%	92%
	40-49	16%	84%
	50-59	13%	87%
	60 and over	6%	94%
Commuter	Yes	11%	89%
	No	10%	90%

Destinatio	ns walk to most		
ofte	Yes	No	
	Total	33%	67%
City	Alpharetta	31%	69%
	Johns Creek	25%	75%
	Roswell	32%	68%
	Sandy Springs	39%	61%
Gender	Male	33%	67%
	Female	33%	67%
Age	18-29	41%	59%
	30-39	32%	68%
	40-49	37%	63%
	50-59	23%	77%
	60 and over	30%	70%
Commuter	Yes	33%	67%
	No	31%	69%



Destinatio	ns walk to most		
often: Fi	Yes	No	
	Total	26%	74%
City	Alpharetta	25%	75%
	Johns Creek	30%	70%
	Roswell	21%	79%
	Sandy Springs	30%	70%
Gender	Male	26%	74%
	Female	26%	74%
Age	18-29	18%	82%
	30-39	30%	70%
	40-49	26%	74%
	50-59	31%	69%
	60 and over	22%	78%
Commuter	Yes	25%	75%
	No	31%	69%

-			
Destinatio			
ofte	Yes	No	
	Total	27%	73%
City	Alpharetta	35%	65%
	Johns Creek	30%	70%
	Roswell	24%	76%
	Sandy Springs	22%	78%
Gender	Male	27%	73%
	Female	26%	74%
Age	18-29	18%	82%
	30-39	32%	68%
	40-49	30%	70%
	50-59	22%	78%
	60 and over	30%	70%
Commuter	Yes	27%	73%
	No	28%	72%



Destinatio			
often: Sc	Yes	No	
	Total	10%	90%
City	Alpharetta	17%	83%
	Johns Creek	5%	95%
	Roswell	13%	87%
	Sandy Springs	9%	91%
Gender	Male	10%	90%
	Female	10%	90%
Age	18-29	6%	94%
	30-39	11%	89%
	40-49	12%	88%
	50-59	8%	92%
	60 and over	11%	89%
Commuter	Yes	10%	90%
	No	9%	91%

				А		
How often do you walk to		Several		•	One a	
destinatior	ns in your area?			times a	month	Don't know/
		week	week	month	or less	Refused
	Total	36%	24%	21%	17%	1%
City	Alpharetta	29%	26%	22%	22%	1%
	Johns Creek	34%	32%	14%	20%	0%
	Roswell	43%	31%	18%	8%	0%
	Sandy Springs	37%	17%	29%	17%	0%
Gender	Male	43%	20%	19%	15%	3%
	Female	31%	27%	23%	18%	0%
Age	18-29	35%	24%	24%	18%	0%
	30-39	32%	29%	18%	17%	3%
	40-49	46%	21%	24%	9%	0%
	50-59	36%	22%	21%	21%	0%
	60 and over	33%	21%	23%	20%	4%
Commuter	Yes	36%	25%	21%	17%	0%
	No	37%	20%	22%	17%	5%



Need more sidewalks?: Your neighborhood		Definitely yes	Probably yes	Probably no	Definitely no	Don't know/ Refused
	Total	33%	22%	17%	25%	4%
City	Alpharetta	32%	21%	14%	31%	3%
	Johns Creek	38%	22%	16%	22%	2%
	Roswell	30%	22%	17%	27%	4%
	Sandy Springs	32%	23%	19%	18%	7%
Gender	Male	30%	22%	16%	28%	4%
	Female	35%	22%	17%	22%	5%
Age	18-29	31%	19%	17%	25%	8%
	30-39	33%	25%	19%	22%	2%
	40-49	36%	23%	18%	22%	2%
	50-59	35%	15%	15%	31%	3%
	60 and over	30%	25%	14%	26%	5%
Commuter	Yes	33%	22%	19%	22%	4%
	No	33%	21%	12%	30%	5%

Need mo	re sidewalks?:	Definitely	Probably	Probably	Definitely	Don't know/
Nearby schools		yes	ves	no	no	Refused
	Total	29%				7%
City	Alpharetta	33%	26%	13%	21%	7%
	Johns Creek	31%	33%	21%	12%	3%
	Roswell	27%	28%	16%	21%	7%
	Sandy Springs	22%	27%	22%	18%	10%
Gender	Male	25%	28%	18%	22%	7%
	Female	32%	28%	18%	14%	7%
Age	18-29	22%	33%	22%	11%	11%
	30-39	28%	37%	14%	18%	3%
	40-49	36%	22%	22%	17%	3%
	50-59	28%	23%	18%	24%	7%
	60 and over	25%	26%	19%	19%	12%
Commuter	Yes	27%	29%	20%	18%	6%
	No	32%	27%	15%	18%	8%



Shopping	re sidewalks?: and business istricts	Definitely yes	Probably yes	Probably no	Definitely no	Don't know/ Refused
	Total	22%	31%	19%	22%	5%
City	Alpharetta	27%	23%	20%	25%	5%
	Johns Creek	25%	32%	21%	19%	3%
	Roswell	20%	34%	17%	24%	5%
	Sandy Springs	16%	33%	22%	21%	8%
Gender	Male	20%	30%	19%	26%	5%
	Female	24%	33%	20%	18%	6%
Age	18-29	19%	36%	8%	28%	8%
	30-39	20%	40%	22%	16%	3%
	40-49	29%	31%	18%	18%	3%
	50-59	21%	22%	22%	31%	4%
	60 and over	19%	27%	23%	25%	7%
Commuter	Yes	21%	33%	22%	20%	5%
	No	25%	30%	13%	25%	6%

	re sidewalks?: major roads	Definitely yes	Probably yes	Probably no	Definitely no	Don't know/ Refused
	Total	34%	27%	20%	14%	5%
City	Alpharetta	40%	23%	18%	16%	3%
	Johns Creek	38%	32%	20%	9%	2%
	Roswell	34%	28%	20%	14%	4%
	Sandy Springs	28%	23%	26%	16%	7%
Gender	Male	34%	26%	22%	14%	4%
	Female	35%	29%	18%	14%	5%
Age	18-29	40%	26%	17%	9%	9%
	30-39	27%	34%	25%	12%	2%
	40-49	41%	26%	20%	11%	2%
	50-59	35%	21%	19%	22%	3%
	60 and over	33%	25%	19%	17%	6%
Commuter	Yes	33%	28%	22%	13%	4%
	No	37%	26%	17%	14%	5%



	re sidewalks?: Parks	Definitely yes	Probably yes	Probably no	Definitely no	Don't know/ Refused
	Total	25%	25%	23%	20%	6%
City	Alpharetta	23%	25%	21%	27%	4%
	Johns Creek	27%	22%	27%	19%	5%
	Roswell	27%	21%	21%	25%	6%
	Sandy Springs	21%	31%	25%	14%	9%
Gender	Male	22%	22%	26%	24%	6%
	Female	28%	28%	21%	17%	6%
Age	18-29	31%	17%	25%	17%	11%
	30-39	28%	27%	26%	17%	2%
	40-49	23%	29%	23%	22%	3%
	50-59	24%	22%	22%	27%	5%
	60 and over	23%	26%	21%	22%	9%
Commuter	Yes	23%	26%	26%	20%	5%
	No	31%	23%	19%	21%	7%

	Do you ever bike to			
	destinations in your			Don't know/
com	nmunity?	Yes	No	Refused
	Total	14%	85%	1%
City	Alpharetta	19%	80%	0%
	Johns Creek	19%	80%	1%
	Roswell	16%	84%	0%
	Sandy Springs	5%	93%	2%
Gender	Male	17%	82%	0%
	Female	11%	88%	1%
Age	18-29	11%	89%	0%
	30-39	15%	85%	0%
	40-49	19%	81%	0%
	50-59	16%	84%	0%
	60 and over	7%	93%	0%
Commuter	Yes	16%	84%	0%
	No	11%	88%	0%



Destinatio			
often: F	Yes	No	
	Total	66%	34%
City	Alpharetta	65%	35%
	Johns Creek	82%	18%
	Roswell	56%	44%
	Sandy Springs	44%	56%
Gender	Male	64%	36%
	Female	69%	31%
Age	18-29	100%	0%
	30-39	63%	37%
	40-49	55%	45%
	50-59	77%	23%
	60 and over	63%	37%
Commuter	Yes	71%	29%
	No	51%	49%

Destinations bike to most						
ofte	Yes	No				
	Total	5%	95%			
City	Alpharetta	8%	92%			
	Johns Creek	0%	100%			
	Roswell	4%	96%			
	Sandy Springs	12%	88%			
Gender	Male	3%	97%			
	Female	7%	93%			
Age	18-29	0%	100%			
	30-39	0%	100%			
	40-49	7%	93%			
	50-59	15%	85%			
	60 and over	0%	100%			
Commuter	Yes	4%	96%			
	No	10%	90%			



Destinatio	ns bike to most		
often:	Yes	No	
	Total	8%	92%
City	Alpharetta	4%	96%
	Johns Creek	5%	95%
	Roswell	9%	91%
	Sandy Springs	4%	96%
Gender	Male	6%	94%
	Female	10%	90%
Age	18-29	0%	100%
	30-39	11%	89%
	40-49	12%	88%
	50-59	0%	100%
	60 and over	7%	93%
Commuter	Yes	6%	94%
	No	14%	86%

Destinatio	Destinations bike to most							
ofte	Yes	No						
	Total	22%	78%					
City	Alpharetta	24%	76%					
	Johns Creek	16%	84%					
	Roswell	21%	79%					
	Sandy Springs	26%	74%					
Gender	Male	23%	77%					
	Female	19%	81%					
Age	18-29	0%	100%					
	30-39	30%	70%					
	40-49	24%	76%					
	50-59	18%	82%					
	60 and over	18%	82%					
Commuter	Yes	22%	78%					
	No	23%	77%					



Destinatio	ns bike to most		
often: Fi	Yes	No	
	Total	17%	83%
City	Alpharetta	12%	88%
	Johns Creek	21%	79%
	Roswell	9%	91%
	Sandy Springs	45%	55%
Gender	Male	21%	79%
	Female	13%	87%
Age	18-29	25%	75%
	30-39	26%	74%
	40-49	13%	87%
	50-59	9%	91%
	60 and over	16%	84%
Commuter	Yes	17%	83%
	No	20%	80%

Destinations bike to most						
ofte	Yes	No				
	Total	35%	65%			
City	Alpharetta	31%	69%			
	Johns Creek	31%	69%			
	Roswell	33%	67%			
	Sandy Springs	54%	46%			
Gender	Male	36%	64%			
	Female	33%	67%			
Age	18-29	0%	100%			
	30-39	26%	74%			
	40-49	56%	44%			
	50-59	33%	67%			
	60 and over	32%	68%			
Commuter	Yes	36%	64%			
	No	33%	67%			



Destinatio	ns bike to most		
often: Sc	Yes	No	
	Total	5%	95%
City	Alpharetta	3%	97%
	Johns Creek	4%	96%
	Roswell	10%	90%
	Sandy Springs	4%	96%
Gender	Male	6%	94%
	Female	4%	96%
Age	18-29	0%	100%
	30-39	7%	93%
	40-49	4%	96%
	50-59	9%	91%
	60 and over	0%	100%
Commuter	Yes	3%	97%
	No	13%	87%

How ofter	n do you ride a	0	A I	A	0	
	tinations in your	Several				
	area?	times a	once a	times a	month	Don't know/
		week	week	month	or less	Refused
	Total	32%	19%	24%	23%	2%
City	Alpharetta	26%	20%	38%	9%	6%
	Johns Creek	44%	11%	15%	30%	0%
	Roswell	34%	12%	24%	28%	2%
	Sandy Springs	12%	64%	14%	10%	0%
Gender	Male	35%	7%	25%	29%	4%
	Female	27%	35%	24%	14%	0%
Age	18-29	25%	25%	25%	25%	0%
	30-39	44%	11%	19%	26%	0%
	40-49	24%	23%	27%	23%	3%
	50-59	35%	18%	24%	19%	4%
	60 and over	21%	28%	29%	16%	5%
Commuter	Yes	31%	19%	26%	22%	2%
	No	37%	19%	20%	23%	2%



	e bicycle lanes?: eighborhood	Definitely yes	Probably yes	Probably no	Definitely no	Don't know/ Refused
	Total	24%				7%
City	Alpharetta	30%	20%	17%	29%	4%
	Johns Creek	26%	34%	16%	23%	1%
	Roswell	20%	27%	22%	20%	11%
	Sandy Springs	21%	30%	19%	19%	11%
Gender	Male	20%	30%	19%	24%	7%
	Female	27%	26%	19%	21%	8%
Age	18-29	19%	31%	17%	19%	14%
	30-39	19%	36%	21%	19%	5%
	40-49	28%	27%	20%	22%	3%
	50-59	29%	18%	18%	30%	6%
	60 and over	25%	24%	19%	22%	10%
Commuter	Yes	21%	32%	20%	21%	6%
	No	31%	20%	18%	23%	8%

	e bicycle lanes?: by schools	Definitely ves	Probably yes	Probably no	Definitely no	Don't know/ Refused
ittear	Total	29%				
City	Alpharetta	32%	28%	13%	17%	9%
	Johns Creek	33%	30%	21%	12%	3%
	Roswell	29%	28%	16%	13%	13%
	Sandy Springs	21%	30%	23%	11%	15%
Gender	Male	27%	29%	19%	14%	11%
	Female	30%	28%	19%	12%	10%
Age	18-29	17%	33%	19%	11%	19%
	30-39	30%	36%	18%	8%	8%
	40-49	38%	29%	16%	12%	5%
	50-59	32%	18%	20%	20%	10%
	60 and over	22%	24%	22%	18%	13%
Commuter	Yes	26%	32%	21%	11%	10%
	No	36%	21%	15%	17%	10%



Shopping	e bicycle lanes?: g and business listricts	Definitely yes	Probably yes	Probably no	Definitely no	Don't know/ Refused
	Total	28%	26%	21%	17%	8%
City	Alpharetta	31%	23%	16%	23%	6%
	Johns Creek	33%	25%	23%	16%	3%
	Roswell	25%	28%	21%	15%	11%
	Sandy Springs	24%	25%	24%	15%	11%
Gender	Male	28%	23%	22%	18%	8%
	Female	27%	29%	20%	15%	8%
Age	18-29	19%	31%	28%	8%	14%
	30-39	27%	34%	17%	15%	6%
	40-49	33%	25%	21%	16%	4%
	50-59	32%	17%	22%	23%	6%
	60 and over	24%	22%	22%	22%	11%
Commuter	Yes	26%	27%	24%	16%	7%
	No	30%	27%	15%	19%	9%

	e bicycle lanes?: major roads	Definitely yes	Probably yes	Probably no	Definitely no	Don't know/ Refused
	Total	33%	26%	18%	15%	8%
City	Alpharetta	37%	25%	11%	23%	4%
	Johns Creek	33%	26%	24%	15%	3%
	Roswell	34%	26%	14%	15%	11%
	Sandy Springs	27%	29%	22%	11%	11%
Gender	Male	31%	25%	20%	16%	8%
	Female	35%	27%	16%	15%	8%
Age	18-29	31%	28%	19%	8%	14%
	30-39	30%	31%	19%	14%	5%
	40-49	39%	27%	17%	14%	4%
	50-59	39%	16%	18%	21%	6%
	60 and over	28%	25%	19%	19%	10%
Commuter	Yes	30%	29%	20%	15%	7%
	No	39%	21%	15%	16%	9%



-						-
	lk or ride a bike					
	n if: The roads					
	pedestrian- and	Definitely	Probably	Probably	Definitely	Don't know/
bike	e-friendly	yes	yes	no	no	Refused
	Total	39%	29%	17%	13%	2%
City	Alpharetta	34%	35%	17%	12%	1%
	Johns Creek	37%	32%	20%	10%	1%
	Roswell	37%	29%	15%	17%	2%
	Sandy Springs	44%	23%	18%	13%	3%
Gender	Male	39%	28%	18%	14%	1%
	Female	40%	31%	15%	12%	2%
Age	18-29	33%	33%	28%	6%	0%
	30-39	44%	33%	13%	8%	1%
	40-49	46%	31%	14%	9%	0%
	50-59	43%	26%	15%	15%	2%
	60 and over	24%	23%	20%	31%	2%
Commuter	Yes	41%	31%	18%	10%	1%
	No	39%	26%	14%	19%	2%

	lk or ride a bike					
more often if: Your						
destinations were closer to		Definitely	Probably	Probably	Definitely	Don't know/
your home		yes	yes	no	no	Refused
	Total	38%	35%	15%	10%	2%
City	Alpharetta	37%	39%	12%	12%	1%
	Johns Creek	38%	36%	18%	7%	1%
	Roswell	39%	35%	11%	12%	2%
	Sandy Springs	36%	33%	17%	10%	4%
Gender	Male	36%	36%	15%	11%	2%
	Female	40%	34%	14%	10%	2%
Age	18-29	39%	39%	17%	6%	0%
	30-39	46%	37%	12%	4%	1%
	40-49	42%	36%	16%	5%	1%
	50-59	35%	36%	13%	14%	3%
	60 and over	22%	28%	20%	28%	2%
Commuter	Yes	37%	38%	15%	8%	2%
	No	39%	31%	14%	14%	2%



In your opinion, how useful is public transit – such as				Not	
trains or buses – for most		Very	Somewhat	useful	Don't know/
people in your area?		useful	useful	at all	Refused
	Total	29%	38%	31%	3%
City	Alpharetta	25%	46%	24%	5%
	Johns Creek	21%	41%	37%	1%
	Roswell	26%	36%	36%	2%
	Sandy Springs	42%	34%	20%	3%
Gender	Male	28%	38%	32%	2%
	Female	29%	38%	30%	3%
Age	18-29	39%	39%	19%	3%
	30-39	26%	42%	32%	1%
	40-49	28%	36%	35%	1%
	50-59	29%	33%	37%	1%
	60 and over	29%	41%	27%	4%
Commuter	Yes	29%	41%	29%	1%
	No	30%	32%	34%	4%

				•		
How often do you ride public transit?				A .		
		0	A Ia	couple	• ••••	
		Several				Den't know/
			once a	of	month	Don't know/
		week	week	month	or less	Refused
	Total	7%	4%	16%	64%	10%
City	Alpharetta	5%	3%	18%	62%	12%
	Johns Creek	3%	3%	19%	71%	5%
	Roswell	8%	4%	13%	61%	14%
	Sandy Springs	14%	6%	16%	56%	8%
Gender	Male	8%	3%	16%	63%	9%
	Female	7%	4%	15%	64%	10%
Age	18-29	17%	3%	17%	47%	17%
	30-39	8%	4%	19%	60%	10%
	40-49	6%	5%	12%	72%	5%
	50-59	5%	3%	15%	72%	5%
	60 and over	4%	4%	15%	66%	11%
Commuter	Yes	9%	5%	17%	62%	7%
	No	4%	2%	12%	68%	13%



	Quality of public transit: Convenience to your home		Good	Fair	Poor	Don't know/ Refused
	Total	8%	20%	24%	35%	13%
City	Alpharetta	6%	16%	25%	38%	14%
	Johns Creek	4%	14%	18%	48%	16%
	Roswell	7%	22%	25%	33%	13%
	Sandy Springs	15%	27%	29%	19%	10%
Gender	Male	8%	21%	21%	38%	12%
	Female	7%	19%	27%	33%	14%
Age	18-29	14%	14%	39%	17%	17%
	30-39	6%	22%	30%	32%	10%
	40-49	6%	22%	16%	44%	12%
	50-59	8%	17%	22%	43%	9%
	60 and over	8%	24%	19%	31%	18%
Commuter	Yes	7%	21%	27%	36%	9%
	No	9%	18%	18%	35%	21%

	f public transit: nce to your job	Excellent	Good	Fair	Poor	Don't know/ Refused
Convenie	Total	8%		-		
City	Alpharetta	4%	17%	16%	41%	22%
	Johns Creek	6%	13%	13%	43%	25%
	Roswell	6%	18%	22%	33%	22%
	Sandy Springs	15%	25%	20%	20%	20%
Gender	Male	9%	20%	17%	34%	19%
	Female	6%	16%	19%	34%	25%
Age	18-29	14%	19%	17%	28%	22%
	30-39	9%	26%	20%	32%	13%
	40-49	6%	18%	19%	38%	19%
	50-59	8%	12%	17%	43%	20%
	60 and over	3%	13%	18%	24%	42%
Commuter	Yes	9%	23%	21%	36%	11%
	No	5%	8%	12%	30%	45%



	Quality of public transit: Convenience to shopping					Don't know/
	areas	Excellent	Good	Fair	Poor	Refused
	Total	6%	22%	27%	30%	14%
City	Alpharetta	9%	18%	29%	29%	15%
	Johns Creek	2%	19%	19%	42%	17%
	Roswell	5%	23%	28%	31%	13%
	Sandy Springs	9%	30%	32%	18%	11%
Gender	Male	8%	23%	27%	30%	13%
	Female	5%	22%	28%	31%	15%
Age	18-29	9%	20%	40%	11%	20%
	30-39	6%	28%	27%	29%	10%
	40-49	6%	26%	22%	34%	13%
	50-59	7%	13%	30%	41%	9%
	60 and over	5%	23%	22%	29%	21%
Commuter	Yes	6%	24%	30%	31%	10%
	No	7%	19%	23%	29%	22%

•	f public transit: eliability	Excellent	Good	Fair	Poor	Don't know/ Refused
	Total	7%	31%	27%	18%	17%
City	Alpharetta	8%	30%	27%	15%	19%
	Johns Creek	7%	22%	20%	33%	18%
	Roswell	6%	36%	23%	18%	16%
	Sandy Springs	8%	36%	31%	11%	13%
Gender	Male	9%	31%	27%	18%	16%
	Female	5%	31%	27%	19%	18%
Age	18-29	6%	44%	22%	6%	22%
	30-39	9%	31%	30%	19%	11%
	40-49	4%	33%	27%	19%	17%
	50-59	9%	25%	28%	26%	12%
	60 and over	7%	30%	21%	18%	24%
Commuter	Yes	7%	33%	30%	18%	12%
	No	6%	28%	21%	20%	26%



-	Quality of public transit: Safety		Good	Fair	Poor	Don't know/ Refused
	Total	7%	37%	25%		17%
City	Alpharetta	7%	33%	27%	13%	19%
	Johns Creek	4%	32%	22%	25%	18%
	Roswell	5%	37%	27%	14%	16%
	Sandy Springs	11%	43%	23%	8%	15%
Gender	Male	9%	38%	24%	11%	17%
	Female	4%	35%	25%	17%	18%
Age	18-29	6%	44%	25%	3%	22%
	30-39	6%	37%	27%	17%	13%
	40-49	5%	40%	24%	15%	16%
	50-59	8%	32%	26%	21%	13%
	60 and over	9%	36%	20%	12%	24%
Commuter	Yes	7%	40%	27%	14%	13%
	No	6%	31%	20%	17%	26%

	f public transit: anliness	Excellent	Good	Fair	Poor	Don't know/ Refused
	Total	7%	34%	27%	15%	17%
City	Alpharetta	6%	24%	33%	17%	20%
	Johns Creek	9%	27%	23%	23%	18%
	Roswell	6%	36%	28%	14%	16%
	Sandy Springs	8%	42%	29%	6%	15%
Gender	Male	10%	33%	25%	16%	17%
	Female	4%	35%	29%	14%	18%
Age	18-29	6%	39%	28%	6%	22%
	30-39	6%	34%	30%	18%	12%
	40-49	7%	32%	30%	16%	16%
	50-59	8%	34%	25%	19%	14%
	60 and over	8%	34%	23%	11%	24%
Commuter	Yes	7%	35%	30%	15%	12%
	No	6%	31%	23%	15%	26%



-						
	e public transit nents: Making it	Extremely			Not a	
	et to locations in	high	High	Somewhat	priority	Don't know/
y y	our city	priority	priority	high priority	at all	Refused
	Total	15%	45%	21%	10%	9%
City	Alpharetta	16%	49%	18%	6%	11%
	Johns Creek	17%	41%	18%	12%	12%
	Roswell	16%	43%	25%	9%	6%
	Sandy Springs	13%	46%	21%	11%	8%
Gender	Male	13%	43%	25%	10%	9%
	Female	16%	47%	17%	11%	9%
Age	18-29	26%	51%	6%	3%	14%
	30-39	15%	52%	18%	11%	4%
	40-49	13%	43%	25%	11%	8%
	50-59	14%	38%	30%	12%	5%
	60 and over	11%	42%	22%	13%	12%
Commuter	Yes	15%	48%	21%	10%	6%
	No	13%	38%	22%	12%	14%

	public transit					
	improvements: Making it					
	et to destinations				Not a	
in the Nort	h Fulton County	high	High	Somewhat	• •	Don't know/
	area	priority	priority	high priority	at all	Refused
	Total	16%	37%	29%	9%	9%
City	Alpharetta	19%	31%	33%	5%	11%
	Johns Creek	14%	37%	25%	12%	12%
	Roswell	19%	40%	27%	9%	6%
	Sandy Springs	16%	36%	31%	8%	8%
Gender	Male	16%	34%	31%	10%	9%
	Female	17%	39%	27%	7%	9%
Age	18-29	29%	40%	17%	0%	14%
	30-39	14%	43%	29%	10%	4%
	40-49	16%	37%	32%	7%	8%
	50-59	15%	34%	33%	12%	5%
	60 and over	14%	30%	31%	13%	12%
Commuter	Yes	18%	39%	29%	8%	6%
	No	14%	33%	28%	12%	14%



Dessible	un un lin transit					
	e public transit	Extremely			Not a	
	ents: Making it et to Atlanta from	Extremely high	High	Somewhat		Don't know/
	ur area?	priority		high priority	• •	Refused
yU	Total		-			
		19%	38%	24%	9%	9%
City	Alpharetta	25%	39%	21%	5%	11%
	Johns Creek	16%	39%	22%	11%	12%
	Roswell	26%	34%	24%	11%	6%
	Sandy Springs	14%	42%	27%	9%	8%
Gender	Male	18%	39%	25%	9%	9%
	Female	21%	38%	23%	9%	9%
Age	18-29	29%	34%	23%	0%	14%
	30-39	19%	46%	22%	9%	4%
	40-49	18%	40%	24%	11%	8%
	50-59	21%	38%	28%	9%	5%
	60 and over	17%	29%	27%	15%	12%
Commuter	Yes	21%	41%	25%	8%	6%
	No	17%	33%	23%	14%	14%

	public transit					
improvements: Making it		Extremely			Not a	
	et to other parts	high	High	Somewhat	priority	Don't know/
of the	metro area	priority	priority	high priority	at all	Refused
	Total	18%	38%	26%	9%	9%
City	Alpharetta	19%	35%	28%	7%	11%
	Johns Creek	15%	38%	24%	12%	12%
	Roswell	20%	41%	23%	9%	6%
	Sandy Springs	19%	36%	28%	9%	8%
Gender	Male	17%	38%	28%	8%	9%
	Female	19%	37%	25%	10%	9%
Age	18-29	25%	36%	22%	3%	14%
	30-39	19%	42%	27%	9%	4%
	40-49	16%	42%	25%	8%	8%
	50-59	17%	38%	29%	10%	5%
	60 and over	16%	29%	28%	15%	12%
Commuter	Yes	19%	41%	27%	8%	6%
	No	17%	31%	25%	12%	14%



Deve	ware and the start					
	upport the state	Yes,	Yes,			
	government and nearby		other	Vee		Densit kin evv/
	counties providing funding		counties	Yes,	Nia	Don't know/
to MARTA?		only	only	both	No	Refused
	Total	3%	5%	72%	13%	6%
City	Alpharetta	2%	4%	79%	10%	5%
	Johns Creek	1%	8%	70%	16%	4%
	Roswell	9%	6%	64%	16%	5%
	Sandy Springs	1%	2%	79%	11%	8%
Gender	Male	2%	6%	70%	16%	6%
	Female	5%	5%	74%	11%	6%
Age	18-29	8%	3%	81%	3%	6%
	30-39	1%	6%	80%	11%	2%
	40-49	4%	7%	68%	16%	7%
	50-59	3%	6%	71%	16%	4%
	60 and over	3%	6%	66%	17%	8%
Commuter	Yes	4%	5%	74%	13%	5%
	No	3%	7%	69%	13%	8%

_						
proposed crossi Chattahoo would help in the Nort area. Do oppose crossi	eaders have l adding a new ng over the schee River that to reduce traffic h Fulton County you support or adding a new ng over the pochee River?	Strongly support	Somewhat support	Somewhat oppose	Strongly	Don't know/ Refused
	Total	44%	33%	9%	6%	8%
City	Alpharetta	48%	33%	7%	3%	10%
	Johns Creek	51%	34%	7%	1%	6%
	Roswell	45%	34%	9%	8%	5%
	Sandy Springs	36%	31%	13%	8%	11%
Gender	Male	46%	32%	10%	6%	7%
	Female	44%	34%	8%	6%	9%
Age	18-29	44%	42%	6%	3%	6%
	30-39	42%	42%	9%	4%	3%
	40-49	51%	27%	9%	4%	9%
	50-59	44%	26%	12%	9%	9%
	60 and over	43%	30%	9%	10%	8%
Commuter	Yes	48%	32%	10%	5%	5%
	No	38%	34%	7%	7%	13%

APPENDIX B

Land Use and Transportation Programs and Policies by Jurisdiction





Alpharetta

Comprehensive Plan 2025 (2008)

Land Use and Economic Development

- Ensure that future land use and development decisions are **consistent with long range planning goals and policies** and that such decisions promote **social and economic well-being**.
- Implement a land use plan that articulates a **physical policy for a compact urban area** and assures the **availability of utilities concurrent with development**.
- Encourage and promote **clean**, **high tech commercial development** that strengthens the economic base of the community and minimizes air and water pollution.
- Promote development that is **pedestrian-oriented and minimizes vehicular trips**.
- Adopt a land use plan that will **accommodate** the projected year 2025 population of 52,370 and employment base of 133,099.
- Use infrastructure as a **tool to guide development** into locations where the land is most cost effectively serviced (i.e., accessible to police, fire, sewer and the urban road network).
- **Implement a system** of interrelated land use and capital improvements planning.
- **Balance development on the east and west sides of the city** through policies that target capital investment in parks, roads and public buildings, and encourage private investment in business and residential development on the west side of the city.
- **Encourage large land holdings** to plan for multiple land uses.
- Develop **corridor design plans** for major entranceways into the city to serve as a guide for future development.
- **Prohibit extension of sewer** in the country estate area of the city.
- Develop subdivisions that foster a sense of community and promote pedestrian mobility, community recreation and an abundance of public open space.
- **Ensure suitable land is available** for the **projected acres** of future single-family development and multi-family development.
- Encourage residential uses in the Downtown at higher densities and in mixed use buildings.
- **Ensure suitable land** is available by the year 2020 for the **projected acres** that will be absorbed by retail uses, office uses and by business centers, industry and warehousing.
- Support a cohesive approach to providing **retail sales and service nodes** within the city thereby **avoiding strip commercial patterns** along arterial routes; these nodes would be developed on a scale that is compatible with residential development and pedestrian access.
- As major entranceways to the City, the interchanges along GA 400 should be **designated for office use** in order to preserve the corporate campus image of the City.
- Support a Downtown that contains a **compact arrangement of retail and commercial** enterprises with office, financial, entertainment, governmental and certain residential development, all de-signed and situated to permit internal pedestrian circulation.
- Continue to **encourage redevelopment of Alpharetta's Downtown** through major streetscape improvements, landscaping, business development, and higher density residential.

Housing

- Housing goals related to land use and urban design
 - Promote and encourage residential densities and designs that ensure **varied living areas and housing types**.
 - Promote and maintain **a supply of available land** for future housing development.

- Balance **residential development on the east and west sides** of the City.
- Housing strategies related to land use and urban design
 - **Preserve the character of distinct residential areas** such as Crabapple and the northwest quadrant horse farms.
 - **Encourage higher residential densities and appropriate mixed uses** close to downtown and other appropriate areas.
 - **Preserve Canton Street between Church Street and Hopewell Road** as residential and designate it as the Garden District of Alpharetta.
 - Maintain a balance between single-family and multi-family development in Alpharetta such that at **least 2/3's of the housing stock is single-family**.
 - Promote subdivisions that foster a sense of community and promote pedestrian mobility, the natural environment, community recreation and public open space.
 - Continue to preserve the area to the northwest as **Country Estate** with a minimum of three acres per unit.

Transportation

- Develop policy statements regarding **rail service** along GA 400 and express bus and HOV lanes.
- Explore the formation of a **Transportation Management Association** (TMA) along GA 400 and/or the Windward/Northpoint area.
- Review development guidelines and subdivision regulations for appropriate language supporting **development of the sidewalk and bicycle systems**.

Downtown Circulation Study (2008)

• **Upgrade bus stop amenities** in the downtown area.

Downtown Master Plan (2003)

- Utilize the Alpharetta Development Authority to **study and promote redevelopment opportunities in the downtown area**, and to **coordinate improvement and maintenance efforts with City departments**.
- Milton High School Site Feasibility Study: Redevelopment of this site has the **potential to be a public/private venture.** The redevelopment area of study may be logically expanded to include the residential/retail area planned along the nature preserve between Milton Avenue and Old Milton Parkway. It is recommended that the **City gain development rights** (perhaps through first right of refusal or partnership with the School Board) so that a detailed feasibility study may be conducted to test the proposed development scenario(s). Time frame: next 6 months through desired sale date for MHS property (2004).
- City Hall Site Feasibility Study: to determine amount of space necessary for City functions, as well as potential tenants or lease ventures. **Time frame: end of 2003**. Land assembly may begin upon completion of detailed program, or sooner if opportunities arise.
- Update Prior Detailed Parking Feasibility: **new locations** have been identified for potential municipal and private lots and decks within the Master Plan. Preliminary assessment of pros and cons of different locations has been made by Walker Parking as part of this study. Most locations shown for shared structured parking are contingent upon further development of the area, and may be studied in conjunction with specific development proposals. Should the City desire a dedicated municipal lot constructed through City initiative, an updated economic feasibility study should be

completed, and various funding mechanisms identified (State, ARC, TAD, etc.). For the City Hall site, this may be part of the City Hall feasibility study. Time frame: as needed.

- Green Space and Trail System Program: in order to fully realize the nature preserve areas, pocket parks and fountains, and trail system, a **detailed planning study is recommended** to identify and quantify each component (in terms of area/scope, design, and cost). Excellent candidate for LCI funding. Time frame: begin planning and LCI process within next 6 months.
- Conduct Detailed **Technical Feasibility for Proposed Transportation Improvements**: This effort may be part of an LCI implementation funds application process, in conjunction with previously mentioned elements such as the trail system. In particular, the proposed median on South Main Street should be studied via detailed survey information and GDOT coordination to determine feasibility (this streetscape improvement may have an impact on available parking, and should be considered alongside the parking analysis). Some improvements should be evaluated once specific development scenarios become more concrete. If the new use of the Milton High School site generates more traffic than the high school, then an impact analysis will determine design criteria for the roads servicing the site (including the proposed new road). The proposed new road may be a public/private venture. Completion of Westside Parkway should modify commuter traffic flow, but the extent still needs to be determined. Potential funding sources: various. Time frame: immediate, ongoing.
- Future Library Site: approach the Library Board about the **development of a replacement facility for the Mayfield Branch.** Also, approach the Friends of the Library to explore the possibility of a fundraiser for construction of a new, potentially City-owned library (in the absence of County funds).

North Point Activity Center LCI (2008)

- Extensions of the Big Creek Greenway are recommended.
- The study also recommends **completion of sidewalks** to fill in existing gaps.
- Study goals in the Appendix of the North Point Activity Center LCI identify goals of enhancing local transit service through **a future transit circulator system**, and future heavy rail service.
- Study goals recommend a **shift in land use policy** from the underlying zoning to three mixed use character areas.
- A new overlay zoning category is recommended to **foster vertical mixed-use development**. The text describes that the adopted future land use and the zoning precludes mixing of land uses within a single development without prescribed development agreements with City Council. As a result, these policies likely limit mixed use development and result in segregated development.
- Lobby for/promote **high capacity transit** in the GA 400 corridor.

Johns Creek

<u>Comprehensive Plan 2030 (2008)</u>

Transportation

- The City of **Johns Creek supports the two-lane improvement plan** derived from the Georgia Department of Transportation (GDOT)/Mulkey public planning process.
- Coordinate with Metropolitan Atlanta Rapid Transit Authority (MARTA), Georgia Regional Transportation Authority (GRTA) and Atlanta Regional Commission (ARC) to **ensure existing and future bus routes and stops are appropriately planned for and are incorporated into the regional transportation networks and land use plan.**
- Continuing to provide access to this area from the Medlock Bridge Road and McGinnis Ferry Road corridors, as well as to Bell Road in the future, is important to **disperse access needs and**

emergency response for this growing area. **Connection to the surrounding community via pedestrian and roadway connections** could **provide commuting choices** for some employees who live in the vicinity of Technology Park.

- A **multi-use trail** is programmed along the west shoulder of Medlock Bridge Road. **Future connections linking to the existing trail and planned extensions** along Bell Road and Rogers Bridge Road **could provide enhanced alternative mobility options**.
- Access to express transit routes through continued GTRA express bus service is recommended.
- **Implementing appropriate access management strategies** along the (State Bridge Road) corridor as it transitions from predominantly commercial to residential uses **is important to preserve the residential character.**
- The City should investigate a fuller use of the capacity on Abbotts Bridge and Parson Road to **minimize impacts on the residential character** of these communities **while accommodating future travel demand**.
- Buice Road is the primary transportation corridor in the area. The long range strategy for accommodating future travel demand focuses on relieving overcapacity intersections and roadway links along the surrounding arterials while preserving Old Alabama and Buice Road as two-lane roads with turn lanes where needed.
- McGinnis Ferry improvements: Important for McGinnis and Bell Road **bike/ped improvements to connect with planned Chattahoochee recreational facilities**
- Coordinate with Pedestrians Educating Drivers on Safety (PEDS) to **coordinate a "Safe Routes to School" program** and other pedestrian programs.
- Collaborate with the National Park Service to **maximize greenway connectivity**.
- Coordinate with adjacent jurisdictions for **interconnected greenways and parks**.
- "Future efforts should **encourage network connectivity between roadways and pedestrian/bicycle facilities.** It is important that the emerging greenway system also be connected to the roadway and pedestrian/bicycle network. **The ultimate goal is to achieve a complete and interconnected pedestrian and bicycle network throughout Johns Creek.**"
- Sidewalk projects
 - **Complete sidewalk network** along all collector and arterial roads within ½ mile of schools, libraries, and parks, as well as along local streets **providing direct access to schools, libraries, and parks.**
 - Complete sidewalks along both sides of McGinnis Ferry Rd from Sargent Rd to Chattahoochee River.
 - **Complete sidewalk network in conjunction with roadway improvements:** Jones Bridge Rd, Old Alabama Rd, Medlock Bridge Rd, Parsons Rd, Barnwell Rd, Rogers Bridge Rd, McGinnis Ferry Rd, other roadways as necessary
- Promote **roadside beautification**.
- Establish gateways and corridors to create a "sense of place".
- Study Medlock Bridge Corridor to identify potential park and ride lot locations
- Work with agencies and adjacent jurisdictions toward **establishing interim express bus service to Alpharetta and Duluth.**
- Support regional efforts for transit enhanced corridor (BRT) along State Bridge Road from Alpharetta to Duluth

Land Use and Economic Development

- Preserve some existing undeveloped land for City park space.
- Enforce existing sidewalk regulations and **support additional measures to accommodate pedestrians** (Citywide)
- Preserve character of existing residential neighborhoods.
- Determine possible locations and uses for a Town Center, City Center or City Hall.
- Pursue a master plan for the redevelopment or development of a Town Center, City Center or City Hall.

- Commit to redeveloping and **enhancing existing commercial development** along major roads and activity nodes.
- Encourage mixed-use development and **design standards that are more human-scaled and less auto-oriented** along main corridors and in activity nodes.
- Consider **increased density to preserve greenspace** in other parts of the City.
- Utilize landscaping, lighting, signage, underground utilities, and building design to **add value to the community**.
- Promote **walkability**, **interaction among businesses**, clear visibility of entry-ways and **centralized open space**.
- Promote walkability between homes, schools, shopping, civic uses and open space.
- Prohibit residential, commercial, and industrial development in the 100-year floodplain.
- Investigate the **creation of a non-profit land trust to solicit and hold conservation easements** for land in and near the City.
- Expand Autrey Mill Nature Preserve to available, adjacent land.
- Connect all current and future parks as well as **develop a continuous greenbelt network** throughout all new development.
- Create a **conservation subdivision ordinance**.
- Crossing improvements
 - Provide pedestrian and bicycle only connections between adjacent neighborhoods.
 - Construct grade separated pedestrian crossings between quadrants in activity areas and for key crossings of major roads: State Bridge/Medlock Bridge (elementary school, new high school, large commercial developments); Newtown area (Newtown Park, Mt. Pisgah Christian, Holy Redeemer)
- Trail/pathway projects
 - Johns Creek Greenway (2 segments)

Medlock Bridge Road Corridor LCI – Not Submitted (2006)

• None listed.

<u> Comprehensive Plan 2030 – Green Plan (2008)</u>

Land Use Recommendations

- The study makes four recommendations for Park development:
 - **Develop three small scenic parks with picnic areas on the Chattahoochee River** to provided access to the river which is currently limited.
 - **Create a community park (25 acres or more) in the central section of the city** (Planning Sub area 2), which currently has no parks.
 - Increase the rate of park acres per 1,000 residents to 6.0 (no timeframe given). This goal is seen as ambitious—it more than doubles the existing rate—but still less than the NRPA minimum standard, due to the perceived lack of available and affordable land and the perception that existing private open space (HOA-controlled, church properties, golf courses) compensates for the lack of public open space.
 - **Develop four to six new neighborhood parks** (average size 15 acres).
- The study also makes five recommendations for developing specific recreation facilities.
 - The study makes five recommendations related to land conservation:
 - Prohibit residential, commercial and industrial development in the 100 year flood plain.

- Support and enforce the Metropolitan River Protection Act within the city limits, continuing a practice to protect the Chattahoochee River and recognize its regional and national significance.
- Investigate the creation of a land trust that could solicit and hold various conservation easements in and near the City
- **Expand the Autrey Mill Nature preserve** to available land nearby

Milton

Comprehensive Plan 2028 (2008)

Land Use and Economic Development

- Encourage development that provides **appropriate employment opportunities** to serve our current and future population.
- Encourage development of a **balanced network of commercial activity centers** to meet the service needs of our citizens while avoiding unattractive and inefficient strip development.
- Encourage **mixed-use developments that are human-scale** and less auto-oriented where appropriate.
- Encourage the **efficient use of land** to avoid potential costs and problems associated with urban sprawl.
- The community wants to maintain the existing residential and rural character of Milton and do not want sprawl. However, **development of residential one-acre lots in the AG-1 zoning district continues to increase the number of low density residential units in the City**, and the fear that a neighborhood use like a corner grocery or drugstore in the neighborhood will eventually turn into a larger commercial intrusion into the community **has made it difficult to site neighborhood facilities** into these large areas of subdivision activity.

Transportation

- Consider creating a "Complete Streets" program to establish road design criteria that includes consideration of transit, bicycle, and pedestrian measures of service in addition to automobile levels of service.
- Create **gateways and corridors** to establish a **"sense of place"** for our community.
- **Committed to creating walkable, bikable, and wheelchair friendly access** for safe and attractive neighborhoods throughout the community, where people have attractive, **barrier free, and low-energy** access options to **schools, parks, and necessary services** (grocery store, drug store).

Milton Trail Plan (2007)

• Plan recommendations include requiring developer construction of planned trail segments along their roadway frontage, requiring "inter-parcel connectivity" of developments adjacent to plan-identified trails, incentives for showers and lockers in commercial developments, and discouragement of cul-de-sac patterns in future developments.

Milton Transportation Plan (In progress)

• A prioritized list of recommendations has not yet been finalized

Crabapple Crossroads Community Plan (2003)

• Explore the possibility of **on-street parallel parking along SR 372- Crabapple Road and Birmingham Hwy**.

- A parking deck or centralized parking location to replace parking at the front of the Alpharetta Government Center and for general use in Crabapple is recommended.
- Policy focused on **improving pedestrian circulation**.
- The vision for Crabapple is to develop as a **mixed-use rural village** while **preserving its historic resources** and developing an **interconnected transportation network.** The village will include a **pedestrian oriented core surrounded by residential uses at its perimeter.**
- Given the high level of historic integrity of the area, and the desire to maintain the "flavor" of the area, it is desirable to **use the historic land use pattern as a foundation for land use policy.**
- Based on residential demand, retail market analysis, land use policy criteria and recommended mix for a "Village" setting, the following overall program components are proposed for the entirety of the study area
- In order to protect greenspace within the Crabapple study area, a TDR program for residential land uses is recommended.
- To encourage the **adaptive use of other historic resources for office and commercial use** and to strengthen the commercial center, **parcels with historic resources are recommended to be designated for commercial and office use.** In addition, a bonus is recommended.
- Provide opportunities for **mixed-use developments** that are **compatible with a village-oriented development**.
- Provide for the **transition of land uses from higher to lower intensity** land uses in a pattern that supports **village type development**.
- Provide a variety of housing choices in Crabapple
- Preserve historic resources
- **Protect environmentally sensitive areas** and create a system of **trails and open space**.
- Recommended to develop a pilot **Green Building Incentive Program** so developers may be awarded a **floor area bonus for commercial or office buildings that incorporate Green Building Components**.

<u>Comprehensive Plan 2025 (2005)</u>

Housing

- Roswell seeks to maintain detached residential versus attached residential **ratio of 65:35**.
- Preserve the general **single-family residential** character of Roswell.
- Retain **detached single-family housing** as **the predominant housing type** in Roswell.

Land Use and Economic Development

- **Redevelopment** is planned for the area along Holcomb Bridge Road east of GA 400.
- The plan calls attention to **deliberate vacancies** and argues that they should be discouraged.
- Comprehensive Plan Short Term Work Program calls for the "implementation of a **gateway master plan** for major entrances to the City that incorporates various recommendations of adopted design guidelines."
- Comprehensive Plan recommends **updating the retail structures** in Roswell.
- Comprehensive Plan recommends the **conversion of some retail** to office use, residential, institutional, etc.
- Comprehensive Plan recommends that **new redevelopment** should be **mixed use and pedestrian friendly**.
- The Comprehensive plan states that **density bonuses** should be considered as an **incentive** for redevelopment.

- Allow Property Owners to **co-finance infrastructure and other improvements** through Business or Community Improvement Districts.
- The Comprehensive Plan recommends that it might be appropriate to encourage redevelopment by **building and operating parking decks**. Specifically, "this tool might be appropriate for South Atlanta Street and Canton Street (within the local historic district) and Midtown Roswell."
- Currently, the City is studying the Holcomb Bridge Road corridor east of GA 400, which includes fast food restaurants, gas stations, convenience and banking outlets, and retail centers. In order to accomplish its goals and vision for the Holcomb Bridge Road corridor, the City is working on a plan that will **discourage sprawl and encourage mixed-use redevelopment** and the preservation of the community's heritage and environmental assets, chief among them being the Chattahoochee River. The plan will contain a complete conceptual master plan for sidewalks and multi-purpose trails that will help overcome the visual barrier created by the presence of GA 400.

Transportation

- The plan expresses a need to **reduce the congestion** around the Roswell Town Center mall area.
- The Comprehensive Plan states, "The City of Roswell has clearly taken the position that it **does not favor major road widenings** in the City."
- The Comprehensive Plan Short Term Work Program recommends that the city "plan and fund **new street networks** in conjunction with **private redevelopment**, where an agreement on cost sharing can be attained."
- The Comprehensive Plan Short Term Work Program calls for the city to "develop a program incorporating **landscaping**/ **streetscaping** into all **major road projects** to provide greater community identity and safety."
- Bicycle and Pedestrian **Policies**
 - Improve safety at places with high incidence of accidents
 - Fill gaps in existing sidewalks
 - Connect schools to nearby residential areas
 - Link to public transportation
 - Coincide with high-priority road improvement projects
 - Connect residential areas to commercial centers
 - Connect residential areas to parks
 - Connect residential areas to town centers
 - Provide bicycle facilities to link the north and south
 - Provide bicycle facilities to link the west and east
 - Connect parks to each other
 - Tie into existing and proposed projects from neighboring communities, and
 - Link facilities within the City to proposed and existing regional and statewide systems.
- Roswell will **protect the capacity of major thoroughfares** through nodal development techniques and **discourage additional strip commercial development**.
- The plan suggests that **access roads built by the City** can be a strong **incentive** for redevelopment. The plan states, "this tool is well suited for use in Midtown Roswell, along South Atlanta Street, and in the area on Holcomb Bridge Road east of GA 400."

Holcomb Bridge Road East Revitalization Plan (2005)

• Promoting and facilitating **redevelopment of C-3 zoned properties** such as King's Market, Market Center at Holcomb Woods (1&2), and the Holcomb Bridge Crossing Shopping Center areas.

- Guiding the **redevelopment of the Old Alabama Road** corridor south of King's Market into a **pedestrian-oriented office and mixed-use center**.
- Encouraging the **redevelopment of existing multi-family housing to senior housing** with associated medical office facilities to promote lifecycle housing opportunities.

Roswell Transportation Master Plan 2006

- The **installation of a grid network** is the main recommendation included in the study. Secondly, the recommendation of the installation of roundabouts is discussed in depth.
- The City should continue to support MARTA's priority of **extending rail service north to Windward Parkway**. Also, development should occur in **compact, walkable villages** that can be easily served by direct bus routes to and from MARTA stations.
- The report identifies the need for **growth in small "villages"** as opposed to rapid, general growth along arterials.
- The City should focus on **balancing retail land uses with office and residential**. Additionally, a grid network should be enforced with new development.

<u>South Atlanta Street LCI (2008)</u>

• **Revised bicycle policies** are recommended.

Mimosa Boulevard Connectivity Study (2006)

- Complete **the Preserve America Grant project**, fund, coordinate and expand the **Alive After Five**, which promotes street life in the area after work hours, recruit a boutique hotel, and incorporate trolley service.
- The report focuses on creating a **mixed-use community** in which vehicular traffic will not be needed to get from one place to the next. Although the trolley service is identified in the study, the report does not focus on transit.
- The report mentions that it is not the intent of the study to promote commercial growth along Mimosa Boulevard, but rather to make it a lovely, historic connection between vibrant historical centers.

Roswell Redevelopment Strategy (2003)

- Access roads and interparcel access discussed as redevelopment tool, including financing by City or public/private partnerships as options.
- **Streetscape improvement programs and financing** discussed as **redevelopment tool**, upgrading sidewalks specifically mentioned.
- Goals related **to Urban Design**
 - Roswell's commercial redevelopment should not only be contained and buffered but also interfaced with surrounding residential areas
 - Roswell's redevelopment should build on its sense of place
 - Roswell should continue to encourage neighborhood retail and the updating of outmoded centers
 - Some retail should be converted to office
 - Some retail should be converted to residential
 - Redevelopment needs to be green, but economically feasible
 - Some retail should be converted to schools and churches
 - Redevelopment should be mixed-use and transit-friendly
 - Implement redevelopment tools related to infrastructure: streetscape improvements, access roads, parking decks, signalization, stormwater management, etc.

- Establish incentives for improving design quality and pedestrian amenities
- Consider public parking interventions in key redevelopment areas
- Consider detailed Redevelopment Plans for other areas of the City such as Holcomb Bridge Road east of GA 400 and Alpharetta Highway north of Holcomb Bridge Road
- As an interim measure to full redevelopment, promote conversion of vacant retail space for nonretail uses such as office and institutional, including churches, schools and non-profits
- Goals related **to zoning**
 - Application of design standards to require quality construction materials will also help to prevent limited lifespan buildings
 - Redevelopment efforts should be focused on "pulsing" retail improvements at nodes to break up continuous strip development.
 - Design guidelines should be applied to these nodes to ensure a strong sense of place and greater likelihood of continued retail success
 - The use of deliberate vacancies as a strategic policy by national retailers to prevent competition should be discouraged. The City should consider adopting an ordinance that targets this practice. Retailers who prefer not to sublease the space they have vacated should be required to terminate their lease and pay the accompanying penalty, or donate the use of the property to a governmental or non-profit entity.
 - Adopt mixed use redevelopment zoning category to establish density bonus and encourage mixed use redevelopment
 - Adopt new zoning ordinance, which allows waiver of development fees for redevelopment projects and streamlined approval procedures for targeted projects

Sandy Springs

Comprehensive Plan 2030 (2007)

Housing

- Quality housing and a **range of housing** size, cost, and density should be encouraged in the City (Housing Opportunities QCO).
- Rezoning for new, freestanding **apartments** is discouraged. This policy does not preclude the replacement of existing multi-family units.
- **Cluster housing** (detached, single-family dwellings on small lots) is preferred in transitional areas (i.e., between commercial and low-density single-family neighborhoods) over attached housing types.
- Attached housing for **seniors** is encouraged to be included in mixed-use developments and areas designated as appropriate for live-work. Senior housing may also be freestanding if located in community or regional live/work areas as designated on the future land use plan map.

Land Use and Economic Development

- Limit manufacturing, industrial, and distribution land uses to those areas currently zoned.
- Economic development efforts in Sandy Springs will focus primary attention on **redevelopment** including the implementation of specific strategies for the revitalization and redevelopment of the Roswell Road corridor and the Town Center area.
- Sandy Springs should correct the common perception that it has no "downtown" by working to establish a sense of place and design the area for gathering and social interaction through redevelopment efforts within its **Town Center**.

- Provide incentives and bonuses for additional density and/or height for the redevelopment of obsolete **commercial areas along the Roswell Road corridor**.
- Continue the provision of public **streetscape improvements** in areas targeted for redevelopment, including upgraded sidewalks, additional pedestrian lighting, and street furniture.
- Protect the character and integrity of **existing neighborhoods**, while also meeting the needs of communities.
- Delineate and maintain firm, visible boundaries of protected neighborhoods, and prevent the encroachment of **incompatible land uses**, including, commercial, office, and multi-family land uses into protected neighborhoods.
- During rezoning and development application review, carefully address the interface between **protected neighborhoods** and commercial areas, especially within the Roswell Road corridor.
- Limit **infill** development within protected neighborhoods to densities that are consistent with the surrounding residential development.
- Effective, compatible **transitions among uses** should be the primary criterion in evaluating any proposed change in land use adjacent to parcels of less intense land uses.
- Improvements that support **pedestrian activity** should be required and provided in **transitoriented developments** along all streets and developments within or connecting to the transit station area or corridor.

Transportation

- **Shared parking** arrangements and reduction of on-site parking requirements should be encouraged in mixed-use developments.
- Provide for **incentives** in support of **mixed-use redevelopment** in live-work areas. The following list includes actions which have been identified as qualifying for incentives:
 - Installation of street grid segments.
 - Construction of sidewalks, bicycle and greenway paths exceeding minimum required standards.
 - Reduction of surface parking.
 - Installation of sidewalks, street trees and pedestrian lights on internal drives.
 - Reduction of curb cuts on Roswell Road.
 - Connection of single-family neighborhoods to nearby businesses through sidewalks and bicycle paths.
- Encourage **Transit-oriented Development (TOD)** adjacent to Metropolitan Atlanta Rapid Transit Authority (MARTA) facilities.
- Cooperate with the Georgia Department of Transportation to improve the **traffic safety operations**, **functions**, **and aesthetics** of Roswell Road.
- Improve traffic signal operations and intersection safety.
- Reduce traffic congestion at "hot spots."
- Consider **mobility needs** that first address local travel within Sandy Springs, then travel to/from the City, with final consideration given to traffic passing through Sandy Springs.
- Provide a **grid system** of streets within downtown and elsewhere to disperse traffic over several roads.
- Provide **additional opportunities** for transit use along key corridors and in downtown and **support** extension of regional rail transit north along GA 400 corridor.
- Incorporate **Bus Rapid Transit** or other **premium transit** (such as express bus with signal preemption or queue jumping technology) along key routes.
- Ensure an **adequate parking supply** in downtown.

- Provide **traffic calming** at appropriate locations and designate routes for truck prohibition where needed.
- Improve **sidewalks** and **bicycle routes** to provide alternative travel options with emphasis on connections to **parks**, **green space**, and the **central business district**.
- **Reduce direct vehicular access** from parcels to congested arterials to improve safety by limiting crash potential.
- Pursue **functional improvement** of the Roswell Road at I-285 Interchange as a high priority.
- Provide for efficient use of **existing infrastructure** (system preservation).
- Improve congestion "bottlenecks" and "hot spots."
- Park once and circulate in downtown Sandy Springs via **transit and pedestrian modes**.
- Provide for **future travel demand**.
- Promote **pedestrian and bicycle travel modes** for access to parks and community facilities.
- Serve **mobility** needs in residential areas while preserving neighborhoods.

Livable Sandy Springs Plan LCI (2001)

- Activity Centers with concentrations of **commercial and civic uses** with enhanced **walkable connections** among the uses and to adjacent residential neighborhoods are recommended including the following types:
 - Primary Activity Center locations: Sandy Springs Village (the mixed-use areas of the Overlay District.)
 - Secondary Activity Center locations: North Sandy Springs; along Roswell Road near Morgan Falls and South Sandy Springs; now non-existent with three possible sites along Roswell Road.
 - District Activity Center. There should be at least one District Activity Center to serve each district. None now exists as a true multi-use center but several commercial areas have the capacity to develop, including Roswell Road at the river, Spalding Road/Mt Vernon crossing, Power's Ferry, and near the Prado on Roswell Road.
- Revise the Sandy Springs **Overlay Zoning District** requirements.
- **Revise the Sandy Springs Overlays Districts** to include: A redrawing of the district boundaries, Vertical mixed-use permitted by right, FAR requirements, Minimum and maximum building heights, Density bonus incentives, Open space ratio, Build-to lines, Architectural standards, Maximum parking requirements, Street cross sections.

Roswell Road Corridor LCI Study (2008)

- Effective feeder network for service to MARTA rail stations; namely Medical Center MARTA Station.
- Incorporation of **walkable communities** and **transit oriented development** near MARTA rail stations.
- **Examination of local circulation routes** within walkable activity centers to link MARTA Rail with walkable areas.
- **Examination of BRT feasibility** or **other premium transit** service in Sandy Springs.
- Zoning Code Overlay District recommendations related to access management
 - Require larger minimum lot frontages
 - Adopt minimum spacing standards for driveways
 - Encourage joint access
 - Require inter-parcel connectivity
 - Require complete on-site circulation
 - Promote activity centers rather than strip development

Sandy Springs Transportation Master Plan (2008)

- **"Safe Routes to School"** and other various pedestrian improvements have been identified.
- The **assessment of transit** has identified **several improvement needs**, as indicated below:
 - Travel time benefits for bus service along key corridors to encourage commute riders.
 - Bus frequency sufficient to encourage new ridership along routes through congested areas.
 - Effective feeder network for service to MARTA rail stations.
 - Incorporation of walkable communities and transit oriented development near MARTA rail stations.
 - Examination of local circulation routes within walkable activity centers to link MARTA rail with walkable areas.
 - Examination of applicability of Bus Rapid Transit or other premium transit service in Sandy Springs.
 - Providing efficient access to MARTA rail stations for use in passenger access to Hartsfield Jackson Atlanta International Airport.
 - Providing adequate long term parking to facilitate use of MARTA for passenger access to Hartsfield Jackson Atlanta International Airport.
 - Recognizing transit circulation needs in Sandy Springs to facilitate use of MARTA for passenger access from Hartsfield Jackson Atlanta International Airport.
- Limited opportunity to increase the vehicular capacity of the transportation network will drive the need to encourage the use of alternative modes of travel. Though transit opportunities exist, the recommended improvements will help **promote transit as a viable opportunity for travel.** Through the transit assessment, the need for **increased bus frequency and travel time benefits** to encourage ridership was identified. Also, enhancements to the existing MARTA system, such as a **more efficient feeder network** and **pedestrian improvements** around stations, were identified as needed improvements to the transit system. Additional transit system needs identified by the community focused on providing efficient access to the airport via MARTA. These needs included **providing increased transit circulation and adequate long term parking**.
- The project list contains ten transit-related projects, ranging from additional transit routes and services to improved pedestrian connections to transit stations and bus stops. The addition of express service and a downtown circulator will increase mobility by providing better connectivity as well as increasing the frequency of bus service within a defined route in the Town Center. Improving the pedestrian system around transit facilities will also promote use and potentially increase ridership by making transit more accessible. The plan also recommends that the City continues coordination with MARTA regarding local bus stop locations and facilities and additionally recommends crossing improvements and street lighting to improve bus stop access. Improvements have also been recommended to the transit network that will facilitate better access to the airport via MARTA

Sandy Springs MARTA Station Area Plan, LCI Supplemental (2003)

• No policies identified.

Capital Paving Program FY 2010 (2009)

• No policies identified.

<u>Sidewalk Program (2006)</u>

• No policies identified.

APPENDIX C

Envision6 Regional Development Types Matrix





Envision6 Regional Development Types Matrix

		Mixe	d Use		Sir	Single Use Employment		
	ka fi			Tilled.			-lat	
	City Constan	High Residential	Activity Center	Town Center	General	Office Deels	Industrial	De sienst Dest
Residential Density per acre	City Center 40	Mixed Use 80	Mixed Use 30	Mixed Use 15	Commercial	Office Park	Industrial	Regional Parks N/A
Job Density per acre Average Height	180 8 to 50	25 8 to 50	70 5 to 40	13 2 to 5	13 1 to 4	40 2 to 4	9 1	
Regional Places								
Central City								
Regional Centers								
Fown Centers								
Station Communities								
nterchange Nodes								
nterstates & Limited Access Facilities								
Freight Corridors								
Jrban Redevelopment Corridors								
Regional Strategic Facilities								
Jrban Neighborhoods								
Mega Corridors								
Suburban Neighborhoods								
Rural Areas								
Regional Environmental								
Regional Parks								
legional Parks				Residen	tial Areas			
	TA	AFT		A MARK				A Sec
	Medium Rise	Low Rise	Townhome	Residential Small Lot	Residential Med Lot	Residential Large Lot	Residential Very Low	Conservation 50% Open Space
Residential Density per acre Job Density per acre	44	22	12	7	5	3	1	0.5
Average Height Regional Places	6	4	2	2	2	2	2	2
<u> </u>								
Central City								
Regional Centers								
Fown Centers								
Station Communities								
nterchange Nodes nterstates & Limited Access Facilities								
Freight Corridors								
Jrban Redevelopment Corridors								
Regional Strategic Facilities								
Jrban Neighborhoods								
lega Corridors								
Suburban Neighborboods								
Suburban Neighborhoods								
Suburban Neighborhoods Rural Areas Regional Environmental Protection Areas								
Rural Areas Regional Environmental								



Land Use • Transportation • Water




City Centers will have the most intense residential and commercial land uses. They serve a regional population and are easily accessible by different transportation modes. In the Atlanta Region, Downtown and Midtown Atlanta are examples of this land use.
Regional Centers are areas of intense retail, office and residential uses. The uses can be integrated or separate. They have a higher density of residential uses but lower job densities than a Central City. Buckhead and Cumberland are examples of a Regional Center in the Atlanta region.
Town Centers are low-intensity centers that serve a local area. They have a mixture of residential and commercial land uses. Snellville and Smyrna are examples within the Atlanta region.
Station Communities are communities that are built around transit. A mixture of uses is fundamental to good Station Communities. In the Atlanta region, Lindbergh Center is an example.
Interchange Nodes have subregional commercial districts with appropriate residential and/or office development.
Interstates and Limited Access Facilities serve as major commuter corridors. They are illustrated on the map as part of the regional strategic transportation system. Stone Mountain Freeway is an example.
Freight Corridors are corridors that serve freight and industrial areas. Fulton Industrial Boulevard is an example.
Urban redevelopment corridors are corridors that have potential to be redeveloped into an activity corridor. An example is Old National Highway.
Regional Strategic Facilities are corridors that serve as backbone of our capacity road network. They have limited development between the nodes. An example is SR 92 in Fayette County.
Urban Neighborhoods are distinct areas that are located in an urban area. They may have a small commercial component that serves the local area. An example would be Grant Park.
Mega Corridors are most intensely developed radial corridors in the region. They may include multiple regional centers. The Area surrounding GA 400 is an example of a mega corridor
Suburban Neighborhoods are areas that are located outside the Central City or Activity Centers. They will be developed at a more of a suburban scale with appropriate commercial development and low intensity mixed-use serving the local area. An example would be North Fulton.
Rural Areas have limited or no development. Housing development that has occurred is on large lots that are not served with sewer. Agriculture uses still can be found in the surrounding area. An example would be Northern Cherokee County.
These are areas where development is restricted due to the sensitive nature of the environment. An example would be water-supply watersheds
Regional Parks serve a regional population. Stone Mountain is an example of this in the Atlanta region.

APPENDIX D

Zoning Maps by Jurisdiction












CITY OF ALPHARETTA FULTON COUNTY, GEORGIA


116A	1,42				
		195	1.104		BOUNDARIES BUBDINSICIN DEVELOPMENT LOCATOR ALPHARETTA CITY LIMIT LINE UN-INCORPORATED FULTON COUNTY
	, ten	1278	107		AB Agrouture RE Residential Edate
2 141 55C 2 141 55C	,ten	.49	1266	DATE OF LAST MAP REVISION	R Single Family Detached Residential R+22 Single Family Detached Residential R+35 Single Family Detached Residential R+32 Single Family Detached Residential R+32 Single Family Detached Residential R+33 Single Family Detached Residential R+31 Single Family Detached Residential
er.	2 ⁷²	in a	3 ¹⁰		R-4A Single Family Attached Residential - Low Dansity R-BA Single Family Attached Residential - Medium Density R-10M Multiple Family Residential (HD- Historic District where indic
OF JO	HNS CR	EEK	3 ⁶	Alpharetta	CUP Community Unit Plan O-P Office-Professional O-I Office-Institutional MU Mixed Use C-1 Neightombood Commercial
*	e th	9 ¹²	317	SOURCE NOTE: BASE NAP PREPARED FROM NAPS, PLATS, LEGAL DESCRIPTIONS, AND OTHER DATA SUPPLIED BY THE FULTON COUNTY ZONING DEPARTMENT AND THE CITY OF ALPHARETTA	C-2 General Commercial PSC Planned Bhopping Center L-1 Light Industrial OSR Open Space and Receational SU Special Lise
the state	e.	3 ¹¹	>1 ⁰		
ST	REET	AND	SUBDI	VISION LOCATION	











Zoning Districts

Adopted from Fulton County R-1 Single Family Dwelling District R-2 Single Family Dwelling District R-2A Single Family Dwelling District R-3 Single Family Dwelling District R-3A Single Family Dwelling District R-4 Single Family Dwelling District R-4A Single Family Dwelling District R-5 Single Family Dwelling District R-5A Single Family Dwelling District R-6 Two Family Dwelling District A - Medium Density Apartment District 06 0311 Landlots A-L Apartment Limited Dwelling District // Highways A-1 Apartment Dwelling District A-O Apartment Office District TR Townhouse Residential Districts



Prepared by the Sandy Springs Geographic Information Systems September 30, 2009 The new betwork of the the net exercise source data from Factor Course and the Carl of Sandy Genge, Knowen the major for Known and purposes only view on to be referenced as a legal occurrent from the improvement of view of the course of the second the Carl second and the course of the second and the second the Carl second and the Carl of Sandy Genge.

Magnamy is reproduced or transmitted for previoual and informational hypotomes, tark to its commensional use. It loans of third workfring to produced or transmitted for commercial pupposes, in any form or by any means, electronic or medical, including photocogying and recording, or by any intornation deraige or reterive algent, except as expressing permitted in writing by the Cky of Sentry R. Requests should be made to the Cky is GD begintment at (170) 170-600 or george weldgend specifications.





APPENDIX E

Bridges in North Fulton County





	Bridge Inventory									
Bridge ID	Feature Type	Road Name	Feature	Year Const	Year Recon	2007 ADT	GDOT Suffic. R'ting			
121-5015-0	Over Stream	New Providence Road	Cooper Sandy Creek	1962		003610	18.71			
121-5019-0	Over Stream	Bell Road	Cauley Creek	1960	1989	006800	26.84			
121-0304-0	Over Stream	Riverside Road	Big Creek	1958		012920	27.27			
121-0281-0	Over Stream	Bethany Road	Cooper Sandy Creek	1951		003230	27.70			
121-5002-0	Over Stream	Clarity Road	Little River	1954		001900	27.78			
121-5022-0	Over Stream	Parsons Road	Johns Creek	1964		006800	29.57			
121-5017-0	Over Stream	Douglas Road	Caney Creek	1955	1962	006800	29.60			
121-0629-0	Over Stream	Windward Pkwy (EBL)	Big Creek	1986		032850	30.27			
121-0630-0	Over Stream	Windward Pkwy (WBL)	Big Creek	1986		032850	30.27			
121-5027-0	Over Stream	Rockmill Way	Foe Killer Creek	1964		000320	34.65			
121-5003-0	Over Stream	Birmingham Road	Chicken Creek Trib.	1961	1994	006800	36.95			
057-0029-0	Over Stream	Arnold Mill Road	Little River	1952		014370	39.45			
121-0288-0	Over Stream	McGinnis Ferry Road	Johns Creek	1962		000500	39.00			
121-0291-0	Over Stream	Old Alabama Road	Johns Creek Trib.	1956	1962	017510	40.13			
121-5176-0	Over Stream	Jett Road	Long Island Creek	1946		002460	40.54			
121-5151-0	Over Stream	Birmingham Road	Little River	1968		006800	40.83			
067-0109-0	Over Stream	I-285	Chattahoochee River	1962	1994	184080	40.99			
121-5133-0	Over Stream	Old Holcomb Bridge Rd	Big Creek	1941		001900	41.83			
121-0305-0	Over Stream	Old Roswell Road	Foe Killer Creek	1951		006800	42.89			
121-0292-0	Over Stream	Old Alabama Rd	Johns Creek	1956		017510	43.94			
121-0451-0	Over Stream	Powers Ferry Road	Long Island Creek	1993	2004	005930	46.63			
121-5020-0	Over Stream	Bell Road	Chattahoochee River Tributary	1958		006800	47.57			
121-5106-0	Over Stream	New Bullpen Road	Little River	1939		008230	48.98			
121-5030-0	Over Stream	Spalding Drive	Ball Mill Creek	1929		001900	49.76			
121-0301-0	Over Stream	Rucker Road	Foe Killer Creek	1951	1989	017270	51.86			
121-5013-0	Over Stream	Wood Road	Chicken Creek	1961		001900	52.09			
121-5016-0	Over Stream	Providence Road	Cooper Sandy Creek	1962		003610	52.63			
121-5008-0	Over Stream	Westbrook Road	Chicken Creek Trib.	1956		001900	53.11			
121-0270-0	Over Road	Northridge Road	SR 400 (US 19)	1968		039350	54.45			
121-5153-0	Over Stream	Freemanville Road	Cooper Sandy Creek	1960		006800	56.24			
121-5202-0	Over Stream	Cogburn Road	Chicken Creek Trib.	1986		010260	58.95			
121-0307-0	Over Road	Maxwell Road	SR 400 (US 19)	1969		022430	59.48			
121-0299-0	Over Road	Webb Bridge Road	SR 400 (US 19)	1969		012850	59.76			
121-5012-0	Over Stream	Batesville Road	Little River	1964		005070	60.25			
121-0031-0	Over Road	Roswell Road	I-285	1961		033400	60.26			
121-5023-0	Over Stream	Kimball Bridge Road	Big Creek	1940		006800	60.64			
121-5004-0	Over Stream	Hamby Road	Chicken Creek	1964		001900	61.25			
121-5005-0	Over Stream	Hamby Road	Chicken Creek Trib.	1966		001900	61.25			
121-5026-0	Over Stream	Buice Road	Johns Creek	1964		008560	61.37			

121-0300-0	Over Stream	Webb Bridge Road	Big Creek	1985		006800	61.48
121-0458-0	Over Stream	Windsor Pkwy	Nancy Creek	1929		009470	61.66
121-5091-0	Over Stream	Hobgood Road	Bear Creek	1960	1985	003820	62.10
121-5259-0	Over Stream	Mansell Road (WBL)	Foe Killer Creek	1991		043720	62.13
121-5006-0	Over Stream	Longstreet Road	Chicken Creek Trib.	1964		001900	62.81
121-5011-0	Over Stream	Batesville Road	Chicken Creek	1962		005070	63.03
121-0306-0	Over Stream	Rockmill Road	Foe Killer Creek Trib.	1951	1971	006800	63.14
121-5007-0	Over Stream	Westbrook Road	Chicken Creek Trib.	1956		001900	63.28
121-5014-0	Over Stream	Wood Road	Chicken Creek Trib.	1956		001900	63.28
121-5100-0	Over Stream	Russell Drive	Rocky Creek	1965		001900	63.51
121-0327-0	Over Road	Northside Drive (SBL)	I-285 (SR 407)	1962	1987	006840	63.60
121-5035-0	Over Stream	Glenridge Road	Marsh Creek	1968		017630	64.16
121-0278-0	Over Stream	Spalding Drive	Crooked Creek	1952	1961	000500	64.86
121-0457-0	Over Stream	Johnson Ferry Road	Chattahoochee River	1969	1981	039270	64.89
121-5009-0	Over Stream	Thompson Road	Chicken Creek Trib.	1962		001900	65.23
121-0477-0	Over Road	Heards Road	I-285 (SR 407)	1962		001990	65.25
121-5258-0	Over Stream	Mansell Road (EBL)	Foe Killer Creek	1991		043720	65.43
121-5130-0	Over Stream	Charles Place	Hog Waller Creek	1960		001900	65.51
121-0456-0	Over Stream	Long Island Drive	Long Island Creek	1927		003720	66.14
121-0454-0	Over Stream	Riverside Drive	Marsh Creek	1931		012170	66.28
121-0085-0	Over Stream	Holcomb Bridge Road	Big Creek	1978		056020	66.86
121-0293-0	Over Stream	Dunwoody Club Drive	Ball Creek	1931		008220	69.08
121-5025-0	Over Stream	Brumbelow Road	Chattahoochee River Trib.	1962		001900	69.67
121-0475-0	Over Road	Kimball Bridge Road	SR 400 (US 19)	1969		006800	69.98
121-5031-0	Over Stream	Hembree Road	Foe Killer Creek	1962		010200	70.06
121-0476-0	Over Road	Pitts Road	SR 400 (US 19)	1968		007180	70.18
121-0309-0	Over Stream	Norcross Street	Hog Waller Creek	1951	1964	016950	70.85
121-5157-0	Over Stream	Azalea Drive	Chattahoochee River Trib.	1960	2004	001900	70.87
121-5134-0	Over Stream	Oxbo Road	Hog Waller Creek	1960	1988	001900	72.31
121-0453-0	Over Stream	Riverside Drive	Chattahoochee River Trib.	1960		008890	73.43
121-0444-0	Over Road	MT. Vernon Hwy	I-285 (SR 407)	1962		010720	73.46
121-0625-0	Over Road	N Northside Dr (NBL)	I-285 (SR 407)	1986		021650	73.66
121-0459-0	Over Road	Hammond Drive	SR 400 (US 19)	1968	1982	019170	74.61
121-0698-0	Over Stream	Birmingham Highway	Chicken Creek	1989		009540	74.82
121-0290-0	Over Stream	Barnwell Road	Hogan Creek	1956	1970	009750	74.88
121-0303-0	Over Road	Haynes Bridge Road	SR 400 (US 19)	1969	1994	025140	75.31
121-0452-0	Over Road	Riverside Drive	I-285 (SR 407)	1962		006490	76.35
121-0754-0	Over Road	Johnson Ferry Road	SR 400 + 2 SR 400 RAMPS	1993		014260	76.87
121-5034-0	Over Stream	Brandon Mill Road	Marsh Creek	1940	1966	001900	78.32
121-0752-0	Over Road	Windsor Parkway	SR 400	1993		009540	80.32
121-5024-0	Over Stream	Waters Road	Long Indian Creek	1961		000050	80.45
121-0455-0	Over Road	Spalding Drive	SR 400 (US 19)	1968		008890	81.87
121-5010-0	Over Steram	Dinsmore Road	Chicken Creek	1965		001900	82.13
121-0753-0	Over Road	Northland Drive	SR 400	1993		003010	82.15

121-5036-0	Over Stream	Lake Forest Drive	Long Island Creek	1935		006800	82.80
121-5028-0	Over Stream	Riverside Road	Chattahoochee River Trib.	1968		001900	83.62
121-5029-0	Over Stream	Riverside Road	Chattahoochee River Trib.	1968		001900	83.62
121-5187-0	Over Stream	Kingsport Drive	Long Island Creek	1966		000320	83.92
121-0086-0	Over Road	Holcomb Bridge Road	SR 400 (US 19)	1969	1987	063230	85.77
121-0316-0	Over Road	Roberts Drive	SR 400 (US 19)	1969		001900	86.78
121-0032-0	Over Stream	Roswell Road	Marsh Creek	1965		036190	89.14
121-5217-0	Over Stream	Coles Way	Chattahoochee River Trib.	1984		000320	90.62
121-5107-0	Over Stream	Hopewell Road	Cooper Sandy Creek	1953		008690	91.07
121-0591-0	Over Stream	Cumming Street	Big Creek Trib.	1966		008230	91.15
121-5093-0	Over Stream	Tanacrest Drive	Chattahoochee River Trib.	1961		001900	92.34
121-0445-0	Over Road	Mt. Vernon Highway	SR 400 (US 19)	1968		011530	93.10
121-0298-0	Over Stream	Windward Pkwy (WBL)	Camp Creek	1986		020810	93.40
121-0749-0	Over Road	Glenridge Parkway	SR 400 + 2 SR 400 RAMPS	1993		023190	93.72
121-0257-0	Over Road	I285R CCB TO SR400	SR 400 NBL (US 19)	1969		008210	94.38
121-0624-0	Over Stream	Windward Pkwy (EBL)	Camp Creek	1986		020810	94.40
121-0443-0	Over Stream	Northside Drive	Long Island Creek	1931		001060	94.52
121-0592-0	Over Stream	P'tree-Dunwoody Rd	Nancy Creek Trib.	1976		034680	94.80
121-0035-0	Over Stream	SR 9	Foe Killer Creek	1973	1988	031050	95.34
121-0310-0	Over Stream	Crabapple Road	Hogwaller Creek	1977		012710	96.19
121-0593-0	Over Stream	Hammond Drive	Nancy Creek Trib.	1976		019170	97.12
121-0034-0	Over Stream	SR 9	Hog Wallow Creek	1980		033650	97.48
121-0034-0	Over Stream	SR 9	Hog Wallow Creek	1980		033650	97.48
121-0697-0	Over Stream	Birmingham Highway	Cooper Sandy Creek	1989		008530	98.72
121-5099-0	Over Stream	Roxburgh Drive	Big Creek Trib.	1975		001900	99.29
121-5209-0	Over Stream	Finley Road	Johns Creek	1986		001900	99.57
121-5257-0	Over Stream	Buice Road	Long Indian Creek	1988		001900	99.86
121-5249-0	Over Stream	Alpine Drive	Hog Waller Creek	1975		000320	99.93
					-		

Source: GDOT



DEPARTMENT OF TRANSPORTATION

One Georgia Center, 600 West Peachtree Street, NW Atlanta, Georgia 30308 Telephone: (404) 631-1000

May 18, 2009

Honorable John Eaves, Chairman Fulton County Board of Commissioners 141 Pryor Street, S.W. Atlanta, Georgia 30303

Dear Commissioner Eaves:

A re-inspection of your County and Federal Aid Secondary bridges has been completed. This re-inspection will maintain your County's Compliance with the Federal Law and Regulations requiring all public bridges be inspected biennially. Only bridges as set forth in the Federal Regulations were inspected. A bridge is defined as a structure including supports erected over a depression or an obstruction, such as water, highways, or railways, and having a track or passageway for carrying traffic or other moving loads and having an opening measured along the center of the roadway of more than twenty feet between undercopings or abutments or spring lines including multi-pipes, where the clear distance between openings is less than half of the smaller contiguous opening.

Attached is a report reflecting the results of the above inspection. It is the responsibility of the county government to forward a copy of this report to local municipalities for bridges owned and maintained by city governments within the county boundaries. It is also the responsibility of the county government to advise local school boards of the location of any bridge structure that is not capable of sustaining school bus loads as noted in this report. This report briefly advises you of the condition of your bridge structures and notes which structures should be posted with load limit signs and which ones should be closed to traffic if conditions do not meet minimum standards according to Federal Law. Those structures requiring posting or closure have been identified within the text with an asterisk (*). It is extremely important that the local jurisdiction comply with Federal Posting and Closing Regulations. Counties not in compliance will not have any projects authorized that utilize federal highway funds until compliance with these regulations has been obtained.

Attached to the report is a copy of the Structure Inventory and Appraisal (SI&A) sheet for each structure in the report. This sheet contains additional information that is not necessarily contained in this written report such as whether or not the bridge rails meet current standards and if delineation signs are present. A Posting Summary sheet of all the structures that require posting showing their load carrying capacities has also been included. Attached to the Posting Summary sheet, you will find a drawing of two load limit signs and a drawing of required bridge closing methods. The R12-1 (Type A) sign is for gross load posting while the R12-5 modified (Type B) sign is for multi-posting. Please note that all structures requiring closing must be properly closed in accordance with the attached methods.

Please note that on the Posting Summary sheet, all bridges marked with a plus sign (+) are presently not posted and require posting. On the same summary sheet, all bridges marked with a pound symbol (#) are presently posted with an inappropriate sign and should be re-posted with a proper type sign and/or proper load limits. The load limit will be in the appropriate column, depending on the type sign recommended. In addition, all bridges marked with a (B) are bridges located on an identified School Bus Route. All bridges carrying school buses should have a minimum capacity of 10 tons.

Assistance in the rehabilitation or replacement of deficient bridges may be obtained through the State Aid Program. This assistance can include funds for materials such as concrete, reinforcement steel, piles or pipe. The state owned crane can be scheduled for repairs as in the replacement of deteriorated piles. Based on your county's transportation needs, eligible deficient bridges can be added to the Construction Work Program for replacement. In addition, engineering services are available through this program. For information with this service, please contact our Office of State Aid at (404) 656-5185.

All structural calculations are based on the inventory stress level. This is the normal design criterion and includes a reasonable factor of safety. Loads exceeding those allowed at the inventory stress level can be applied on an occasional basis without seriously damaging the structure but the operating rating (at the higher operating stress level) should generally not be exceeded without a detailed structural analysis.

If you have any questions concerning any of the structures in this report or need a copy of the Bridge Inventory Coding Guide to interpret the Structure Inventory and Appraisal sheet, please contact Mr. Kerry Wood, of my office, at (404) 635-8189.

Sincerely,

Mike Clements, P.E. State Bridge Maintenance Engineer

MLC/gmc Enclosures

 cc: Cindy Loe, Ph.D., Superintendent, Fulton County Board of Education Carol Bentley, Safety Investigation, Fulton County Schools Angela Parker, Public Works Director, Fulton County Rachel Brown, Acting District Engineer, District 7, Chamblee (via email) Ernay Robinson, Area Engineer, District 7, Area 3, Hapeville (via email) David Huff, State Aid (via email) Jerry Cooper, Bridge Inspection Supervisor (via email) File

Georgia Department of Transportation

Posting Summary for Fulton County

	LOCATION ID	STRUCTURE ID	ACTION	H TRUCK	TYPE-3 TRUCK	TIMBER TRUCK	HS TRUCK	3S2 TRUCK
В	121-02365F-004.28N	121-0283-0	POSTED	20	19	28		
В	121-02564F-001.53E	121-0284-0	POSTED	19	19	24		
# B	121-02564F-003.10E	121-0286-0	REPOST FOR	14	13	18	15	23
В	121-02564F-005.47E	121-0287-0	POSTED	15	15	20	17	
# B	121-02564F-007.12E	121-0288-0	REPOST FOR	10	12	15		18
В	121-09069M-008.95E	121-0355-0	POSTED	11	14	20		
В	121-09075M-000.80N	121-5201-0	POSTED	09	12	16	15	22
В	121-09104M-000.33E	121-0294-0	POSTED	08	10	15	13	20
# B	121-09104M-001.03E	121-0295-0	REPOST FOR	19	19	24		
#B	121-09248M-001.88N	121-0453-0	REPOST FOR	17	18	26		
В	121-09381M-001.68W	121-5063-0	POSTED	10	12	15		18
В	121-09407M-001.38E	121-0305-0	CLOSED	13	13	18	16	20
В	121-09407M-001.66E	121-0306-0	CLOSED	19	19	24		
В	121-09408M-000.08E	121-0304-0	POSTED	11	11	13	12	17
+ B	121-09415M-001.80N	121-5016-0	POST FOR	16	17	24		
В	121-09479M-004.54E	121-0291-0	POSTED	15	14	19	16	
+ B	121-09479M-005.33E	121-0292-0	POST FOR	15	15	20		24
+	121-00003X-000.38N	121-5002-0	POST FOR	06				
	121-00004X-000.01E	121-5151-0	POSTED	10	12	15		18
В	121-00004X-003.99E	121-5003-0	POSTED	10	10	13	13	16
В	121-00012X-000.17E	121-5004-0	POSTED	19	19	23		
В	121-00012X-000.67E	121-5005-0	POSTED	18	18	23		
В	121-00034X-006.31S	121-5153-0	POSTED	18	18	22		
+B	121-00064X-000.94N	121-5017-0	POST FOR	07				
В	121-00072X-001.44E	121-5019-0	POSTED	10	12	15		18
В	121-00072X-002.29E	121-5020-0	POSTED	18	17	22		
В	121-00079X-001.52N	121-5022-0	POSTED	10	12	15		17

	LOCATION ID	STRUCTURE ID	ACTION	H TRUCK	TYPE-3 TRUCK	TIMBER TRUCK	HS TRUCK	3S2 TRUCK
+ B	121-00103X-000.53S	121-5024-0	POST FOR	19	18	23		
В	121-00111X-000.75N	121-5026-0	POSTED	19	18	23		
	121-00126X-000.14W	121-5027-0	CLOSED					
+ B	121-00219X-000.59S	121-5034-0	POST FOR	18	18	22		
# B	121-00331X-000.578	121-5176-0	REPOST FOR	11	13	17		18
В	121-00415X-000.01W	121-5038-0	POSTED	20	19	24		
	121-00420X-001.20N	121-5040-0	POSTED	10	12	15		18
	121-00426X-002.30N	121-5044-0	POSTED	10	12	15		18
В	121-00435X-001.74W	121-5046-0	POSTED	03				
В	121-00443X-000.34N	121-5050-0	POSTED	10	12	15		18
В	121-00485X-008.46S	121-5056-0	POSTED	13	17	23		24
	121-00515X-001.01N	121-5061-0	POSTED	10	12	15		18
В	121-00518X-000.35N	121-5064-0	POSTED	19	19	24		
#	121-00522X-000.19E	121-5065-0	REPOST FOR	11	14	18		20
+ B	121-00614X-001.02N	121-5077-0	POST FOR	10	12	15		18
# B	121-00618X-000.59S	121-5078-0	REPOST FOR	10	12	15		18
# B	121-00621X-000.28E	121-5079-0	REPOST FOR	10	12	15		18
В	121-00629X-000.01W	121-5081-0	POSTED	09	10	14	16	18
+	121-00637X-000.42E	121-5086-0	NEED TO CLOSE					
В	121-00650X-001.10N	121-5274-0	POSTED	10	12	15		18
В	121-01390X-002.95E	121-5109-0	POSTED	10	12	15		18
	121-01392X-006.02N	121-5114-0	POSTED	06	13	15	11	19
	121-01527X-000.14E	121-5118-0	POSTED	05		1		1
	121-01529X-002.14N	121-5119-0	POSTED	10	10	14	12	15
#	121-01529X-002.96N	121-5120-0	REPOST FOR	09			······	<u> </u>
В	121-01638X-000.25E	121-5210-0	POSTED	20	19	24		
+B	121-02233X-003.02E	121-0629-0	POST FOR	12	12	16		
+ B	121-02233X-003.03E	121-0630-0	POST FOR	12	12	16		1
В	121-02233X-003.73E	121-5286-0	POSTED	13	17	24		

	LOCATION ID	STRUCTURE ID	ACTION	H TRUCK	TYPE-3 TRUCK	TIMBER TRUCK		3S2 TRUCK
В	121-03079X-000.55E	121-5134-0	POSTED	19	19	24		
# B	121-03337X-000.09E	121-5133-0	REPOST FOR	10	09	14	12	15
	121-05016X-000.44S	121-5197-0	CLOSED					
В	121-07001X-000.03N	121-5198-0	POSTED	14	14	17	16	23

Bridge Posted incorrectly, Reposting required


+ Bridge not Posted, Posting Required

B Bridge located on an identifying School Bus Route

All Bridges carrying School Buses should have a minimum capacity of 10 Tons.

Please indicate which alternate closing method the county uses to close a structure.


Note: It is recommended that advanced weight limit signs be placed.



LOCAL BRIDGE CLOSING METHODS

NOTE: In addition to the above permanent closure, appropriate advance warning signs and barricades should be used. Please reference the Manual on Uniform Traffic Control Devices, current edition. Also, advanced warning signs should be used at the last intersection prior to each end of the structure.

Georgia Weight Limit Signs



Revised 1-25-99

LOCALLY OWNED FEDERAL AID ROUTE BRIDGE INSPECTIONS:

STRUCTURE ID 121-0511-0 / LOCATION ID 121-00846F-001.33E FAS 846, CR 1391, Fayetteville Road under CSX Railroad

This non-roadway railroad structure has been inspected for clearance purposes only. The minimum vertical clearance is substandard and requires posting. Our records indicate the minimum vertical clearance to be 9'-10". At the present time, the County should verify this clearance and post this structure in accordance with the Manual on Uniform Traffic Control Devices (current edition) Low Clearance Sign. Inspection of the structural components is the responsibility of the owner.

STRUCTURE ID 121-5312-0 / LOCATION ID 121-01324F-006.40N FAU 1324, CR 1386, Stonewall Tell Road over Camp Creek

This bridge structure is in good condition with no reported deficiencies.

STRUCTURE ID 121-0280-0 / LOCATION ID 121-02356F-001.88E FAS 2356, CR 1391, Hutchenson Ferry Road over Dry Branch

This bridge culvert is in good condition with no reported deficiencies.

STRUCTURE ID 121-5307-0 / LOCATION ID 121-02364F-001.01E F 2364, CR 1331, Rucker Road over Foe Killer Creek

This bridge structure is in good condition. Erosion at the western abutment has exposed the foundation piles and should be repaired to prevent loss of fill and possible damage to the roadway.

STRUCTURE ID 121-0282-0 / LOCATION ID 121-02365F-001.45N FAS 2365, CR 1323, Hopewell Road over Chicken Creek Tributary

This bridge culvert is in good condition but has approximately 0.5 feet of scour damage at the inlet end of barrels #2 and #3. This scour damage should be monitored for further signs of degradation.

*STRUCTURE ID 121-0283-0 / LOCATION ID 121-02365F-004.28N FAS 2365, CR 1323, Hopewell Road over Chicken Creek At the present time, Post this structure for 20 Tons H-Truck; 19 Tons Type 3

Truck and 28 Tons Timber Truck.

This structure requires posting due to overstress caused by the extra dead load of the 4.5 inch asphalt overlay. Upgrading the load carrying capacity to a point where posting is not required would require removal of this overlay. The following maintenance

recommendations are provided to maintain this structure at the current rating. This bridge structure is in good condition but has corrosion of the steel superstructure. The beams throughout the structure should be cleaned and painted. The beaver dam located upstream of the structure should be removed to prevent further accumulation of debris and reduce the possibility of scour.

*STRUCTURE ID 121-0284-0 / LOCATION ID 121-02564F-001.53E FAS 2564, CR 41, McGinnis Ferry Road over Camp Creek Tributary At the present time, Post this structure for 19 Tons H-Truck; 19 Tons Type 3 Truck and 24 Tons Timber Truck.

This structure requires posting due to overstress caused by the extra dead load of the 3.5 inch asphalt overlay. Upgrading the load carrying capacity to a point where posting is not required would require removal of this overlay. The following maintenance recommendations are provided to maintain this structure at the current rating. This bridge structure is in satisfactory condition with the exception of the steel substructure piles. The steel piles throughout the structure should be cleaned and painted. The joints throughout the deck should be cleaned and sealed. Vegetation growing in the vicinity of the structure should be cut and removed.

*STRUCTURE ID 121-0286-0 / LOCATION ID 121-02564F-003.10E FAS 2564, CR 1319, McGinnis Ferry Road over Big Creek

At the present time, Post this structure for 14 Tons H-Truck; 13 Tons Type 3 Truck; 18 Tons Timber Truck; 15 Tons HS-Truck and 23 Tons Type 3S2 Truck.

This structure requires posting due to insufficient flexural capacity of the steel piles. Any upgrade of the load carrying capacity would require strengthening or replacement of the substructure and removal of the asphalt overlay. The following maintenance

recommendations are provided to maintain this structure at the current rating. This bridge structure is in fair condition with corrosion of the steel piles. The piles in bent #2 should be protected with reinforced concrete encasements extending from a point 2 feet below the mud line to a point 2 feet above normal water. The concrete encasements at bent #3 have been undermined and should be extended to points 2 feet below the mud line. The steel piles throughout the structure should be cleaned and painted. Spalls in the cap at bent #2 and #3 should be repaired and the bearing material replaced to prevent future spalling. Minor spalls on the bottom of the precast superstructure units should be repaired to protect the exposed reinforcement steel from corrosion. Spalling of the asphalt overlay should be repaired. The bridge railing on the western end of the structure is loose and should be repaired. At the time of the inspection the posting signs were incorrect. The existing signs have the silhouette of a Type 3-S-2 Truck instead of the HS Type Truck and the Type 3 Truck is incorrectly posted. The HS Truck and the Type 3 Truck are therefore considered as not being posted. The signing must be corrected.

*STRUCTURE ID 121-0287-0 / LOCATION ID 121-02564F-005.47E FAS Route 2564, CR 1319, McGinnis Ferry Road over Caney Creek At the present time, Post this structure for 15 Tons H-Truck; 15 Tons Type 3 Truck; 20 Tons Timber Truck and 17 Tons HS-Truck.

This structure requires posting due to insufficient flexural capacity of the steel piles and the excessive 5.0 inch asphalt overlay. Any upgrade of the load carrying capacity would require strengthening or replacement of the substructure and removal of the asphalt overlay. This bridge structure is in good condition with no other reported deficiencies.

*STRUCTURE ID 121-0288-0 / LOCATION ID 121-02564F-007.12E FAS 2564, CR 1319, McGinnis Ferry Road over Johns Creek At the present time, Post this structure for 10 Tons H-Truck; 12 Tons Type 3 Truck; 15 Tons Timber Truck and 18 Tons Type 3S2 Truck.

This structure requires posting due to the low original design capacity of the structure and due to the concrete deck slabs not being properly bolted together. A replacement structure is required to upgrade this structure to a point where posting is no longer required. The following maintenance recommendations are provided to maintain this structure at the current rating. The cracks and spalls in all precast waffle panels should be sealed to protect the reinforcement steel from corrosion. All of the deck joints have failed and should be cleaned and sealed. At the time of inspection, the posting signs were inadequate. The existing signs have the silhouette of a Tri-Axle Truck instead of a Type 3 Truck. The Type 3 Truck is therefore considered as not being posted. The signing must be corrected.

STRUCTURE ID 121-0289-0 / LOCATION ID 121-02564F-012.08E FAS 2564, CR 1319, McGinnis Ferry Road over Chattahoochee River

This bridge structure is in fair condition. The steel beams and bearing assemblies are corroded and should be cleaned and painted. Scour and undermining of the footing at bent #3 should be repaired before load reductions or possible closure become necessary. The deck joints have failed and should be cleaned and sealed. Dirt and debris in the deck gutters and drains should be removed to allow proper drainage.

STRUCTURE ID 121-0317-0 / LOCATION ID 121-09000M-001.80N FAM 9000, CS 3003, Herchell Road over Camp Creek

This bridge structure is in satisfactory condition but has corrosion and section loss of the steel superstructure members. The steel beams throughout the structure should be cleaned and painted. The cracking in the northern abutment should be sealed.

STRUCTURE ID 121-0319-0 / LOCATION ID 121-09000M-005.80N FAM 9000, CS 3003, Dodson Drive over South Utoy Creek

This bridge structure is in fair condition. However, scour damage at the southern abutment should be corrected with rip rap. Both abutments exhibit signs of scaling and cracking which should be sealed.

STRUCTURE ID 121-0572-0 / LOCATION ID 121-09003M-000.07N FAM 9003, CS 1790, Decatur Street under Pedestrian Overpass

This non-roadway pedestrian structure was inspected for clearance purposes only. The minimum vertical clearance does not require posting. Inspection of the structural components is the responsibility of the owner.

STRUCTURE ID 121-0571-0 / LOCATION ID 121-09003M-000.08N FAM 9003, CS 1790, Decatur Street under Pedestrian Overpass

This non-roadway pedestrian structure was inspected for clearance purposes only. The minimum vertical clearance does not require posting. Inspection of the structural components is the responsibility of the owner.

STRUCTURE ID 121-0570-0 / LOCATION ID 121-09003M-000.14N FAM 9003, CS 1790, Decatur Street under Pedestrian Overpass

This non-roadway pedestrian structure was inspected for clearance purposes only. The minimum vertical clearance does not require posting. Inspection of the structural components is the responsibility of the owner.

STRUCTURE ID 121-0004-0 / LOCATION ID 121-09003M-002.68N FAM 9003, CS 3498, Marietta Street over Southern and CSX Railroad

This bridge structure is in good condition. The steel superstructure is corroded and should be cleaned and painted. The silicone joint at abutment #1 has failed and should be cleaned and sealed. The armored joint at abutment #2 should be tightened and sealed.

STRUCTURE ID 121-0005-0 / LOCATION ID 121-09003M-003.73N FAM 9003, CS 3498, Marietta Boulevard over Southern and CSX Railroad

This bridge structure is in fair condition. The ends of the steel beams and bearing assemblies are corroded and should be cleaned and painted. The deck joints have failed and should be cleaned and sealed. Spans #1 and #2 exhibit signs of scaling on the deck which has exposed the reinforcing steel. The reinforcing steel should be cleaned and sealed. The scaling should then be repaired. The asphalt pavement at the end of the structure shows signs of deep rutting and should be repaired to provide a smooth transition onto the bridge structure. Dirt and debris in the deck gutters should also be cleaned to allow proper drainage. Collision damage to the right handrail should be repaired. The handrail posts should be re-attached securely to the curb.

STRUCTURE ID 121-0006-0 / LOCATION ID 121-09003M-004.38N FAM 9003, CS 3498, Marietta Boulevard over Spur Railroad Track

This bridge structure is in fair condition with corrosion of the steel superstructure. The steel beams in span #2 should be cleaned and painted. The deck joints have also failed and should be cleaned and sealed. The slope at abutment #1 has severe erosion and should be repaired.

STRUCTURE ID 121-0681-0 / LOCATION ID 121-09003M-006.95N FAM 9003, CS 3498, Marietta Boulevard over Sewage Channel & Service Road

This bridge culvert is in satisfactory condition. Spalling within the barrels has exposed the reinforcement steel. These spalls should be sealed.

STRUCTURE ID 121-5322-0 / LOCATION ID 121-09003M-007.05N FAM 9003, CS 3498, Atlanta Road Over Chattahoochee River

This bridge structure is in good condition with no reported deficiencies.

STRUCTURE ID 121-0512-0 / LOCATION ID 121-09007M-002.04N FAM 9007, CS 1860, Piedmont Avenue under Marta Rail Line

This non-roadway MARTA structure was inspected for clearance purposes only. The minimum vertical clearance does not require posting. Inspection of the structural components is the responsibility of the owner.

STRUCTURE ID 121-0513-0 / LOCATION ID 121-09007M-002.06N FAM 9007, CS 1860, Piedmont Avenue under CSX Railroad

This non-roadway railroad structure was inspected for clearance purposes only. The minimum vertical clearance does not require posting. Inspection of the structural components is the responsibility of the owner.

*STRUCTURE ID 121-0322-0 / LOCATION ID 121-09007M-002.60N FAM 9007, CS 1868, Courtland Street over Decatur Street and CSX Railroad At the present time, Post this structure for 15 Tons H-Truck; 18 Tons Type 3 Truck; 25 Tons Timber Truck and 32 Tons Type 3S2 Truck.

This structure requires posting due to the low original design capacity of the structure. A replacement structure is required to upgrade this structure to a point where posting is no longer required. The following maintenance recommendations are provided to maintain this structure at the current rating. This bridge structure is in fair condition. The steel beams and columns throughout the structure are corroded and should be cleaned and painted. The edge beams at the joints and the bottom of the deck have extensive spalling with exposed reinforcement steel. The exposed reinforcement steel throughout the deck should be covered to protect it from corrosion. Due to the age of the structure, the spalling will probably continue and is of concern due to the large volume of pedestrian traffic under the bridge. The deck joints throughout the structure have failed and are contributing to the deterioration of the concrete at the joints and should be cleaned and sealed. Some of the concrete footings supporting the steel piles are damaged and should be repaired.

STRUCTURE ID 121-0682-0 / LOCATION ID 121-09007M-003.82N FAM 9007, CS 3462, Juniper Street under Pedestrian Overpass

This non-roadway pedestrian structure was inspected for clearance purposes only. The minimum vertical clearance does not require posting. Inspection of the structural components is the responsibility of the owner.

STRUCTURE ID 121-0627-0 / LOCATION ID 121-09007M-004.58N FAM 9007, CS 3462, Juniper Street under Pedestrian Overpass

This non-roadway pedestrian structure was inspected for clearances only. The minimum vertical clearance does not require posting. Inspection of the structural components is the responsibility of the owner.

STRUCTURE ID 121-0036-0 / LOCATION ID 121-09007M-005.42N FAM 9007, CS 3463, Piedmont Avenue over Southern Railroad

This bridge structure is in fair condition. The joints at bents #2 and #3 are jammed and have allowed the structure to shift laterally approximately 2 inches. The joints should be cleaned of all debris and sealed with a flexible sealant to prevent any further lateral movement. The concrete cap at bent #2 under beams #3, #8 and #9 and bent #3 under beams #2 and #8 have spalled and exposed the reinforcement steel. These spalls should be repaired.

STRUCTURE ID 121-0037-0 / LOCATION ID 121-09007M-005.51N FAM 9007, CS 3463, Piedmont Avenue over Clear Creek

This bridge structure is in good condition. The steel beams, diaphragms, and bearing assemblies are corroded and should be cleaned and painted. A void under the cap at the north abutment should be filled. The deck joints have failed and should be cleaned and sealed. Dirt and debris in the deck gutters and drains should be removed to allow proper drainage. Vegetation around the structure should be cut and removed.

STRUCTURE ID 121-0068-0 / LOCATION ID 121-09013M-003.92N FAM 9013, CS 3484, Bolton Road over Southern Railroad

This bridge structure is in good condition with corrosion of the steel superstructure. The steel beams and bearings throughout the structure should be cleaned and painted. The gland in the deck joint at the north abutment has failed and should be replaced. A section of the aluminum joint at this location is missing and should be repaired. The remaining joints through out the deck have also failed and should be cleaned and sealed.

STRUCTURE ID 121-0501-0 / LOCATION ID 121-09013M-005.44N FAM 9013, CS 3484, Bolton Road under CSX Railroad

This non-roadway structure has been inspected for clearance only. The minimum vertical clearance is substandard and requires posting. Our records indicate the minimum vertical clearance to be 13' -11". At the present time, post this structure in accordance with the Manual on Uniform Traffic Control Devices (current edition) Low Clearance Sign. Inspection of the structural components is the responsibility of the owner.

STRUCTURE ID 121-0683-0 / LOCATION ID 121-09013M-005.79N FAM 9013, CS 3484, Bolton Road over Whetstone Creek

This bridge culvert is in good condition. However the accumulated debris at the inlet end should be removed.

STRUCTURE ID 121-0324-0 / LOCATION ID 121-09013M-006.20N FAM 9013, CS 253, Moores Mill Road over CSX Railroad

This bridge structure is in satisfactory condition with corrosion of the steel superstructure. The steel beams throughout the structure should be cleaned and painted. The drop inlet at the south end of the structure is clogged with debris and should be cleaned out to allow proper drainage of the approach roadway. The deck joints throughout the structure have failed and should be cleaned and sealed.

STRUCTURE ID 121-0325-0 / LOCATION ID 121-09013M-006.71N FAM 9013, CS 253, Moores Mill Road over Peachtree Creek

This bridge structure is in fair condition with corrosion of the steel superstructure. The steel beams throughout the structure should be cleaned and painted. Scour in the vicinity of bent #2 and bent #3 should be corrected. One of the upstream wing walls has cracked and shifted approximately 3 inches. This wingwall should be stabilized and the crack sealed.

STRUCTURE ID 121-0672-0 / LOCATION ID 121-09013M-012.30N FAM 9013, CS 3369, E. Paces Ferry Road under Pedestrian Overpass

This non-roadway pedestrian structure was inspected for clearance purposes only. The minimum vertical clearance does not require posting. Inspection of the structural components is the responsibility of the owner.

STRUCTURE ID 121-0328-0 / LOCATION ID 121-09035M-000.01E FAM 9035, CS 3090, Paces Ferry Road over Chattahoochee River

This bridge structure is in satisfactory condition with significant scour under the column seal of columns #1 and #2 at bent #4. On the left face of column #1, a void approximately 2 feet high extends 6 feet under the seal. On the front and left faces, the voids are approximately 1 foot high and extend 4 feet under the seal. Column #2 has a void under the right back corner and the front face that is 6 inches high and extends 1 foot under the seal. This undermining should be repaired with sand bag forms followed by grout pumped in the voids. The drift in the channel should also be removed. Voids under the cap at the east abutment and erosion down the end roll should be repaired. The steel bearing assemblies have corroded and should be securely grouted in place. The deck joints throughout the structure have failed and should be cleaned and sealed. The accumulated debris at bents #2, #3, #4 and #5 should be removed.

STRUCTURE ID 121-0329-0 / LOCATION ID 121-09035M-001.50E FAM 9035, CS 3090, Paces Ferry Road over Nancy Creek

This bridge structure is in good condition with corrosion of the steel superstructure. The steel beams throughout the structure should be cleaned and painted.

STRUCTURE ID 121-0574-0 / LOCATION ID 121-09042M-001.31N FAM 9042, CS 2661, Hollywood Road over Proctor Creek Tributary

This bridge culvert is in fair condition. Up to 3.5 feet of scour at the inlet end is undermining the wingwall and should be repaired with rip rap to prevent structural damage.

STRUCTURE ID 121-5294-0 / LOCATION ID 121-09042M-001.80N FAM 9042, CS 2661, Hollywood Road over Procter Creek

This bridge structure is in good condition with no reported deficiencies.

STRUCTURE ID 121-0331-0 / LOCATION ID 121-09042M-002.53N FAM 9042, CS 2661, Hollywood Road over Southern Railroad Yard

This bridge structure is in fair condition. The concrete beams in span #5 have extensive spalling with exposed reinforcement steel which has heavy section loss. These spalls should be repaired to prevent further deterioration of the beams. The steel beams in spans #1 and #2 are corroded and should be cleaned and painted. Collision damage to the right side handrail should also be repaired. At the time of inspection this structure was posted with a restricted load limit sign. This sign is not needed and may be removed.

STRUCTURE ID 121-5180-0 / LOCATION ID 121-09044M-000.93E FAM 9044, CS 809, Baker Road over Proctor Creek Tributary

This bridge culvert is in good condition with no reported deficiencies.

STRUCTURE ID 121-0332-0 / LOCATION ID 121-09045M-004.90E FAM 9045, CS 843, Simpson Street over Proctor Creek

This bridge structure is in good condition. The steel beams are corroded and should be cleaned and painted.

STRUCTURE ID 121-5241-0 / LOCATION ID 121-09045M-005.11E FAM 9045, CS 843, Simpson Street over Marta Rail Line

This all concrete bridge structure is in good condition but the deck joints at both abutments have failed. These joints should be repaired, cleaned and sealed.

STRUCTURE ID 121-0333-0 / LOCATION ID 121-09045M-006.62E FAM 9045, CS 843, Jones Avenue over Southern and CSX Railroad

This bridge structure is in satisfactory condition with the exception of the steel superstructure. The steel beams and bearing assemblies throughout the structure are corroded and should be cleaned and painted. The steel deck joints at the eastern abutment and bent #2 are loose and should be repaired.

STRUCTURE ID 121-0563-0 / LOCATION ID 121-09045M-007.94E FAM 9045, CS 1810, Alexander Street over Techwood Spring Street Connector

This all concrete bridge structure is in good condition with no serious reported structural defects. The retaining wall panels beneath the structure are leaning out of plumb and should be monitored for further signs of movement.

STRUCTURE ID 121-0515-0 / LOCATION ID 121-09045M-008.82E FAM 9045, CS 1810, Ralph McGill Boulevard under Southern Railroad

This non-roadway railroad structure has been inspected for clearance purposes only. The minimum vertical clearance is substandard and requires posting. Our records indicate the minimum vertical clearance to be 14'-00". At the present time, the county should verify this clearance and post this structure in accordance with the Manual on Uniform Traffic Control Devices (current edition) Low Clearance Sign. Inspection of the structural components is the responsibility of the owner.

STRUCTURE ID 121-0335-0 / LOCATION ID 121-09048M-001.10N FAM 9048, CS 2645, Northwest Road over Proctor Creek

This bridge structure is in good condition with corrosion of the steel superstructure. The steel beams throughout the structure should be cleaned and painted. The deck joints throughout the structure have failed and should be cleaned and sealed.

STRUCTURE ID 121-0338-0 / LOCATION ID 121-09052M-000.32E FAM 9052, CS 1057, Benjamin E. Mays Road over North Utoy Creek

This bridge structure is in fair condition. Spalls on the beams and bottom of the deck should be repaired to protect the reinforcing steel. The previous repairs to the scour at the east abutment have failed and additional repairs are required.

STRUCTURE ID 121-0089-0 / LOCATION ID 121-09053M-001.41E FAM 9053, CR 4176, Cascade Road over Branch of Utoy Creek

This bridge culvert is in fair condition but has channel bed scour problems at the inlet end of the structure. This scour damage is 3 feet in depth and should be repaired with rip rap before undermining of the structure can occur. One of the southern wingwall is cracked. This crack is 2 inches in width and should be sealed. Old form work in the channel approximately 10 feet upstream of the structure should also be removed to allow proper stream flow. The 2 feet of accumulated silt in barrel #2 should be removed to allow for proper flow of water through the structure.

STRUCTURE ID 121-0090-0 / LOCATION ID 121-09053M-003.54E FAM 9053, CR 4176, Cascade Road over CSX Railroad

This bridge structure is in fair condition. The steel beams and bearing assemblies are corroded and should be cleaned and painted. The steel armored joint at the west abutment is loose and should be tightened. The remaining deck joints have also failed and should be cleaned and sealed.

STRUCTURE ID 121-0091-0 / LOCATION ID 121-09053M-004.20E FAM 9053, CR 4176, Cascade Road over South Utoy Creek

This bridge structure is in good condition but has extensive drift accumulated at bent #2 and on a utility line. This drift should be removed to prevent further drift accumulation and the possibility of scour. The steel piles at bent #2 should be protected with reinforced concrete encasements extending from a point 2 feet below the mud line to a point 2 feet above normal water. The deck joints throughout the structure have failed and should be cleaned and sealed.

STRUCTURE ID 121-0516-0 / LOCATION ID 121-09053M-010.40E FAM 9053, CS 2328, Glenn Street under Norfolk Southern Railroad

This non-roadway railroad structure has been inspected for clearance purposes only. The minimum vertical clearance is substandard and requires posting. Our records indicate the minimum vertical clearance to be 13'-11". At the present time, the City should verify this clearance and post this structure in accordance with the Manual on Uniform Traffic Control Devices (current edition) Low Clearance Sign. Inspection of the structural components is the responsibility of the owner.

STRUCTURE ID 121-0517-0 / LOCATION ID 121-09053M-010.90E FAM 9053, CS 2260, Georgia Avenue under NorfolkSouthern Railroad

This non-roadway railroad structure has been inspected for clearance purposes only. The minimum vertical clearance is substandard and requires posting. Our records indicate the minimum vertical clearance to be 13'-07". At the present time, the City should verify this clearance and post this structure in accordance with the Manual on Uniform Traffic Control Devices (current edition) Low Clearance Sign. Inspection of the structural components is the responsibility of the owner.

STRUCTURE ID 121-5290-0 / LOCATION ID 121-09054M-000.85N FAM 9054, CR 495, Old Fairburn Road over Wolf Creek

This bridge culvert is in good condition with no reported structural defects. However, the void under the southern sidewalk should be repaired. The channel should be excavated and the accumulated silt in the barrels should be removed to provide a proper hydraulic section.

STRUCTURE ID 121-5301-0 / LOCATION ID 121-09054M-002.67N CR 495, Old Fairburn Road over Camp Creek

This all concrete structure is in good condition with no reported deficiencies.

*STRUCTURE ID 121-0341-0 / LOCATION ID 121-09054M-002.85N FAM 9054, CR 1349, Fairburn Road over CSX Railroad

This bridge structure is not considered to be safe for live vehicular loading, and thus falls below standards as set forth in accordance with the Federal Law, Title 23, USC, and Federal Regulations, and should be closed until repairs or replacement can be made. This bridge requires immediate closing due to excessive deterioration of the timber deck specifically span #7. The city has steel plated over a broken through section in the southbound lane. The northbound lane has an area in span #7 in which the deck members are broken and the apshalt has cracked through. This area is moving vertically under live loads. The excessive 7 inch asphalt riding surface substantially reduces the capacity of this structure and should be removed. The riding surface has pot holes which should be repaired. Our records indicate that this structure is located on a school bus route. If this route is utilized by school bus traffic, this bridge should be upgraded to a 10 Ton or better capacity. To accomplish this, a replacement structure would be required.

Please note that all structures requiring closing must be properly closed in accordance with the attached methods. In addition, appropriate advanced warning signs and barricades should be used. Please reference the Manual on Uniform Traffic Control Devices, current edition. Also, advanced warning signs should be used at the last intersection prior to each end of the structure.

At the time of the inspection, this structure was properly closed according to the approved closing alternatives.

STRUCTURE ID 121-0343-0 / LOCATION ID 121-09054M-008.54N FAM 9054, CR 1349, Fairburn Road over South Utoy Creek

This bridge structure is in good condition with no reported deficiencies.

STRUCTURE ID 121-0344-0 / LOCATION ID 121-09054M-008.60N FAM 9054, CR 1349, Fairburn Road over North Utoy Creek

This bridge structure is in satisfactory with moderate scour along the base of both abutments that should be repaired. At the time for the inspection, this structure was posted with restrictive load limit signs. These signs are not required and may be removed at the discretion of the county.

STRUCTURE ID 121-5318-0 / LOCATION ID 121-09054M-008.74N FAM 9054, CR 1349, Fairburn Road Over CSX Railroad (638628J)

This bridge structure is in good condition with no reported deficiencies.

STRUCTURE ID 121-0347-0 / LOCATION ID 121-09054M-010.70N FAM 9054, CR 1349, Fairburn Road over Sandy Creek

This bridge structure is in good condition with corrosion of the steel superstructure. The steel beams throughout the structure should be cleaned and painted. The sheet piling driven at the south upstream side of the structure to provide protection for the approach roadway are falling over and a properly constructed wingwall should be utilized at this location.

STRUCTURE ID 121-5277-0 / LOCATION ID 121-09056M-000.72E FAM 9056, CS 3029, Stone Road over North Fork Camp Creek

This bridge structure is in good condition. The deck joints have failed and should be cleaned and sealed.

STRUCTURE ID 121-0350-0 / LOCATION ID 121-09057M-004.10N FAM 9057, CS 2991, Childress Drive over South Utoy Creek

This bridge structure is in fair condition. The steel beams are corroded and should be cleaned and painted. Erosion at the south left shoulder should be immediately repaired.

STRUCTURE ID 121-0351-0 / LOCATION ID 121-09057M-006.40N FAM 9057, CS 2841, Lynhurst Drive over North Utoy Creek

This bridge structure is in good condition. The steel beams are corroded and should be cleaned and painted.

STRUCTURE ID 121-0575-0 / LOCATION ID 121-09060M-000.32N FAM 9060, CS 3072, Stone Hogan Connector over North Fork Camp Creek

This bridge culvert is in good condition. Minor scour at the inlet end should be monitored for further signs of degradation. Drift at the inlet and outlet ends should also be removed to allow proper stream flow.

STRUCTURE ID 121-0518-0 / LOCATION ID 121-09064M-000.53N FAM 9064, CS 6029, Norman Berry Road under Norfolk Southern Railroad

This non-roadway railroad structure was inspected for clearance purposes only. The minimum vertical clearance does not require posting. Inspection of the structural components is the responsibility of the owner.

STRUCTURE ID 121-0598-0 / LOCATION ID 121-09064M-002.97N FAM 9064, CS 6029, M-9064 Norman Berry Road under Southern Railroad

This non-roadway railroad structure was inspected for clearance purposes only. The existing minimum vertical clearance does not require posting. Inspection of the structural components is the responsibility of the owner.

STRUCTURE ID 121-0354-0 / LOCATION ID 121-09065M-001.72E FAM 9065, CS 1394, Campbellton Road over South Utoy Creek

This bridge structure is in fair condition. The steel beams are corroded and should be cleaned and painted. Cracking in the deck should be sealed to protect the reinforcing steel and the steel beams.

STRUCTURE ID 121-5271-0 / LOCATION ID 121-09069M-003.52E FAM 9096, CR 1374, Butner Road over Deep Creek

This bridge structure is in good condition with no reported deficiencies.

STRUCTURE ID 121-0272-0 / LOCATION ID 121-09069M-006.85E FAM 9069, CR 1374, Butner Road over Camp Creek Tributary

This bridge culvert is in satisfactory condition but has channel bed scour problems at the outlet end of the structure. This scour damage is 2.0 feet in depth and should be repaired with rip rap to prevent serious structural damage.

STRUCTURE ID 121-0273-0 / LOCATION ID 121-09069M-008.15E FAM 9069, CR 1374, Butner Road over Wolf Creek

This bridge culvert is in satisfactory condition with cracking of the eastern outlet wingwall and the adjacent barrel wall. These cracks should be sealed to protect the reinforcing from corrosion. The accumulated drift and debris at the inlet end should also be removed.

*STRUCTURE ID 121-0355-0 / LOCATION ID 121-09069M-008.95E FAM 9069, CR 1374, Butner Road over Camp Creek At the present time, Post this structure for 11 Tons H-Truck; 14 Tons Type 3

Truck and 20 Tons Timber Truck. This structure requires posting due to the extensive deterioration and cracking of the concrete substructure. A replacement structure is required to upgrade this structure to a point where posting is no longer required. The following maintenance recommendations are provided to maintain this structure at the current rating. This bridge structure is in poor condition. The concrete cap at bent #3 has minor cracks, while the cap at bent #2 has cracks ranging from 0.25 to 0.75 inches wide. These conditions should be corrected with properly designed reinforced concrete encasements. The concrete handrail in span #2 and #3 on the right side of the structure has incurred severe collision damage and should be repaired. The accumulated debris at bent #3 should be removed to reduce the further accumulation of drift and the possibility of scour. The 1.0 foot of scour at bents #2 and #3 should be repaired with rip rap.

STRUCTURE ID 121-0356-0 / LOCATION ID 121-09070M-000.50E FAM 9070, CS 791, Johnson Road over Proctor Creek

This all concrete bridge structure is in good condition with no reported deficiencies.

STRUCTURE ID 121-0357-0 / LOCATION ID 121-09071M-001.80N FAM 9071, CS 1220, Delowe Drive over South Utoy Creek Tributary

This bridge culvert is in good condition with no reported deficiencies.

STRUCTURE ID 121-0358-0 / LOCATION ID 121-09072M-002.02N FAM 9072, CS 1211, Stanton Street over South Utoy Creek

This bridge culvert is in good condition. However, the accumulated drift at the inlet end should be removed to prevent possible scour.

STRUCTURE ID 121-0359-0 / LOCATION ID 121-09073M-000.60N FAM 9073, CS 2397, Techwood Drive over Southern Railroad and M-9161

This bridge structure is in fair condition with general age deterioration throughout. The deck joints throughout the structure have failed and should be cleaned and sealed. The steel beams and bearings through out the structure exhibit signs of corrosion and should be cleaned and painted. Some of the rocker bearings at bents #13 and #17 are not in the correct position. *All of the bearings throughout the structure should be reviewed by the city and the inclination and disposition of the bearings recorded as well as the ambient temperature. The bearings should be in a vertical position when the temperature is approximately 60 degrees Fahrenheit. Any bearings in need of repair should be repositioned to the correct angle for the temperature on the day of the repair.* The handrail in spans #10, #11 and #12 has incurred collision damage and has been repaired with guardrail. It is recommended that these sections be more permanently repaired with an aluminum handrail to match the existing rail in the structure. Spalling with exposed reinforcement steel should be cleaned and sealed. The asphalt overlay exhibits signs of pot holes and cracking. The cracks should be sealed and the pot holes repaired.

*STRUCTURE ID 121-0010-0 / LOCATION ID 121-09073M-000.95N FAM 9073, CS 3586, Spring Street over Southern Railroad and Parking Lots At the present time, Post this structure for 13 Tons H-Truck; 21 Tons Type 3 Truck; 25 Tons Timber Truck; 16 Tons HS-Truck and 25 Tons Type 3S2 Truck.

This structure requires posting due to the low original design capacity of the structure. A partial replacement of the structure is required to upgrade this structure to a point where posting is no longer required. This bridge structure has had old spans #9 through #16 reconstructed. The new portion is in good condition with no reported deficiencies. The older portion is in poor condition with extensive deterioration. The steel girders are corroded resulting in spalls of the gunite coating. The majority of the bearings are frozen due to corrosion. The deck joints have failed and should be cleaned and sealed. The majority of the steel armored joints are loose and should be tightened. The concrete deck has extensive cracking. The steel H-pile safety support at bent 18 should be monitored. The asphalt overlay has extensive cracking and potholes which should be sealed and repaired. Any significant upgrading of this bridge would require replacement of the old portion of the structure. At the time of the inspection one of the posting signs was missing. This sign is required and must be replaced.

STRUCTURE ID 121-0684-0 / LOCATION ID 121-09073M-001.44N FAM 9073, CS 3479, Spring Street under Pedestrian Overpass

This non-roadway pedestrian structure was inspected for clearance purposes only. The minimum vertical clearance does not require posting. Inspection of the structural components is the responsibility of the owner.

STRUCTURE ID 121-0685-0 / LOCATION ID 121-09073M-002.15N FAM 9073, CS 3479, Spring Street under Pedestrian Overpass

This non-roadway pedestrian structure was inspected for clearance purposes only. The minimum vertical clearance does not require posting. Inspection of the structural components is the responsibility of the owner.

STRUCTURE ID 121-5242-0 / LOCATION ID 121-09074M-000.93N FAM 9074, CR 1388, Welcome All Road over South Fulton Parkway CR 2043

This all concrete bridge structure is in good condition with no reported structural deficiencies. The deck joints throughout the structure have failed and should be cleaned and sealed. The void in the vicinity of the southern abutment should also be repaired.

STRUCTURE ID 121-0361-0 / LOCATION ID 121-09074M-001.43N FAM 9074, CR 1388, Welcome All Road over CSX Railroad

This bridge structure is in good condition. The deck joints have failed and should be cleaned and sealed. The steel bearings are corroded and should be cleaned and sealed. Debris on the caps should be removed. Some of the expansion sleeves on the bridge railing are missing and should be replaced.

*STRUCTURE ID 121-0362-0 / LOCATION ID 121-09074M-003.37N FAM 9074, CR 1388, Welcome All Road over Camp Creek Post for 09 Tons, Type A Sign.

This structure requires posting due to the severe corrosion and section loss of the steel piles. Repairs to the piles at bent #2 and bent #3 are required to upgrade the load carrying capacity. The following maintenance is recommended to maintain this structure at the current rating. This bridge structure is in poor condition. The steel piles are corroded and should be cleaned and painted. The steel piles at bent #3 have severe section loss and some piles at bent #2 are also heavily corroded. All piles at bents #2 and #3 should be repaired with reinforced concrete encasements that extend from a point 2 feet below the mud line to a point 2 feet above normal water. The deck joints have failed and should be cleaned and sealed. The void under the approach slab and the cap at the north abutment should be filled to prevent possible damage to the approach slab. If the piles at bents #2 and #3 are properly repaired, the load carrying capacity of this structure could be significantly upgraded.

*STRUCTURE ID 121-5201-0 / LOCATION ID 121-09075M-000.80N FAM 9075, CR 1385, Buffington Road over Morning Creek Tributary At the present time, Post this structure for 09 Tons H-Truck; 12 Tons Type 3 Truck; 16 Tons Timber Truck; 15 Tons HS-Truck and 22 Tons Type 3S2 Truck.

This structure requires posting due to insufficient pile capacity of the timber substructure. A replacement substructure is required to upgrade this structure to a point where posting is no longer required. The following maintenance recommendations are provided to maintain this structure at the current rating. The piles throughout the structure exhibit signs of advanced decay and should be scheduled for replacement. The precast concrete cap at bent #2 has cracking under one of the exterior beams. This cracking should be sealed to prevent corrosion of the steel reinforcement. Spalls located in the vicinity of the connection bolts of the precast superstructure panels should be sealed to protect the reinforcement steel from corrosion. The deck joints have failed and should be cleaned and sealed. At the time of inspection, the structure was not properly posted. The structure was posted with the Piggy-Back Type Truck. This sign in not required and should be removed.

STRUCTURE ID 121-5243-0 / LOCATION ID 121-09075M-002.02N FAM 9075, CR 1385, Buffington Road over Morning Creek

This bridge culvert is in good condition erosion under the sidewalk on the upstream side. This erosion should be immediately repaired.

STRUCTURE ID 121-0275-0 / LOCATION ID 121-09077M-001.50E FAM 9077, CR 1384, Flat Shoals Road over Morning Creek Tributary

This bridge structure is in satisfactory condition. At the time of the inspection, this structure was posted with restrictive load limit signs. These signs are not required and may be removed at the discretion of the county.

STRUCTURE ID 121-0277-0 / LOCATION ID 121-09077M-003.48E FAM 9077, CR 1384, Flat Shoals Road over Morning Creek

This bridge culvert is in good condition but has slight channel bed scour at the inlet end of the structure. Rip rap has been placed at the inlet end but additional repair is required.

STRUCTURE ID 121-0369-0 / LOCATION ID 121-09077M-004.07E FAM 9077, CR 1384, Flat Shoals Road over Morning Creek Tributary

This bridge culvert is in good condition with no reported serious structural defects.

STRUCTURE ID 121-0371-0 / LOCATION ID 121-09079M-001.72N FAM 9079, CS 6022, Central Avenue over Norman Berry Drive

This bridge structure is in good condition but has corrosion of the steel superstructure. The steel beams throughout the structure should be cleaned and painted. The deck joints throughout the structure have failed and should be cleaned and sealed.

STRUCTURE ID 121-0519-0 / LOCATION ID 121-09080M-000.10E FAM 9080, CS 6007, Willingham Drive under CSX Railroad

This non-roadway railroad structure was inspected for clearance purposes only. The minimum vertical clearance does not require posting. Inspection of the structural components is the responsibility of the owner.

STRUCTURE ID 121-0622-0 / LOCATION ID 121-09080M-000.12E FAM 9080, CS 6007, Willingham Drive under Marta Rail Line

This non-roadway MARTA structure was inspected for clearance purposes only. The minimum vertical clearance does not require posting. Inspection of the structural components is the responsibility of the owner.

STRUCTURE ID 121-0367-0 / LOCATION ID 121-09082M-001.99E FAM 9082, CR 1389, Washington Road over Fur Creek

This bridge culvert is in good condition but has 2.0 feet of channel bed scour at both the inlet and outlet ends of the structure. The culvert floor at the inlet has begun to undermine. These areas of scour and undermining should be repaired with rip rap before serious damage to the structure can occur. Drift accumulated at the inlet end of the structure should be removed to allow proper stream flow through the structure and reduce the potential for scour.

STRUCTURE ID 121-0368-0 / LOCATION ID 121-09082M-002.12E FAM 9082, CR 1389, Washington Road over Camp Creek

This bridge structure is in good condition but has surface corrosion on all substructure piles. The piles should be cleaned and painted. The deck joints throughout the structure have failed and should be cleaned and sealed.

STRUCTURE ID 121-5183-0 / LOCATION ID 121-09082M-005.52E FAM 9082, CS 6382, Irene Kidd Parkway over Marta

This bridge structure is in good condition. The deck joints are failing and should be cleaned and sealed. A spall in beam #1 should be repaired. The right sidewalk has settled at the east abutment and should be repaired.

STRUCTURE ID 121-5184-0 / LOCATION ID 121-09082M-005.60E FAM 9082, CS 6382, Irene Kidd Parkway over CSX Railroad

This concrete bridge structure is in good condition with no reported structural defects.

STRUCTURE ID 121-5185-0 / LOCATION ID 121-09082M-005.68E FAM 9082, CS 6382, Irene Kidd Parkway over Central of Georgia Railroad

This bridge structure is in good condition. The metal expansion joints are loose and should be tightened. Spalls along the joints should also be repaired.

STRUCTURE ID 121-0576-0 / LOCATION ID 121-09085M-001.75N FAM 9085, CS 1381, Browns Mill Road over South River Tributary

This bridge structure is in fair condition. The steel beams are corroded and should be cleaned and painted.

STRUCTURE ID 121-0376-0 / LOCATION ID 121-09085M-003.11N FAM 9085, CS 1381, Browns Mill Road over South River

This bridge structure is in fair condition. The steel beams are corroded and have minor section loss. The beams should be cleaned and painted to prevent further section loss.

STRUCTURE ID 121-0577-0 / LOCATION ID 121-09085M-004.16N FAM 9085, CS 1537, Constitution Road over South River Tributary

This bridge culvert is in good condition. Two holes in the outlet apron should be filled to prevent water flow (piping) underneath the structure. Minor scour at the inlet end should be moinitored for signs of further degradation.

STRUCTURE ID 121-0581-0 / LOCATION ID 121-09086M-000.74N FAM 9086, CS 521, Pryor Road over South River Tributary

This bridge culvert is in fair condition with no structural defects reported.

STRUCTURE ID 121-0377-0 / LOCATION ID 121-09086M-001.18N FAM 9086, CS 1317, Macon Drive over South River

This bridge structure is in good condition. The deck joints have failed and should be cleaned and sealed.

STRUCTURE ID 121-0525-0 / LOCATION ID 121-09086M-001.98N FAM 9086, CS 1289, Pryor Road under CSX Railroad

This non-roadway railroad structure was inspected for clearance purposes only. The minimum vertical clearance does not require posting. Inspection of the structural components is the responsibility of the owner.

STRUCTURE ID 121-0524-0 / LOCATION ID 121-09086M-002.40N FAM 9086, CS 1289, Pryor Street under Norfolk Southern Railroad

This non-roadway railroad structure was inspected for clearance purposes only. The minimum vertical clearance does not require posting. Inspection of the structural components is the responsibility of the owner.

STRUCTURE ID 121-0686-0 / LOCATION ID 121-09089M-000.30N FAM 9089, CS 1536, River Industrial Boulevard over Federal Prison Branch

This bridge culvert is in good condition with channel bed scour at both the inlet and outlet ends of the structure. The scour damage is minor at the inlet end of the structure and is 1.2 feet deep at the culvert outlet. This scour damage should be repaired with rip rap at both the inlet and outlet ends of the structure. The northern inlet wingwall is cracked and should be sealed.

STRUCTURE ID 121-0578-0 / LOCATION ID 121-09089M-001.15N FAM 9089, CS 1536, Forest Park Road over Federal Prison Creek

This bridge structure is in good condition with no reported deficiencies.

STRUCTURE ID 121-0379-0 / LOCATION ID 121-09093M-002.40N FAM 9093, CS 3186, Forest Park Road over South River

This bridge structure is in good condition. The steel beams and bearing assemblies are corroded and should be cleaned and painted. The deck joints have never been sealed. The joints should be cleaned and sealed. Voids beneath the caps at both abutments have exposed the steel foundation piles. These voids should be filled and the piles covered to protect them from corrosion.

STRUCTURE ID 121-0599-0 / LOCATION ID 121-09095M-000.01E FAM 9095, CS 6000, M-9095 Virginia Avenue under CSX Railroad-Marta

This non-roadway structure was inspected for clearance purposes only. The existing minimum vertical clearance does not require posting. Inspection of the structural components is the responsibility of the owner.

STRUCTURE ID 121-0382-0 / LOCATION ID 121-09095M-001.34E FAM 9095, CS 6000, Virginia Avenue over Flint River

This bridge culvert is in good condition. Vegetation around the structure should be cut and removed. Minor scour at the inlet end should be monitored for signs of further degradation.

STRUCTURE ID 121-0579-0 / LOCATION ID 121-09096M-002.11E FAM 9096, CR 9999, Loop Road over Flint River

This bridge culvert is in good condition with no reported serious structural defects. Drift accumulated at the inlet end of the structure should be removed.

*STRUCTURE ID 121-0294-0 / LOCATION ID 121-09104M-000.33E

FAM 9104, CR 581, Bethsaida Road over Morning Creek Tributary At the present time, Post this structure for 08 Tons H-Truck; 10 Tons Type 3 Truck; 15 Tons Timber Truck; 13 Tons HS-Truck and 20 Tons Type 3S2 Truck.

This structure requires posting due to the low original design capacity, plus extensive decay of the timber substructure components. All the piles at bent #2 exhibit signs of advanced decay and have reduced load carrying capacities. A complete replacement of the substructure is required to upgrade this structure to a point where posting is no longer required. The following maintenance recommendations are provided to maintain this structure at the current rating. The nuts on one of the connecting bolts on one of the precast superstructure deck panels in span #1, and two of these bolts in span #2 are missing and must be replaced. The eastern approach roadway has settled and should be leveled with the deck. Our records indicate that this structure is located on a school bus route. If this route is utilized by school bus traffic, this bridge should be upgraded to a 10 ton or better capacity. Due to the extensive number of replacement piles required in the substructure, any cost effective upgrade of this structure would require complete replacement of the substructure. The precast concrete superstructure could be salvaged and utilized after the substructure is replaced.

*STRUCTURE ID 121-0295-0 / LOCATION ID 121-09104M-001.03E FAM 9104, CR 1115, Bethsaida Road over Morning Creek At the present time, Post this structure for 19 Tons H-Truck; 19 Tons Type 3 Truck and 24 Tons Timber Truck.

This structure requires posting due to overstress caused by the extra dead load of the 3.0 inch asphalt overlay. Any upgrade of the load carrying capacity would require removal of this overlay. The following maintenance recommendations are provided to maintain this structure at the current rating. This bridge structure is in satisfactory condition with corrosion of the steel substructure. The steel piles throughout the structure should be cleaned and painted. At the time of inspection, the encasements at bent #3 had been undermined and should be extended to a point 2 feet below the mud line. Two of the connecting bolt nuts for the precast concrete superstructure units are missing and should be replaced. Minor spalls have exposed the reinforcement steel of the pre-cast panel. These spalls should be repaired to protect the steel from corrosion. The existing signs have the silhouetie of an HS Truck instead of a Timber Truck. The Timber Truck is therefore considered as not being posted. The signing must be corrected.

STRUCTURE ID 121-0385-0 / LOCATION ID 121-09112M-000.50E FAM 9112, CS 3191, Hutchens Road over Poole Creek

This bridge structure is in good condition with no reported deficiencies.

STRUCTURE ID 121-0008-0 / LOCATION ID 121-09124M-004.01N FAM 9124, CS 3478, Whitehall Street over Southern Railroad

This bridge structure is in good condition. The deck joints have failed and should be cleaned and sealed. Vegetation on the structure's fencing should be removed.

STRUCTURE ID 121-0009-0 / LOCATION ID 121-09124M-004.60N FAM 9124, CS 3478, Whitehall Street over Spring Street

This bridge structure is in good condition but has several items in need of repair. The steel beams throughout the structure are corroded and should be cleaned and painted. There are cracks and spalls along the coping on the bottom side of the deck in spans #2 and #3. This loose concrete should be removed to prevent it from falling on traffic underneath the structure. The deck joints throughout the structure have also failed and should be cleaned and sealed.

STRUCTURE ID 121-0594-0 / LOCATION ID 121-09124M-004.62N FAM 9124, CS 3478, Forsyth-Whitehall under Marta Rail Line

This non-roadway MARTA structure was inspected for clearance purposes only. The minimum vertical clearance does not require posting. Inspection of the structural components is the responsibility of the owner.

STRUCTURE ID 121-0595-0 / LOCATION ID 121-09124M-004.63N FAM 9124, CS 3478, Whitehall-Fulton under Marta Rail Line

This non-roadway MARTA structure was inspected for clearance purposes only. The minimum vertical clearance does not require posting. Inspection of the structural components is the responsibility of the owner.

STRUCTURE ID 121-0386-0 / LOCATION ID 121-09128M-000.99E FAM 9128, CS 1047, Beecher Street over Utoy Creek

This bridge structure is in good condition with no reported deficiencies.

STRUCTURE ID 121-0387-0 / LOCATION ID 121-09130M-001.16N FAM 9130, CS 1149, Lawton Street over CSX Railroad

This bridge structure is in satisfactory condition but has corrosion of the steel superstructure. The steel beams throughout the structure should be cleaned and painted. The polymer joint header at the southern abutment has spalled and should be repaired. The deck joints throughout the structure have failed and should be cleaned and sealed.

STRUCTURE ID 121-0388-0 / LOCATION ID 121-09130M-001.20N FAM 9130, CS 1149, Lawton Street over White Street

This all concrete bridge structure is in satisfactory condition with general deterioration throughout the structure. The transverse and longitudinal cracks in the deck should be sealed.

STRUCTURE ID 121-0390-0 / LOCATION ID 121-09133M-000.69E FAM 9133, CS 1002, Westview Drive over White Street

This bridge structure is in satisfactory condition. The deck surface has spalls throughout. The spall located at bent #5 is approximately 5 feet long, 1.5 feet wide, and 2 inches deep. This large spall has a temporary asphalt patch that should be replaced with a permanent concrete repair. The steel beams are also corroded and should be cleaned and painted. The deck joints throughout the structure have failed and should be cleaned and sealed.

STRUCTURE ID 121-0520-0 / LOCATION ID 121-09134M-001.30E FAM 9134, CS 904, M.L.K. Jr. Drive under CSX Railroad

This non-roadway railroad structure was inspected for clearance purposes only. The minimum vertical clearance is substandard and requires posting. Our records indicate the minimum vertical clearance to be 13'-02". At the present time, the city should verify this clearance and post this structure in accordance with the Manual on Uniform Traffic Control Devices (current edition) Low Clearance Sign. Inspection of the structural components is the responsibility of the owner.

STRUCTURE ID 121-0521-0 / LOCATION ID 121-09134M-002.40E FAM 9134, CS 904, M.L.K. Jr. Drive under Pedestrian Overpass

This non-roadway pedestrian structure was inspected for clearance purposes only. The minimum vertical clearance does not require posting. Inspection of the structural components is the responsibility of the owner.

STRUCTURE ID 121-0391-0 / LOCATION ID 121-09134M-002.92E FAM 9134, CS 904, M.L.K. Jr. Drive over Southern Railroad and Mangum Street

This bridge structure is in fair condition with general age deterioration throughout. Several spalls in the deck should have the asphalt patches removed and be repaired with concrete. Several pieces of loose concrete over the parking lot area should be removed to prevent them from falling on people and objects below. The ends of the steel beams and the bearing assemblies are corroded and should be cleaned and painted. Numerous anchor bolts are loose or missing at the bearing assemblies and should be tightened or replaced. Reinforcing steel that has been exposed by spalling throughout the structure should be cleaned and sealed. Damaged or missing portions of the handrail should be repaired or replaced. The deck joints have failed and should be cleaned and sealed. Dirt and debris in the deck gutters and drains should be removed to allow proper drainage. Some areas of the deck drainage system are corroded and leaking. The city should repair or replace the drainage system and make sure the system is performing as intended. *At the time of inspection, this structure was posted with restrictive load limit signs. These signs are not required and may be removed*.

*STRUCTURE ID 121-5239-0 / LOCATION ID 121-09134M-003.25E FAM 9134, CS 904, M.L.K. Jr. Drive over Parking Lot At the present time, Post this structure for 13 Tons H-Truck; 28 Tons Type 3 Truck and 36 Tons Timber Truck.

This structure requires posting due to the low original design capacity of the structure. A replacement structure is required to upgrade this structure to a point where posting is no longer required. The following maintenance recommendations are provided to maintain this structure at the current rating. The northern half of the bridge structure is in good condition with no reported deficiencies. The southern half of this bridge structure was closed at the time of inspection. This portion of the bridge structure is in poor condition with extensive deterioration of the concrete components. Extensive spalls were observed in both the substructure and superstructure with severe corrosion of the reinforcement steel. The steel beams exhibit signs of corrosion. All exposed reinforcement steel throughout the structure should be cleaned and sealed to protect it from corrosion. The deck joints throughout the structure should be cleaned and sealed.

STRUCTURE ID 121-0393-0 / LOCATION ID 121-09135M-000.30N FAM 9135, CS 942, Anderson Avenue over CSX and Marta Rail Lines

This bridge structure is in fair condition. The steel beams and the steel bent added at the north abutment are corroded and should be cleaned and painted. Cracks and spalls located on the the caps at bents #2, #3, and #4, and on the column of bent #4 should be sealed. The deck joints have failed and should be cleaned and sealed. The sidewalk on the right has settled and there is a void under the left sidewalk. These pose a hazard to pedestrians and should be repaired.

STRUCTURE ID 121-0394-0 / LOCATION ID 121-09136M-000.29N FAM 9136, CS 797, West Lake Avenue over CSX and Marta Rail Lines

This bridge structure is in poor condition. There is heavy corrosion and major section loss at beam ends and bearings, which should be cleaned and painted. It is recommended that temporary shoring be installed until permanent repairs are made. The deck joints have failed and are contributing to the corrosion of the superstructure components. These joints should be cleaned and sealed. The sidewalk approaches have settled, creating tripping hazards and should be repaired. Dirt and debris should also be cleaned from the right sidewalk.

STRUCTURE ID 121-0395-0 / LOCATION ID 121-09137M-000.13N FAM 9137, CS 867, Chappell Road over Marta Rail Line

This all concrete bridge structure is in good condition with no reported serious structural defects. However, the deck joints throughout the structure have failed and should be cleaned and sealed. The minor spall in the cap at bent #2 should be sealed.

STRUCTURE ID 121-0396-0 / LOCATION ID 121-09141M-000.45N FAM 9141, CS 57, Chattahoochee Avenue over CSX and Southern Railroad

This bridge structure is in fair condition. The steel beams and bearing assemblies should be cleaned and painted. The deck joints have failed and should be cleaned and sealed. The steel armored joints at both abutments are loose and should be tightened. Erosion at both abutments should be repaired.

STRUCTURE ID 121-0397-0 / LOCATION ID 121-09141M-001.00N FAM 9141, CS 57, Chattahoochee Avenue over Peachtree Creek Tributary

This bridge structure is in good condition. The steel beams are corroded and should be cleaned and painted. Scour at the north abutment should be repaired to prevent undermining.

STRUCTURE ID 121-0398-0 / LOCATION ID 121-09142M-002.12N FAM 9142, CS 37, Bohler Road over Peachtree Creek

This bridge structure is in fair condition. The steel beams are corroded and should be cleaned and painted. Debris caught between the beams should be removed.

STRUCTURE ID 121-0399-0 / LOCATION ID 121-09142M-003.67N FAM 9142, CS 6, West Wesley Road over Nancy Creek

This bridge structure is in satisfactory condition with corrosion of the steel superstructure. The accumulated debris on the cap at bent #2 should be removed. The steel beams throughout the structure should be cleaned and painted. The southern right drop inlet is clogged with debris and should be cleaned to allow proper drainage. It was noted at the time of inspection that this structure is inundated during periods of heavy rain. If this structure is scheduled for replacement in the near future, it should be replaced at a higher elevation.

STRUCTURE ID 121-0400-0 / LOCATION ID 121-09143M-000.50N FAM 9143, CS 135, Howell Mill Road over Southern Railroad

This bridge structure is in good condition. The steel H-piles and the steel beams are corroded and should be cleaned and painted. Collision damage to beam #2 in span #3 should be monitored for further signs of deterioration and fatigue cracking. The deck joints have failed and should be cleaned and sealed.

STRUCTURE ID 121-0401-0 / LOCATION ID 121-09143M-001.20N FAM 9143, CS 135, Howell Mill Road over CSX Railroad

This bridge structure is in good condition. The deck joints are beginning to leak and should be cleaned and sealed. Cracks in the north abutment at the wingwall should be sealed to protect the steel reinforcement.

STRUCTURE ID 121-0403-0 / LOCATION ID 121-09143M-003.40N FAM 9143, CS 135, Howell Mill Road over Peachtree Creek

This bridge structure is in poor condition with corrosion and section loss of the steel superstructure. The steel beams and bearing assemblies throughout the structure should be cleaned, cover plated in areas of section loss and painted. The cracks and spalls in the cap under beams #1 and #9 at bent #3 and beam #7 at bent #4 should be immediately repaired. The deck joints throughout the structure have failed and should be cleaned and sealed. Repairs have been made to the erosion in the south end roll but additional repair is required. The delamination area in the gutter of span #1 should be permanently repaired. *If the corrosion and section loss is not repaired, this could result in posting or closing of the structure*.

STRUCTURE ID 121-0404-0 / LOCATION ID 121-09144M-000.60E FAM 9144, CS 101, Huff Road over CSX Railroad

This bridge structure is in good condition. The steel beams and bearing assemblies are corroded and should be cleaned and painted. The deck joints have failed and should be cleaned and sealed. Dirt and debris in the deck gutters and drains should be removed to allow proper drainage. Spalls in the handrail should be repaired.

STRUCTURE ID 121-0408-0 / LOCATION ID 121-09149M-002.63E FAM 9149, CS 1773, Virginia Avenue over Southern Railroad

This bridge structure is in good condition. The deck joints have failed and should be cleaned and sealed.

STRUCTURE ID 121-0688-0 / LOCATION ID 121-09154M-000.27E FAM 9154, CS 2000, Harris & Spring Streets under Pedestrian Overpass

This non-roadway pedestrian structure was inspected for clearance purposes only. The minimum vertical clearance does not require posting. Inspection of the structural components is the responsibility of the owner.

STRUCTURE ID 121-0689-0 / LOCATION ID 121-09154M-000.44E FAM 9154, CS 2000, Harris Street under Pedestrian Overpass

This non-roadway pedestrian structure was inspected for clearance purposes only. The minimum vertical clearance does not require posting. Inspection of the structural components is the responsibility of the owner.

STRUCTURE ID 121-0690-0 / LOCATION ID 121-09154M-000.46E FAM 9154, CS 2000, Harris/Peachtree Connector under Pedestrian Overpass

This non-roadway pedestrian structure was inspected for clearance purposes only. The minimum vertical clearance does not require posting. Inspection of the structural components is the responsibility of the owner.

STRUCTURE ID 121-0691-0 / LOCATION ID 121-09155M-000.21E FAM 9155, CS 2001, International Boulevard under Pedestrian Overpass

This non-roadway pedestrian structure was inspected for clearance purposes only. The minimum vertical clearance does not require posting. Inspection of the structural components is the responsibility of the owner.

STRUCTURE ID 121-5320-0 / LOCATION ID 121-09158M-000.20N FAM 9158, CS 665, Peachtree Street Over CSX Railroad

This bridge structure is in good condition with no reported deficiencies.

STRUCTURE ID 121-0414-0 / LOCATION ID 121-09158M-001.58N FAM 9158, CS 665, West Peachtree - Marta over I-75

This bridge structure is in good condition but has deck joint failure at the abutments. The deck joints should be cleaned and sealed.

STRUCTURE ID 121-0580-0 / LOCATION ID 121-09161M-000.25E FAM 9161, CS 1985, Mitchell Street over Abandoned Railroad

This bridge culvert is in poor condition with extensive deterioration and cracking throughout the structure. Since the tracks beneath the structure have been removed, it would be in the best interest of the City to negotiate with the railroad for the removal of this structure if at all possible.

*STRUCTURE ID 121-0415-0 / LOCATION ID 121-09161M-000.34E FAM 9161, CS 1985, Mitchell Street over Southern Railroad

This bridge structure is not considered to be safe for live vehicular loading, and thus falls below standards as set forth in accordance with the Federal Law, Title 23, USC, and Federal Regulations, and should be closed until repairs or replacement can be made. This bridge structure requires immediate closing due to major deterioration and section loss in critical structural components. Our records indicate that this structure is located on a school bus route. If this structure is utilized by school bus traffic, this structure should be upgraded to a 10 Ton or greater capacity.

Please note that all structures requiring closing must be properly closed in accordance with the attached methods. In addition, appropriate advanced warning signs and barricades should be used. Please reference the Manual on Uniform Traffic Control Devices, current edition. Also, advanced warning signs should be used at the last intersection prior to each end of the structure.

At the time of the inspection, this structure was improperly closed according to the approved closing alternatives.

STRUCTURE ID 121-0417-0 / LOCATION ID 121-09164M-001.30N FAM 9164, CS 2003, Central Avenue over Georgia Railroad, Marta & Lower Wall Street

This bridge structure is in fair condition with cracking throughout the entire structure. These cracks should be sealed and all exposed reinforcement steel covered. The deck joints throughout the structure have failed and should be cleaned and sealed. At the time of inspection, this structure was posted with restrictive load limit signs. These signs are not required and may be removed.

STRUCTURE ID 121-0692-0 / LOCATION ID 121-09164M-001.72N FAM 9164, CS 2003, Peachtree Center under Pedestrian Overpass

This non-roadway pedestrian structure was inspected for clearance purposes only. The minimum vertical clearance does not require posting. Inspection of the structural components is the responsibility of the owner.

STRUCTURE ID 121-0693-0 / LOCATION ID 121-09164M-001.92N FAM 9164, CS 2003, Peachtree Center under Pedestrian Overpass

This non-roadway pedestrian structure was inspected for clearance purposes only. The minimum vertical clearance does not require posting. Inspection of the structural components is the responsibility of the owner.

STRUCTURE ID 121-0522-0 / LOCATION ID 121-09165M-000.52N FAM 9165, CS 1431, Hill Street under CSX Railroad

This non-roadway railroad structure was inspected for clearance purposes only. The minimum vertical clearance does not require posting. Inspection of the structural components is the responsibility of the owner.

STRUCTURE ID 121-0523-0 / LOCATION ID 121-09165M-002.48N FAM 9165, CS 1431, Hill Street under CSX Railroad

This non-roadway railroad structure was inspected for clearance purposes only. The minimum vertical clearance is substandard and requires posting. Our records indicate the minimum vertical clearance to be 13'-06". At the present time, the city should verify this clearance and post this structure in accordance with the Manual on Uniform Traffic Control Devices (current edition) Low Clearance Sign. Inspection of the structural components is the responsibility of the owner.

STRUCTURE ID 121-5248-0 / LOCATION ID 121-09166M-004.84N FAM 9166, CS 2044, Pryor Street under Pedestrian Overpass

This non-roadway pedestrian structure was inspected for clearance purposes only. The minimum vertical clearance does not require posting. Inspection of the structural components is the responsibility of the owner.

STRUCTURE ID 121-0421-0 / LOCATION ID 121-09170M-001.57N FAM 9170, CS 2368, McDaniel Street over Southern Railroad

This bridge structure is in good condition. The deck joints have failed and should be cleaned and sealed. The deck drain at the south abutment should be cleaned out to allow proper drainage. A spall in the endpost at the south abutment should also be repaired.

STRUCTURE ID 121-5298-0 / LOCATION ID 121-09171M-002.60N FAM 9171, CS 1259, Lakewood Avenue over Southern Railroad

This bridge structure is in good condition. The deck joints have failed and should be cleaned and sealed. Cracks in the deck should also be sealed.

STRUCTURE ID 121-0582-0 / LOCATION ID 121-09172M-000.31E FAM 9172, CS 1348, Clair Drive over South River Tributary

This bridge structure is in fair condition. The steel beams are corroded and should be cleaned and painted.

STRUCTURE ID 121-0526-0 / LOCATION ID 121-09175M-000.63E FAM 9175, CS 2199, Confederate Avenue under CSX Railroad

This non-roadway railroad structure has been inspected for clearance purposes only. The minimum vertical clearance is substandard and requires posting. Our records indicate the minimum vertical clearance to be 13'-00". At the present time, the City should verify this clearance and post this structure in accordance with the Manual on Uniform Traffic Control Devices (current edition) Low Clearance Sign. Inspection of the structural components is the responsibility of the owner.

STRUCTURE ID 121-0527-0 / LOCATION ID 121-09180M-002.57N FAM 9180, CS 520, Boulevard under CSX Railroad

This non-roadway railroad structure was inspected for clearance purposes only. The minimum vertical clearance is substandard and requires posting. Our records indicate the minimum vertical clearance to be 13'-10". At the present time, the city should verify this clearance and post this structure in accordance with the Manual on Uniform Traffic Control Devices (current edition) Low Clearance Sign. Inspection of the structural components is the responsibility of the owner.

STRUCTURE ID 121-0628-0 / LOCATION ID 121-09180M-003.40N FAM 9180, CS 520, Boulevard under Pedestrian Overpass

This non-roadway pedestrian structure was inspected for clearance purposes only. The minimum vertical clearance does not require posting. Inspection of the structural components is the responsibility of the owner.

STRUCTURE ID 121-0528-0 / LOCATION ID 121-09182M-000.70E FAM 9182, CS 2197, Ormewood Avenue under CSX Railroad

This non-roadway railroad structure was inspected for clearance purposes only. The minimum vertical clearance does not require posting. Inspection of the structural components is the responsibility of the owner.

STRUCTURE ID 121-0427-0 / LOCATION ID 121-09183M-000.80E FAM 9183, CS 2176, Berne Street over CSX Railroad

This bridge structure is in good condition. The deck joints are failing and should be cleaned and sealed.

STRUCTURE ID 121-0023-0 / LOCATION ID 121-09184M-001.39E FAM 9184, CS 3460, Edgewood Avenue over Airline Street

This bridge structure is in good condition but has corrosion of the steel superstructure. The steel beams throughout the structure should be cleaned and painted. The deck joints at both abutments have failed and should be cleaned and sealed.

STRUCTURE ID 121-0024-0 / LOCATION ID 121-09184M-001.42E FAM 9184, CS 3460, Edgewood Avenue over Southern Railroad

This bridge structure is in poor condition with general age deterioration throughout. The concrete beams are cracked and spalled with exposed reinforcement steel. These cracks and spalls should be repaired. The bearing assemblies at the abutments are severely corroded and should be replaced. The deck joints have also failed and should be cleaned and sealed.

STRUCTURE ID 121-0428-0 / LOCATION ID 121-09187M-000.92E FAM 9187, CS 610, Highland Avenue over Southern Railroad

This bridge structure is in good condition with no serious reported structural defects. However, the deck joints at both abutments have failed and should be cleaned and sealed. Erosion under the slope paving at both abutments should be repaired.

STRUCTURE ID 121-0529-0 / LOCATION ID 121-09189M-001.10E FAM 9189, CS 1835, North Avenue under Southern Railroad

This non-roadway railroad structure was inspected for clearance purposes only. The minimum vertical clearance does not require posting. Inspection of the structural components is the responsibility of the owner.

STRUCTURE ID 121-0530-0 / LOCATION ID 121-09189M-001.11E FAM 9189, CS 1835, North Avenue under Southern Railroad Spur

This non-roadway railroad structure was inspected for clearance purposes only. The minimum vertical clearance is substandard and requires posting. Our records indicate the minimum vertical clearance to be 14'-04". At the present time, the city should verify this clearance and post this structure in accordance with the Manual on Uniform Traffic Control Devices (current edition) Low Clearance Sign. Inspection of the structural components is the responsibility of the owner.

STRUCTURE ID 121-0430-0 / LOCATION ID 121-09199M-000.30N FAM 9199, CS 497, Lenox Road over South Fork Peachtree Creek

This bridge structure is in fair condition. The steel beams are corroded and should be cleaned and painted. Dirt and debris in the deck drains should be removed to allow proper drainage. It was noted at the time of inspection that the superstructure is inundated during periods of heavy rain. If this structure is replaced in the future, it is recommended that it be replaced at a higher elevation.

STRUCTURE ID 121-0566-0 / LOCATION ID 121-09200M-001.06S FAM 9200, CS 1708, Williams Street over Techwood-Spring St. Connector

This bridge structure is in good condition with no serious reported structural defects. The deck joints throughout the structure have failed and should be cleaned and sealed. Three of the retaining wall panels beneath the structure are out of plumb 10 inches and should be repaired.

STRUCTURE ID 121-0694-0 / LOCATION ID 121-09200M-001.33S FAM 9200, CS 1708, Williams Street under Pedestrian Overpass

This non-roadway pedestrian structure was inspected for clearance purposes only. The minimum vertical clearance does not require posting. Inspection of the structural components is the responsibility of the owner.

STRUCTURE ID 121-0695-0 / LOCATION ID 121-09200M-001.36S FAM 9200, CS 1708, Williams Street under Pedestrian Overpass

This non-roadway pedestrian structure was inspected for clearance purposes only. The minimum vertical clearance does not require posting. Inspection of the structural components is the responsibility of the owner.

STRUCTURE ID 121-0433-0 / LOCATION ID 121-09202M-001.50E FAM 9202, CS 533, Montgomery Ferry Drive over Clear Creek

This bridge structure is in fair condition with age deterioration of the concrete.

*STRUCTURE ID 121-5278-0 / LOCATION ID 121-09202M-001.70E FAM 9202, CS 533, Montgomery Ferry Drive over Southern Railroad At the present time, Post this structure for 15 Tons H-Truck; 15 Tons Type 3 Truck; 19 Tons Timber Truck and 16 Tons HS-Truck.

This structure requires posting due to the superstructure having insufficient flexural capacity. A replacement structure is required to upgrade the load carrying capacity to a point where posting is no longer required. This bridge structure is in good condition with no other reported deficiencies.

STRUCTURE ID 121-0016-0 / LOCATION ID 121-09204M-000.20E FAM 9204, CS 3483, Fair Drive over South River Tributary

This bridge culvert is in good condition. Drift at the inlet end should be removed to prevent additional accumulation and possible scour.

STRUCTURE ID 121-0018-0 / LOCATION ID 121-09204M-000.48E FAM 9204, CS 3483, Fair Drive over South River Tributary

This bridge culvert is in good condition. Drift at the inlet end, including an old car, should be removed to prevent additional accumulation and further scour. This obstruction restricts the stream flow here and could cause overtopping and damage to the roadway during a highwater event. Silt in barrels #1 and #2 should be removed to allow proper stream flow. Up to 1 foot of scour at the inlet end of barrel #3 should be monitored for signs of further degradation.

STRUCTURE ID 121-0435-0 / LOCATION ID 121-09205M-000.10E FAM 9205, CS 53, Collier Road over Peachtree Creek Tributary

This bridge structure is in satisfactory condition with corrosion and section loss of the superstructure. The steel beams throughout the structure should be cleaned and painted. Scour located at the west abutment has not resulted in undermining. This portion of the stream bank should be stabilized with large rip rap to prevent future scour and the possibility of undermining the abutment. Debris around the utility line and on the exterior beam at the upstream side should be removed. Erosion under the approach pavement should be immediately repaired.

STRUCTURE ID 121-0531-0 / LOCATION ID 121-09205M-000.40E FAM 9205, CS 53, Collier Road under CSX Railroad

This non-roadway structure was inspected for clearances only. The minimum vertical clearance does not require posting. Inspection of the structural components is the responsibility of the owner.

STRUCTURE ID 121-0436-0 / LOCATION ID 121-09205M-002.30E FAM 9205, CS 53, Collier Road over Tanyard Creek

This bridge structure is in good condition. Cracking in the deck and spalls on the underside should be cleaned and sealed to protect the steel reinforcement. The deck joints have failed and should be cleaned and sealed.

STRUCTURE ID 121-0437-0 / LOCATION ID 121-09205M-002.60E FAM 9205, CS 53, Collier Road over CSX Railroad

This bridge structure is in fair condition. The steel beams and bearing assemblies are corroded and should be cleaned and painted. The concrete encasements of the steel beams have spalled exposing the original beam and should be repaired. Spalls in the handrail should also be repaired.

STRUCTURE ID 121-0532-0 / LOCATION ID 121-09206M-000.20E FAM 9206, CS 16, De Foors Ferry Road under CSX Railroad

This non-roadway structure has been inspected for clearances only. The minimum vertical clearance is substandard and requires posting. Our records indicate the minimum vertical clearance to be 12'-07". At the present time, the county should verify this clearance and post this structure in accordance with the Manual on Uniform Traffic Control Devices (current edition) Low Clearance Sign. Inspection of the structural components is the responsibility of the owner.

STRUCTURE ID 121-0438-0 / LOCATION ID 121-09206M-000.96E FAM 9206, CS 16, De Foors Ferry Road over Peachtree Creek Tributary

This bridge culvert is in good condition with up to 1.2 feet of channel bed scour at the inlet end. The accumulated drift at the inlet end should be removed and all scour repaired with rip rap.

STRUCTURE ID 121-0439-0 / LOCATION ID 121-09207M-000.30N FAM 9207, CS 3, Ridgewood Road over Peachtree Creek

This bridge structure is in satisfactory condition with corrosion of the steel superstructure. The steel beams throughout the structure should be cleaned and painted.

STRUCTURE ID 121-0440-0 / LOCATION ID 121-09208M-001.00E FAM 9208, CS 4, West Paces Ferry Road over Nancy Creek

This all concrete bridge structure is in good condition. However, both approaches have settled from 1 to 3 inches. The approaches should be leveled to reduce impact loading of the structure.

STRUCTURE ID 121-0442-0 / LOCATION ID 121-09212M-001.93N FAM 9212, CR 1318, Northside Drive over Nancy Creek

This bridge structure is in satisfactory condition with corrosion of the steel superstructure components. All of the steel beams and bearings should be cleaned and painted. Erosion under the northern curb should be repaired.

STRUCTURE ID 121-0443-0 / LOCATION ID 121-09212M-004.30N FAM 9212, CR 1318, Northside Drive over Long Island Creek

This bridge structure is in satisfactory condition. The minor scour at both abutments should be monitored.

STRUCTURE ID 121-0038-0 / LOCATION ID 121-09213M-000.48N FAM 9213, CS 3463, Chester Bridge Road over CSX Railroad

This bridge structure is in fair condition. The steel beams in span #3 are corroded and should be cleaned and painted. The deck has shifted along the skew and has jammed the deck joints. This has caused minor spalls on the curb, overhang, lateral supports, beams, and caps. These joints should be repaired. The deck joints should also be cleaned and sealed. Spalls on the caps at bents #4 and #5 should be repaired to protect the reinforcing steel.

STRUCTURE ID 121-0039-0 / LOCATION ID 121-09213M-000.70N FAM 9213, CS 3463, Chester Bridge Road over South Fork Peachtree Creek

This all concrete bridge structure is in satisfactory condition. The deck joints throughout the structure have failed and should be cleaned and sealed.

STRUCTURE ID 121-0040-0 / LOCATION ID 121-09213M-001.56N FAM 9213, CS 3463, Lenox Road over North Fork Peachtree Creek

This bridge structure is in good condition. The deck joints throughout the structure have failed and should be cleaned and sealed.

STRUCTURE ID 121-0446-0 / LOCATION ID 121-09213M-003.09N FAM 9213, CS 434, Lenox Road over Southern Railroad & Marta Rail Line

This bridge structure is in good condition. The deck joints have failed and should be cleaned and sealed. Potholes near the north abutment should be repaired to provide a safe driving environment.

STRUCTURE ID 121-0507-0 / LOCATION ID 121-09215M-000.88E FAM 9215, CS 3487, Lindbergh Drive under Southern Railroad

This non-roadway structure has been inspected for clearances only. The minimum vertical clearance is substandard and requires posting. Our records indicate the minimum vertical clearance to be 13' 11". At the present time, the city should verify this clearance and post this structure in accordance with the Manual on Uniform Traffic Control Devices (current edition) Low Clearance Sign. Inspection of the structural components is the responsibility of the owner.

STRUCTURE ID 121-0606-0 / LOCATION ID 121-09215M-001.03E FAM 9215, CS 3487, Lindbergh Road over Marta Rail Line

This all concrete bridge structure is in good condition with no reported structural deficiencies. The deck joints throughout the structure have failed and should be cleaned and sealed.

STRUCTURE ID 121-5314-0 / LOCATION ID 121-09219M-000.35N Norfolk Southern Railroad Under M9219/ Roxboro Road

This non-roadway railroad structure was inspected for clearance purposes only. The minimum vertical clearance does not require posting. Inspection of the structural components is the responsibility of the owner.

STRUCTURE ID 121-0583-0 / LOCATION ID 121-09219M-000.37N FAM 9219, CR 2066, Roxboro Road under Marta Rail Line

This non-roadway structure was inspected for clearances only. The minimum vertical clearance does not require posting. Inspection of the structural components is the responsibility of the owner.

STRUCTURE ID 121-0447-0 / LOCATION ID 121-09219M-003.30N FAM 9219, CR 2066, Peachtree-Dunwoody Road over Nancy Creek

This bridge structure is in fair condition. Scour at the southern abutment and at bent #3 should be repaired with rip rap.

STRUCTURE ID 121-0592-0 / LOCATION ID 121-09219M-005.23N FAM 9219, CR 2069, Peachtree-Dunwoody Road over Nancy Creek Tributary

This bridge culvert is in good condition but has a scour problem around a utility line near the outlet end of the structure. This scour damage should be repaired with rip rap.

STRUCTURE ID 121-0448-0 / LOCATION ID 121-09243M-001.04N FAM 9243, CR 300, Powers Ferry Road over Nancy Creek

This bridge structure is in poor condition with corrosion of the steel components. The steel beams, bearing assemblies and temporary repairs to the bearing areas should be cleaned and painted. The deck joints throughout the structure have failed and should be cleaned and sealed. The cap under beam #4 at bent #2 has spalled and should be immediately repaired. The spall in the back wall at the northern abutment between beams 5 and 6 should be repaired.

STRUCTURE ID 121-0449-0 / LOCATION ID 121-09244M-001.60N FAM 9244, CS 2498, Wieuca Road over Nancy Creek Tributary

This bridge structure is in satisfactory condition with corrosion of the steel superstructure. The steel beams throughout the structure should be cleaned and painted.

STRUCTURE ID 121-0450-0 / LOCATION ID 121-09244M-001.80N FAM 9244, CS 2498, Wieuca Road over Nancy Creek

This bridge structure is in satisfactory condition with corrosion of the steel superstructure. The steel beams throughout the structure should be cleaned and painted. The concrete deck has extensive deterioration with exposed reinforcement steel on the bottom. This reinforcement steel should be covered to protect it from corrosion. An open crack in the north abutment should be sealed to protect the steel reinforcement from corrosion.

STRUCTURE ID 121-5262-0 / LOCATION ID 121-09245M-000.85E FAM 9245, CS 2497, Old Ivy Road under Marta Rail Line

This non-roadway MARTA structure was inspected for clearance purposes only. The minimum vertical clearance does not require posting. Inspection of the structural components is the responsibility of the owner.

STRUCTURE ID 121-0451-0 / LOCATION ID 121-09247M-001.50N FAM 9247, CR 300, Powers Ferry Road over Long Island Creek

This bridge structure is in fair condition. However, erosion beneath the cap at both abutments should be repaired to protect the steel foundation piles from corrosion.

*STRUCTURE ID 121-0453-0 / LOCATION ID 121-09248M-001.88N FAM 9248, CR 209, Riverside Drive over Chattahoochee River Tributary At the present time, Post this structure for 17 Tons H-Truck; 18 Tons Type 3 Truck and 26 Tons Timber Truck.

This structure requires posting due to insufficient shear capacity of the concrete superstructure. A replacement structure is required to upgrade this structure to a point where posting is no longer required. This bridge structure is in good condition with no reported deficiencies. The existing signs have the silhouette of an HS Truck instead of a Type 3 Truck and the Piggy Back Truck instead of the Timber Truck. The Type 3 Truck and the Timber Truck are therefore considered as not being posted. The signing must be corrected.

STRUCTURE ID 121-0454-0 / LOCATION ID 121-09248M-003.35N FAM 9248, CR 209, Riverside Drive over Marsh Creek

This bridge structure is in fair condition with general age deterioration throughout. Debris accumulated in the deck gutters and drains should be removed to allow proper drainage of the deck.

STRUCTURE ID 121-0456-0 / LOCATION ID 121-09249M-000.50N FAM 9249, CR 296, Long Island Drive over Long Island Creek

This bridge structure is in fair condition with no reported deficiencies.

STRUCTURE ID 121-0458-0 / LOCATION ID 121-09254M-002.20E FAM 9254, CR 361, Windsor Parkway over Nancy Creek

This bridge structure is in satisfactory condition, but has collision damage to the left wing wall and bridge railing at the western abutment. This damage should be repaired. Scour around the base of all substructure units should be repaired by adding rip rap.

STRUCTURE ID 121-0593-0 / LOCATION ID 121-09255M-002.08E FAM 9255, CR 262, Hammond Drive over Nancy Creek Tributary

This bridge culvert is in good condition with 1.8 feet of scour at the inlet end of the structure. This scour should be repaired with rip rap before undermining of the structure can occur.

STRUCTURE ID 121-0278-0 / LOCATION ID 121-09268M-000.50E FAM 9268, CR 1435, Spalding Drive over Crooked Creek

This bridge structure is in fair condition with corrosion of the steel components. Beam #1 at the west abutment and beams #1 and #2 at the east abutment, have minor section loss. These areas of section loss should be cover plated. The steel beams and piling throughout the structure should then be cleaned and painted. Erosion on the right side of the eastern abutment should be repaired.

STRUCTURE ID 121-5280-0 / LOCATION ID 121-09315M-000.10E FAM 9315, CS 1940, International Boulevard under Pedestrian Bridge

This non-roadway pedestrian structure was inspected for clearance purposes only. The minimum vertical clearance does not require posting. Inspection of the structural components is the responsibility of the owner.

STRUCTURE ID 121-0535-0 / LOCATION ID 121-09315M-000.24E FAM 9315, CS 1940, International Boulevard under Southern Railroad

This non-roadway railroad structure was inspected for clearance purposes only. The minimum vertical clearance does not require posting. Inspection of the structural components is the responsibility of the owner.

STRUCTURE ID 121-0536-0 / LOCATION ID 121-09315M-000.25E FAM 9315, CS 1940, International Boulevard under Southern Railroad

This non-roadway railroad structure was inspected for clearance purposes only. The minimum vertical clearance does not require posting. Inspection of the structural components is the responsibility of the owner.

STRUCTURE ID 121-0584-0 / LOCATION ID 121-09315M-000.35E FAM 9315, CS 1940, International Boulevard under Pedestrian Overpass

This non-roadway pedestrian structure was inspected for clearance purposes only. The minimum vertical clearance does not require posting. Inspection of the structural components is the responsibility of the owner.

STRUCTURE ID 121-0281-0 / LOCATION ID 121-09373M-001.14N FAM 9373, CS 1324, Bethany Road over Cooper Sandy Creek

This bridge structure is in poor condition with corrosion of the steel substructure components. The steel piles in the stream channel should be cleaned and painted. Furthermore, these piles should be protected with reinforced concrete encasements extending from points 2 feet below the mud line to a point 2 feet above normal water. Spalls on the bottom of the beams have exposed portions of the reinforcement steel. This reinforcement should be covered to protect it from corrosion.

STRUCTURE ID 121-0268-0 / LOCATION ID 121-09378M-000.38W FAM 9378, CR 1373, Rivertown Road over King Branch

This all concrete bridge structure is in good condition with no reported serious structural defects. However, the deck joints at each abutment have failed and should be cleaned and sealed.

STRUCTURE ID 121-0510-0 / LOCATION ID 121-09379M-003.73N FAM 9379, CR 1316, Cole Street under CSX Railroad

This non-roadway structure has been inspected for clearances only. The minimum vertical clearance is substandard and requires posting. Our records indicate the minimum vertical clearance to be 9'-08". At the present time, the county should verify this clearance and post this structure in accordance with the Manual on Uniform Traffic Control Devices (current edition) Low Clearance Sign. Inspection of the structural components is the responsibility of the owner.

*STRUCTURE ID 121-5063-0 / LOCATION ID 121-09381M-001.68W FAM 9381, CR 516, Koweta Road over Deep Creek

At the present time, Post this structure for 10 Tons H-Truck; 12 Tons Type 3 Truck; 15 Tons Timber Truck and 18 Tons Type 3S2 Truck.

This structure requires posting due to the concrete deck slabs not being properly bolted together. The following maintenance recommendations are provided to maintain this structure at the current rating. This bridge structure is in fair condition but the precast concrete superstructure units are not properly bolted together and do not provide adequate load distribution. Spalls in the concrete beams should be sealed to protect the reinforcement steel within. Erosion in the vicinity of the eastern abutment has exposed the foundation piling. These piles should be covered to protect them from the environment. The deck joints have failed and should be cleaned and sealed. If these units were properly bolted and grouted together, this bridge could be upgraded to a point where posting would no longer be required.

STRUCTURE ID 121-0293-0 / LOCATION ID 121-09387M-000.49E FAM 9387, CR 1435, Dunwoody Club Drive over Ball Creek

This bridge structure is in good condition but has corrosion of the steel superstructure units. The steel beams throughout the structure should be cleaned and painted. One of the wingwalls at the western abutment has broken and should be repaired.

STRUCTURE ID 121-5296-0 / LOCATION ID 121-09404M-000.00E FAM 9404, CS 03242, Pine Grove Road Over Willeo Creek

This bridge structure is in good condition with no reported deficiencies.

STRUCTURE ID 121-0309-0 / LOCATION ID 121-09405M-000.51E FAM 9405, CS 3233, Norcross Street over Hog Waller Creek

This bridge structure is in good condition but has corrosion of the steel superstructure. The steel beams throughout the structure should be cleaned and painted.

STRUCTURE ID 121-0310-0 / LOCATION ID 121-09406M-000.82N FAM 9406, CR 1441, Crabapple Road over Hogwaller Creek

This bridge culvert is in good condition with up to 1.3 feet of scour at both the inlet and outlet ends of the structure. This scour should be repaired with rip rap before serious damage can occur. The extensive drift accumulated across the inlet end of the structure should be removed to prevent further accumulation and the possibility of additional scour.

*STRUCTURE ID 121-0305-0 / LOCATION ID 121-09407M-001.38E FAM 9407, CR 1332, Old Roswell Road over Foe Killer Creek

At the present time, Post this structure for 13 Tons H-Truck; 13 Tons Type 3 Truck; 18 Tons Timber Truck; 16 Tons HS-Truck and 20 Tons Type 3S2 Truck. At the time of the inspection, this structure was closed and being replaced. Please notify the Georgia Department of Transportation, Office of Maintenance, when traffic is placed on the new structure.

*STRUCTURE ID 121-0306-0 / LOCATION ID 121-09407M-001.66E FAM 9407, CR 1332, Rockmill Road over Foe Killer Creek Tributary At the present time, Post this structure for 19 Tons H-Truck; 19 Tons Type 3 Truck and 24 Tons Timber Truck.

At the time of the inspection, this structure was closed and being replaced. Please notify the Georgia Department of Transportation, Office of Maintenance, when traffic is placed on the new structure.

*STRUCTURE ID 121-0304-0 / LOCATION ID 121-09408M-000.08E FAM 9408, CR 1437, Riverside Road over Big Creek

At the present time, Post this structure for 11 Tons H-Truck; 11 Tons Type 3 Truck; 13 Tons Timber Truck; 12 Tons HS-Truck and 17 Tons Type 3S2 Truck.

This structure requires posting due to insufficient shear capacity of the concrete superstructure and of the concrete intermediate bent caps. Any upgrade of the load carrying capacity would require a replacement structure. The following maintenance recommendations are provided to maintain this structure at the current rating. This bridge structure is in satisfactory condition but has drift accumulated both in the stream channel and along the utility line at the site. This drift should be removed to prevent further accumulation and the possibility of scour. The deck joints throughout the structure have failed and should be cleaned and sealed. The left handrail has incurred collision damage and should be repaired.

STRUCTURE ID 121-5273-0 / LOCATION ID 121-09409M-001.90N FAM 9409, CR 1334, Haynes Bridge Road over Big Creek

This all concrete bridge structure is in good condition with no reported serious structural defects. However, the deck joints at each abutment have failed and should be cleaned and sealed.

STRUCTURE ID 121-0301-0 / LOCATION ID 121-09410M-000.30E FAM 9410, CR 1331, Rucker Road over Foe Killer Creek

This bridge structure is in fair condition with no reported deficiencies.

STRUCTURE ID 121-0300-0 / LOCATION ID 121-09411M-005.80E FAM 9411, CR 70, Webb Bridge Road over Big Creek

This bridge structure is in good condition with no reported deficiencies.

STRUCTURE ID 121-5107-0 / LOCATION ID 121-09413M-002.41N FAM 9413, CR 1323, Hopewell Road over Cooper Sandy Creek

This bridge culvert is in good condition with no reported deficiencies.

*STRUCTURE ID 121-5016-0 / LOCATION ID 121-09415M-001.80N FAM 9415, CR 27, Providence Road over Cooper Sandy Creek At the present time, Post this structure for 16 Tons H-Truck; 17 Tons Type 3 Truck and 24 Tons Timber Truck.

This structure requires posting due to the low original design capacity of the structure. A replacement structure is required to upgrade this structure to a point where posting is no longer required. This bridge structure is in fair condition with no reported deficiencies. At the time of the inspection, the posting signs were missing. These signs are required and must be replaced.

STRUCTURE ID 121-5031-0 / LOCATION ID 121-09430M-002.33E FAM 9430, CR 186, Hembree Road over Foe Killer Creek

This bridge structure is in good condition. However, extensive drift accumulated against the upstream side of the structure should be removed to allow proper stream flow through the structure and reduce the potential for scour.

STRUCTURE ID 121-0290-0 / LOCATION ID 121-09479M-000.33E FAM 9479, CR 107, Barnwell Road over Hogan Creek

This bridge structure is in fair condition with minor cracks in the masonry wall at the east abutment which should be monitored for further signs of deterioration. A large drift accumulation on the utility line upstream from the structure should be removed. At the time of the inspection, this structure was posted with restrictive load limit signs. These signs are not required and may be removed at the discretion of the county.

*STRUCTURE ID 121-0291-0 / LOCATION ID 121-09479M-004.54E FAM 9479, CR 110, Old Alabama Road over Johns Creek Tributary At the present time, Post this structure for 15 Tons H-Truck; 14 Tons Type 3 Truck; 19 Tons Timber Truck and 16 Tons HS-Truck.

This structure requires posting due to insufficient flexural capacity of the steel piles. Any upgrade of the load carrying capacity would require strengthening or replacement of the substructure and removal of the asphalt overlay. The following maintenance recommendation is provided to maintain this structure at the current rating. The steel piles throughout the structure are corroded and should be cleaned and painted.

*STRUCTURE ID 121-0292-0 / LOCATION ID 121-09479M-005.33E FAM 9479, CR 110, Old Alabama Road over Johns Creek

At the present time, Post this structure for 15 Tons H-Truck; 15 Tons Type 3 Truck; 20 Tons Timber Truck and 24 Tons Type 3S2 Truck.

This structure requires posting due to overstress caused by the extra dead load of the 6.5 inch asphalt overlay. Any upgrade of the load carrying capacity would require removal of this overlay. The following maintenance recommendations are provided to maintain this structure at the current rating. The pile encasement at pile #4 in bent #4 is undermining and should be extended to a point 2 feet below the mud line. At the time of the inspection, the posting sign on the eastern end of the structure was missing. This sign is required and must be replaced.

STRUCTURE ID 121-5258-0 / LOCATION ID 121-09486M-001.47E FAM 9486, CR 2227, Mansell Road EBL over Foe Killer Creek

This all concrete bridge structure is in good condition with no reported deficiencies.

STRUCTURE ID 121-5259-0 / LOCATION ID 121-09486M-001.48E FAM 9486, CR 2227, Mansell Road WBL over Foe Killer Creek

This all concrete bridge structure is in good condition with no reported deficiencies.

STRUCTURE ID 121-5260-0 / LOCATION ID 121-09486M-002.33E FAM 9486, CR 2227, Mansell Road EBL over Big Creek

This bridge structure is in good condition with corrosion of the steel substructure. All of the steel H-piles should be cleaned and painted.

STRUCTURE ID 121-5261-0 / LOCATION ID 121-09486M-002.34E FAM 9486, CR 2227, Mansell Road WBL over Big Creek

This bridge structure is in good condition with corrosion of the piling in bents #4 thru #7. All steel H-piling should be cleaned and painted.

LOCALLY OWNED BRIDGE INSPECTIONS:

*STRUCTURE ID 121-5002-0 / LOCATION ID 121-00003X-000.38N CR 3, Clarity Road over Little River Post for 06 Tons, Type A Sign.

This structure requires posting due to the low original design capacity of the structure. A replacement structure is required to upgrade this structure to a point where posting is no longer required. This bridge structure is in good condition with no reported deficiencies. If the timber runners were re-positioned directly above the beams, this bridge could be upgraded to a 9 Ton capacity. At the time of the inspection, the posting sign on the northern end of the structure was missing. This sign is required and must be replaced.

*STRUCTURE ID 121-5151-0 / LOCATION ID 121-00004X-000.01E CR 4, Birminngham Road over Little River

At the present time, Post this structure for 10 Tons H-Truck; 12 Tons Type 3 Truck; 15 Tons Timber Truck and 18 Tons Type 3S2 Truck.

This structure requires posting due to the concrete deck slabs not being properly bolted together. The following maintenance recommendations are provided to maintain this structure at the current rating. This bridge structure is in satisfactory condition with the exception of the substructure units. The concrete encasement at pile #2 of bent #2 has undermined. This encasement should be extended to a point 2 feet below the existing mud line. If the concrete superstructure units were properly bolted and grouted together, this bridge could be upgraded to a point where posting would no longer be required.

*STRUCTURE ID 121-5003-0 / LOCATION ID 121-00004X-003.99E CR 4, Birmingham Road over Chicken Creek Tributary

At the present time, Post this structure for 10 Tons H-Truck; 10 Tons Type 3 Truck; 13 Tons Timber Truck; 13 Tons HS-Truck and 16 Tons Type 3S2 Truck. This structure requires posting due to the concrete deck slabs not being properly bolted together. The following maintenance recommendations are provided to maintain this structure at the current rating. This bridge structure is in satisfactory condition with corrosion of the steel substructure units. The steel piles throughout the structure should be cleaned and painted. Furthermore, these piles should be protected with reinforced concrete encasements extending from points 2 feet below the mud line to a point 2 feet above normal water. The pre-cast concrete superstructure panels have areas of spalls with exposed reinforcement steel on the underside of the deck. This reinforcement steel should be cleaned and sealed to protect it from corrosion. If the deck slabs are properly bolted together, then this structure could be significantly upgraded.

*STRUCTURE ID 121-5004-0 / LOCATION ID 121-00012X-000.17E CR 12, Hamby Road over Chicken Creek

At the present time, Post this structure for 19 Tons H-Truck; 19 Tons Type 3 Truck and 23 Tons Timber Truck.

This structure requires posting due to overstress caused by the extra dead load of the 4 inch asphalt overlay. Any upgrade of the load carrying capacity would require removal of this overlay. This bridge structure is in satisfactory condition with no other reported deficiencies.

*STRUCTURE ID 121-5005-0 / LOCATION ID 121-00012X-000.67E CR 12, Hamby Road over Chicken Creek Tributary

At the present time, Post this structure for 18 Tons H-Truck; 18 Tons Type 3 Truck and 23 Tons Timber Truck.

This structure requires posting due to overstress caused by the extra dead load of the 4 inch asphalt overlay. The following maintenance recommendations are provided to maintain this structure at the current rating. This bridge structure is in satisfactory condition with the exception of the substructure which is in fair condition. The foundation piles beneath both abutments are exposed and should be cleaned, painted and covered to protect them from corrosion. Any upgrade of the load carrying capacity would require removal of the asphalt overlay.

STRUCTURE ID 121-5177-0 / LOCATION ID 121-00013X-000.30N CS 13, Coronet Way under CSX Railroad

This non-roadway structure was inspected for clearances only. The minimum vertical clearance does not require posting. Inspection of the structural components is the responsibility of the owner.

STRUCTURE ID 121-5006-0 / LOCATION ID 121-00013X-000.31E CR 13, Longstreet Road over Chicken Creek Tributary

This bridge structure is in good condition with no reported structural deficiencies. At the time of inspection, this structure was posted with a restrictive load limit sign. This sign is not required and may be removed.

STRUCTURE ID 121-5007-0 / LOCATION ID 121-00018X-000.57S CR 18, Westbrook Road over Chicken Creek Tributary

This bridge structure is in good condition with no serious reported structural defects. Problems with the approach pavement and pot holes should be repaired. At the time of inspection, this structure was posted with a restrictive load limit sign. This sign is not required and may be removed.

STRUCTURE ID 121-5008-0 / LOCATION ID 121-00018X-000.97S CR 18, Westbrook Road over Chicken Creek Tributary

This all concrete bridge structure is in fair condition. Minor cracking and spalls on the bottom of several superstructure panels have exposed the reinforcement steel. These spalls should be repaired to protect the reinforcement steel from corrosion. *At the time of inspection, this structure was posted with a restrictive load limit sign. This sign is not required and may be removed.*

STRUCTURE ID 121-5009-0 / LOCATION ID 121-00019X-000.38N CR 19, Thompson Road over Chicken Creek Tributary

This bridge structure is in good condition with no reported deficiencies.

STRUCTURE ID 121-5010-0 / LOCATION ID 121-00020X-001.18W CR 20, Dinsmore Road over Chicken Creek

This bridge structure is in satisfactory condition with drift accumulated at bent #2. This drift should be removed to reduce further accumulation and the possibility of scour. At the time of inspection, this structure was posted with a restrictive load limit sign. This sign is not required and may be removed.

STRUCTURE ID 121-5011-0 / LOCATION ID 121-00023X-000.69N CR 23, Batesville Road over Chicken Creek

This bridge structure is in satisfactory condition with undermining of the concrete encasements at piles #1 and #3 at bent #2. These encasements should be extended to a point 2 feet below the mud line.

STRUCTURE ID 121-5012-0 / LOCATION ID 121-00023X-001.31N CR 23, Batesville Road over Little River

This bridge structure is in satisfactory condition with spalling of the concrete superstructure. Beam #1 in Span #1 is spalled rear of bent #2. This spall should be sealed. At the time of inspection, this structure was posted with a restrictive load limit sign. This sign is not required and may be removed.

STRUCTURE ID 121-5013-0 / LOCATION ID 121-00024X-000.43N CR 24, Wood Road over Chicken Creek

This bridge structure is in fair condition with undermining of the pile encasements at bent #3. The encasements should be extended to a point 2 feet below the mud line. The cracks and spalls in all precast concrete superstructure panels should be sealed to protect the reinforcement steel from corrosion. *At the time of inspection, this structure was posted with a restrictive load limit sign. This sign is not required and may be removed.*

STRUCTURE ID 121-5014-0 / LOCATION ID 121-00024X-000.91N CR 24, Wood Road over Chicken Creek Tributary

This bridge structure is in satisfactory condition with no reported serious structural defects. The old timber pile cut-offs left in the stream channel should be removed to reduce the potential for drift accumulation. The spalling in the cap at the southern abutment should be sealed.

STRUCTURE ID 121-5015-0 / LOCATION ID 121-00027X-001.93N CR 27, New Providence Road over Cooper Sandy Creek

This bridge structure is in good condition with no reported deficiencies.

STRUCTURE ID 121-5303-0 / LOCATION ID 121-00034X-004.28S CR 34, Freemanville Road over Chicken Creek

This bridge structure is in good condition with no reported deficiencies. At the time of the inspection, this structure was posted with restrictive load limt signs. These signs are not required and may be removed at the discretion of the county.

*STRUCTURE ID 121-5153-0 / LOCATION ID 121-00034X-006.31S CR 34, Freemanville Road over Cooper Sandy Creek

At the present time, Post this structure for 18 Tons H-Truck; 18 Tons Type 3 Truck and 22 Tons Timber Truck.

This structure requires posting due to overstress caused by the extra dead load of the 4.5 inch asphalt overlay. Any upgrade of the load carrying capacity would require removal of this overlay. At the present time, no maintenance repairs are required to maintain this structure at the current rating.

STRUCTURE ID 121-5202-0 / LOCATION ID 121-00037X-003.03N CR 37, Cogburn Road over Chicken Creek Tributary

This bridge structure is in good condition with no reported serious structural defects.

STRUCTURE ID 121-5225-0 / LOCATION ID 121-00055X-000.05N CS 55, Seaboard Industrial Boulevard over Peachtree Creek Tributary

This bridge culvert is in good condition with no reported structural deficiencies. However, erosion behind the curbs and in the vicinity of the catch basins should be repaired. The accumulated debris located at the inlet ends should also be removed.

STRUCTURE ID 121-5226-0 / LOCATION ID 121-00056X-000.02E CS 56, Logan Circle (North) over Peachtree Creek Tributary

This bridge culvert is in good condition with no reported structural deficiencies. Rip rap at the outlet end of barrel #2 should be redistributed to reduce further bank erosion. The south eastern pavement has begun to settle and should be monitored for signs of further settlement.

STRUCTURE ID 121-5227-0 / LOCATION ID 121-00056X-000.55E CS 56, Logan Circle (South) over Peachtree Creek Tributary

This bridge culvert is in good condition. However, the accumulated silt in barrel #2 should be removed to allow proper flow of water through the structure.

*STRUCTURE ID 121-5017-0 / LOCATION ID 121-00064X-000.94N CR 64, Douglas Road over Caney Creek Post for 07 Tons, Type A Sign.

This structure requires posting due to insufficient flexural capacity of the steel superstructure. A replacement structure is required to upgrade this structure to a point where posting is no longer required. This bridge structure is in good condition with no serious reported structural defects. Our records indicate that this structure is located on a school bus route. If this route is utilized by school bus traffic, this bridge should be upgraded to a 10 ton or better capacity. To accomplish this a replacement structure would be required. Due to re-evaluation of the structure, the posting capacity of this structure has been decreased. At the time of the inspection, the posting signs were missing. These signs are required and must be replaced.

STRUCTURE ID 121-5209-0 / LOCATION ID 121-00067X-000.48N CR 67, Finley Road over Johns Creek

This bridge culvert is in good condition with no reported deficiencies.

*STRUCTURE ID 121-5019-0 / LOCATION ID 121-00072X-001.44E CR 72, Bell Road over Cauley Creek

At the present time, Post this structure for 10 Tons H-Truck; 12 Tons Type 3 Truck; 15 Tons Timber Truck and 18 Tons Type 3S2 Truck.

This structure requires posting due to the concrete deck slabs not being properly grouted. The following maintenance recommendations are provided to maintain this structure at the current rating. The connecting bolts for the precast concrete superstructure units are loose and /or missing and therefore causing the panels to not act as a unit. These panels should be properly bolted. The joints throughout the deck have failed and should be cleaned and sealed. If the panels were properly bolted together, the structure could be significantly upgraded.

*STRUCTURE ID 121-5020-0 / LOCATION ID 121-00072X-002.29E CR 72, Bell Road over Chattahoochee River Tributary

At the present time, Post this structure for 18 Tons H-Truck; 17 Tons Type 3 Truck and 22 Tons Timber Truck.

This structure requires posting due to the excessive 6.5 inch overlay that has reduced the live load carrying capacity of the structure. If the excessive overlay was removed, posting of this structure would no longer be required. At the present time, no maintenance repairs are required to maintain this structure at the current rating.

STRUCTURE ID 121-5150-0 / LOCATION ID 121-00077X-000.03N CS 77, Marietta Road over Southern Railroad/Inman Yard

This bridge structure is in good condition. The deck joints have failed and should be cleaned and sealed. Cracks in the north abutment should be cleaned and sealed. *An electrical line was run under the access panel on the bottom of the steel box beam. This electric line should be relocated to allow access.*

STRUCTURE ID 121-5149-0 / LOCATION ID 121-00077X-000.93N CS 77, Marietta Road over CSX Railroad

This bridge structure is in fair condition. The gland joints at bents #2, #3 and #4 are leaking and should be replaced. The polymer joint at bent # 5 should also be replaced. The longitudinal joints between the precast concrete deck panels are leaking and one panel has spalled. Corrosion of the pre-stressing strands in this type of panel can result in beam failure. These panels need to be monitored for signs of deterioration since more serious corrosion might be hidden and not inspectable. It is recommended that the asphalt overlay be removed and replaced along with the installation of a waterproof membrane under the overlay. Spalls located on the superstructure panels and on the substructure units should be repaired to protect the exposed reinforcement steel. The concrete "stay blocks" which retain the superstructure units have cracked and sheared and should be repaired. Spalling concrete at these stay blocks poses a danger to people below. Safety nets should be installed until more permanent repairs can be made. The separation between the left wingwall and cap at the south abutment and a large crack at the right side of the cap should be repaired. The damaged handrail and post at the south abutment should be repaired. It was noted at the time of inspection that this structure is posted with a restricted load limit sign. This sign is not required and may be removed.

*STRUCTURE ID 121-5022-0 / LOCATION ID 121-00079X-001.52N CR 79, Parsons Road over Johns Creek

At the present time, Post this structure for 10 Tons H-Truck; 12 Tons Type 3 Truck; 15 Tons Timber Truck and 17 Tons Type 3S2 Truck.

This structure requires posting due to the concrete deck slabs not being properly bolted together. The following maintenance recommendations are provided to maintain this structure at the current rating. The steel piling should be protected with reinforced concrete encasements extending from points 2 feet below the mud line to a point 2 feet above normal water. The connecting bolts for the recast concrete superstructure units are missing between panels #1 and #2 in span #2 and panel #7 and #8 in span #3. The accumulated dirt in the deck gutters should be removed to allow for proper drainage. If the panels were properly bolted together, the structure could be significantly upgraded.

STRUCTURE ID 121-5023-0 / LOCATION ID 121-00085X-001.63E CR 85, Kimball Bridge Road over Big Creek

This bridge structure is in satisfactory condition with accumulated drift at the inlet end. This drift should be removed. At the time of the inspection, this structure was posted with restrictive load limit signs. These signs are not required and may be removed at the discretion of the county.

*STRUCTURE ID 121-5024-0 / LOCATION ID 121-00103X-000.53S CR 103, Waters Road over Long Indian Creek

At the present time, Post this structure for 19 Tons H-Truck; 18 Tons Type 3 Truck and 23 Tons Timber Truck.

This structure requires posting due to the dead load from the 6 inch overlay that has reduced the load carrying capacity of this structure. If the excessive overlay were removed, load limit posting of this structure would no longer be required. Erosion and wingwall cracking at the upstream end of both abutments should be repaired. The downstream wingwalls at both abutments have also failed and should be replaced.

STRUCTURE ID 121-5025-0 / LOCATION ID 121-00109X-000.77N CR 109, Brumbelow Road over Chattahoochee River Tributary

This bridge structure is in satisfactory condition with undermining of the concrete encasements at bent #2. These encasements should be extended to a point 2 feet below the mud line. Erosion in the vicinity of both abutments should be repaired.

*STRUCTURE ID 121-5026-0 / LOCATION ID 121-00111X-000.75N CR 111, Buice Road over Johns Creek

At the present time, Post this structure for 19 Tons H-Truck; 18 Tons Type 3 Truck and 23 Tons Timber Truck.

This structure requires posting due to the dead load from the 3 inch overlay that has reduced the load carrying capacity of this structure. If the excessive overlay were removed, load limit posting of this structure would no longer be required. This bridge is in satisfactory condition. The concrete encasements for pile #4 at bent #3 and piles #1 and #3 at bent #4 have undermined and should be extended downward to a point 2 feet below the mud line.

STRUCTURE ID 121-5257-0 / LOCATION ID 121-00111X-003.45N CR 111, Buice Road over Long Indian Creek

This bridge culvert is in good condition with up to 1.2 feet of scour at the inlet end. This scour should be repaired with rip rap to prevent possible structural damage.

STRUCTURE ID 121-5285-0 / LOCATION ID 121-00119X-002.86E FAS 1891, CR 119, State Bridge Road over Johns Creek

This all concrete bridge structure is in good condition with no reported deficiencies.

STRUCTURE ID 121-5319-0 / LOCATION ID 121-00119X-002.87E FAP 1891, CR 119, State Bridge Road WBL over Johns Creek

This bridge structure is in good condition with no reported deficiencies.

*STRUCTURE ID 121-5027-0 / LOCATION ID 121-00126X-000.14W CR 126, Rockmill Way over Foe Killer Creek

At the time of the inspection, this structure was closed to traffic. It is our understanding that this structure will be removed when an adjacent project is completed. Please notify the Georgia Department of Transportation, Office of Maintenance, when this structure is removed.

STRUCTURE ID 121-5028-0 / LOCATION ID 121-00137X-000.80S CR 137, Riverside Road over Chattahoochee River Tributary

This bridge structure is in good condition with no reported deficiencies.

STRUCTURE ID 121-5029-0 / LOCATION ID 121-00137X-001.28S CR 137, Riverside Road over Chattahoochee River Tributary

This bridge structure is in satisfactory condition with minor cracks and spalls on the bottom of all panels. A spall on the bottom of the beam in panel #11 at abutment #2 has exposed the reinforcement steel approximately 2 feet. This spall should be repaired to protect the reinforcement steel from corrosion.

STRUCTURE ID 121-5030-0 / LOCATION ID 121-00138X-001.25E CR 138, Spalding Drive over Ball Mill Creek

This bridge structure is in poor condition with scour and undermining problems at the eastern abutment. The scour and undermining should be immediately repaired with rip rap before serious damage can occur to the structure. The eastern left wingwall has incurred some collision damage and should also be repaired.

STRUCTURE ID 121-5313-0 / LOCATION ID 121-00188X-001.07W CR 188 Uupper Hembree Road Over Four Killer Creek

This bridge structure is in good condition with no reported deficiencies.

STRUCTURE ID 121-5292-0 / LOCATION ID 121-00189X-000.18N CR 189, Harris Road over Foe Killer Creek Tributary

This bridge culvert is in good condition with no reported structural defects.

*STRUCTURE ID 121-5034-0 / LOCATION ID 121-00219X-000.59S CR 219, Brandon Mill Road over Marsh Creek

At the present time, Post this structure for 18 Tons H-Truck; 18 Tons Type 3 Truck and 22 Tons Timber Truck.

This structure requires posting due to the dead load from the 4 inch overlay that has reduced the load carrying capacity of this structure. If the excessive overlay were removed, load limit posting of this structure would no longer be required. Erosion around the base of both abutments should be repaired by adding rip rap. At the time of the inspection, the posting signs for this structure were missing. These signs are required and must be replaced.

STRUCTURE ID 121-5035-0 / LOCATION ID 121-00255X-001.29N CR 255, Glenridge Road over Marsh Creek

This bridge structure is in fair condition. Channel bed scour beneath the footing at bent #2 should be repaired with rip rap.

STRUCTURE ID 121-5289-0 / LOCATION ID 121-00256X-002.04N CR 256, Glenlake Parkway over Marsh Creek

This bridge culvert is in good condition but has channel bed scour at both the inlet and outlet ends of the structure. The inlet scour damage is 1.7 feet in depth, and the outlet scour is 2.2 feet deep. The outlet culvert floor has begun to undermine. All scour and undermining should be repaired with rip rap before serious structural damage can occur. Drift accumulated at the culvert inlet should also be removed to allow proper stream flow through the structure.

STRUCTURE ID 121-5178-0 / LOCATION ID 121-00263X-000.70N CS 263, Randall Mill Road over Nancy Creek

This bridge structure is in good condition. The steel beams are corroded and should be cleaned and painted. Up to 2.0 feet of scour around bent #2 should be monitored for signs of further degradation. Vegetation around the structure should be cut and removed. Dirt and debris in the deck gutters and drains should be removed to allow proper drainage.

STRUCTURE ID 121-5036-0 / LOCATION ID 121-00299X-001.14S CR 299, Lake Forest Drive over Long Island Creek

This bridge structure is in fair condition. However, holes in the deck between beams #9 and #10 should be repaired. The minor scour and undermining at the northern abutment should be monitored.

STRUCTURE ID 121-5037-0 / LOCATION ID 121-00299X-003.83S CR 299, Lake Forest Drive over Nancy Creek

This bridge structure is in good condition with the exception of the substructure. Both abutments are cracked approximately 1 inch. The south abutment has rotated forward 1 inch. The south abutment should be stabilized and all cracks sealed. A scour hole under the north span has been repaired with rip rap, but more should be added.

*STRUCTURE ID 121-5176-0 / LOCATION ID 121-00331X-000.57S CR 331, Jett Road over Long Island Creek

At the present time, Post this structure for 11 Tons H-Truck; 13 Tons Type 3 Truck; 17 Tons Timber Truck and 18 Tons Type 3S2 Truck.

This structure requires posting due to the low original design capacity of the structure. A replacement structure is required to upgrade this structure to a point where posting is no longer required. This bridge structure is in good condition with no reported deficiencies. At the time of the inspection, the posting sign on the northern end had the incorrect truck silhouettes and the sign on the southern end had the incorrect weight limit for the timber truck. These signs must be replaced.

*STRUCTURE ID 121-5038-0 / LOCATION ID 121-00415X-000.01W CR 415, Woodruff Road over Little Pea Creek Tributary

At the present time, Post this structure for 20 Tons H-Truck; 19 Tons Type 3 Truck and 24 Tons Timber Truck.

This structure requires posting due to overstress caused by the extra dead load of the 2.5 inch asphalt overlay. Any upgrade of the load carrying capacity would require removal of this overlay. The following maintenance recommendations are provided to maintain this structure at the current rating. The exposed steel piles in both abutments should be covered to protect the piles from corrosion. Four of the bolts connecting the precast concrete superstructure units are missing and should be properly replaced.

STRUCTURE ID 121-5299-0 / LOCATION ID 121-00416X-000.85W CR 416, Waterworks Road Over Cedar Creek

This bridge structure is in good condition with no reported structural deficiencies. However, the scour problem in the vicinity of the eastern abutment should be repaired with rip rap. At the time of the inspection, this structure was posted with restrictive load limit signs. These signs are not required and may be removed at the discretion of the county.

*STRUCTURE ID 121-5040-0 / LOCATION ID 121-00420X-001.20N CR 420, Phillips Road over Little Bear Creek

At the present time, Post this structure for 10 Tons H-Truck; 12 Tons Type 3 Truck; 15 Tons Timber Truck and 18 Tons Type 3S2 Truck.

This structure requires posting due to not being constructed as designed. The precast concrete superstructure units are not properly bolted together and do not provide adequate load distribution. If these units were properly bolted together, this bridge could be upgraded to a point where posting would no longer be required. The following maintenance recommendation is provided to maintain this structure at the current rating. Localized scour at each abutment should be corrected with rip rap.

STRUCTURE ID 121-5315-0 / LOCATION ID 121-00421X-001.04E CR 421, Rico-Tatum Road Over Cedar Branch

This bridge culvert is in good condition with no reported deficiencies.

STRUCTURE ID 121-5042-0 / LOCATION ID 121-00424X-001.57S CR 424, Atlanta Newnan Road over Cedar Creek

This bridge structure is in satisfactory condition with spalling of the concrete deck slab in span #1. The spall has exposed reinforcement steel which should be sealed to protect the reinforcement steel from corrosion. The concrete pile encasements at bent #2 have been undermined and should be extended to a point 2 feet below the existing mud line. Two of the slab units in span #1 are not properly bolted together. These bolts should be replaced. The settlement under both abutments should also be repaired.

STRUCTURE ID 121-5043-0 / LOCATION ID 121-00426X-000.59N CR 426, Sardis Church Road over Dry Branch

This bridge structure is in good condition with no reported deficiencies.

*STRUCTURE ID 121-5044-0 / LOCATION ID 121-00426X-002.30N CR 426, Vernon Grove Road over Longino Creek

At the present time, Post this structure for 10 Tons H-Truck; 12 Tons Type 3 Truck; 15 Tons Timber Truck and 18 Tons Type 3S2 Truck.

This structure requires posting due to the concrete deck slabs not being properly bolted together. The precast concrete superstructure units are not properly bolted together, have begun to separate as much as 1.5 inches and do not provide adequate load distribution. If these units were properly bolted together and grouted, this bridge could be upgraded to a point where posting would no longer be required.

STRUCTURE ID 121-5045-0 / LOCATION ID 121-00433X-001.10W CR 433, Woodruff Road over Bear Creek

This bridge structure is in good condition with no reported deficiencies.

*STRUCTURE ID 121-5046-0 / LOCATION ID 121-00435X-001.74W CR 435, Garretts Ferry Road over Chattahoochee River Tributary *Post for 03 Tons, Type A Sign.*

This structure requires posting due the major scour and undermining at the western abutment. The following maintenance recommendations are provided to maintain this structure at the current rating. To repair this structure, full bearing would have to be established under the cap. Once the cap has been stabilized, the end roll should be protected with rip rap or other scour protection measures. The east abutment was constructed with similar methods and is susceptible to scour. Preventative measures should also be added to the east abutment to protect it from scour. Minor cracking and spalling on the bottom of several panels has exposed the reinforcement steel. These spalls should be repaired to protect the reinforcement steel from corrosion. Our records indicate that this structure is located on a school bus route. If this route is utilized by school bus traffic, this bridge should be upgraded to a 10 ton or better capacity. To accomplish this, both abutments should be stabilized and the fill material protected from scour.

STRUCTURE ID 121-5047-0 / LOCATION ID 121-00438X-000.78W CR 438, Hamilton Road over White Oak Creek

This bridge structure is in good condition but three of the bolts connecting the precast concrete superstructure units together are missing and should be replaced.

STRUCTURE ID 121-5048-0 / LOCATION ID 121-00441X-002.44E CR 441, Jones Ferry Road over White Oak Creek

This bridge culvert is in good condition with no reported serious structural defects. However, small beaver dams located within all barrels should be removed.

STRUCTURE ID 121-5049-0 / LOCATION ID 121-00442X-001.54S CR 442, Westside Road over Mill Branch

This all concrete bridge structure is in satisfactory condition with minor cracks and spalls on the bottom of several panels which has exposed the reinforcement steel. These spalls should be repaired to protect the reinforcement steel from corrosion.

*STRUCTURE ID 121-5050-0 / LOCATION ID 121-00443X-000.34N CR 443, Phillips Road over Longino Creek

At the present time, Post this structure for 10 Tons H-Truck; 12 Tons Type 3 Truck; 15 Tons Timber Truck and 18 Tons Type 3S2 Truck.

This structure requires posting due to the concrete deck slabs not being properly bolted together. The following maintenance recommendations are provided to maintain this structure at the current rating. This bridge structure is in satisfactory condition but was not constructed as designed. The precast concrete superstructure panels are not properly bolted together, have begun to separate as much as 3 inches and do not provide adequate load distribution. The cap at the northern abutment exhibits signs of cracking and should be sealed. If these units were properly bolted together and then grouted, this bridge could be upgraded to a point where posting would no longer be required.

STRUCTURE ID 121-5051-0 / LOCATION ID 121-00449X-000.43S CR 449, Short Road over Pea Creek

This bridge structure is in good condition with minor cracks and spalls on the bottom of several panels which has exposed the reinforcement steel. These spalls should be repaired to protect the reinforcement steel from corrosion. All of the deck joints have failed and should be cleaned and sealed.

STRUCTURE ID 121-5052-0 / LOCATION ID 121-00456X-001.01E CR 456, Creel Road over Little Pea Creek

This bridge structure is in good condition with undermining of the concrete encasements at bent #2. The accumulated drift at bent #2 should be removed and the encasements extended to a point 2 feet below the existing mud line. Erosion at the eastern abutment has exposed the foundation piles. This erosion damage should be corrected and the foundation piles covered to protect them from corrosion. The deck joints have failed and should be cleaned and sealed. *It was noted at the time of inspection that this structure is posted with a restricted load limit sign. This sign is not needed and can be removed at the County's discretion.*

STRUCTURE ID 121-5053-0 / LOCATION ID 121-00476X-002.55W CR 476, Boat Rock Road over Cascade Creek

This bridge culvert is in good condition. Silt accumulated in barrels #1 and #3 should be removed to allow proper stream flow through the structure and reduce the potential for scour. Vegetation growing in the vicinity of the structure should be cut and removed.

STRUCTURE ID 121-5203-0 / LOCATION ID 121-00482X-000.24N CS 482, Garson Drive over Marta

This bridge structure is in good condition with no reported deficiencies.

STRUCTURE ID 121-5304-0 / LOCATION ID 121-00485X-002.39S CR 485, Enon Road over Camp Creek

This bridge structure is in good condition with no deficiencies reported.

STRUCTURE ID 121-5269-0 / LOCATION ID 121-00485X-003.62S CR 485, Enon Road over Camp Creek Tributary

This bridge culvert is in good condition with up to 1.0 foot of scour at outlet end which should be monitored for signs of further degradation. The accumulated drift at the inlet end should also be removed. Cracks and spalls in the northern outlet wing wall should be sealed.

*STRUCTURE ID 121-5056-0 / LOCATION ID 121-00485X-008.46S CR 485, Demooney Road over Deep Creek

At the present time, Post this structure for 13 Tons H-Truck; 17 Tons Type 3 Truck; 23 Tons Timber Truck and 24 Tons Type 3S2 Truck.

This structure requires posting due to the low original design capacity of the structure. A replacement structure is required to upgrade this structure to a point where posting is no longer required. This bridge is in satisfactory condition. Our records indicate that a "State Aid" project for pile encasements has been approved. Our records also indicate that this structure is presently scheduled for future contract replacement.

STRUCTURE ID 121-5302-0 / LOCATION ID 121-00493X-002.08N CR 493, Northcutt Road over Pea Creek

This bridge structure is in good condition with no reported deficiencies. At the time of the inspection, this structure was posted with restrictive load limit signs. These signs are not required and may be removed at the discretion of the county.

STRUCTURE ID 121-5058-0 / LOCATION ID 121-00498X-000.37N CR 498, Aldredege Road over Wolf Creek

This bridge structure is in satisfactory condition but has undermining of the pile encasements at bent #2. All encasements should be extended to a point 2 feet below the mud line.

STRUCTURE ID 121-5059-0 / LOCATION ID 121-00498X-001.32N CR 498, Merk Road over Camp Creek

This bridge structure is in good condition but has major stream bank scour at bents #3 and #5. This scour has increased the unbraced pile lengths and should be repaired with rip rap. The piles at bent #3 should be repaired with properly designed sway bracing. The bent should be further protected with reinforced concrete encasements extending from a point 2 feet above normal water to a point 2 feet below the mud line. The deck joints at both abutments have failed and should be cleaned and sealed. The accumulated drift at bents #3 and #4 should be removed. *Repairs should include sway bracing bent #3, taking erosion control measures to stop stream bed scour and removal of debris from bent #4. This debris build up is one cause of continued scour at bent #3. If an addition 4 feet of scour takes place at this location a bridge closure will be required.*

STRUCTURE ID 121-5060-0 / LOCATION ID 121-00500X-000.28E CR 500, Wilkerson Mill Road over Little Bear Creek

This bridge structure is in fair condition with spalls at the bolt holes in spans #1 and #2. These spalls should be sealed.

*STRUCTURE ID 121-5061-0 / LOCATION ID 121-00515X-001.01N CR 515, Jones Bridge Road over Line Creek

At the present time, Post this structure for 10 Tons H-Truck; 12 Tons Type 3 Truck; 15 Tons Timber Truck and 18 Tons Type 3S2 Truck.

This structure requires posting due to the concrete deck slabs not being properly bolted together. The following maintenance recommendations are provided to maintain this structure at the current rating. The precast concrete deck units are not properly bolted together, have separated as much as 2.25 inches and do not provide adequate load distribution. There is exposed reinforcement and broken strands in panels #4, #5 and #6. These panels should be repaired or replaced. If these units were properly bolted and grouted together, this bridge could be upgraded to a point where posting would no longer be required.

STRUCTURE ID 121-5062-0 / LOCATION ID 121-00515X-003.24N CR 515, Jones Bridge Road over Deep Creek

This bridge structure is in good condition. However, the deck joints throughout the structure have failed and should be cleaned and sealed.

*STRUCTURE ID 121-5064-0 / LOCATION ID 121-00518X-000.35N CR 518, Derrick Road over Deep Creek Tributary At the present time, Post this structure for 19 Tons H-Truck; 19 Tons Type 3 Truck and 24 Tons Timber Truck.

This structure requires posting due to overstress caused by the extra dead load of a 3 inch asphalt overlay. Any upgrade of the load carrying capacity would require removal of this overlay. The following maintenance recommendations are provided to maintain this structure at the current rating. The pile encasements at bent #2 have been undermined and should be extended to a point 2 feet below the existing mud line. One bolt in span #2 is missing between panel #6 and #7 and should be replaced. If the excessive overlay is removed then this structure could be significantly upgraded.

STRUCTURE ID 121-5211-0 / LOCATION ID 121-00519X-000.31W CS 519, Armour Drive under Marta Rail Line

This non-roadway MARTA structure was inspected for clearance purposes only. The minimum vertical clearance does not require posting. Inspection of the structural components is the responsibility of the owner.

STRUCTURE ID 121-5135-0 / LOCATION ID 121-00519X-000.33W CS 519, Armour Drive under Southern Railroad

This non-roadway structure was inspected for clearances only. The minimum vertical clearance does not require posting. Inspection of the structural components is the responsibility of the owner.

*STRUCTURE ID 121-5065-0 / LOCATION ID 121-00522X-000.19E CR 522, Red Mill Road over Banks Creek

At the present time, Post this structure for 11 Tons H-Truck; 14 Tons Type 3 Truck; 18 Tons Timber Truck and 20 Tons Type 3S2 Truck.

At the time of the inspection, this structure was improperly closed to traffic. Please note that all structures requiring closing must be properly closed in accordance with the attached methods. In addition, appropriate advanced warning signs and barricades should be used. Please reference the Manual on Uniform Traffic Control Devices, current edition. Also, advanced warning signs should be used at the last intersection prior to each end of the structure.

STRUCTURE ID 121-5310-0 / LOCATION ID 121-00539X-000.22S CR 539, Ben Hill Road over Temple Grove Creek

This bridge culvert is in good condition. Silt building up at the inlet end should be removed to allow proper stream flow.

STRUCTURE ID 121-5068-0 / LOCATION ID 121-00552X-001.35E CR 552, Scarbrough Road over Wolf Creek

This bridge structure is in satisfactory condition. The cap at bent #2 and the bottom of several of the panels are spalled and should be cleaned and sealed to protect the reinforcing bars within.

STRUCTURE ID 121-5283-0 / LOCATION ID 121-00559X-001.20E CR 559, Hall Road over Line Creek Tributary

This bridge structure is in good condition with no reported deficiencies.

STRUCTURE ID 121-5284-0 / LOCATION ID 121-00559X-001.28E CR 559, Hall Road over Line Creek

This bridge structure is in good condition with no reported deficiencies.

STRUCTURE ID 121-5071-0 / LOCATION ID 121-00562X-001.77W CR 562, High Point Road over Deep Creek

This bridge structure is in good condition. One bolt is missing in span #2 between panel #2 and #3 which should be replaced. The deck joints have failed and should be cleaned and sealed. The grout between the deck panels should also be replaced. The spalls in the cap at bent #3 and at the joint at the western abutment should be repaired.

STRUCTURE ID 121-5072-0 / LOCATION ID 121-00574X-000.37W CR 574, Pleasant Hill Road over Cater Creek

This bridge structure is in good condition with the exception of the substructure which is in satisfactory condition. The pile encasement at pile #5 in bent #2 has begun to undermine and should be extended to a point 2 feet below the mud line. Erosion under the cap at the east abutment has exposed the piles. The piles should be covered to protect them from corrosion and the source of the surface water found and diverted.

STRUCTURE ID 121-5073-0 / LOCATION ID 121-00575X-000.03E CR 575, Burdette Road over Morning Creek Tributary

This bridge structure is in good condition. The encasements at piles #1, #2 and #3 at the western abutment and pile #3 at the eastern abutment have undermined and should be extended to points 2 feet below the mud line. The bolts are missing in panels #1 and #2 and #4 and #5. These bolts should be replaced to properly distribute the loads.

STRUCTURE ID 121-5291-0 / LOCATION ID 121-00593X-001.69S CR 593, Old Bill Cook Road over Morning Creek Tributary

This new bridge culvert is in good condition with no reported structural deficiencies. However, the channel at both ends should be excavated and the accumulated silt in barrels #2 and #3 should be removed. The settlement of the roadway should be monitored.

STRUCTURE ID 121-5076-0 / LOCATION ID 121-00607X-001.29N CR 607, Mallory Road over CSX Railroad (638608X)

This bridge structure is in good condition with minor corrosion of the steel piles. The steel piles throughout the structure should be cleaned and painted. The spalls in the cap at the southern abutment and bent #2 should be sealed. The northern approach roadway has settled and should be leveled with the deck.

*STRUCTURE ID 121-5077-0 / LOCATION ID 121-00614X-001.02N CR 614, Oakley Road over Broadanax Creek

At the present time, Post this structure for 10 Tons H-Truck; 12 Tons Type 3 Truck; 15 Tons Timber Truck and 18 Tons Type 3S2 Truck.

This structure requires posting due to the concrete deck slabs not being properly bolted together. The following maintenance recommendations are provided to maintain this structure at the current rating. This bridge structure is in good condition but was not constructed as designed. The precast concrete superstructure units are not properly bolted together, have separated as much as 4 inches and do not provide adequate load distribution. The spalling of the deck slab at the northern abutment should be repaired. If these units were properly bolted and grouted together, this bridge could be upgraded to a point where posting would no longer be required. At the time of the inspection, the posting sign was missing on the northern end. This sign is required and must be replaced.

*STRUCTURE ID 121-5078-0 / LOCATION ID 121-00618X-000.59S CR 618, Peter Road over Broadanax Creek

At the present time, Post this structure for 10 Tons H-Truck; 12 Tons Type 3 Truck; 15 Tons Timber Truck and 18 Tons Type 3S2 Truck.

This structure requires posting due to the concrete deck slabs not being properly bolted together. The following maintenance recommendations are provided to maintain this structure at the current rating. This bridge structure is in good condition but was not constructed as designed. The precast concrete superstructure units are not properly bolted together and do not provide adequate load distribution. The steel piling at bent #2 also exhibit signs of corrosion and should be cleaned and painted. If the concrte superstructure units were properly bolted and grouted together, this bridge could be upgraded to a point where posting would no longer be required. At the time of the inspection, the structure was improperly posted. The amounts for the Timber and Type 3S2 are too high and should be replaced. The Piggyback sign should be removed.

*STRUCTURE ID 121-5079-0 / LOCATION ID 121-00621X-000.28E CR 621, Harris Road over White Water Creek Tributary

At the present time, Post this structure for 10 Tons H-Truck; 12 Tons Type 3 Truck; 15 Tons Timber Truck and 18 Tons Type 3S2 Truck.

This structure requires posting due to the concrete deck slabs not being properly bolted together. The following maintenance recommendations are provided to maintain this structure at the current rating. This bridge structure is in satisfactory condition but was not constructed as designed. The precast concrete superstructure units are not properly bolted together and do not provide adequate load distribution. The cattle fence across the channel is catching drift. This fence should be removed. If the concrete superstructure units were properly bolted and grouted together, this bridge could be upgraded to a point where posting would no longer be required. At the time of the inspection, the posting sign on the western end was missing. This sign is required and must be replaced.

STRUCTURE ID 121-5080-0 / LOCATION ID 121-00628X-000.16E CR 628, Landrum Road over Trickham Creek

This bridge structure is in good condition with no reported structural deficiencies. Voids under the right end of the west abutment should be repaired. The pile encasements at bent #2 have undermined and should be extended to a point 2 feet below the mud line.

*STRUCTURE ID 121-5081-0 / LOCATION ID 121-00629X-000.01W CR 629, Johnson Road over Line Creek

At the present time, Post this structure for 09 Tons H-Truck; 10 Tons Type 3 Truck; 14 Tons Timber Truck; 16 Tons HS-Truck and 18 Tons Type 3S2 Truck. This structure requires posting due to insufficient pile capacity of the timber substructure. Any significant upgrading of this bridge would require a complete replacement of the substructure. This bridge structure is in satisfactory condition with the exception of the timber substructure. All of the exposed timber piling in this structure exhibit signs of major decay and rot and have reduced capacities. Our records indicate that this structure is located on a school bus route. If this route is utilized by school bus traffic, this bridge should be upgraded to a 10 ton or better capacity. To accomplish this, the substructure should be replaced.

STRUCTURE ID 121-5082-0 / LOCATION ID 121-00629X-001.32W CR 629, Johnson Road over Shoal Creek

This bridge structure is in poor condition with rot and decay of the timber substructure. The timber piles should be monitored for signs of further deterioration. Voids beneath and behind both abutment caps should be filled. Properly designed bulkheads should be constructed to replace the rotting timber bulkheads. *Due to re-evaluation of the structure, the posting capacity of this structure has been increased slightly. At the time of the inspection, this structure was posted with restrictive load limit signs. These signs are not required and may be removed at the discretion of the county.*

STRUCTURE ID 121-5308-0 / LOCATION ID 121-00629X-003.11W CR 629, Johnson Road over Peeks Creek

This reinforced concrete bridge culvert is in good condition with no reported deficiencies.

STRUCTURE ID 121-5275-0 / LOCATION ID 121-00635X-000.25N CR 635, Creekwood Road over Borum Springs Creek

This bridge structure is in good condition with no reported structural deficiencies. The steel piles and lateral bracing have surface corrosion due to not having a protective paint system. The members should be cleaned and painted. All concrete pile encasements at bent #2 have been undermined and should be extended to a point 2 feet below the existing mud line. The accumulated drift at bent #2 should be removed to reduce further accumulation and the possibility of scour.

*STRUCTURE ID 121-5086-0 / LOCATION ID 121-00637X-000.42E CR 637, Mann Road over Line Creek

This bridge structure is not considered to be safe for live vehicular loading, and thus falls below standards as set forth in accordance with the Federal Law, Title 23, USC, and Federal Regulations, and should be closed until repairs or replacement can be made. A replacement structure is required to upgrade this structure to a point where posting is no longer required.

Please note that all structures requiring closing must be properly closed in accordance with the attached methods. In addition, appropriate advanced warning signs and barricades should be used. Please reference the Manual on Uniform Traffic Control Devices, current edition. Also, advanced warning signs should be used at the last intersection prior to each end of the structure.

At the time of the inspection, this structure was not properly closed according to the approved closing alternatives.

STRUCTURE ID 121-5087-0 / LOCATION ID 121-00641X-000.02N CS 641, Brookridge Drive over Clear Creek

This all concrete earth filled arch is in satisfactory condition with the exception of the deck which is in satisfactory condition due to random cracking. These cracks should be sealed to prevent erosion of the earth fill within the arch section. Vegetation growing in the vicinity of the structure should be cut and removed.

STRUCTURE ID 121-5084-0 / LOCATION ID 121-00642X-001.91W CR 642, Herndon Road over Bear Creek

This bridge structure is in good condition. Voids beneath the caps at both abutments should be repaired.

STRUCTURE ID 121-5088-0 / LOCATION ID 121-00647X-000.02E CS 647, Park Drive over Southern Railroad

This concrete arch is in poor condition with general deterioration throughout the structure. Several spalls and cracks throughout the structure have exposed portions of the reinforcement steel. These cracks and spalls should be sealed to protect the reinforcement steel and to prevent further corrosion. The deck drains are clogged with debris which should be removed to allow proper drainage. *At the time of the inspection this structure was posted with restrictive load limit signs. These signs are not required and may be removed*.

STRUCTURE ID 121-5317-0 / LOCATION ID 121-00647X-000.81W CR 647, McClure Road Over Line Creek

This bridge structure is in good condition with erosion under the western approach. This erosion should be repaired.

*STRUCTURE ID 121-5274-0 / LOCATION ID 121-00650X-001.10N CR 650, Ono Road over Bear Creek

At the present time, Post this structure for 10 Tons H-Truck; 12 Tons Type 3 Truck; 15 Tons Timber Truck and 18 Tons Type 3S2 Truck.

This structure requires posting due to not being constructed as designed. The precast concrete superstructure units are not properly bolted together and do not provide adequate load distribution. If these units were properly bolted together and grouted, this bridge could be upgraded to a point where posting would no longer be required. This bridge structure is in good condition. The concrete encasements for piles #2, #3, #4 and #5 at bent #2 have undermined. These encasements should be extended downward to a point 2 feet below the existing mud line. A beaver dam at bent #2 should also be removed to allow proper stream flow beneath the structure.

STRUCTURE ID 121-5091-0 / LOCATION ID 121-00651X-001.66N CR 651, Hobgood Road over Bear Creek

This bridge structure is in good condition with no reported structural deficiencies. The concrete pile encasements at piles #4, #5, and #6 at bent #2 have been undermined and should be extended to a point 2 feet below the existing mud line.

STRUCTURE ID 121-0457-0 / LOCATION ID 121-00655X-002.16N CR 655, Johnson Ferry Road over Chattahoochee River

This bridge structure is in good condition but has corrosion of the steel superstructure bearings in the original portion of the structure. These bearings have slight section loss and should be cleaned and painted. The anchor bolts at the bearings exhibit signs of section loss and should be repaired. Settlement under the cap at the southern abutment has exposed the foundation piles resulting in corrosion and section loss. These piles should be cleaned, painted and covered to protect them from further corrosion. The deck joints throughout the structure have failed and should be cleaned and sealed. The accumulated debris at column #4 of bent #4 should be removed to reduce the further accumulation and the possibility of scour. The deck drains and catch basins are clogged with dirt and debris which should be removed.

STRUCTURE ID 121-5092-0 / LOCATION ID 121-00656X-001.04N CR 656, Petersburg Road over Bear Creek

This bridge structure is in good condition with the exception of the substructure which is in satisfactory condition. Scour at bent #2 has undermined the encasements. The encasements should be extended to a point 2 feet below the existing mud line. The cracks in the concrete overlay should also be sealed.

STRUCTURE ID 121-5228-0 / LOCATION ID 121-00716X-000.92S CS 716, Marietta Boulevard over CSX Railroad Spur

This bridge structure is in good condition. Cracks in the cap at the north abutment should be sealed. Voids beneath the cap of both abutments should be filled to protect the foundation piles from corrosion. These voids are the result of leaking deck joints, which have failed and should be cleaned and sealed. The catch basins at both ends of the bridge should be cleaned out to allow proper drainage.

STRUCTURE ID 121-5093-0 / LOCATION ID 121-00719X-000.19W CR 719, Tanacrest Drive over Chattahoochee River Tributary

This bridge culvert is in good condition but has channel bed scour problems at both the inlet and outlet ends of the structure. The inlet scour is 2.0 feet in depth, and the outlet scour is 1.0 foot deep. These areas of scour damage should be repaired with rip rap before undermining of the structure can occur.

STRUCTURE ID 121-5179-0 / LOCATION ID 121-00747X-000.10S CS 747, Kerry Circle over Proctor Creek

This bridge culvert is in good condition. Up to 3.0 feet of scour at the inlet and outlet ends is beginning to undermine the wingwalls and should be repaired with rip rap to prevent structural damage. An inlet wingwall is separating from barrel #2 and should be stabilized. Drift at the inlet end should be removed to prevent further accumulation and additional scour.

STRUCTURE ID 121-5154-0 / LOCATION ID 121-00769X-000.40N CS 769, Lotus Avenue over Proctor Creek Tributary

This bridge structure is in satisfactory condition with corrosion of the steel components. The steel beams and bearing assemblies throughout the structure should be cleaned and painted. A portion of the south western wing wall has failed and should be replaced.

STRUCTURE ID 121-5155-0 / LOCATION ID 121-00782X-000.02W CS 782, Spring Street over Proctor Creek Tributary

This bridge culvert is in good condition. Drift at the inlet end should be removed to prevent further accumulation and possibile scour. Minor scour at the inlet end should be monitored for signs of further degradation.

STRUCTURE ID 121-5094-0 / LOCATION ID 121-00794X-000.04S CS 794, Francis Place over Proctor Creek

This bridge structure is in satisfactory condition with corrosion of the steel superstructure. The steel beams throughout the structure should be cleaned and painted. Significant scour was observed at the south abutment which should be corrected with some type of rip rap.

STRUCTURE ID 121-5095-0 / LOCATION ID 121-00795X-000.13W CS 795, Hortense Way over Proctor Creek

This bridge structure is in good condition. However, the deck joints throughout the structure have failed and should be cleaned and sealed.

STRUCTURE ID 121-5238-0 / LOCATION ID 121-00809X-000.01E FAP 212-1, CR 809, Capps Ferry Road over Chattahoochee River

This bridge structure is in good condition. Drift around bents #3, #4, and #5 should be removed to prevent scour and allow proper stream flow. Settlement at the eastern abutment has exposed the foundation piles. These piles should be covered to protect them from corrosion. The deck joints have failed and should be cleaned and sealed. Dirt and debris in the deck gutters should be removed to allow proper drainage.

STRUCTURE ID 121-5300-0 / LOCATION ID 121-00809X-005.71E CR 809, South Fulton Parkway Over Cedar Branch

This all concrete bridge structure is in good with no reported deficiencies.

STRUCTURE ID 121-5181-0 / LOCATION ID 121-00813X-000.01W CS 813, North Avenue under CSX Railroad

This non-roadway railroad structure was inspected for clearance purposes only. The minimum vertical clearance does not require posting. Inspection of the structural components is the responsibility of the owner.

STRUCTURE ID 121-5245-0 / LOCATION ID 121-00813X-000.13W CS 813, North Avenue under Marta Rail Line

This non-roadway MARTA structure was inspected for clearance purposes only. The minimum vertical clearance does not require posting. Inspection of the structural components is the responsibility of the owner.

STRUCTURE ID 121-5246-0 / LOCATION ID 121-00876X-000.15E CS 876, Mobile Street over Marta

This bridge structure is in good condition. The joints at both abutments are full of debris and should be cleaned out.

STRUCTURE ID 121-5099-0 / LOCATION ID 121-00928X-001.19N CR 928, Roxburgh Drive over Big Creek Tributary

This bridge culvert is in fair condition with serious scour at both ends of the structure. This scour damage is approximately 2.4 feet deep with 1.2 feet of undermining of the culvert barrels and wingwalls. Scour at the inlet end of the structure may be due to a utility line crossing approximately 20 feet upstream from the structure. The left wingwall at the inlet end of the structure has separated from the culvert 2.5 feet. The scour at the outlet end is 1.5 feet in depth *The scour and undermining should be immediately corrected, adequate aprons constructed at both ends, and the separated wingwall replaced. Trees growing behind the culvert wingwalls should be cut and removed.*

STRUCTURE ID 121-5182-0 / LOCATION ID 121-00961X-000.09N CS 961, MARTA Under Fairfield Place

This non-roadway structure was inspected for clearances only. The minimum vertical clearance does not require posting. Inspection of the structural components is the responsibility of the owner.

STRUCTURE ID 121-5100-0 / LOCATION ID 121-01024X-000.47S CS 1024, Russell Drive over Rocky Creek

This bridge structure is in fair condition with corrosion of the steel substructure. The steel piles throughout the structure should be cleaned and painted.

STRUCTURE ID 121-5101-0 / LOCATION ID 121-01036X-000.22E CR 1036, Greentree Trail over Wolf Creek

This bridge culvert is in good condition with no reported structural defects. Drift accumulated at the culvert inlet should be removed to allow proper stream flow through the structure and reduce the potential for channel bed scour.

STRUCTURE ID 121-5102-0 / LOCATION ID 121-01099X-000.55N CR 1099, Kimberly Mill Road over Kimberly Creek

This bridge structure is in good condition with undermining of the concrete encasements. The pile encasements at bent #2 have been undermined and should be extended to a point 2 feet below the existing mud line The deck joints throughout the structure have failed and should be cleaned and sealed. The void underneath the cap at the south abutment should be filled. The spalling of the cap at bent #3 should also be repaired.

STRUCTURE ID 121-5212-0 / LOCATION ID 121-01170X-000.02E CS 1170, Dill Avenue under Marta Rail Line

This non-roadway MARTA structure was inspected for clearance purposes only. The minimum vertical clearance does not require posting. Inspection of the structural components is the responsibility of the owner.

STRUCTURE ID 121-5213-0 / LOCATION ID 121-01170X-000.03E CS 1170, Dill Avenue under Marta Rail Line

This non-roadway MARTA structure was inspected for clearance purposes only. The minimum vertical clearance does not require posting. Inspection of the structural components is the responsibility of the owner.

STRUCTURE ID 121-5204-0 / LOCATION ID 121-01170X-000.05E CS 1170, Dill Avenue under CSX Railroad

This non-roadway railroad structure was inspected for clearance purposes only. The minimum vertical clearance does not require posting. Inspection of the structural components is the responsibility of the owner.

STRUCTURE ID 121-5214-0 / LOCATION ID 121-01191X-000.02E CS 1191, Astor Avenue under Marta Rail Line

This non-roadway MARTA structure was inspected for clearance purposes only. The minimum vertical clearance does not require posting. Inspection of the structural components is the responsibility of the owner.

STRUCTURE ID 121-5215-0 / LOCATION ID 121-01191X-000.03E CS 1191, Astor Avenue under Marta Rail Line

This non-roadway MARTA structure was inspected for clearance purposes only. The minimum vertical clearance does not require posting. Inspection of the structural components is the responsibility of the owner.

STRUCTURE ID 121-5205-0 / LOCATION ID 121-01191X-000.04E CS 1191, Astor Avenue under CSX Railroad

This non-roadway railroad structure was inspected for clearance purposes only. The minimum vertical clearance does not require posting. Inspection of the structural components is the responsibility of the owner.

STRUCTURE ID 121-5206-0 / LOCATION ID 121-01194X-000.16N CS 1194, Murphy Avenue over Astor Avenue

This bridge structure is in good condition with corrosion of the steel superstructure. The steel beams throughout the structure should be cleaned and painted. The deck joint at each abutment has failed and should be cleaned and sealed.

STRUCTURE ID 121-5156-0 / LOCATION ID 121-01219X-000.21W CS 1219, Alison Street over South Utoy Creek Tributary

This bridge culvert is in good condition. Up to 2.0 feet of scour at the inlet end should be repaired with rip rap to prevent undermining. Drift at the inlet end shold also be removed to prevent further accumulation and increased scour.

STRUCTURE ID 121-5218-0 / LOCATION ID 121-01246X-000.81S CS 1246, Brewer Blvd. over South River Tributary

This bridge culvert is in good condition with no reported deficiencies.

STRUCTURE ID 121-5103-0 / LOCATION ID 121-01277X-000.84N CR 1277, Great Southwest Parkway over North Utoy Creek

This bridge structure is in fair condition with spalls and exposed reinforcement steel in the concrete superstructure which should be sealed. Piles #9 and #11 in bent #2 should be protected with reinforced concrete encasements that extend from a point 2 feet below the mud line to a point 2 feet above normal water. A void beneath the cap at the northern abutment should be filled. The deck joints have failed and should be cleaned and sealed. Spalls have exposed the reinforcing steel within the deck slabs. The reinforcing steel should be cleaned and covered to protect them from the environment.

STRUCTURE ID 121-5229-0 / LOCATION ID 121-01293X-000.20W CS 1293, Joyland Place over South River Tributary

This bridge culvert is in good condition with no reported deficiencies.

STRUCTURE ID 121-5230-0 / LOCATION ID 121-01296X-000.32E CS 1296, Thornton Street over South River Tributary

This bridge culvert is in good condition. Up to 2.0 feet of scour at the outlet apron should be repaired with rip rap to prevent undermining.

STRUCTURE ID 121-0591-0 / LOCATION ID 121-01321X-000.58E CR 1321, Cumming Street over Big Creek Tributary

This bridge culvert is in good condition but has erosion of the roadway shoulder. This erosion has reached the wingwall and should be repaired to ensure the stability of the roadway and the wingwall.

STRUCTURE ID 121-5106-0 / LOCATION ID 121-01322X-000.79N CR 1322, New Bullpen Road over Little River

This all concrete bridge structure is in fair condition with no reported deficiencies.

STRUCTURE ID 121-5157-0 / LOCATION ID 121-01350X-001.63W CR 1350, Azalea Drive over Chattahoochee River Tributary

This bridge structure is in good condition with no reported deficiencies.

STRUCTURE ID 121-5158-0 / LOCATION ID 121-01350X-003.05W CR 1350, Willeo Road over Willeo Creek

This bridge structure is in satisfactory condition with corrosion of the steel substructure. The steel piles throughout the structure should be cleaned and painted. The precast concrete superstructure and the concrete substructure caps have cracks and spalls with exposed reinforcement steel in various locations throughout the structure. These spalls should be repaired to protect the reinforcement steel from corrosion.

STRUCTURE ID 121-5279-0 / LOCATION ID 121-01361X-000.51E CS 1361, Tell Road over Camp Creek Tributary

This bridge structure is in good condition. The deck joints have failed and should be cleaned and sealed. Dirt and debris in the deck drains should be removed to allow proper drainage.

*STRUCTURE ID 121-5109-0 / LOCATION ID 121-01390X-002.95E CR 1390, Barnes Road over White Oak Creek

At the present time, Post this structure for 10 Tons H-Truck; 12 Tons Type 3 Truck; 15 Tons Timber Truck and 18 Tons Type 3S2 Truck.

This structure requires posting due to the concrete deck slabs not being properly bolted together. The following maintenance recommendations are provided to maintain this structure at the current rating. This bridge structure is in satisfactory condition with corrosion of the steel substructure. The steel piling throughout the structure should be cleaned and painted. The piles at the east abutment should be further protected with reinforced concrete encasements extending from a point 2 feet below the existing mud line to a point 2 feet above normal water. The deck panels throughout the structure have cracks and spalls with exposed reinforcement steel which should be repaired to prevent corrosion of the reinforcement steel. The lack of railing on this structure should be addressed. If these units were properly bolted and grouted together, this bridge could be upgraded to a point where posting would no longer be required. At the time of inspection, the posting signs were missing and must replaced.

STRUCTURE ID 121-5293-0 / LOCATION ID 121-01390X-003.42E CR 1390, Rico Road over Moss Creek

This bridge structure is in good condition with no serious reported structural defects. However, erosion under the western abutment has exposed one of the steel H-piles. This erosion should be repaired.

STRUCTURE ID 121-5111-0 / LOCATION ID 121-01390X-004.32E CR 1390, Rico Road over Longino Creek

This bridge structure is in fair condition, but the bolts connecting the precast concrete superstructure units are loose and should be tightened. Major scour located at the western abutment should be repaired with rip rap. Longitudinal cracks in all caps should also be sealed to protect the reinforcement steel from corrosion.

STRUCTURE ID 121-5112-0 / LOCATION ID 121-01392X-003.31N CR 1392, Cochran Mill Road over Little Bear Creek

This bridge structure is in satisfactory condition, but the concrete pile encasements at piles #4, #5, and #6 at bent #2 are undermined and should be extended downward to points 2 feet below the existing mud line. Several of the bolts connecting the precast concrete superstructure units are missing and should be replaced.

STRUCTURE ID 121-5113-0 / LOCATION ID 121-01392X-003.44N CR 1392, Cochran Mill Road over Bear Creek

This bridge structure is in good condition with no reported deficiencies.

STRUCTURE ID 121-5311-0 / LOCATION ID 121-01392X-005.28N CR 11392, Cochran Mill Road Over Little Pea Creek

This bridge culvert is in good condition with no reported deficiencies.

*STRUCTURE ID 121-5114-0 / LOCATION ID 121-01392X-006.02N CR 1392, Cochran Mill Road over Pea Creek

At the present time, Post this structure for 06 Tons H-Truck; 13 Tons Type 3 Truck; 15 Tons Timber Truck; 11 Tons HS-Truck and 19 Tons Type 3S2 Truck.

This structure requires posting due to the low original design capacity of the structure. A replacement structure is required to upgrade this structure to a point where posting is no longer required. The following maintenance recommendations are provided to maintain this structure at the current rating. The timber deck has an asphalt overlay. Pot holes in the asphalt overlay should be repaired.

*STRUCTURE ID 121-5115-0 / LOCATION ID 121-01483X-000.13N CS 1483, Woodland Road over Intrenchment Creek

This structure requires posting due to the low original design capacity. A replacement structure is required to upgrade the load carrying capacity to a point where posting is no longer required. The following maintenance is recommended to maintain this structure at the current rating. This bridge structure is in good condition. Minor scour at both abutments should be monitored for signs of further degradation.

STRUCTURE ID 121-5116-0 / LOCATION ID 121-01500X-000.44N CR 1500, Bishop Road over Bear Creek

This bridge structure is in good condition with erosion of the stream banks which should be repaired with rip rap.

STRUCTURE ID 121-5117-0 / LOCATION ID 121-01505X-001.04S CR 1505, Oakley Industrial Boulevard over Broadanax Creek

This bridge culvert is in good condition with no reported deficiencies.

*STRUCTURE ID 121-5118-0 / LOCATION ID 121-01527X-000.14E CR 1527, Porter Terry Road over Little Pea Creek *Post for 05 Tons, Type A Sign.*

This structure requires posting due to the substantial scour and undermining under the caps at both abutments. A replacement substructure is required to upgrade this structure to a point where posting is no longer required. The following maintenance recommendations are provided to maintain this structure at the current rating. This bridge structure is in poor condition with scour and erosion at both abutments. This scour and erosion should be repaired with rip rap. Minor cracks and spalls with exposed reinforcement steel in the concrete superstructure deck panels should be repaired to prevent corrosion of the reinforcement steel. A soil riding surface was present on this structure which further reduces its live load carrying capacity and should be removed.

*STRUCTURE ID 121-5119-0 / LOCATION ID 121-01529X-002.14N CR 1529, Cochran Road over Deep Creek

At the present time, Post this structure for 10 Tons H-Truck; 10 Tons Type 3 Truck; 14 Tons Timber Truck; 12 Tons HS-Truck and 15 Tons Type 3S2 Truck.

This structure requires posting due to the low original design capacity of the structure. A replacement structure is required to upgrade this structure to a point where posting is no longer required. This bridge structure is in poor condition with minor corrosion which should be monitored. Due to re-evaluation of the structure, the posting capacity of this structure has been increased slightly. At the time of the inspection, this structure was posted with restrictive load limit signs. These signs may be revised to reflect the adjusted loads.

*STRUCTURE ID 121-5120-0 / LOCATION ID 121-01529X-002.96N CR 1529, Cochran Road over Camp Creek *Post for 09 Tons, Type A Sign.*

This structure requires posting due to the low original design capacity of the structure. A replacement structure is required to upgrade this structure to a point where posting is no longer required. This bridge structure is in satisfactory condition. Due to re-evaluation of the structure, the posting capacity of this structure has been decreased. At the time of the inspection, the posting signs were incorrect. These signs are required and must be corrected.

*STRUCTURE ID 121-5231-0 / LOCATION ID 121-01536X-001.63N CS 1536, Forrest Park Road over Southern Railroad

At the present time, Post this structure for 13 Tons H-Truck; 12 Tons Type 3 Truck; 17 Tons Timber Truck; 14 Tons HS-Truck and 21 Tons Type 3S2 Truck.

This structure requires posting due to the low original design capacity. A replacement structure is required to upgrade the load carrying capacity to a point where posting is no longer required. The following maintenance is recommended to maintain this structure at the current rating. This bridge structure is in good condition. The steel beams and bearings are corroded and should be cleaned and painted. The deck joints have failed and should be cleaned and sealed.

*STRUCTURE ID 121-5210-0 / LOCATION ID 121-01638X-000.25E CR 1638, Stacks Road over CSX Railroad

At the present time, Post this structure for 20 Tons H-Truck; 19 Tons Type 3 Truck and 24 Tons Timber Truck.

This structure requires posting due to overstress caused by the extra dead load of the 3.0 inch asphalt overlay. Any upgrade of the load carrying capacity would require removal of this overlay. The following maintenance recommendations are provided to maintain this structure at the current rating. This bridge structure is in satisfactory condition with corrosion of the steel substructure. The steel piling throughout the structure should be cleaned and painted. The void that has resulted under the cap and under the approach roadway should also be filled.

*STRUCTURE ID 121-5121-0 / LOCATION ID 121-01767X-000.03E CS 1767, Bankhead Avenue over Southern & CSX Railroad

This bridge structure was closed to vehicular traffic at the time of inspection and should remain closed until replaced. According to our records this structure has been closed since 2003.

STRUCTURE ID 121-0410-0 / LOCATION ID 121-01790X-003.11E CS 1790, Decatur Street over M-9180 Boulevard

This bridge structure is in satisfactory condition with corrosion of the steel superstructure. The steel beams in span #2 should be cleaned and painted.

STRUCTURE ID 121-5186-0 / LOCATION ID 121-01790X-004.26E CS 1790, DeKalb Avenue under Pedestrian Overpass

This non-roadway pedestrian structure was inspected for clearance purposes only. The minimum vertical clearance does not require posting. Inspection of the structural components is the responsibility of the owner.

STRUCTURE ID 121-5237-0 / LOCATION ID 121-01814X-000.10S CS 1814, North Angier Avenue under Conveyor Belt

This non-roadway conveyor belt structure was inspected for clearance purposes only. The minimum vertical clearance does not require posting. Inspection of the structural components is the responsibility of the owner.

STRUCTURE ID 121-5219-0 / LOCATION ID 121-01853X-000.03E CS 1853, Linden Street under Pedestrian Overpass

This non-roadway pedestrian structure was inspected for clearance purposes only. The minimum vertical clearance does not require posting. Inspection of the structural components is the responsibility of the owner.

STRUCTURE ID 121-5187-0 / LOCATION ID 121-01865X-000.20S CR 1865, Kingsport Drive over Long Island Creek

This bridge structure is in satisfactory condition with items in need of repair. The stream bank at bent #3 has scoured and should be repaired with rip rap. The void beneath the cap of the northern abutment should also be filled. A properly designed bulkhead should be constructed at the northern abutment to prevent further loss of roadway fill and the possibility of additional settlement of the roadway. Concrete spalls in the superstructure panels have exposed the steel reinforcement. These spalls should be repaired to protect the reinforcement from corrosion.

STRUCTURE ID 121-5188-0 / LOCATION ID 121-01877X-000.14S CR 1877, Phipps Road over CSX Railroad

This bridge structure is in good condition. The steel beams and bearings are corroded and should be cleaned and painted. The deck joints have failed and should be cleaned and sealed. The catch basins at both ends of the structure should be cleaned out to allow proper drainage.

STRUCTURE ID 121-5136-0 / LOCATION ID 121-01903X-000.54E CS 1903, Jones Avenue under CSX Railroad

This non-roadway railroad structure was inspected for clearance purposes only. The minimum vertical clearance is substandard and requires posting. Our records indicate the minimum vertical clearance to be 11'-03". At the present time, the city should verify this clearance and post this structure in accordance with the Manual on Uniform Traffic Control Devices (current edition) Low Clearance Sign. Inspection of the structural components is the responsibility of the owner. It was noted at the time of inspection that the tracks had been removed from this structure, and it may be in the best interest of the City to negotiate with the railroad for the removal of this structure.

STRUCTURE ID 121-5139-0 / LOCATION ID 121-01916X-000.06E CS 1916, Jett Street under CSX Railroad

This non-roadway railroad structure was inspected for clearance purposes only. The minimum vertical clearance does not require posting. Inspection of the structural components is the responsibility of the owner.

STRUCTURE ID 121-5189-0 / LOCATION ID 121-01923X-000.96S CS 1923, Sunset Avenue under Marta Rail Line

This non-roadway MARTA structure was inspected for clearance purposes only. The minimum vertical clearance does not require posting. Inspection of the structural components is the responsibility of the owner.

STRUCTURE ID 121-5208-0 / LOCATION ID 121-02018X-000.02N CS 2018, Crossover under Marta Rail Line

This non-roadway MARTA structure was inspected for clearance purposes only. The minimum vertical clearance does not require posting. Inspection of the structural components is the responsibility of the owner.

STRUCTURE ID 121-5161-0 / LOCATION ID 121-02020X-000.21W CS 2020, Church Street under CSX RR (50403A)

This non-roadway structure has been inspected for clearances only. The minimum vertical clearance is substandard and requires posting. Our records indicate the minimum vertical clearance to be 10'-08". At the present time, the county should verify this clearance and post this structure in accordance with the Manual on Uniform Traffic Control Devices (current edition) Low Clearance Sign. Inspection of the structural components is the responsibility of the owner.

STRUCTURE ID 121-5270-0 / LOCATION ID 121-02038X-000.29S CS 2038, Forsyth Street over CSX Railroad and parking lot

This bridge structure is in good condition. The steel beams in spans #5 through #7 are starting to corrode and should be cleaned and painted. The deck joints have failed and should be cleaned and sealed.

STRUCTURE ID 121-5163-0 / LOCATION ID 121-02042X-000.08W CS 2042, Wall Street over Lower Wall St. & Parking Lot

This bridge structure is in fair condition with age deterioration of both the superstructure and deck. The majority of the concrete deck exhibits signs of extensive cracking and efflorescence and is covered with a variable depth asphalt riding surface that ranges from 4 to 8 inches in depth. The deck drains are clogged with debris that should be removed to allow proper drainage of the deck. The deck joints throughout the structure have failed and should be cleaned and sealed.

STRUCTURE ID 121-5255-0 / LOCATION ID 121-02043X-000.50W FAP 212-1, CR 2043, South Fulton Parkway EBL over CSX Railroad

This all concrete bridge structure is in good condition. Debris accumulated in the bridge gutters should be removed to allow proper drainage of the deck.

STRUCTURE ID 121-5254-0 / LOCATION ID 121-02043X-001.67W FAP 212-1, CR 2043, South Fulton Highway over Wolf Creek Tributary

This bridge culvert is in good condition with no reported structural deficiencies. The channel bed scour at both ends of the structure should be monitored for signs of further degradation.

STRUCTURE ID 121-5253-0 / LOCATION ID 121-02043X-004.35W FAP 212-1, CR 2043, South Fulton Highway WBL over Deep Creek

This all concrete bridge structure is in good condition. However, the deck joints throughout the structure have failed and should be cleaned and sealed.

STRUCTURE ID 121-5252-0 / LOCATION ID 121-02043X-004.36W FAP 212-1, CR 2043, South Fulton Highway EBL, Over Deep Creek

This all concrete bridge structure is in good condition. However, the deck joints throughout the structure have failed and should be cleaned and sealed.

STRUCTURE ID 121-5316-0 / LOCATION ID 121-02043X-004.55W Federal Aid Primary Route 2121, CR 2043, South Fulton Parkway Over Bear Creek

This bridge structure is in good condition with no reported deficiencies.

STRUCTURE ID 121-5267-0 / LOCATION ID 121-02043X-006.60W FAP 212-1, CR 2043, South Fulton Parkway WBL, Over Line Creek

This all concrete bridge structure is in good condition but has items in need of repair. A void beneath the cap of both abutments should be filled. The deck joints at both abutments have failed and should be cleaned and sealed. Debris accumulated in the deck gutters should be removed to allow proper drainage of the deck.

STRUCTURE ID 121-5266-0 / LOCATION ID 121-02043X-006.61W FAP 212-1, CR 2043, South Fulton Parkway EBL over Line Creek

This all concrete bridge structure is in good condition but has several items in need of repair. The void beneath both abutment caps should be filled. The deck joints at both abutments have failed and should be cleaned and sealed. Debris accumulated in the deck gutters should be removed to allow proper drainage of the deck. The catch basin at the western end of the structure is clogged with debris and should be cleaned out to allow proper drainage of the roadway.

STRUCTURE ID 121-5265-0 / LOCATION ID 121-02043X-008.28W FAP 212-1, CR 2043, South Fulton Parkway over Pea Creek

This bridge culvert is in good condition, but the construction joints approximately 50 feet into the culvert from each end are open from 2 to 3 inches. The fill behind the exterior walls is beginning to erode. This void should be filled and the construction joint sealed to prevent further loss of fill material.

STRUCTURE ID 121-5175-0 / LOCATION ID 121-02044X-000.40S CS 2044, Pryor Street over CSX Railroad

This bridge structure is in fair condition with the exception of the superstructure which is in poor condition. Beam #12 in span #6 has incurred significant collision damage and has a 4 to 6 inch sweep with a major bend in the lower flange. Both the City of Atlanta and the Railroad are aware of this deficiency and it is our understanding that the City is negotiating with the Railroad for the repair of this damage. It is strongly recommended that this damage be repaired as soon as possible. The deck joints throughout the structure have failed and should be cleaned and sealed.

STRUCTURE ID 121-5221-0 / LOCATION ID 121-02046X-000.07E CS 2046, Brotherton Street Under Marta Rail Line

This non-roadway MARTA structure was inspected for clearance purposes only. The minimum vertical clearance does not require posting. Inspection of the structural components is the responsibility of the owner.

STRUCTURE ID 121-5164-0 / LOCATION ID 121-02051X-000.43S CS 2051, Butler Street under CSX Railroad

This non-roadway railroad structure was inspected for clearance purposes only. The minimum vertical clearance does not require posting. Inspection of the structural components is the responsibility of the owner.

STRUCTURE ID 121-5165-0 / LOCATION ID 121-02051X-000.45S CS 2051, Butler Street under Marta Rail Line

This non-roadway MARTA structure was inspected for clearance purposes only. The minimum vertical clearance does not require posting. Inspection of the structural components is the responsibility of the owner.

STRUCTURE ID 121-5250-0 / LOCATION ID 121-02051X-000.46S CS 2051, Jessie Hill, Jr. Drive under Pedestrian Overpass

This non-roadway pedestrian structure was inspected for clearance purposes only. The minimum vertical clearance does not require posting. Inspection of the structural components is the responsibility of the owner.

STRUCTURE ID 121-5233-0 / LOCATION ID 121-02059X-000.05N CS 2059, Equitable Place under Pedestrian Overpass

This non-roadway pedestrian structure was inspected for clearance purposes only. The minimum vertical clearance does not require posting. Inspection of the structural components is the responsibility of the owner.

STRUCTURE ID 121-5166-0 / LOCATION ID 121-02062X-000.02E CS 2062, Thornton Avenue under CSX RR (50401L)

This non-roadway structure has been inspected for clearances only. The minimum vertical clearance is substandard and requires posting. Our records indicate the minimum vertical clearance to be 11'-03". At the present time, the county should verify this clearance and post this structure in accordance with the Manual on Uniform Traffic Control Devices (current edition) Low Clearance Sign. Inspection of the structural components is the responsibility of the owner.

STRUCTURE ID 121-5167-0 / LOCATION ID 121-02063X-000.58S CS 2063, Grant & Hilliard under Norfolk Southern Railroad

This non-roadway railroad structure was inspected for clearance purposes only. The minimum vertical clearance is substandard and requires posting. Our records indicate the minimum vertical clearance to be 13'-09". At the present time, the city should verify this clearance and post this structure in accordance with the Manual on Uniform Traffic Control Devices (current edition) Low Clearance Sign. Inspection of the structural components is the responsibility of the owner.

STRUCTURE ID 121-5232-0 / LOCATION ID 121-02080X-000.02S CR 2080, Krog Street under Convyer Belt

This non-roadway conveyor belt structure was inspected for clearance purposes only. The minimum vertical clearance is substandard and requires posting. Our records indicate the minimum vertical clearance to be 14'-02". At the present time, the city should verify this clearance and post this structure in accordance with the Manual on Uniform Traffic Control Devices (current edition) Low Clearance Sign. Inspection of the structural components is the responsibility of the owner.

STRUCTURE ID 121-5148-0 / LOCATION ID 121-02080X-000.29S CR 2080, Estoria Street under CSX Railroad

This non-roadway railroad structure was inspected for clearance purposes only. The minimum vertical clearance is substandard and requires posting. Our records indicate the minimum vertical clearance to be 12'-03". At the present time, the city should verify this clearance and post this structure in accordance with the Manual on Uniform Traffic Control Devices (current edition) Low Clearance Sign. Inspection of the structural components is the responsibility of the owner.

STRUCTURE ID 121-5190-0 / LOCATION ID 121-02103X-000.45E CS 2103, Fulton Terrace Street under CSX Railroad

This non-roadway railroad structure was inspected for clearance purposes only. The minimum vertical clearance does not require posting. Inspection of the structural components is the responsibility of the owner.

STRUCTURE ID 121-0624-0 / LOCATION ID 121-02233X-002.14E CR 2233, Windward Pkwy EBL over Camp Creek

This bridge structure is in good condition. The steel piles throughout the structure should be cleaned and painted. The piles at bent #2 should be further protected with reinforced concrete encasements extending from a point 2 feet below the mud line to a point 2 feet above normal water. The deck joints throughout the structure have failed and should be cleaned and sealed.

STRUCTURE ID 121-0298-0 / LOCATION ID 121-02233X-002.15E CR 2233, Windward Parkway WBL over Camp Creek

This bridge structure is in good condition but has corrosion of the steel substructure units. The steel piling throughout the structure should be cleaned and painted. The piles at bent #2 should be further protected with reinforced concrete encasements extending from a point 2 feet below the mud line to a point 2 feet above normal water. Voids under the eastern abutment should be repaired to protect the foundation piles. The deck joints throughout the structure have failed and should be cleaned and sealed.

*STRUCTURE ID 121-0629-0 / LOCATION ID 121-02233X-003.02E CR 2233, Windward Pkwy EBL over Big Creek

At the present time, Post this structure for 12 Tons H-Truck; 12 Tons Type 3 Truck and 16 Tons Timber Truck.

This structure requires posting due to insufficient pile capacity of the steel substructure. The following maintenance recommendations are provided to maintain this structure at the current rating. This bridge structure is in poor condition with corrosion and section loss of the steel substructure piles. The piles throughout the structure should be cleaned and painted. The piles at bent #3 should be further protected with reinforced concrete encasements that extend from a point 2 feet below the mud line to a point 2 feet above normal water. The deck joints throughout the structure have failed and should be cleaned and sealed. Concrete spalls with exposed reinforcement steel in the superstructure panels of spans #1 and #4 should be repaired to protect the steel from corrosion. If structural pile encasements were added at bent #3, load limit posting could be upgraded significantly.

*STRUCTURE ID 121-0630-0 / LOCATION ID 121-02233X-003.03E CR 2233, Windward Pkwy WBL over Big Creek

At the present time, Post this structure for 12 Tons H-Truck; 12 Tons Type 3 Truck and 16 Tons Timber Truck.

This structure requires posting due to insufficient pile capacity of the steel substructure. The following maintenance recommendations are provided to maintain this structure at the current rating. This bridge structure is in poor condition with corrosion and section loss of the steel substructure piles. The steel piles throughout the structure should be cleaned, cover plated in areas of section loss and painted. The piles at bent #3 should be further protected with reinforced concrete encasements that extend from a point 2 feet below the mud line to a point 2 feet above normal water. The deck joints throughout the structure have failed and should be cleaned and sealed. If structural pile encasements were added at bent #3, load limit posting would be significantly upgraded.

*STRUCTURE ID 121-5286-0 / LOCATION ID 121-02233X-003.73E CR 2233, Windward Parkway over Big Creek Tributary

At the present time, Post this structure for 13 Tons H-Truck; 17 Tons Type 3 Truck and 24 Tons Timber Truck.

This structure requires posting due to the excessive unbraced length of the piles at bent #3. The piles in bent #3 have a maximum unsupported length of 17 feet. Adequately designed sway bracing should be added to this bent. These piles should be further protected with reinforced concrete encasements extending from a point 2 feet below the mud line to a point 2 feet above normal water. If adequately designed lateral bracing were added to the piles of bent #3, and concrete encasements were added to bent #3, load limit posting for this structure would no longer be required. The following maintenance recommendations are provided to maintain this structure at the current rating. The piles are corroded and should be cleaned and painted. The deck joints have failed and should be cleaned and sealed.

STRUCTURE ID 121-5207-0 / LOCATION ID 121-02353X-000.01S CS 2353, Sylvan Road under Marta Rail Line

This non-roadway MARTA structure was inspected for clearance purposes only. The minimum vertical clearance does not require posting. Inspection of the structural components is the responsibility of the owner.

*STRUCTURE ID 121-5123-0 / LOCATION ID 121-02407X-000.11W CS 2407, Nelson Street over Southern Railroad & Parking Lot

This bridge structure was closed to vehicular traffic at the time of inspection and should remain closed until replaced. According to our records this structure has been closed since 1993.

STRUCTURE ID 121-5168-0 / LOCATION ID 121-02429X-000.10E CS 2429, Glenn Street under Norfolk Southern Railroad

This non-roadway railroad structure has been inspected for clearance purposes only. The minimum vertical clearance is substandard and requires posting. Our records indicate the minimum vertical clearance to be 10'-08". At the present time, the City should verify this clearance and post this structure in accordance with the Manual on Uniform Traffic Control Devices (current edition) Low Clearance Sign. Inspection of the structural components is the responsibility of the owner.

STRUCTURE ID 121-5234-0 / LOCATION ID 121-02488X-000.45N CS 2488, North Stratford Road over Nancy Creek Tributary

This bridge culvert is in good condition. Up to 2.5 feet of scour at the outlet end is undermining the remaining wing wall and should be repaired with rip rap to prevent structural damage. An inlet wing wall has seperated from barrel #2 and should also be stabilized and repaired.

STRUCTURE ID 121-5192-0 / LOCATION ID 121-02490X-000.41N CS 2490, North Ivy Road over Nancy Creek Tributary

This bridge culvert is in good condition. Up to 2.7 feet of scour at the inlet end of barrel #2 should be repaired with rip rap to prevent possible structural damage.

STRUCTURE ID 121-5193-0 / LOCATION ID 121-02490X-000.61N CS 2490, North Ivy Road over Nancy Creek Tributary

This bridge culvert is in satisfactory condition with up to 2.0 feet of scour at the inlet end. This scour damage should be repaired with rip rap to prevent possible structural damage.

*STRUCTURE ID 121-5235-0 / LOCATION ID 121-02499X-000.16E CS 2499, Mountain Way Road over Nancy Creek Tributary At the present time, Post this structure for 17 Tons H-Truck; 17 Tons Type 3 Truck and 20 Tons Timber Truck.

This structure requires posting due to insufficient flexural capacity of the steel superstructure. A replacement structure is required to upgrade this structure to a point where posting is no longer required. The following maintenance recommendations are provided to maintain this structure at the current rating. This bridge structure is in good condition with corrosion of the steel superstructure. The steel beams throughout the structure should be cleaned and painted.

*STRUCTURE ID 121-5125-0 / LOCATION ID 121-02509X-000.06E CS 2509, Lakemoore Drive over Nancy Creek Tributary

At the present time, Post this structure for 15 Tons H-Truck; 14 Tons Type 3 Truck; 18 Tons Timber Truck and 22 Tons Type 3S2 Truck.

This structure requires posting due to insufficient flexural capacity of the steel superstructure. A replacement structure is required to upgrade this structure to a point where posting is no longer required. This bridge structure is in satisfactory condition with no reported deficiencies.

STRUCTURE ID 121-5126-0 / LOCATION ID 121-02518X-000.29N CS 2518, Rickenbacker Drive over Nancy Creek

This bridge structure is in good condition with corrosion of the steel superstructure. The steel beams throughout the structure should be cleaned and painted. The deck joints throughout the structure have failed and should be cleaned and sealed. Drift has collected on the utility lines on the upstream side of the structure. This drift should be removed. The tree growing out of the joint at the south western wing wall should be removed.

STRUCTURE ID 121-5194-0 / LOCATION ID 121-02798X-000.02N CS 2798, Westland Boulevard under Marta Rail Line

This non-roadway MARTA structure was inspected for clearance purposes only. The minimum vertical clearance does not require posting. Inspection of the structural components is the responsibility of the owner.

STRUCTURE ID 121-5236-0 / LOCATION ID 121-02822X-001.34S CR 2822, Peyton Road over North Utoy Creek

This bridge structure is in good condition. The steel beams are corroded and should be cleaned and painted.

STRUCTURE ID 121-5217-0 / LOCATION ID 121-02836X-000.10E CR 2836, Coles Way over Chattahoochee River Tributary

This all concrete bridge structure is in good condition with no reported serious structural defects. However, the deck joints throughout the structure have failed and should be cleaned and sealed.

STRUCTURE ID 121-5287-0 / LOCATION ID 121-02856X-000.46N CS 2856, Brownlee Road over Utoy Creek

This bridge structure is in good condition. The deck joints have failed and should be cleaned and sealed. Debris in the bridge gutters should be removed to allow proper drainage.

*STRUCTURE ID 121-5169-0 / LOCATION ID 121-02992X-000.66S CS 2992, Adams Drive over South Utoy Creek

This bridge structure is not considered to be safe for live vehicular loading, and thus falls below standards as set forth in accordance with the Federal Law, Title 23, USC, and Federal Regulations, and should be closed until repairs or replacement can be made. At the time of the inspection this bridge culvert was closed due to failure of one of the southern wingwalls and erosion of the approach roadway. The roadway erosion should be repaired. The failed wingwall should be replaced. The inlet scour damage is 1.5 feet in depth, and the outlet scour is 3.0 feet deep. The culvert outlet has begun to undermine. Concrete aprons should be constructed at both the inlet and outlet ends of the structure and the aprons should be further protected with rip rap. The accumulated drift at the inlet end of the structure should be removed to reduce the further accumulation and the possibility of additional scour. Our records indicate that this structure is located on a school bus route. If this route is utilized by school bus traffic, this bridge should be upgraded to a 10 ton or better capacity. To accomplish this, the above noted repairs must be made.

Please note that all structures requiring closing must be properly closed in accordance with the attached methods. In addition, appropriate advanced warning signs and barricades should be used. Please reference the Manual on Uniform Traffic Control Devices, current edition. Also, advanced warning signs should be used at the last intersection prior to each end of the structure.

At the time of the inspection, this structure was properly closed according to the approved closing alternatives.

STRUCTURE ID 121-5128-0 / LOCATION ID 121-02997X-000.15S CS 2997, Harbin Road over South Utoy Creek

This bridge structure is in fair condition. Erosion behind one of the south wingwalls should be repaired.

*STRUCTURE ID 121-5134-0 / LOCATION ID 121-03079X-000.55E CS 3079, Oxbo Road over Hog Waller Creek

At the present time, Post this structure for 19 Tons H-Truck; 19 Tons Type 3 Truck and 24 Tons Timber Truck.

This structure requires posting due to overstress caused by the extra dead load of the 2.5 inch asphalt overlay. Any upgrade of the load carrying capacity would require removal of this overlay. The following maintenance recommendations are provided to maintain this structure at the current rating. This bridge structure is in good condition. However, the accumulated drift at bent #2 should be removed.

STRUCTURE ID 121-5130-0 / LOCATION ID 121-03114X-000.20E CS 3114, Charles Place over Hog Waller Creek

This bridge structure is in satisfactory condition. However, the steel piles throughout the structure are corroded and should be cleaned and painted. The deck joints have failed and should be cleaned and sealed.

STRUCTURE ID 121-5249-0 / LOCATION ID 121-03120X-000.17W CS 3120, Alpine Drive over Hog Waller Creek

This bridge culvert is in good condition with no reported structural defects.

STRUCTURE ID 121-5170-0 / LOCATION ID 121-03125X-000.66E CS 3125, Oak Drive over South River Tributary

This bridge culvert is in good condition. A crack in an upsteam wing wall should be repaired.

STRUCTURE ID 121-5263-0 / LOCATION ID 121-03204X-000.01N CR 3204, Jones Road over Willeo Creek

This bridge structure is in good condition but has corrosion of the steel substructure piles. The steel piles throughout the structure should be cleaned and painted. Erosion under span #3 should also be repaired.

*STRUCTURE ID 121-5133-0 / LOCATION ID 121-03337X-000.09E CS 3337, Old Holcomb Bridge Road over Big Creek

At the present time, Post this structure for 10 Tons H-Truck; 09 Tons Type 3 Truck; 14 Tons Timber Truck; 12 Tons HS-Truck and 15 Tons Type 3S2 Truck. This structure requires posting due to the low original design capacity of the structure. A replacement structure is required to upgrade this structure to a point where posting is no longer required. The following maintenance recommendations are provided to maintain this structure at the current rating. The steel beams are corroded and should be cleaned and painted. The deck joints throughout the structure have failed and should be cleaned and sealed. The accumulated drift under the bridge should be removed. Vegetation growing in the vicinity of the structure should also be cut and removed. Due to re-evaluation of the structure, the posting capacity of this structure has been decreased. At the time of the inspection, the posting signs were incorrect. These signs are required and must be corrected.

STRUCTURE ID 121-5172-0 / LOCATION ID 121-03470X-000.04S CS 3470, Richard Russell over Parking Lot & Southern Railroad

This bridge structure is in good condition with no reported serious structural defects. The steel beams and caps are corroded and should be cleaned and painted. The deck joints throughout the structure have failed and should be cleaned and sealed.

STRUCTURE ID 121-5281-0 / LOCATION ID 121-04187X-001.30N CR 4187, Oakley International Boulevard over Trickum Creek

This bridge structure is in good condition with no reported structural defects. However, the deck joints through out the structure have failed and should be cleaned and sealed.

*STRUCTURE ID 121-5197-0 / LOCATION ID 121-05016X-000.44S CS 5016, Stonewall Drive over Dixie Lake Tributary

At the time of the inspection, this structure was closed to traffic. Please notify the Georgia Department of Transportation, Office of Maintenance when the repairs or replacement have been completed.

STRUCTURE ID 121-5268-0 / LOCATION ID 121-06351X-000.30N CS 6351, Desert Drive over Camp Creek

This all concrete bridge structure is in good condition, but the concrete encasement of pile #1 at bent #2 has undermined. This encasement should be extended downward to a point 2 feet below the existing mud line. The accumulated drift on the upstream side should also be removed.

*STRUCTURE ID 121-5198-0 / LOCATION ID 121-07001X-000.03N CS 7001 over Camp Creek

At the present time, Post this structure for 14 Tons H-Truck; 14 Tons Type 3 Truck; 17 Tons Timber Truck; 16 Tons HS-Truck and 23 Tons Type 3S2 Truck.

This structure requires posting due to insufficient flexural capacity of the steel superstructure. A replacement structure is required to upgrade this structure to a point where posting is no longer required. At the present time, no maintenance repairs are required to maintain this structure at the current rating.

STRUCTURE ID 121-0600-0 / LOCATION ID 121-07116X-000.77S CS 7116, East Main Street over Virginia Avenue

This all concrete bridge structure is in good condition. However, the deck joint at the northern abutment has failed and should be cleaned and sealed.

STRUCTURE ID 121-5216-0 / LOCATION ID 121-07134X-000.24E CS 7134, Lee Street under CSX Railroad

This non-roadway railroad structure was inspected for clearance purposes only. The existing minimum vertical clearance does not require posting. Inspection of the structural components is the responsibility of the owner.

STRUCTURE ID 121-5222-0 / LOCATION ID 121-07134X-000.32E CS 7134, Lee Street under Marta

This non-roadway MARTA structure was inspected for clearance purposes only. The existing minimum vertical clearance does not require posting. Inspection of the structural components is the responsibility of the owner.

STRUCTURE ID 121-5223-0 / LOCATION ID 121-07134X-000.34E CS 7134, Lee Street under Marta

This non-roadway MARTA structure was inspected for clearance purposes only. The existing minimum vertical clearance does not require posting. Inspection of the structural components is the responsibility of the owner.

STRUCTURE ID 121-5224-0 / LOCATION ID 121-07134X-000.35E CS 7134, Lee Street under Marta

This non-roadway MARTA structure was inspected for clearance purposes only. The existing minimum vertical clearance does not require posting. Inspection of the structural components is the responsibility of the owner.

STRUCTURE ID 121-5247-0 / LOCATION ID 121-08021X-000.17N CS 8021, International Boulevard over Flint River Tributary

This bridge culvert is in good condition. Drift accumulated across the culvert inlet should be removed to prevent possible scour damage.

STRUCTURE ID 121-5323-0 / LOCATION ID 121-08022X-000.02S CR 8022, North Commerce Drive Over Camp Creek

This bridge structure is in good condition with no reported deficiencies. The deck joint at bent #2 has failed and should be cleaned and sealed.

STRUCTURE ID 121-0473-0 / LOCATION ID 121-20065X-000.01N CS 20065, Service Road To Omni over International Boulevard

This bridge structure is in good condition with the exception of the superstructure that is in satisfactory condition due to extensive corrosion. The steel beams and bearings throughout the structure should be cleaned and painted. Settlement at the southern abutment has exposed portions of the foundation piling. These piles should either be covered or painted to protect them from corrosion. The deck drains throughout the structure are clogged with debris and should be cleaned out to allow proper drainage of the deck.

STRUCTURE ID 121-0474-0 / LOCATION ID 121-20065X-000.02N CS 20065, International Boulevard Viaduct at The Georgia Dome

This bridge structure is in fair condition with corrosion of the steel components. The steel beams and bearings should be cleaned and painted. A spall in the cap at bent #14 beneath beam #2 and at bent #15 beneath beams #2 and #3 should be repaired. The deck drains throughout the structure are clogged with debris and should be cleaned out to allow proper drainage. The deck joints throughout the structure have failed and should be cleaned and sealed. At the time of the inspection, a portion of this structure was under construction. Please notify the Georgia Department of Transportation, Office of Maintenance, when this construction is complete.


APPENDIX F

Labor Shed and Commute Shed Maps by Jurisdiction







All North Fulton Commute Shed Analysis




All North Fulton Labor Shed Analysis




Alpharetta Commute Shed Analysis




Alpharetta Labor Shed Analysis




Johns Creek Commute Shed Analysis




Johns Creek Labor Shed Analysis




Milton Commute Shed Analysis




Milton Labor Shed Analysis




Mountain Park Commute Shed Analysis




Mountian Park Labor Shed Analysis




Roswell Commute Shed Analysis




Roswell Labor Shed Analysis



Sandy Springs Commute Shed Analysis



Sandy Springs Labor Shed Analysis



APPENDIX G

Bicycle and Pedestrian Level-of-Service Model Descriptions





Study Network Bicycle and Pedestrian Performance Measures

The existing conditions report describes the current level of accommodation provided to bicyclists and pedestrians by the study network roadways. As discussed in that report, the selected performance measures to describe existing conditions are bicycle and pedestrian Level-of-Service. This appendix provides technical descriptions of the Bicycle Level-of-Service Model and the Pedestrian Level-of-Service Model.

Description of the Bicycle Level-of-Service Model

On-road bicycling conditions in North Fulton County have a tremendous effect on people's choice to bicycle and the selection of their route. As part of this study, the Consultant will perform an evaluation of bicycling conditions on the County's collector and arterial roadway network. The *Bicycle Leve- of-Service1 Model (Version 2.0)* will be used as the foundation of the evaluation of the existing bicycling conditions in North Fulton County. This statistically-calibrated mathematical equation is the most accurate method of evaluating the bicycling conditions of shared roadway environments. It uses the same measurable traffic and roadway factors that transportation planners and engineers use for other travel modes. With statistical precision, the *Model* clearly reflects the effect on bicycling suitability or "compatibility" due to factors such as roadway width, bike lane widths and striping combinations, traffic volume, pavement surface conditions, motor vehicles speed and type and on-street parking.

The *Bicycle LOS Model* is based on the proven research documented in *Transportation Research Record 1578*² published by the Transportation Research Board of the National Academy of Sciences. It was developed with a background of over 200,000 miles of evaluated urban, suburban, and rural roads and streets across North America. It has been adopted by numerous states and metropolitan areas as the recommended standard methodology for determining existing and anticipated bicycling conditions. Many urbanized area planning agencies and state highway departments are using this established method of evaluating their roadway networks. These include metropolitan areas across North America such as Baltimore MD, Gainesville FL, Birmingham AL, Philadelphia PA, San Antonio TX, Houston TX, Buffalo NY, Anchorage AK, Lexington KY, and Tampa FL as well as state departments of transportation such as, Delaware Department of Transportation (DelDOT), New York State Department of Transportation (NYDOT), Maine Department of Transportation (MeDOT) and others.

In addition to describing the *Model*, this section also documents the necessary data requirements and the associated data collection and compilation guidelines.

¹ Landis, Bruce W. "Real-Time Human Perceptions: Toward a Bicycle Level-of-Service" *Transportation Research Record 1578*, Transportation Research Board, Washington DC 1997.

² FDOT, 2002 Quality / Level-of-Service Handbook, Florida Department of Transportation (2002), pp.20-21.

Bicycle Level-of-Service Model

Version 2.0 of the *Bicycle LOS Model* will be employed to evaluate the study network segments. Its form is shown below:

Table G-1: Bicycle Level-of-Service Model				
	Bicycle LOS = $a_1 \ln (Vol_{15}/L_n) + a_2 SP_t (1+10.38HV)^2 + a_3 (1/PC_5)^2 + a_4 (W_e)^2 + C$			
Where:				
Vol ₁₅ =	Volume of directional traffic in 15 minute time period			
$Vol_{15} =$	(ADT x D x K _d) / (4 x PHF)			
Where:				
ADT=	Average Daily Traffic on the segment or link			
D=	Directional Factor			
K _d =	Peak to Daily Factor			
PHF=	Peak Hour Factor			
L _n =	Total number of directional <i>through</i> lanes			
SP _t =	Effective speed limit			
SP _t =	$1.1199 \ln(SP_p - 20) + 0.8103$			
Where:				
SP _p =	Posted speed limit (a surrogate for average running speed)			
HV=	percentage of heavy vehicles (as defined in the 1994 Highway Capacity Manual)			
$PC_5 =$	FHWA's five point pavement surface condition rating			
W _e =	Average effective width of outside through lane:			
Where:				
$W_e =$	$W_v - (10 \text{ ft } x \% \text{ OSPA})$ and $W_l = 0$			
$W_e =$	$W_v + W_l (1 - 2 x \% \text{ OSPA}) \text{ and } W_l > 0 \& W_{ps} = 0$			
$W_e =$	W_v + W_l - 2 (10 x % OSPA) and W_l > 0 & W_{ps} > 0 and a bike lane exists			
Where:				
$W_t =$	total width of outside lane (and shoulder) pavement			
OSPA =	percentage of segment with occupied on-street parking			
$W_l =$	width of paving between the outside lane stripe and the edge of pavement			
W _{ps} =	width of pavement striped for on-street parking			
$W_v =$	Effective width as a function of traffic volume			
and:				
W _v =	W_t if ADT > 4,000veh/day			
$W_v =$	$W_t(\text{2-0.00025 x ADT})$ if ADT \leq 4,000 veh/day, and if the street/road is undivided and unstriped			
	$a_1: 0.507$ $a_2: 0.199$ $a_3: 7.066$ $a_4: -0.005$ $C: 0.760$			
	$(a_1 - a_4)$ are coefficients established by the multi-variate regression analysis			

The *Bicycle LOS* score resulting from the final equation is stratified into service categories "A, B, C, D, E, and F" (according to the ranges shown below) to reflect users' perception of the road segment's level-of-service for bicycle travel. This stratification is in accordance with the linear scale established during the referenced research (i.e., the research project bicycle participants' aggregate

response to roadway and traffic stimuli). The *Model* is particularly responsive to the factors that are statistically significant. An example of its sensitivity to various roadway and traffic conditions is shown below.

Table G-2: Bicycle and PedestrianLevel-of-Service Score Stratification			
LOS Score			
< 1.50			
1.51-2.50			
2.51-3.50			
3.51-4.50			
4.51—5.50			
> 5.50			

Tab	le G-3: Bicycle and Peo	destrian Level-of-Serv	vice Score Categori	es
Bicycle L	$OS = a_1 ln (Vol_{15}/L_n) +$	a ₂ SP _t (1+10.38HV) ² +	+ a ₃ (1/PR ₅) ² + a ₄ (V	W _e) ² + C
a₁: 0.507 Baseline example inputs		a ₃ : 7.066	a ₄ : -0.005	C: 0.760
% HV = 1 L = 2 lan				
$SP_{p} = 40 \text{ m}$ $W_{e} = 12 \text{ ft}$ $PR_{5} = 4 (gc)$				
<u>Inputs</u> Baseline Bicycle LOS Sc	ore	<u>BLO</u> 3.98		<u>hange</u> /A
Result Variations with La	ane Width and Lane Strip	ing Changes (T-statistic	c = 9.844)	
W _t =10 ft W _t =11 ft		4.20 4.09		ncrease ncrease
W _t =12 ft W _t =13 ft	(baseline aver	3.85	3% r	hange eduction
W _t =14 ft W _t =15 ft (W _I = 3 ft) W _t =16 ft (W _I = 4 ft)			(3.08) 10%	eduction (23%) reduction (32%) reduction
$W_{t} = 17 \text{ ft} (W_{1} = 5 \text{ ft})$		3.25		(43%) reduction
Traffic Volume (ADT) var ADT=1,000 Very Low ADT=5,000 Low	iations (T-statistic = 5.68	9) 2.75 3.54		decrease decrease
ADT=12,000 Average ADT=15,000 High	(baseline avera	ge) 3.98 4.09		hange ncrease
ADT=25,000 Very High		4.35		ncrease
Pavement Surface condi	tions (T-statistic = 4.902)		0001	
PR₅=2 Poor PR₅=3 Fair		5.30 4.32		increase eduction
PR ₅ =4 Good	(baseline avera			hange
PR₅=5 Very Good		3.82	4% r	reduction
Heavy Vehicles in percent HV=0 No Volume	ntages (Combined speed	and heavy vehicles T-s 3.80		decrease
HV=1 Very Low	(baseline ave			hange
HV=2 Low		4.18		ncrease
HV=5 Moderate		4.88		increase
HV=10 High		6.42		increase
HV=15 Very High		8.39		% increase

Data Collection and Inventory Guidelines

Following is the list of data required for computation of the *Bicycle LOS* scores as well as the associated guidelines for their collection and compilation into the programmed database. Unless otherwise specified, the Consultant will collect the data.

<u>Average Daily Traffic (ADT)</u> - is the average daily traffic volume on the segment or link. The programmed database will convert these volumes to Vol_{15} using the Directional Factor (D), Peak to Daily Factor (K_d) and Peak Hour Factor (PHF) for the road segment. This data will be provided by ARC.

<u>Percent Heavy Vehicles(HV)</u> - is the percentage of heavy vehicles (as defined in the 1994 Highway *Capacity Manual*). This data will be <u>estimated</u> by ARC.

<u>Number of lanes of traffic (L)</u> - is the total number of *through* traffic lanes of the road segment and its configuration. (e.g., D = Divided, U = Undivided, OW = One Way, S = Center Turning Lane). The programmed database will convert these lanes into directional lanes. The presence of continuous right-turn lanes should be noted in the comments field.

<u>Posted Speed Limit (S_p) </u> – is recorded as posted.

 $\underline{W_t \text{ total width of pavement}}$ - is measured from the center of the road, yellow stripe, or (in the case of a multilane configuration) the lane separation striping to the edge of pavement or to the gutter pan of the curb. When there is angled parking adjacent to the outside lane, W_t is measured to the traffic-side end of the parking stall stripes.

 W_{ps} width of pavement striped for on-street parking – is recorded only if there is parking to the right of a striped bike lane. If there is parking on two sides on a one-way, single lane street, report the combined width of the striped parking.

 $\underline{W_l}$ width of paving between the outside lane stripe and the edge of pavement - is measured from the outside lane stripe to the edge of pavement or to the gutter pan of the curb. When there is angled parking adjacent to the outside lane, W_l is measured to the traffic-side end of the parking stall stripes.

<u>OSPA %</u> - is an estimate the percentage of the segment (excluding driveways) along which there is occupied on-street parking at the time of survey. Record each side separately. If the parking is allowed only during off-peak periods and parking restrictions change widths and laneage, indicate the geometric changes in the comments field. Note: Indicate any "angled parking" in the comments field.

<u>Designated Bike Lane</u> – is indicated as "Y" if there is a bike lane on the segment; otherwise the field is coded as "N."

Pavement Condition:

<u>Travel Lane (PCt</u>) - is the pavement condition of the motor vehicle travel lane according to the FHWA's five-point pavement surface condition rating shown below. Half-point values (4.5, 3.5, and occasionally 2.5) may also be coded.

<u>Shoulder or Bike lane (PC₁)</u> - is the pavement condition of the shoulder or bike lane according to the FHWA's five point pavement surface condition rating shown below. Halfpoint values (4.5, 3.5, and occasionally 2.5) may also be coded.

This evaluation method is easily updated in the future. As traffic and roadway conditions change (primarily only traffic volumes will change, unless road reconstruction occurs) the database or programmed spreadsheet can be updated.

Table G-4: FHWA's Five-Point Pavement Surface Condition Rating				
RATING	PAVEMENT CONDITION			
5.0 (Very Good)	Only new or nearly new pavements are likely to be smooth enough and free of cracks and patches to qualify for this category.			
4.0 (Good)	.0 (Good) Pavement, although not as smooth as described above, gives a first class ride and exhibits signs of surface deterioration			
3.0 (Fair)	Riding qualities are noticeably inferior to those above; may be barely tolerable for high-speed traffic. Defects may include rutting, map cracking, and extensive patching.			
2.0 (Poor)	Pavements have deteriorated to such an extent that they affect the speed of free-flow traffic. Flexible pavement has distress over 50 percent or more of the surface. Rigid pavement distress includes joint spalling, patching, etc.			
(Very Poor)	Pavements that are in an extremely deteriorated condition. Distress occurs over 75 percent or more of the surface.			

Source: U.S. Department of Transportation. Highway Performance Monitoring System-Field Manual. Federal Highway Administration. Washington, DC, 1987

Existing Pedestrian Conditions (Pedestrian LOS)

Similar to the evaluation procedure used for the bicycle mode, this is an evaluation of pedestrians' perceived safety and/or comfort with respect to motor vehicle traffic. It identifies the quality of service for pedestrians that currently exists within the roadway environment. This section documents the <u>additional</u> data requirements, data collection and compilation guidelines (other than the items listed in the bicycle portion) and results of the evaluation.

The *Pedestrian Level-of-Service (Pedestrian LOS) Model*³ Version 2.0 has been used for the evaluation of walking conditions. This model is the most accurate method of evaluating the walking conditions within shared roadway environments. It uses the same measurable traffic and roadway factors that transportation planners and engineers use for other travel modes. With statistical precision, the *Model* clearly reflects the effect on walking suitability or "compatibility" due to factors such as roadway width, presence of sidewalks and intervening buffers, barriers within those buffers, traffic volume, motor vehicles speed, and on-street parking. The form of the *Pedestrian Level-of-Service Model*, and the definition of its terms are as follows:

³ Landis, B.W., V.R. Vattikitti, R.M. Ottenberg, D.S. McLeod, M. Guttenplan, Modeling the Roadside Walking Environment: Pedestrian LOS, *Transportation Research Record 1773*, Transportation Research Board, National Research Council, Washington, DC, 2001.

Table G-5: The Pedestrian Level-of-Service Model ⁴ Version 2.0					
Ped LOS = - 1.2276 ln $(W_{ol} + W_l + f_p x \% OSP + f_b x W_b + f_{sw} x W_s)$					
	+ 0.0091 (Vol ₁₅ /L) + 0.0004 SPD ² + 6.0468				
Where:					
$W_{ol} =$	Width of outside lane (feet)				
$W_1 =$	Width of shoulder or bike lane (feet); or If there is un-striped parking and				
%0SP≥25	then $W_l=10'$ to account for lateral displacement of traffic				
$f_p =$	On-street parking effect coefficient (=0.5)				
%OSP =	Percent of segment with on-street parking				
$f_b =$	Buffer area barrier coefficient (=5.37 for trees spaced 20 feet on center)				
$W_b =$	Buffer width (distance between edge of pavement and sidewalk, feet)				
$f_{sw} =$	Sidewalk presence coefficient= $6 - 0.3W_s$ if $W_s \le 10$, otherwise $f_{sw} = 3$)				
W _s =	Width of sidewalk (feet)				
$Vol_{15} =$	Average traffic during a fifteen (15) minute period				
L=	Total number of (through) lanes (for road or street)				
SPD =	Average running speed of motor vehicle traffic (mi/hr)				

The Pedestrian LOS score resulting from the final equation is pre-stratified into service categories "A, B, C, D, E, and F", according to the ranges shown below, which reflect users' perception of the road segments level-of-service for pedestrian travel. This stratification is in accordance with the linear scale established during the research (i.e., the research project participants' aggregate response to roadway and traffic stimuli).

Table G-6: Pedestrian Level-of-Service Categories				
Level-of-Service	Pedestrian LOS Score			
А	≤ 1.5			
В	$>$ 1.5 and \leq 2.5			
С	> 2.5 and ≤ 3.5			
D	$>$ 3.5 and \leq 4.5			
Е	$>$ 4.5 and \leq 5.5			
F	> 5.5			

The *Pedestrian LOS Model* is used by planners and engineers throughout the United States in a variety of planning and design applications. The *Pedestrian LOS Model* can be used to conduct a benefits comparison among proposed sidewalk/roadway cross-sections, identify roadways that are candidates for reconfiguration for sidewalk improvements, and to prioritize and program roadways for sidewalk improvements.

⁴ Landis, B.W., V.R. Vattikitti, R.M. Ottenberg, D.S. McLeod, M. Guttenplan, Modeling the Roadside Walking Environment: Pedestrian LOS, *Transportation Research Record 1773*, Transportation Research Board, National Research Council, Washington, DC, 2001.

ADDITIONAL DATA COLLECTION AND INVENTORY GUIDELINES

Following is the <u>additional</u> list of data used in the computation of the Pedestrian LOS scores. Also described are the associated guidelines for their collection and compilation into the database.

<u>Width of Buffer (W_b) </u> – is the width of a grass buffer. The width of the buffer is measured from the edge of pavement or back of curb to the beginning edge of the sidewalk. If a sidewalk has trees planted within its surface, then the horizontal width of the sidewalk occupied by the trees is considered the buffer width.


<u>Width of Sidewalk (W_s)</u> – is the width of the sidewalk, measured from either the edge of pavement, if a grass buffer is not present. If a grass buffer is present, the width is measured from the edge of the buffer to the back side of the sidewalk.

<u>Sidewalk Percentage</u> – is the percentage of sidewalk coverage (estimated in increments of 25%) of the segment; this is to be collected directionally


<u>Tree Spacing in Buffer</u> – is the spacing of trees within a buffer, measured from the center (width of spacing between trees). Trees can either be in a grass buffer or in sidewalk islands.

<u>Cross-section</u> – a "C" is recorded if there is a curb and gutter on the segment, an "S" if there is an open shoulder. Note: Indicate any ditches or swales adjacent to the edge of pavement of the segment in the comments field.


<u>Roadside Profile Condition</u> – This data item is collected to assist in determining the lateral area available for bicycle lane or paved shoulder and sidewalk construction. It is the area between the outside edge of the pavement and the right-of-way line. The profile condition assists in determining the type of facility, hence its cost [i.e., bicycle lane or paved shoulder or bike path]. Roadside profiles were classified as one of the three types illustrated below. Condition 1, buildable shoulder, is defined as an area adjoining the edge of pavement with a minimum width of seven feet and a maximum cross-slope of 6%. Condition 2 is a swale. Condition 3 is a ditch or canal. The ARC is to provide total right-of-way width.



Roadside Profile Conditions '1'.



Roadside Profile Conditions '2'.



Roadside Profile Conditions '3'.

2.0		2	2	2	2	2	2 2	2	1	1	2	2 2	2	2 2	2	2.0	2	2	2	2	2	2	2	5	5	5
									_				Width				Bike		- "	Tree	e '	a "				Budaatabaa
Segment ID	City	Road Name	From	То	Len- gth	Lar	nes (L)			Tks.	Post. Spd.		Of Paveme		Occ. Park.	Pavecon	Lane/ Pavd.	Cross	Buff. Width	Spcg. in	% with	Swalk Width	Road Profile	Bicy		Pedestrian LOS
ID					(mi)		Dir	Con	Roadway	(HV)	(SPp)	Wt	WI	W _{ps}	(OSPA)	PCt	Shidr.	Sec.	(BW)	Buffer	Sidewalk	(Ws)	Cond		Grade	Value Gra
		A sector second			0.00	#	#		ADT	(%)	mph	(ft)			(%)	(15)	(Y/N)	(C/S)	(ft)	(ft/ctr)	(DIR)	(ft)	(1,2,3)	(17)	(AF)	(17) (A
1.0 A	, ap	Academy St	N Main St	Plymouth Ln	0.93	2	1	U	11250	3	35	-	2.9	-	0	4.0	Y	C	2.0	0	62	6.0	2	4.04	D	3.26 C
1.0 B	, ab	Academy St	N Main St	Plymouth Ln	0.93	2	1	U	11250	3	35	-	2.9		0	4.0	Y	C	2.0	0	98	6.0	2	4.04	D	2.71 C
		Broadwell Rd	Rucker Road	Crabapple	0.81	2	1	LT	6162	4	35	11.0			0	5.0	N	C	2.0	0	50	5.0	3	3.85	D	3.25 C
-		Broadwell Rd	Rucker Road	Crabapple	0.81	2	1	LT	6162	4	35	11.0			0	5.0	N	C	2.0	0	50	5.0	3	3.85	D	3.25 C
		Canton St	Milton Ave	Pebble Trail	0.81	2	1	U	10052	2	35	12.4	0.0		0	3.5	N	S	2.9	0	93	5.0	2	3.82	D	2.78 C
		Canton St	Milton Ave	Pebble Trail	0.81	2	1	U	10052	2	35	12.4			0	3.5	N	S	2.9	0	60	5.0	2	3.82	D	3.23 C
		Cogburn Rd	N Main St	Hopewell Plantation Dr	0.46	2	1	U	3392	2	35	10.1	0.0	-	0	3.0	Y	C	2.0	0	39	5.0	2	3.56	D	3.32 C
		Cogburn Rd	N Main St	Hopewell Plantation Dr	0.46	2	1	U	3392	2	35	10.1	0.0	-	0	3.0	Y	C	2.0	0	100	5.0	2	3.56	D	2.40 B
		Crabapple Rd	Arnold Mill Road	Green Road	0.53	2	1	U	15764	2	35	12.0 12.0		-	0	4.0	N	C	2.0	0	0	5.0	2	3.95	D	4.44 D
		Crabapple Rd	Arnold Mill Road	Green Road	0.53	2	1	U U	15764	2	35 35	12.0			0	4.0 3.5	N	C	2.0 8.0	0	75 0	5.0	2	3.95	D	3.41 C 4.58 E
		Crabapple Rd	Green Road	Birmingham Hwy	0.71	2	1	U	18100		35	12.0			0	3.5	N	C	8.0	0	75	8.0 8.0	3	4.17 4.17	D	
		Crabapple Rd	Green Road	Birmingham Hwy	1.46	2	-	-	18100	2		-			-		N	C C		-						
		Douglas Rd	Jones Bridge Road	McGinnis Ferry Road	1.46	2	1	U	10764	2	35 35	10.6	0.0		0	5.0 5.0	N N	C C	2.0 2.0	0	75	5.0 5.0	2	3.76 3.76	D	3.18 C 3.18 C
		Douglas Rd Georgia Highway 9	Jones Bridge Road	McGinnis Ferry Road	0.44	2		LT	10764	6	45	10.6	0.0		0		Y	C	2.0	0	100	5.0	2	5.23	E	3.18 C 3.71 D
		Georgia Highway 9 Georgia Highway 9	Cogburn Rd	Windward Pkwy W	0.44	2	1	LT	21546	6	45	12.7	0.0	-	0	4.0	Y Y	C	2.0	0	100	5.0	2	5.23	E	3.71 D 3.71 D
			Cogburn Rd	Windward Pkwy W	0.86	2	1	U	21546	3	45	12.7			0	4.0	Y	c	2.0	0	100	5.0	3	4.32	D	3.58 D
		Haynes Bridge Rd Haynes Bridge Rd	City Limits	Mansell	0.86	2	1	U	19074	3	45	12.2			0	4.5	r Y	c	2.0	0	0	5.0	3	4.32	D	4.93 E
		Haynes Bridge Rd	City Limits	Mansell	0.52	4	2	U	19074	4	45	12.2		-	0	4.5	Y	c	2.0	0	100	5.0	2	4.44	D	3.34 C
		Haynes Bridge Rd	Mansell	North Point Pkwy	0.52	4	2	U	23012	4	45	12.4	0.0	-	0	4.5	Y	c	2.0	0	100	5.0	2	4.44	D	3.34 C
		Haynes Bridge Rd	Mansell	North Point Pkwy	1.66	- 6	3		23012	4	45	12.4			0	4.5	Y	c	3.0	0	100	5.0	1	4.48	D	3.32 C
		Haynes Bridge Rd	N. Point Pkwy N. Point Pkwy	Old Milton Pkwy Old Milton Pkwy	1.66	6	3	D	38206 38206	4	45	12.0			0	4.5	Y	C	3.0	0	100	5.0	1	4.48	D	3.32 C
		Haynes Bridge Rd		,	0.37	4	2	D	27480	3	35	12.0			0	4.5	Y	c	2.0	0	100	5.0	2	4.12	D	3.21 C
		Haynes Bridge Rd	Old Milton Pkwy	Academy	0.37	4	2	D	27480	3	35		0.0		0	4.5	Y	C	2.0	0	100	5.0	2	4.12	D	3.21 C
		Hopewell Rd	Old Milton Pkwy	Academy	0.39	2	1	U	9196	3	35	11.1			0	3.5	N	c	2.5	0	0	5.0	2	4.14	D	4.13 D
		Hopewell Rd	Pebble Trail Pebble Trail	Vaughn Drive	0.39	2	1	U	9196	3	35	11.1		-	0	3.5	N	C	2.5	0	0	5.0	2	4.14	D	4.13 D
		Kimball Bridge Rd	Northpoint Pkwy	Vaughn Drive Westside Pkwy	1.04	2	1	U	8642	2	35	11.0			0	3.5	N	S	0.0	0	0	0.0	3	3.91	D	4.11 D
		Kimball Bridge Rd	Northpoint Pkwy	Westside Pkwy	1.04	2	1	U	8642	2	35	11.0			0	3.5	N	S	0.0	0	0	0.0	3	3.91	D	4.11 D
		Kimball Bridge Rd	North Point	Waters	1.17	2	1	U	14876	2	35	10.5	0.0		0	3.5	N	S	2.0	0	25	5.0	3	4.24	 D	4.17 D
		Kimball Bridge Rd	North Point	Waters	1.17	2	1	U	14876	2	35	10.5			0	3.5	N	S	2.0	0	50	5.0	3	4.24	D	3.80 D
		Kimball Bridge Rd	Waters	State Bridge	1.82	2	1	U	8994	2	35		0.0		0	4.5	Y	C	3.0	0	100	5.0	2	3.65	 D	2.64 C
		Kimball Bridge Rd	Waters	State Bridge	1.82	2	1	U	8994	2	35	-	0.0		0	4.5	Y	С	3.0	0	100	5.0	2	3.65	D	2.64 C
		Kimball Bridge Rd	State Bridge	Webb Bridge Way	0.23	4	2	D	16236	3	45		0.0		0	4.5	N	C	2.0	0	20	5.0	2	4.07	 D	4.19 D
		Kimball Bridge Rd	State Bridge	Webb Bridge Way	0.23	4	2	D	16236	3	45			0.0	0	4.5	N	С	2.0	0	50	5.0	2	4.07	D	3.78 D
		Kimball Bridge Rd	Webb Bridge way	Bridgeway Christian Academey	0.47	2	1	U	23378	4	45	-	0.0	-	0	4.5	N	С	2.0	0	25	5.0	2	4.71	Е	4.87 E
		Kimball Bridge Rd	Webb Bridge way	Bridgeway Christian Academey	0.47	2	1	U	23378	4	45		0.0		0	4.5	N	С	2.0	0	75	5.0	2	4.71	Е	4.19 D
		Kimball Bridge Rd	Bridgeway Christian Academey	Jones Bridge	0.30	2	1	U	23378	4	45		5.5		0	4.5	Y	s	2.0	0	0	0.0	1	2.77	с	4.75 E
		Kimball Bridge Rd	Bridgeway Christian Academey	Jones Bridge	0.30	2	1	U	23378	4	45	-		0.0	0	4.5	N	S	2.0	0	0	0.0	1	2.77	С	4.75 E
		Mansell Rd	Old Alabama Conn	Haynes Bridge	0.49	4	2	D	17968	3	45		0.0	-	0	3.5	Y	С	2.0	0	100	5.0	2	4.36	D	3.16 C
		Mansell Rd	Old Alabama Conn	Haynes Bridge	0.49	4	2	D	17968	3	45		0.0		0	3.5	Y	С	2.0	0	100	5.0	2	4.36	D	3.16 C
		Mansell Rd	Old Roswell	N. Point Pkwy	1.11	4	2	D	33630	4	45		0.0		0	3.5	Y	С	2.0	0	100	5.0	2	4.94	Е	3.79 D
		Mansell Rd	Old Roswell	N. Point Pkwy	1.11	4	2	D	33630	4	45			0.0	0	3.5	Y	С	2.0	0	100	5.0	2	4.94	Е	3.79 D
		Mansell Rd	N. Point Pkwy	Old Alabama Conn	0.84	4	2	D	20730	4	45	-	0.0	-	0	4.0	Y	С	2.0	0	100	5.0	2	4.48	D	3.25 C
		Mansell Rd	N. Point Pkwy	Old Alabama Conn	0.84	4	2	D	20730	4	45			0.0	0	4.0	Y	С	2.0	0	50	5.0	2	4.48	D	3.92 D
		Center Bridge Rd	Westside Pkwy	Fanfare Way	0.14	2	1	D	8848	2	35	-	0.0	-	0	3.5	Y	С	2.0	0	100	5.0	1	3.51	D	2.57 C
		CENTER Bridge Rd	Westside Pkwy	Fanfare Way	0.14	2	1	D	8848	2	35	14.3	0.0	0.0	0	3.5	Y	С	2.0	0	100	5.0	1	3.51	D	2.57 C
		Mayfield Rd	Bethany	Providence	1.32	2	1	U	7800	2	35	10.3	0.0	0.0	0	4.0	N	S	0.0	0	0	0.0	3	3.78	D	4.14 D
		Mayfield Rd	Bethany	Providence	1.32	2	1	U	7800	2	35	10.3	0.0	0.0	0	4.0	Ν	S	0.0	0	0	0.0	3	3.78	D	4.14 D
		Mayfield Rd	Providence	Canton	0.72	2	1	С	11002	2	35	9.5	0.0	0.0	0	3.5	Y	С	2.0	0	100	5.0	2	4.19	D	2.87 C
28.1 B	Alph	Mayfield Rd	Providence	Canton	0.72	2	1	С	11002	2	35	9.5	0.0	0.0	0	3.5	Y	С	2.0	0	25	5.0	2	4.19	D	4.05 D
20.1 D									11002			1														

						1							Widt	th			Bike			Tree				1			
					Len-				-		Post.		Of		Occ.		Lane/		Buff.	Spcg.	%	Swalk	Road		ycle	Pedes	
Segment ID ID	City	Road Name	From	То	gth (mi)	-	nes (L) Dir	Con	Roadway	Tks. (HV)	Spd. (SPp)		Pavem	nent W _{ps}	Park. (OSPA)	Pavecon PCt	Pavd. Shidr.	Cross Sec.	Width (BW)	in Buffer	with Sidewalk	Width (Ws)	Profile Cond	L(Score	OS Grade	LO Value	OS Grade
					(111)	-	#	COII	ADT	(%)	mph	(ft)	(ft)	(ft)	(%)	(15)	(Y/N)	(C/S)	(ft)	(ft/ctr)	(DIR)	(tt)	(1,2,3)	(17)	(AF)	(17)	(AF)
29.0 A	Alph	Mayfield Rd	Birmingham Hwy	Bethany	0.94	2	1	U	13258	3	45	11.0			0	4.0	N	s	0.0	0	0	0.0	3	4.38	D	4.70	Е
29.0 B	Alph	Mayfield Rd	Birmingham Hwy	Bethany	0.94	2	1	U	13258	3	45	11.0	0.0	0.0	0	4.0	N	S	0.0	0	0	0.0	3	4.38	D	4.70	E
		Mcginnis Ferry Rd	Bethany Bend	400	0.57	2	1	U	14144	3	45	10.1	0.0	0.0	0	3.5	N	S	2.0	0	40	5.0	2	4.65	E	4.26	D
31.0 B	Alph	Mcginnis Ferry Rd	Bethany Bend	400	0.57	2	1	U	14144	3	45	10.1	0.0	0.0	0	3.5	N	S	2.0	0	50	5.0	2	4.65	E	4.11	D
31.1 A	Alph	Mcginnis Ferry Rd	400	Union Hill	0.53	2	1	LT	13690	3	45	10.3	0.0	0.0	0	5.0	N	S	0.0	0	0	0.0	3	4.31	D	4.82	E
		Mcginnis Ferry Rd	400	Union Hill	0.53	2	1	LT	13690	3	45	10.3	0.0	0.0	0	5.0	N	S	0.0	0	0	0.0	3	4.31	D	4.82	Е
		Mcginnis Ferry Rd	Union Hill	McFarland	1.11	2	1	U	16414	8	45	11.5	0.0	0.0	0	4.5	N	S	0.0	0	0	0.0	2	5.76	F	4.84	Е
		Mcginnis Ferry Rd	Union Hill	McFarland	1.11	2	1	U	16414	8	45	11.5	0.0	0.0	0	4.5	N	s	0.0	0	0	0.0	2	5.76	F	4.84	Е
		Mcginnis Ferry Rd	McFarland	Douglas	1.14	2	1	LT	19208	8	45	12.0	0.0	0.0	0	4.5	N	S	2.0	0	0	5.0	3	5.78	F	4.96	Е
		Mcginnis Ferry Rd	McFarland	Douglas	1.14	2	1	LT	19208	8	45	12.0	0.0	0.0	0	4.5	N	S	2.0	0	25	5.0	3	5.78	F	4.62	E
		Mid Broadwell Rd	Crabapple	Wills	2.10	2	1	U	3726	3	40	10.5	0.0	0.0	0	5.0	N	С	2.0	0	40	5.0	3	3.47	с	3.44	с
		Mid Broadwell Rd	Crabapple	Wills	2.10	2	1	U	3726	3	40	10.5	0.0	0.0	0	5.0	N	С	2.0	0	40	5.0	3	3.47	С	3.44	С
		Milton Ave	Canton St	Hwy 9	0.03	2	1	U	26164	3	35	12.0	0.0	0.0	0	4.0	Y	С	3.5	65	100	5.0	1	4.41	D	2.55	с
		Milton Ave	Canton St	Hwy 9	0.03	2	1	U	26164	3	35	12.0	0.0	0.0	0	4.0	Y	С	3.5	65	100	5.0	1	4.41	D	2.55	с
		Milton Ave	Wills	Canton St	0.82	2	1	U	16892	3	35	11.9	0.0	0.0	0	3.5	N	С	1.5	0	0	4.0	2	4.35	D	4.50	D
		Milton Ave	Wills	Canton St	0.82	2	1	U	16892	3	35	11.9	0.0	0.0	0	3.5	N	С	1.5	0	0	4.0	2	4.35	D	4.50	D
		Morrison Pkwy	Hembree	Haynes Bridge [Westside Pkwy]	0.63	4	2	U	19588	3	40	11.5			0	3.5	N	S	0.0	0	0	0.0	1	4.38	D	4.47	D
		Morrison Pkwy	Hembree	Haynes Bridge [Westside Pkwy]	0.63	4	2	U	19588	3	40	11.5	0.0	0.0	0	3.5	N	S	0.0	0	0	0.0	1	4.38	D	4.47	D
		N Main St	Milton/Academy	Mayfield	0.39	4	2	U	35208	4	45	11.3			0	3.5	Y	C	2.0	0	100	4.0	2	5.03	Е	3.99	D
		N Main St	Milton/Academy	Mayfield	0.39	4	2	U	35208	4	45	11.3	-		0	3.5	Y	С	2.0	0	100	4.0	2	5.03	E	3.99	D
		N Main St	Mayfield Rd	Winthrope Park Dr	0.56	3	2	LT	27286	4	45	11.8	-		0	4.0	N	С	2.5	0	46	4.0	2	4.90	E	4.87	E
		N Main St	Mayfield Rd	· ·	0.56	3	2	LT	27286	4	45	11.8	_	-	0	4.0	N	C	2.5	0	24	4.0	2	4.90	E	5.16	E
		N Main St		Winthrope Park Dr	0.21	2	1	U	27286	4	45	14.0		_	0	4.0	N	c	2.0	0	50	5.0	2	4.61	E	4.62	E
		N Main St	Winthrope Park Dr	Winthrope Chase Dr	0.21	2	1	U		4	45	14.0	_	_	0	4.0	N	c	2.0	0	50	5.0	2	4.61	E	4.62	E
39.0 A			Winthrope Park Dr Mansell Rd	Winthrope Chase Dr Haynes Bridge	1.43	-	3	D	27286	2	35	12.4	-		0	5.0	Y	C	2.0	0	100	5.0	2	1.93	В	2.26	
		North Point Pkwy	Mansell Rd	Haynes Bridge	1.43	6	3	D	6334	2	35	12.4		_	0	5.0	Y	C	2.0	0	70	5.0	2	1.93	В	2.66	c
			Haynes Bridge	Kimbal Bridge	0.84	6	3	D	6334	3	40	12.1	-		0	4.5	N	C	2.0	0	0	8.0	1	3.69	D	4.01	D
39.1 A	, "bu	North Point Pkwy	Haynes Bridge	Kimbal Bridge	0.84	6	3	D	16390	3	40	12.2	-		0	4.5	N	C	2.0	0	0	8.0	1	3.69	D	4.01	D
		North Point Pkwy	Kimbal Bridge	Old Milton Pkwy	1.29	4	2	D	16390	3	40	11.8			0	5.0	N	c	2.0	0	75	5.0	2	3.11	c	2.87	c
			Kimbal Bridge	Old Milton Pkwy	1.29	-	2	D	6264	3	40	11.8	-	_	0	5.0	N	c	2.0	0	75	5.0	2	3.11	c	2.87	c
		North Point Pkwy	Old Milton Pkwy	-	0.83	4	2	D	6264	3	40	11.8			0	4.5	Y	c	2.0	0	100	5.0	2	4.05	D	3.01	c
		North Point Pkwy	Old Milton Pkwy	Webb Bridge way Webb Bridge way	0.83	4		D	18310	3	40			0.0	0	4.5	Y	c	2.0	0	100	5.0	2	4.05	D	3.01	
		North Point Pkwy		Windward Parkwy	0.83	4	2	D	18310		40	11.8	_		0	4.5		c	2.0	0	50	5.0	2	3.88	D	3.48	
		North Point Pkwy	Webb Bridge way	,	0.90	-			12692	3		_	0.0		•		N			0						3.48	
		North Point Pkwy	Webb Bridge way	Windward Parkwy		4	2	D	12692	3	40	-			0	4.5	N	C	2.0	0	50	5.0	2	3.88	D		C
		Old Alabama Conn	City Limit	Mansell Rd	0.48	2	1	U	14278	6	45		0.0	-	0	4.0	Y	C	2.0	0	75	5.0	1	5.12	E	3.65	D
		Old Alabama Conn	City Limit	Mansell Rd	0.48	2	1	U	14278	6	45	-	0.0		0	4.0	Y	C	2.0	0	100	5.0	1	5.12	E	3.31	C
		Old Milton Pkwy	Wills Road	Hwy 9	0.82	4	2	D	28184	3	35	12.0	_	_	0	4.0	Y	C	15.0	0	100	8.0	1	4.23	D	2.72	C
		Old Milton Pkwy	Wills Road	Hwy 9	0.82	4	2	D	28184	3	35	-	0.0		0	4.0	Y	C	15.0	0	100	8.0	1	4.23	D	2.72	C
		Old Milton Pkwy	Hwy 9	Westside Pkwy	0.85	6	3	D	32658	4	45	-	0.0	_	0	4.5	Y	C	2.0	0	100	5.0	2	4.35	D	3.21	C
		Old Milton Pkwy	Hwy 9	Westside Pkwy	0.85	6	3	D	32658	4	45	-	0.0		0	4.5	Y	С	2.0	0	100	5.0	2	4.35	D	3.21	C
		Old Milton Pkwy	North Point	Westside Pkwy	1.22	6	3	D	5692	3	45		0.0		0	4.5	Y	С	2.0	0	100	5.0	2	2.23	В	2.56	C
		Old Milton Pkwy	North Point	Westside Pkwy	1.22	6	3	D	5692	3	45	-		0.0	0	4.5	Y	С	2.0	0	100	5.0	2	2.23	В	2.56	С
		Old Milton Pkwy	Kimbal Bridge	North Point	1.96	4	2	D	48066	4	45	-	0.0	_	0	4.0	Y	С	2.0	0	100	5.0	1	4.93	E	4.35	D
		Old Milton Pkwy	Kimbal Bridge	North Point	1.96	4	2	D	48066	4	45	-	0.0		0	4.0	Y	С	2.0	0	75	5.0	1	4.93	E	4.69	E
		Old Roswell Rd	Warsaw[city limit]	Mansell	0.41	2	1	U	2500	2	35	15.0	_		0	4.0	N	С	0.0	0	0	0.0	2	2.63	с	3.03	С
		Old Roswell Rd	Warsaw[city limit]	Mansell	0.41	2	1	U	2500	2	35		2.5		0	4.0	N	С	0.0	0	0	0.0	2	2.63	С	3.03	С
42.1 A	Alph	Old Roswell Rd	Mansell	Old Roswell[westside pkwy]	0.25	4	2	D	26518	4	40	12.0	_	_	0	5.0	Y	С	5.0	0	100	5.0	2	4.39	D	3.22	С
		Old Roswell Rd	Mansell	Old Roswell[westside pkwy]	0.25	4	2	D	26518	4	40	12.0			0	5.0	Y	С	5.0	0	100	5.0	2	4.39	D	3.22	С
		Providence Rd	Mayfield Road	City Line	0.90	2	1	U	4424	2	35		0.0	_	0	4.5	N	S	0.0	0	0	0.0	2	3.28	с	3.82	D
		Providence Rd	Mayfield Road	City Line	0.90	2	1	U	4424	2	35	-		0.0	0	4.5	N	S	0.0	0	0	0.0	2	3.28	С	3.82	D
44.0 A	Alph	Rock Mill Rd	Old Roswell	Sanctuary Pkwy[Westsied Pkwy]	0.66	4	2	D	22740	4	40	12.0	0.0	0.0	0	5.0	Y	С	5.0	0	100	5.0	2	4.32	D	3.08	С

											Width			Bike			Tree			_				
O a main set 15	0:4	Deed No	F	.	Len-	1	(1)		T ! -	Post.	Of	Occ.	Deverse	Lane/	0	Buff.	Spcg.	%	Swalk	Road	Bicy	-	Pedes	
Segment ID ID	City	Road Name	From	То	gth (mi)	Lanes Th	(L) Dir Con	Roadway	Tks. (HV)	Spd. (SPp)	Pavement Wt WI W _{ps}	Park. (OSPA)	Pavecon PC _t	Pavd. Shidr.	Cross Sec.	Width (BW)	in Buffer	with Sidewalk	Width (Ws)	Profile Cond	LC Score	OS Grade	LO Value	JS Grade
							#	ADT	(%)	mph	(ft) (ft) (ft)	(%)	(15)	(Y/N)	(C/S)	(ft)	(ft/ctr)	(DIR)	(ft)	(1,2,3)	(17)	(AF)	(17)	(AF)
	B Alph Rock M		Old Roswell	Sanctuary Pkwy[Westsied Pkwy]	0.66	4	2 D	2274	0 4	40	12.0 0.0 0.0	0	5.0	Y	С	5.0	0	100	5.0	2	4.32	D	3.08	С
45.0	A Alph Rucker		Roswell City Limits	Broadwell	0.45	2	1 U	2080	8 3	35	11.2 0.0 0.0	0	5.0	N	С	2.0	0	50	5.0	2	4.22	D	4.10	D
45.0			Roswell City Limits	Broadwell	0.45	2	1 U	2080	8 3	35	11.2 0.0 0.0	0	5.0	N	С	2.0	0	50	5.0	2	4.22	D	4.10	D
45.1	A Alph Rucker		Broadwell	Wills Road	1.85	2	1 U	2930	2 3	35	12.4 0.0 0.0	0	4.0	N	С	2.0	0	50	5.0	2	4.41	D	4.53	E
45.1	- P		Broadwell	Wills Road	1.85	2	1 U	2930	2 3	35	12.4 0.0 0.0	0	4.0	N	С	2.0	0	50	5.0	2	4.41	D	4.53	E
46.0	P.		Old Milton Pkwy	Academy St	0.34	4	2 U	2744	0 5	35	11.7 0.0 0.0	0	3.5	Y	С	2.5	0	100	4.0	1	4.86	E	3.32	С
46.0			Old Milton Pkwy	Academy St	0.34	4	2 U	2744	0 5	35	11.7 0.0 0.0	0	3.5	Y	С	2.5	0	100	4.0	1	4.86	E	3.32	С
47.0	A Alph S Main		Haney Dr	Northfall Ln	0.46	4	2 LT	3282	6 4	45	12.2 0.0 0.0	0	3.5	N	С	2.0	0	76	5.0	2	4.89	E	4.07	D
47.0			Haney Dr	Northfall Ln	0.46	4	2 LT	3282	6 4	45	12.2 0.0 0.0	0	3.5	N	С	2.0	0	13	5.0	2	4.89	E	4.92	E
47.1	A Alph S Main		Northfall Ln	Old Milton Pkwy	0.72	4	2 U	3612	4 4	45	11.9 0.0 0.0	0	3.5	N	С	2.4	0	32	4.0	1	4.97	E	4.85	E
47.1	I.		Northfall Ln	Old Milton Pkwy	0.72	4	2 U	3612	4 4	45	11.9 0.0 0.0	0	3.5	N	С	2.4	0	56	4.0	1	4.97	E	4.54	E
49.0	A Alph State Bi		Old Milton Pkwy	Kimbal Bridge	0.26	1	1 OW	908	2 3	45	12.4 0.0 0.0	0	4.0	Y	С	2.0	0	0	5.0	2	4.31	D	4.73	E
49.0			Old Milton Pkwy	Kimbal Bridge	0.26	1	1 OW	908	2 3	45	12.4 0.0 0.0	0	4.0	Y	С	2.0	0	100	5.0	2	4.31	D	3.39	С
51.0	A Alph Waters		Jones Bridge Rd	Kimball Bridge Rd	1.35	2	1 U	1206		35	13.0 0.0 0.0	0	3.5	N	С	2.0	0	0	5.0	2	3.84	D	4.12	D
51.0	I.		Jones Bridge Rd	Kimball Bridge Rd	1.35	2	1 U	1206		35	13.0 0.0 0.0	0	3.5	N	С	2.0	0	0	5.0	2	3.84	D	4.12	D
52.0	A Alph Webb B		Plymouth Lane	Westside Pkwy	0.40	2	1 U	969	4 3	35	11.0 0.0 0.0	0	3.0	N	С	2.0	0	0	5.0	2	4.35	D	4.17	D
52.0			Plymouth Lane	Westside Pkwy	0.40	2	1 U	969	4 3	35	11.0 0.0 0.0	0	3.0	N	С	2.0	0	73	5.0	2	4.35	D	3.12	С
	A Alph Webb B		Westside Pkwy	Morris Rd	0.67	2	1 U	1206	8 3	35	12.2 0.0 0.0	0	4.5	N	С	2.0	0	0	5.0	2	3.90	D	4.20	D
	B Alph Webb B		Westside Pkwy	Morris Rd	0.67	2	1 U	1206	8 3	35	12.2 0.0 0.0	0	4.5	N	С	2.0	0	27	5.0	2	3.90	D	3.83	D
52.2	A Alph Webb B		North Point Dr	Webb Bridge Way	2.46	2	1 U	1258	2 3	40	13.0 0.0 0.0	0	4.0	Y	С	2.0	0	100	5.0	2	4.02	D	3.00	С
52.2			North Point Dr	Webb Bridge Way	2.46	2	1 U	1258	2 3	40	13.0 0.0 0.0	0	4.0	Y	С	2.0	0	20	5.0	2	4.02	D	4.04	D
53.0			Kimbal Bridge	Webb Bridge Way	0.29	2	1 U	1280	6 2	30	12.3 0.0 0.0	0	4.0	Y	С	1.5	0	100	5.0	2	3.67	D	2.76	С
53.0			Kimbal Bridge	Webb Bridge Way	0.29	2	1 U	1280	6 2	30	12.3 0.0 0.0	0	4.0	Y	С	1.5	0	100	5.0	2	3.67	D	2.76	С
54.0	A Alph Webb R		Cogburn Rd	Cogburn Rd	0.05	2	1 U	379	0 2	20	11.3 0.0 0.0	0	2.5	N	S	0.0	0	0	0.0	1	2.81	С	3.39	С
54.0	B Alph Webb R	Rd	Cogburn Rd	Cogburn Rd	0.05	2	1 U	379	0 2	20	11.3 0.0 0.0	0	2.5	N	S	0.0	0	0	0.0	1	2.81	С	3.39	С
	A Alph Westsid		Sanctuary Pkwy	Hembree	1.16	4	2 D	2451	2 4	40	11.7 0.0 0.0	0	3.5	N	С	14.0	40	0	5.0	1	4.70	E	4.64	E
	B Alph Westsid		Sanctuary Pkwy	Hembree	1.16	4	2 D	2451	2 4	40	11.7 0.0 0.0	0	3.5	N	С	14.0	40	0	5.0	1	4.70	E	4.64	E
	A Alph Westsid		Haynes Bridge	Old Milton Pkwy	0.74	4	2 D	588	2 3	40	11.7 0.0 0.0	0	4.5	Y	С	15.0	0	100	5.0	1	3.09	С	2.14	В
	B Alph Westsid		Haynes Bridge	Old Milton Pkwy	0.74	4	2 D	588	2 3	40	11.7 0.0 0.0	0	4.5	Y	С	15.0	0	100	5.0	1	3.09	С	2.14	В
55.2	A Alph Westsid	de Pkwy	Old Milton Pkwy	Webb Bridge	0.92		0 X	926	2 2	Х	X 0.0 0.0	0	Х	N	х	0.0	0	0	0.0	x		UC	0.00	UC
55.2	B Alph Westsid	de Pkwy	Old Milton Pkwy	Webb Bridge	0.92		0 X	926	2 2	Х	X 0.0 0.0	0	Х	N	Х	0.0	0	0	0.0	х		UC	0.00	UC
	A Alph Westsid		Webb Bridge	South of Cumming Street	0.73	4	2 D	537	0 3	40	12.0 0.0 0.0	0	5.0	Y	С	2.0	0	100	5.0	1	2.81	С	2.49	В
	B Alph Westsid		Webb Bridge	South of Cumming Street	0.73	4	2 D	537	D 3	40	12.0 0.0 0.0	0	5.0	Y	С	2.0	0	50	5.0	1	2.81	С	3.17	С
	A Alph Westsid		South of Cumming Street	Windward	0.34	4	2 D	713	6 3	40	12.0 0.0 0.0	0	4.0	Y	С	2.0	0	100	5.0	1	3.48	С	2.55	С
	B Alph Westsid		South of Cumming Street	Windward	0.34	4	2 D	713	₆ 3	40	12.0 0.0 0.0	0	4.0	Y	С	2.0	0	50	5.0	1	3.48	С	3.24	С
	A Alph Windwa		North Point Pkwy	Compass Pointe Chase	2.10		2 D	2197	8 4	40	11.7 0.0 0.0	0	4.0	Y	С	2.0	0	75	5.0	1	4.49	D	3.50	С
	B Alph Windwa		North Point Pkwy	Compass Pointe Chase	2.10		2 D	2197	8 4	40	11.7 0.0 0.0	0	4.0	Y	С	2.0	0	100	5.0	1	4.49	D	3.15	С
	A Alph Windwa		Compass Pointe Chase	McGinnis Ferry Road	1.18		2 U	2796	0 4	40	12.5 0.0 0.0	0	3.5	Y	С	2.0	0	100	5.0	2	4.67	Е	3.37	С
	B Alph Windwa		Compass Pointe Chase	McGinnis Ferry Road	1.18		2 U	2796	0 4	40	12.5 0.0 0.0	0	3.5	Y	С	2.0	0	100	5.0	2	4.67	E	3.37	С
	A Alph Windwa		Hwy 9	Sh. Center DW[West of 400]	0.63		2 D	2333		35	12.0 0.0 0.0	0	4.5	Y	С	2.0	0	100	5.0	2	4.04	D	3.05	С
	B Alph Windwa		Hwy 9	Sh. Center DW[West of 400]	0.63		2 D	2333	₆ 3	35	12.0 0.0 0.0	0	4.5	Y	С	2.0	0	100	5.0	2	4.04	D	3.05	С
	A Alph Windwa		Sh. Center DW west of 400	N. Point Pkwy	0.84	4	2 D	3078	8 3	35	15.7 4.0 0.0	0	4.5	Y	С	2.0	0	100	5.0	2	2.96	С	3.24	С
	B Alph Windwa		Sh. Center DW west of 400	N. Point Pkwy	0.84	4	2 D	3078	8 3	35	15.7 4.0 0.0	0	4.5	Y	С	2.0	0	100	5.0	2	2.96	С	3.24	С
	A JC Abbotts		City Limit	Boles	0.32	2	1 U	2945	8 4	45	13.3 0.0 0.0	0	4.5	N	S	0.0	0	0	0.0	3	4.65	E	5.44	E
	B JC Abbotts		City Limit	Boles	0.32	2	1 U	2945	8 4	45	13.3 0.0 0.0	0	4.5	N	S	0.0	0	0	0.0	3	4.65	E	5.44	Е
	A JC Abbotts		Boles	Parsons Rd	0.28	2	1 U	2043	8 4	45	11.6 0.0 0.0	0	4.5	N	S	0.0	0	0	0.0	3	4.67	E	5.07	Е
	B JC Abbotts		Boles	Parsons Rd	0.28	2	1 U	2043	8 4	45	11.6 0.0 0.0	0	4.5	N	S	0.0	0	0	0.0	3	4.67	E	5.07	E
	A JC Abbotts		Parsons Rd	Medlock Bridge Rd		-	1 U	1428	4 3	45	11.5 0.0 0.0	0	3.5	N	С	0.0	0	0	7.0	2	4.51	E	4.72	E
59.2	B JC Abbotts	Bridge Rd	Parsons Rd	Medlock Bridge Rd	0.86	2	1 U	1428	4 3	45	11.5 0.0 0.0	0	3.5	Ν	С	0.0	0	0	7.0	2	4.51	E	4.72	Е
	A JC Abbotts		Medlock Bridge	Parsons Rd	1.52	2	1 U	1292	_в з	45	12.0 0.0 0.0	0	4.0	N	С	2.0	0	50	5.0	3	4.25	D	3.90	D
59.3	B JC Abbotts	Bridge Rd	Medlock Bridge	Parsons Rd	1.52	2	1 U	1292	8 3	45	12.0 0.0 0.0	0	4.0	Ν	С	2.0	0	50	5.0	3	4.25	D	3.90	D

	\top												Width				Bike			Tree				П			,
	+					Len-			_		Post.		Of		Occ.		Lane/		Buff.	Spcg.	%	Swalk	Road	Bicy		Pedes	
Segment ID ID	Ci	ity	Road Name	From	То	gth L (mi) T	anes (L h Di	,	Roadway	Tks. (HV)	Spd. (SPp)	Wt	Pavemei WI	nt W _{ps}	Park. (OSPA)	Pavecon PCt	Pavd. Shidr.	Cross Sec.	Width (BW)	in Buffer	with Sidewalk	Width (Ws)	Profile Cond	LO Score	OS Grade	LC Value	OS Grade
	+						t #		ADT	(%)	(SPP) mph	(ft)		(ft)	(%)	(15)	(Y/N)	(C/S)	(BVV)	(ft/ctr)	(DIR)	(VVS) (ft)	(1,2,3)	(17)	(AF)	(17)	(AF)
59.4 /	A J	JC Abbo	otts Bridge Rd	Parsons Rd	Jones Bridge Rd	0.96	2 1	U	17812	3	45	13.0		0.0	0	4.0	N	С	2.0	0	50	5.0	3	4.28	D	4.13	D
59.4 F	вJ	JC Abbo	otts Bridge Rd	Parsons Rd	Jones Bridge Rd	0.96	2 1	U	17812	3	45	13.0	2.0	0.0	0	4.0	N	С	2.0	0	50	5.0	3	4.28	D	4.13	D
60.0 /	A J	JC Barn	well Rd	Holcomb Bridge Rd	JonesBridge (bkms Barnwell)	2.51 2	2 1	U	12232	3	40	11.7	0.0	0.0	0	4.5	N	S	0.0	0	0	0.0	3	4.07	D	4.40	D
60.0 E	вJ	JC Barn	well Rd	Holcomb Bridge Rd	JonesBridge (bkms Barnwell)	2.51 2	2 1	U	12232	3	40	11.7	0.0	0.0	0	4.5	N	S	0.0	0	0	0.0	3	4.07	D	4.40	D
61.0 A	A J	JC Bell I	Rd	1 SR 141	Boles	1.44 2	2 1	U	4426	3	45	12.0	0.0	0.0	0	4.5	Y	С	3.0	0	20	5.0	3	3.60	D	3.80	D
61.0 E	вJ	JC Bell I	Rd	1 SR 141	Boles	1.44 2	2 1	U	4426	3	45	12.0	0.0	0.0	0	4.5	Y	С	3.0	0	100	5.0	3	3.60	D	2.68	С
61.1 A	A J	JC Bell I	Rd	2 Boles	McGinnis Ferry	2.14 2	2 1	U	12784	3	45	10.7	0.0	0.0	0	3.5	Ν	С	2.0	0	40	5.0	3	4.54	E	4.13	D
61.1 F	вJ	JC Bell I	Rd	2 Boles	McGinnis Ferry	2.14 2	2 1	U	12784	3	45	10.7	0.0	0.0	0	3.5	N	С	2.0	0	20	5.0	3	4.54	E	4.42	D
62.0 /	A J	JC Bole	s Rd	Bell	Parsons	0.93 2	2 1	U	15760	3	45	11.3	0.0	0.0	0	4.5	N	С	2.0	0	15	5.0	3	4.33	D	4.62	Е
62.0 F	вJ	JC Bole	s Rd	Bell	Parsons	0.93 2	2 1	U	15760	3	45	11.3	0.0	0.0	0	4.5	Ν	С	2.0	0	75	5.0	3	4.33	D	3.76	D
63.0 /	A J	JC Buice	e Rd	Jones Bridge Rd	Old Alabama	2.85	2 1	U	4332	3	45	11.7	0.0	0.0	0	5.0	N	S	2.0	0	0	5.0	3	3.58	D	4.10	D
63.0 F	вJ	JC Buice	e Rd	Jones Bridge Rd	Old Alabama	2.85 2	2 1	U	4332	3	45	11.7	0.0	0.0	0	5.0	N	S	2.0	0	0	5.0	3	3.58	D	4.10	D
65.0 /	A J	JC Hayr	nes Bridge Rd	Old Alabama	City Limit	0.96	2 1	U	12166	3	45	12.5	0.0	0.0	0	3.5	Y	С	2.0	0	50	5.0	2	4.31	D	3.82	D
65.0 F	зJ	JC Hayr	nes Bridge Rd	Old Alabama	City Limit	0.96 2	2 1	U	12166	3	45	12.5	0.0	0.0	0	3.5	Y	С	2.0	0	100	5.0	2	4.31	D	3.15	С
67.0 A			ns Creek Pkwy	McGinnis Ferry	Medlock Bridge Rd	1.18 4	2	D	9058	3	45	12.0	0.0	0.0	0	4.0	Y	С	10.0	0	100	5.0	1	3.86	D	2.56	с
			ns Creek Pkwy	McGinnis Ferry	Medlock Bridge Rd	1.18 4	2	D	9058	3	45	12.0	0.0	0.0	0	4.0	Y	С	10.0	0	100	5.0	1	3.86	D	2.56	С
68.0 /	A J	JC Jone	es Bridge Rd	Barnwell Rd	Old Alabama	0.67 2	2 1	U	11706	3	40	12.0	0.0	0.0	0	4.0	Y	С	3.0	10	100	5.0	3	4.11	D	2.35	В
			es Bridge Rd	Barnwell Rd	Old Alabama	0.67 2	2 1	U	11706	3	40	12.0	0.0	0.0	0	4.0	Y	С	3.0	10	5	5.0	3	4.11	D	4.24	D
69.0 <i>F</i>	A J	JC Jone	es Bridge Rd	Old Alabama	Waters	0.46 2	2 1	U	14254	3	45	12.0	0.0	0.0	0	5.0	Y	С	2.0	0	100	5.0	2	4.14	D	3.29	с
			es Bridge Rd	Old Alabama	Waters	0.46 2	2 1	U	14254	3	45	12.0	0.0	0.0	0	5.0	Y	С	2.0	0	50	5.0	2	4.14	D	3.98	D
			es Bridge Rd	Waters	Buice	0.95 2	2 1	U	14334	3	45	11.8	0.0	0.0	0	5.0	N	С	2.0	0	50	5.0	2	4.18	D	3.99	D
			es Bridge Rd	Waters	Buice	0.95 2	2 1	U	14334	3	45	11.8	0.0	0.0	0	5.0	N	С	2.0	0	20	5.0	2	4.18	D	4.41	D
			es Bridge Rd	Buice	State Bridge	0.95 2	2 1	U	14212	3	45	11.0		0.0	0	5.0	N	С	2.0	0	70	5.0	3	4.28	D	3.76	D
			es Bridge Rd	Buice	State Bridge	0.95 2	2 1	U	14212	3	45	11.0	0.0	0.0	0	5.0	N	С	2.0	0	50	5.0	3	4.28	D	4.05	D
			es Bridge Rd	State Bridge	Taylor	0.46 4	2		24396	4	45	10.0		0.0	0	4.5	Y	С	2.0	0	80	5.0	2	4.73	E	3.79	D
			es Bridge Rd	State Bridge	Taylor	0.46 4	2		24396	4	45	10.0	-	0.0	0	4.5	Y	С	2.0	0	100	5.0	2	4.73	E	3.48	С
			es Bridge Rd	Taylor	Weather Vane Dr	0.67 2	2 1	U	24416	4	45	11.2		0.0	0	4.5	N	С	0.0	0	0	0.0	1	4.81	E	5.35	E
			es Bridge Rd	Taylor	Weather Vane Dr	0.67 2		-	24416	4	45	11.2		0.0	0	4.5	N	С	0.0	0	0	0.0	1	4.81	E	5.35	E
			es Bridge Rd	Weather Vane	Douglas	0.85 2			18786	3	45	16.0		0.0	0	5.0	Y	С	2.0	0	100	5.0	3	2.90	С	3.44	с
			es Bridge Rd	Weather Vane	Douglas	0.85 2			18786	3	45	16.0		0.0	0	5.0	Y	С	2.0	0	100	5.0	3	2.90	С	3.44	С
			es Bridge Rd	Douglas	McGinnis Ferry	1.43 2		-	8206	2	45	10.8	_	0.0	0	4.5	N	S	2.0	0	0	5.0	5	3.83	D	4.43	D
			es Bridge Rd	Douglas	McGinnis Ferry		2 1		8206	2	45	1	0.0		0	4.5	N	S	2.0	0	40	5.0	5	3.83	D	3.85	D
			innis Ferry Rd	Douglas Road	Jones Bridge	1.03 2		-	21816	8	45		0.0		0	4.5	Y	С	2.0	0	0	5.0	3	5.85	F	5.12	E
			innis Ferry Rd	Douglas Road	Jones Bridge	1.03 2			21816	8	45		0.0		0	4.5	Y	C	2.0	0	100	5.0	3	5.85	F	3.75	D
			innis Ferry Rd	Jones Bridge Rd	Sargent	1.42 2			20670		45	12.0			0	4.5	N	S	0.0	0	0	0.0	3	4.63	E	5.05	E
			innis Ferry Rd	Jones Bridge Rd	Sargent	1.42 2			20670	4	45		0.0		0	4.5	N	S	0.0	0	0	0.0	3	4.63	E	5.05	E
			innis Ferry Rd	Sargent	Bell Rd	3.07 >			15378	2	X	X		0.0	0	X	N	X	0.0	0	0	0.0	X	 	UC	0.00	UC
			innis Ferry Rd	Sargent	Bell Rd		(####		15378		X	X	-		0	X	N	X	0.0	0	0	0.0	x		UC	0.00	UC
			innis Ferry Rd	Bell Rd	City Limit		1		21276	4	45		0.0		0	4.0	N	C	2.0	0	0	5.0	2	4.86	E	5.18	E
			innis Ferry Rd	Bell Rd	City Limit		1		21276		45	-	0.0		0	4.0	N	C	2.0	0	25	5.0	2	4.86	E	4.83	E
			lock Bridge Rd	Chattahochee River Park	Old Alabama Rd	1.17 4			56618	5	55	20.8	-		0	4.5	N	С	0.0	0	0	0.0	2	1.59	В	5.79	F
			lock Bridge Rd	Chattahochee River Park	Old Alabama Rd	1.17 4			56618	5	55		9.3		0	4.5	N	C	0.0	0	0	0.0	2	1.59	В	5.79	F
			lock Bridge Rd	Old Alabama Rd	State Bridge Rd	0.47 4			30598	4	45		7.8		0	4.0	N	C	2.0	0	50	5.0	2	1.62	B	3.91	D
			lock Bridge Rd	Old Alabama Rd	State Bridge Rd	0.47 4	2		30598	4	45		7.8		0	4.0	N	C C	2.0	0	75	5.0	2	1.62	В	3.67	0
			lock Bridge Rd	State Bridge Rd	McGinnis Ferry	3.74 2		_	48584	5	55	20.6			0	5.0	N	C	2.0	0	35	8.0	3	1.90	B	6.05	F
			lock Bridge Rd	State Bridge Rd	McGinnis Ferry	3.74 2			48584	5	55	20.6	-		0	5.0	N	C	2.0	0	35	8.0	3	1.90	В	6.05	F
		JC Morte		Jones Bridge Rd	State Bridge Rd	0.46		U	9106		35	13.0		0.0	0	4.5	N	C	2.0	0	15	5.0	2	3.45	c	3.74	
		JC Morte		Jones Bridge Rd	State Bridge Rd	0.46 2		-	9106		35		0.0		0	4.5	N	C C	2.0	0	15	5.0	2	3.45	C C	3.74	D
		JC Morte		State Bridge Rd	State Bridge Rd	1.98 2	_	-	3998	2	35	4	0.0		0	4.5	N	C	2.0	0	40	5.0	2	3.13	c	3.16	c
		IC Morte		State Bridge Rd	State Bridge Rd	1.98 2			3998	2	35		0.0		0	4.5	N	C C	2.0	0	50	5.0	2	3.13	C	3.03	C
75.0 A	₹ J(IC Nest	oit Ferry Rd	Holcomb Bridge Rd	Old Alabama Rd	2.41 2	1	U	17022	3	40	11.7	0.0	0.0	0	3.5	N	С	2.0	0	20	5.0	3	4.49	D	4.41	D

											Width			Bike			Tree				I 1	<u> </u>		
					Len-					Post.	Of	Occ.	_	Lane/		Buff.	Spcg.	%	Swalk	Road	Bicy		Pedes	
Segment ID ID	City	Road Name	From	То	gth La (mi) Th	anes (L) n Dir		Roadway	Tks. (HV)	Spd. (SPp)	Pavement Wt WI W _{ps}	Park. (OSPA)	Pavecon PC _t	Pavd. Shidr.	Cross Sec.	Width (BW)	in Buffer	with Sidewalk	Width (Ws)	Profile Cond	LC Score	OS Grade	LO Value	OS Grade
10					#			ADT	(%)	mph	(ft) (ft) (ft)		(15)	(Y/N)	(C/S)	(ft)	(ft/ctr)	(DIR)	(ft)	(1,2,3)	(17)	(AF)	(17)	(AF)
75.0	B JC Nesbit F	erry Rd	Holcomb Bridge Rd	Old Alabama Rd	2.41 2	1	U	17022	3	40	11.7 0.0 0.0	0	3.5	Ν	С	2.0	0	0	5.0	3	4.49	D	4.69	Е
76.0	A JC Old Alab	oama Rd	Medlock Bridge Rd	Coleherne Court	2.34 3	2	U	14118	3	45	12.3 0.0 0.0	0	4.0	Ν	С	0.0	0	0	0.0	1	4.26	D	4.62	E
76.0	B JC Old Alab	oama Rd	Medlock Bridge Rd	Coleherne Court	2.34 3	2	U	14118	3	45	12.3 0.0 0.0	0	4.0	Ν	С	0.0	0	0	0.0	1	4.26	D	4.62	E
76.1	A JC Old Alab	oama Rd	Coleherne Court	Hayden Walk Dr	0.26 4	2	LT	13902	3	45	11.4 0.0 0.0	0	4.0	Ν	С	0.0	0	0	0.0	2	4.15	D	4.43	D
76.1	B JC Old Alab	oama Rd	Coleherne Court	Hayden Walk Dr	0.26 4	2	LT	13902	3	45	11.4 0.0 0.0	0	4.0	Ν	С	0.0	0	0	0.0	2	4.15	D	4.43	D
76.2	A JC Old Alab	oama Rd	Hayden Walk Dr	Jones Bridge Rd	1.26 2	1	U	16664	3	45	11.0 0.0 0.0	0	3.5	Ν	S	2.0	0	0	5.0	3	4.64	E	4.91	E
76.2	B JC Old Alab	ama Rd	Hayden Walk Dr	Jones Bridge Rd	1.26 2	1	U	16664	3	45	11.0 0.0 0.0	0	3.5	Ν	S	2.0	0	40	5.0	3	4.64	E	4.34	D
77.0			Nesbit Ferry Rd	Jones Bridge Rd	1.40 4	2	U	24620	4	45	11.1 0.0 0.0	0	4.0	Y	С	2.0	0	100	5.0	2	4.72	E	3.46	С
77.0	B JC Old Alab	oama Rd	Nesbit Ferry Rd	Jones Bridge Rd	1.40 4	2	U	24620	4	45	11.1 0.0 0.0	0	4.0	Y	С	2.0	0	100	5.0	2	4.72	Е	3.46	С
78.0	A JC Parsons	Rd	E Medlock Bridge Rd	Abbotts Bridge Rd	1.58 2	1	U	13594	2	35	12.5 0.0 0.0	0	4.0	Y	С	2.0	0	100	5.0	2	3.82	D	2.92	С
78.0	B JC Parsons	Rd	E Medlock Bridge Rd	Abbotts Bridge Rd	1.58 2	1	U	13594	2	35	12.5 0.0 0.0	0	4.0	Y	С	2.0	0	50	5.0	2	3.82	D	3.59	D
78.1	A JC Parsons	Rd	W Medlock Bridge Rd	Abbotts Bridge Rd	0.71 2	1	U	10678	2	35	10.3 0.0 0.0	0	4.5	N	С	2.0	0	30	5.0	3	3.84	D	3.86	D
78.1	B JC Parsons	Rd	W Medlock Bridge Rd	Abbotts Bridge Rd	0.71 2	1	U	10678	2	35	10.3 0.0 0.0	0	4.5	Ν	С	2.0	0	10	5.0	3	3.84	D	4.16	D
79.0			Jones Bridge Rd	McGinnis Ferry	1.61 2	1	U	9668	3	45	12.0 0.0 0.0		4.0	Y	С	2.0	0	10	5.0	2	4.10	D	4.26	D
79.0			Jones Bridge Rd	McGinnis Ferry	1.61 2	1	U	9668	3	45	12.0 0.0 0.0		4.0	Y	С	2.0	0	100	5.0	2	4.10	D	3.02	С
80.0			Kimball Bridge Rd	Indian Village Dr	0.33 4	2	D	24028	3	45	12.0 0.0 0.0	_	4.5	Y	С	2.0	0	100	8.0	2	4.34	D	3.20	С
80.0			Kimball Bridge Rd	Indian Village Dr	0.33 4	2	D	24028	3	45	12.0 0.0 0.0		4.5	Y	С	2.0	0	100	8.0	2	4.34	D	3.20	С
80.1			Indian Village Dr	Medlock Bridge Rd	3.26 4	2	D	24028	3	45	12.4 0.0 0.0		5.0	Y	С	2.0	0	100	5.0	2	4.23	D	3.38	С
80.1	B JC State Bri		Indian Village Dr	Medlock Bridge Rd	3.26 4		D	24028	3	45	12.4 0.0 0.0		5.0	Y	С	2.0	0	100	5.0	2	4.23	D	3.38	С
80.2			Medlock Bridge Rd	City Limit	0.95 4	2	D	33958	3	45	12.4 0.0 0.0	0	5.0	Y	С	0.0	0	100	5.0	2	4.44	D	3.85	D
80.2			Medlock Bridge Rd	City Limit	0.95 4	2	D	33958	3	45	12.4 0.0 0.0		5.0	Y	С	0.0	0	50	5.0	2	4.44	D	4.49	D
84.0	A Milt Arnold M	1ill Rd	City Limit (s)	New Providence	0.37 2	1	U	21512	5	45	18.0 2.9 0.0	0	4.0	N	S	2.0	0	0	5.0	2	4.13	D	4.60	E
84.0	B Milt Arnold M	1ill Rd	City Limit (s)	New Providence	0.37 2	1	U	21512	5	45	18.0 2.9 0.0	0	4.0	N	S	2.0	0	50	5.0	2	4.13	D	4.07	D
84.1	A Milt Arnold M	1ill Rd	New Providence	City Limit (N)	2.64 2	1	U	21364	5	45	12.0 0.0 0.0		3.5	N	S	0.0	0	0	0.0	3	5.17	E	5.10	E
84.1			New Providence	City Limit (N)	2.64 2	1	U	21364	5	45	12.0 0.0 0.0	0	3.5	N	S	0.0	0	0	0.0	3	5.17	E	5.10	E
	A Milt Batesville		Birmingham Highway	City Limit	1.32 2	1	U	11010	3	45	11.5 0.0 0.0	0	3.5	N	S	0.0	0	0	0.0	3	4.38	D	4.53	E
85.0	B Milt Batesville	e Rd	Birmingham Highway	City Limit	1.32 2		U	11010	3	45	11.5 0.0 0.0		3.5	N	S	0.0	0	0	0.0	3	4.38	D	4.53	E
	A Milt Bethany		Highway 9	Morris /McGinnis Ferry	1.41 2		U	7854	3	40	11.0 0.0 0.0		4.5	N	S	2.0	0	75	5.0	2	3.93	D	3.14	С
	B Milt Bethany		Highway 9	Morris /McGinnis Ferry	1.41 2	1	U	7854	3	40	11.0 0.0 0.0		4.5	N	S	2.0	0	25	5.0	2	3.93	D	3.85	D
88.0	A Milt Bethany	Rd	Haygood	Hopewell	0.70 2	1	U	3836	6	40	10.5 0.0 0.0	0	3.5	N	S	0.0	0	0	0.0	2	4.50	D	3.98	D
	B Milt Bethany		Haygood	Hopewell	0.70 2		U	3836	6	40	10.5 0.0 0.0		3.5	N	S	0.0	0	0	0.0	2	4.50	D	3.98	D
	A Milt Bethany		Hopewell	Highway 9	1.53 2		U	11242	8	40	10.5 0.0 0.0		4.0	N	S	10.0	0	40	5.0	3	5.61	F	3.78	
	B Milt Bethany		Hopewell	Highway 9	1.53 2	-	U	11242	8	40	10.5 0.0 0.0		4.0	N	S	10.0	0	0	5.0	3	5.61	F	4.48	D
	A Milt Bethany		Mayfield	Haygood Rd	2.02 2	_	U	4748	6	40	10.0 0.0 0.0		3.5	N	S	0.0	0	0	0.0	3	4.83	E	4.15	D
	B Milt Bethany		Mayfield	Haygood Rd	2.02 2		U	4748	6	40	10.0 0.0 0.0		3.5	N	S	0.0	0	0	0.0	3	4.83	E	4.15	D
	A Milt Birmingh		1 Mayfield	New Providence	2.18 2	_	U	11718	3	45	11.6 0.0 0.0		4.0	N	S	2.0	0	25	5.0	2	4.24	D	4.20	D
	B Milt Birmingh		1 Mayfield	New Providence	2.18 2		U	11718	3	45	11.6 0.0 0.0		4.0	N	S	2.0	0	25	5.0	2	4.24	D	4.20	D
	A Milt Birmingh		2 Hickory Flat Rd	New Providence	3.72 2	_	U	6308	3	45	11.6 0.0 0.0		4.0	N	S	0.0	0	0	0.0	3	3.94	D	4.23	D
	B Milt Birmingh		2 Hickory Flat Rd	New Providence	3.72 2	-	U	6308	3	45	11.6 0.0 0.0		4.0	N	S	0.0	0	0	0.0	3	3.94	D	4.23	D
	A Milt Birmingh		3 Hickory Flat Rd	City Limit	1.67 2		U	5706	3	45	11.8 0.0 0.0		3.5	N	S	0.0	0	0	0.0	3	4.02	D	4.17	D
	3 Milt Birmingh		3 Hickory Flat Rd	City Limit	1.67 2		U	5706	3	45	11.8 0.0 0.0		3.5	N	S	0.0	0	0	0.0	3	4.02	D	4.17	D
	A Milt Birmingh		Hickory Flat Rd	Freemanville	0.76 2		U	13602	3	45	10.4 0.0 0.0		4.0	N	S	2.0	0	0	5.0	3	4.45	D	4.80	E
	B Milt Birmingh		Hickory Flat Rd	Freemanville	0.76 2		U	13602	3	45	10.4 0.0 0.0		4.0	N	S	2.0	0	0	5.0	3	4.45	D	4.80	E _
	A Milt Birmingh		Freemanville	Cogburn	1.99 2	-	U	12190	3	45	10.4 0.0 0.0		4.0	N	S	2.0	0	0	5.0	3	4.39	D	4.71	E
	B Milt Birmingh		Freemanville	Cogburn	1.99 2		U	12190	3	45	10.4 0.0 0.0		4.0	N	S	2.0	0	0	5.0	3	4.39	D	4.71	E
	A Milt Cogburn		Hopewell Plantation Dr	Webb Rd	0.12 2	_	U	3790	2	35	13.3 2.9 0.0		3.5	N	S	0.0	0	0	0.0	2	3.22	C	3.54	D
	B Milt Cogburn		Hopewell Plantation Dr	Webb Rd	0.12 2		U	3790	2	35	13.3 2.9 0.0		3.5	N	S	0.0	0	0	0.0	2	3.22	C	3.54	D
	A Milt Cogburn		Webb Rd	Bethany	1.43 2	_	-	11054	3	40	10.1 0.0 0.0		5.0	N	S	2.0	0	40	5.0	3	4.13	D	3.91	D
	B Milt Cogburn		Webb Rd	Bethany	1.43 2	-	U	11054	3	40	10.1 0.0 0.0		5.0	N	S	2.0	0	40	5.0	3	4.13	D	3.91	D
	A Milt Cogburn		Bethany	Francis	1.35 2	_	U	14190	3	40	10.9 0.0 0.0		5.0	N	S	0.0	0	0	0.0	3	4.17	D	4.60	E
93.2	B Milt Cogburn	Rd	Bethany	Francis	1.35 2	1	U	14190	3	40	10.9 0.0 0.0	0	5.0	N	S	0.0	0	0	0.0	3	4.17	D	4.60	E

											Width			Bike			Tree							
					Len-	.		-		Post.	Of	Occ.		Lane/	_	Buff.	Spcg.	%	Swalk	Road		ycle	Pedes	
Segment ID ID	City	Road Name	From	То	gth (mi)	Lanes Th	(L) Dir Con	Roadway	Tks. (HV)	Spd. (SPp)	Pavement Wt WI W _{ps}	Park. (OSPA)	Pavecon PCt	Pavd. Shidr.	Cross Sec.	Width (BW)	in Buffer	with Sidewalk	Width (Ws)	Profile Cond	LC Score	OS Grade	LO Value	OS Grade
					(,		#	ADT	(%)	mph	(ft) (ft) (ft)	(%)	(15)	(Y/N)	(C/S)	(ft)	(ft/ctr)	(DIR)	(ft)	(1,2,3)	(17)	(AF)	(17)	(AF)
94.0	A Milt Cox R	Rd	Arnold Mill Road	King	0.69	2	1 U	12520	3	40	12.5 0.0 0.0	0	4.5	Ν	S	15.0	0	75	5.0	3	3.98	D	3.06	С
94.0	B Milt Cox R	Rd	Arnold Mill Road	King	0.69	2	1 U	12520	3	40	12.5 0.0 0.0	0	4.5	Ν	S	15.0	0	0	5.0	3	3.98	D	4.33	D
97.0	A Milt Deerfie	ield Pkwy	Windward Parkwy	Webb	0.97	4	2 D	9656	5 2	35	11.8 0.0 0.0	0	4.5	Y	С	5.0	40	1	5.0	2	3.42	С	3.87	D
97.0	B Milt Deerfie	ield Pkwy	Windward Parkwy	Webb	0.97	4	2 D	9656	5 2	35	11.8 0.0 0.0	0	4.5	Y	С	5.0	40	100	5.0	2	3.42	С	2.08	в
97.1	A Milt Deerfie	ield Pkwy	Webb	Highway 9	0.76	4	2 D	4346	5 2	35	11.8 0.0 0.0	0	4.5	Ν	С	2.0	0	80	5.0	2	2.23	В	2.58	С
97.1	B Milt Deerfie	ield Pkwy	Webb	Highway 9	0.76	4	2 D	4346	5 2	35	11.8 0.0 0.0	0	4.5	Ν	С	2.0	0	80	5.0	2	2.23	В	2.58	С
98.0	A Milt Francis	is Rd	Cogburn	City Line	1.57	2	1 U	5734	4 3	40	11.7 0.0 0.0	0	4.0	Y	s	2.0	0	50	5.0	2	3.79	D	3.32	С
98.0	B Milt Francis	is Rd	Cogburn	City Line	1.57	2	1 U	5734	4 3	40	11.7 0.0 0.0	0	4.0	Y	S	2.0	0	100	5.0	2	3.79	D	2.63	С
99.0	A Milt Freem	nanville Rd	Mayfield Road	Providence	1.78	2	1 U	2506	₅ 3	40	11.0 0.0 0.0	0	3.5	Ν	S	0.0	0	0	0.0	3	3.07	С	3.51	D
99.0	B Milt Freem	nanville Rd	Mayfield Road	Providence	1.78	2	1 U	2506	5 3	40	11.0 0.0 0.0	0	3.5	Ν	S	0.0	0	0	0.0	3	3.07	С	3.51	D
99.1	A Milt Freem	nanville Rd	Providence(N)	Birmingham	3.51	2	1 U	2960) <u>3</u>	45	10.4 0.0 0.0	0	3.0	Ν	S	0.0	0	0	0.0	2	3.70	D	3.88	D
99.1	B Milt Freem	nanville Rd	Providence(N)	Birmingham	3.51	2	1 U	2960) <u>3</u>	45	10.4 0.0 0.0	0	3.0	Ν	S	0.0	0	0	0.0	2	3.70	D	3.88	D
100.0	A Milt Georgi	jia Highway 9	Windward	Deerfield Parkway	1.09	2	1 U	19644	4 6	45	12.0 0.0 0.0	0	5.0	Y	С	2.0	0	100	6.0	2	5.10	E	3.53	D
	B Milt Georgi		Windward	Deerfield Parkway	1.09	2	1 U	19644	4 6	45	12.0 0.0 0.0	0	5.0	Y	С	2.0	0	90	6.0	2	5.10	E	3.67	D
100.1	A Milt Georgi	jia Highway 9	Deerfield Parkway	Bethany Bend	0.83	2	1 U	19832	2 6	45	12.8 0.0 0.0	0	5.0	N	С	2.0	0	50	5.0	2	5.01	E	4.26	D
	B Milt Georgi		Deerfield Parkway	Bethany Bend	0.83	2	1 U	19832	2 6	45	12.8 0.0 0.0	0	5.0	Ν	С	2.0	0	50	5.0	2	5.01	Е	4.26	D
100.2	A Milt Georgi	jia Highway 9	Bethany Bend	County Line	1.12	2	1 U	17036	5 5	45	13.0 0.0 0.0	0	5.0	Y	С	2.0	0	50	5.0	3	4.62	E	4.08	D
	B Milt Georgi		Bethany Bend	County Line	1.12	2	1 U	17036		45	13.0 0.0 0.0	0	5.0	Y	С	2.0	0	100	5.0	3	4.62	Е	3.43	С
101.0	A Milt Hamby	y Rd	Horrewell	County Line	1.26	2	1 U	10026	5 3	45	10.7 0.0 0.0	0	4.0	N	S	0.0	0	0	0.0	2	4.27	D	4.55	E
	B Milt Hamby		Horrewell	County Line	1.26	2	1 U	10026	5 3	45	10.7 0.0 0.0	0	4.0	Ν	S	0.0	0	0	0.0	2	4.27	D	4.55	Е
	A Milt Haygo		Bethany	Redd	0.50	2	1 U	4490) <u>6</u>	40	11.5 0.0 0.0	0	3.5	N	S	0.0	0	0	0.0	2	4.66	E	3.96	D
102.0	B Milt Haygo	ood Rd	Bethany	Redd	0.50	2	1 U	4490	6	40	11.5 0.0 0.0	0	3.5	Ν	S	0.0	0	0	0.0	2	4.66	E	3.96	D
	A Milt Hickor	ry Flat Rd	Birmingham Highway	City Limit	1.32	2	1 U	10410) 3	45	10.7 0.0 0.0	0	3.0	N	s	0.0	0	0	0.0	3	4.61	E	4.58	E
103.0			Birmingham Highway	City Limit	1.32	2	1 U	10410) 3	45	10.7 0.0 0.0	0	3.0	Ν	S	0.0	0	0	0.0	3	4.61	E	4.58	E
	A Milt Hopew		Redd	City Limit	2.24	2	1 U	8792	-	45	10.2 0.0 0.0	0	3.5	N	S	0.0	0	0	0.0	3	4.40	D	4.54	E
	B Milt Hopew		Redd	City Limit	2.24	2	1 U	8792	-	45	10.2 0.0 0.0	0	3.5	Ν	S	0.0	0	0	0.0	3	4.40	D	4.54	Е
	A Milt Hopew		Francis	Redd	1.44	2	1 U	8704	-	45	9.9 0.0 0.0	0	4.0	N	S	0.0	0	0	0.0	3	4.27	D	4.56	Е
	B Milt Hopew		Francis	Redd	1.44	2	1 U	8704		45	9.9 0.0 0.0	0	4.0	Ν	S	0.0	0	0	0.0	3	4.27	D	4.56	Е
	A Milt Hopew		Francis	County Line	4.04	2	1 U	10244		45	10.2 0.0 0.0	0	5.0	N	s	0.0	0	0	0.0	3	4.17	D	4.63	Е
	B Milt Hopew		Francis	County Line	4.04	2	1 U	10244	-	45	10.2 0.0 0.0	0	5.0	N	S	0.0	0	0	0.0	3	4.17	D	4.63	Е
	A Milt Hopew		Vaughn Drive	Southfield Ln	0.22	2	1 U	7648	-	45	10.1 0.0 0.0	0	3.5	N	S	2.0	0	23	5.0	3	4.34	D	4.13	D
	B Milt Hopew		Vaughn Drive	Southfield Ln		2	1 U	7648	•	45	10.1 0.0 0.0	0	3.5	N	S	2.0	0	0	5.0	3	4.34	D	4.48	D
	A Milt N Mair		Winthrope Chase Dr	Cogburn Rd			1 U	27088	-	45	13.4 0.0 0.0	0	3.5	N	С	2.0	0	57	5.0	1	4.84	Е	4.56	E
	B Milt N Mair		Winthrope Chase Dr	Cogburn Rd	0.37		1 U	27088		45	13.4 0.0 0.0	0	3.5	N	C	2.0	0	0	5.0	1	4.84	E	5.28	E
		Bull Pen Rd (W)	City Limit	Birmingham Highway	0.79	2	1 U	6886		40	10.3 0.0 0.0	0	3.2	N	S	0.0	0	0	0.0	3	4.27	D	4.24	D
		Bull Pen Rd (W)	City Limit	Birmingham Highway	0.79	2	1 U	6886	-	40	10.3 0.0 0.0	0	3.2	N	S	0.0	0	0	0.0	3	4.27	D	4.24	D
	A Milt New P		Birmingham Highway	Arnold Mill Raod	3.64	2	1 U	3062	_	45	10.2 0.0 0.0	0	4.0	N	S	0.0	0	0	0.0	2	4.48	D	3.93	D
	B Milt New P		Birmingham Highway	Arnold Mill Raod	3.64	2	1 U	3062		45	10.2 0.0 0.0	0	4.0	Ν	S	0.0	0	0	0.0	2	4.48	D	3.93	D
	A Milt Provide		Burmingham	Freemanville			1 U	3464		45	11.8 0.0 0.0	0	4.0	N	S	0.0	0	0	0.0	3	4.45	D	3.87	D
	B Milt Provide		Burmingham	Freemanville			1 U	3464		45	11.8 0.0 0.0	0	4.0	N	S	0.0	0	0	0.0	3	4.45	D	3.87	D
	A Milt Provide		Freemanville	Bethany (W)	1.00		1 U	6558		45	11.4 0.0 0.0	0	4.0	N	C	2.0	0	60	5.0	3	3.97	D	3.42	c
	B Milt Provide		Freemanville	Bethany (W)	1.00		1 U	6558	-	45	11.4 0.0 0.0	0	4.0	N	C	2.0	0	20	5.0	3	3.97	D	3.98	D
	A Milt Provide		Bethany	Citt Limit (N)			1 U	3376	-	45	11.8 0.0 0.0	0	3.5	N	S	0.0	0	0	0.0	3	3.50	c	3.85	D
	B Milt Provide		Bethany	Citt Limit (N)	1.26	2	1 U	3376		45	11.8 0.0 0.0	0	3.5	N	s	0.0	0	0	0.0	3	3.50	c	3.85	D
	A Milt Red R			Hopewell			1 U	5838		45	10.5 0.0 0.0	0	4.0	N	S	0.0	0	0	0.0	3	4.02	D	4.33	D
	B Milt Red R		Haygood		0.13		1 U		-	45	10.5 0.0 0.0	0		N	s	0.0	0	0	0.0	3	4.02	D	4.33	D
	A Milt Alphar		E Crossville Rd	Hopewell	2.07		2 LT	5838		45	12.5 0.0 0.0	0	4.0	Y	C	2.0	0	100	5.0	2	4.02	E	3.65	D
	B Ros Alphar		E Crossville Rd	Hembree Rd	2.07		2 LT	30780		45	12.5 0.0 0.0 12.5 0.0 0.0	0	3.5	Y	c	2.0	0	100	5.0	2	4.82	E	3.65	D
	A Ros Alphan			Hembree Rd	1.44		2 LT	30780		40	12.5 0.0 0.0 12.5 0.0 0.0	0	3.5	Y	s	1.1	0	100	5.0	2	4.02	E	3.05	D
			Canton Street	Holcomb Bridge	1.44		2 LT 2 LT	36904	•	40	12.5 0.0 0.0 12.5 0.0 0.0	0	3.5	Y	S	1.1	0	95	5.0	2	4.78	E	3.83	D
	B Ros Alphare		Canton Street	Holcomb Bridge			2 LI 1 U	36904				0	3.5	Y			0						3.83	
121.0	A Ros Arnold		Crabapple Road	Milton City Limit	0.24	2	ı U	17338	5	35	12.0 0.0 0.0	U	3.5	Y	С	2.0	U	100	5.0	2	4.80	E	ა.15	С

											. <u></u>		Width	h			Bike			Tree							<u> </u>
					Len-				_		Post.		Of		Occ.		Lane/		Buff.	Spcg.	%	Swalk	Road	Bicy		Pedes	
Segment ID ID	City	Road Name	From	То	gth (mi)		es (L) Dir	Con	Roadway	Tks. (HV)	Spd. (SPp)	Wt	Paveme WI		Park. (OSPA)	Pavecon PCt	Pavd. Shidr.	Cross Sec.	Width (BW)	in Buffer	with Sidewalk	Width (Ws)	Profile Cond	LO Score	OS Grade	LO Value)S Grade
10					(111)	#		COIL	ADT	(%)	mph	(ft)			(%)	(15)	(Y/N)	(C/S)	(BVV) (ft)	(ft/ctr)	(DIR)	(tvs) (ft)	(1,2,3)	(17)	(AF)	(17)	(AF)
121.0 B	Ros	Arnold Mill Rd	Crabapple Road	Milton City Limit	0.24	2	1	U	17338	5	35	12.0	0.0	0.0	0	3.5	Y	С	2.0	0	100	5.0	2	4.80	E	3.15	С
123.0 A	Ros	Canton St	Elizabeth Lane	Woodstock Road	0.22	2	1	U	8780	2	25	11.6	0.0	0.0	0	3.5	Y	С	2.0	0	100	5.0	2	3.50	С	2.42	в
123.0 B	Ros	Canton St	Elizabeth Lane	Woodstock Road	0.22	2	1	U	8780	2	25	11.6	0.0	0.0	0	3.5	Y	С	2.0	0	100	5.0	2	3.50	с	2.42	В
124.0 A	Ros	Canton St	Woodstock Road	Pine Grove	0.55	2	1	U	13380	3	25	16.1	0.0	0.0	0	4.0	Y	С	1.5	0	100	5.0	2	3.05	С	2.57	С
124.0 B	Ros	Canton St	Woodstock Road	Pine Grove	0.55	2	1	U	13380	3	25	16.1	0.0	0.0	0	4.0	Y	С	1.5	0	100	5.0	2	3.05	С	2.57	С
125.0 A	Ros	Coleman Rd	Willeo Rd	Willeo Rd	0.22	2	1	U	11844	2	35	11.6	0.0	0.0	0	4.0	Ν	С	2.0	0	0	5.0	2	3.85	D	4.24	D
125.0 B	Ros	Coleman Rd	Willeo Rd	Willeo Rd	0.22	2	1	U	11844	2	35	11.6	0.0	0.0	0	4.0	Ν	С	2.0	0	0	5.0	2	3.85	D	4.24	D
127.0 A	Ros	Cox Rd	King Road	City Limit	2.54	2	1	U	7636	3	40	12.2	0.0	0.0	0	4.5	Ν	s	1.0	0	40	9.0	3	3.77	D	3.45	С
127.0 B	Ros	Cox Rd	King Road	City Limit	2.54	2	1	U	7636	3	40	12.2	0.0	0.0	0	4.5	Ν	S	1.0	0	0	9.0	3	3.77	D	4.07	D
128.0 A	Ros	Crabapple Rd	Canton Street	Elizabeth Lane	0.11	2	1	U	8780	2	35	10.5	0.0	0.0	0	4.5	Y	С	2.0	0	100	4.0	3	3.72	D	2.82	с
128.0 B	Ros	Crabapple Rd	Canton Street	Elizabeth Lane	0.11	2	1	U	8780	2	35	10.5	0.0	0.0	0	4.5	Y	С	2.0	0	0	4.0	3	3.72	D	4.18	D
128.1 A	Ros	Crabapple Rd	Elizabeth Lane	Crossville Road	0.83	2	1	U	10872	2	35	11.5	0.0	0.0	0	4.0	Υ	С	2.0	0	100	4.0	2	3.82	D	2.91	с
128.1 B	Ros	Crabapple Rd	Elizabeth Lane	Crossville Road	0.83	2	1	U	10872	2	35	11.5	0.0	0.0	0	4.0	Υ	С	2.0	0	100	4.0	2	3.82	D	2.91	С
128.2 A	Ros	Crabapple Rd	Hembree Road	Crossville Road	0.91	2	1	U	19700	3	40	11.0	0.0	0.0	0	3.5	Y	С	2.0	0	100	4.0	1	4.65	E	3.61	D
128.2 B	Ros	Crabapple Rd	Hembree Road	Crossville Road	0.91	2	1	U	19700	3	40	11.0	0.0	0.0	0	3.5	Y	С	2.0	0	100	4.0	1	4.65	E	3.61	D
128.3 A	Ros	Crabapple Rd	Hembree Road	Etris Road	0.81	2	1	U	13122	3	40	11.0	0.0	0.0	0	4.5	Y	С	2.0	0	100	5.0	3	4.18	D	3.09	С
128.3 B	Ros	Crabapple Rd	Hembree Road	Etris Road	0.81	2	1	U	13122	3	40	11.0	0.0	0.0	0	4.5	Y	С	2.0	0	50	5.0	3	4.18	D	3.81	D
128.5 A	Ros	Crabapple Rd	Arnold Mill	Rucker Road	0.32	2	1	U	13554	3	40	10.5	0.0	0.0	0	4.0	Ν	С	5.0	0	50	5.0	3	4.35	D	3.82	D
		Crabapple Rd	Arnold Mill	Rucker Road	0.32	2	1	U	13554	3	40	10.5	0.0	0.0	0	4.0	Ν	С	5.0	0	50	5.0	3	4.35	D	3.82	D
		E Crossville Rd	Crabapple Road	Alpharetta Street	1.29	6	3	D	38752	2	45	12.0	0.0	0.0	0	3.5	Y	С	2.0	0	100	4.0	2	4.26	D	3.49	С
129.0 B	Ros	E Crossville Rd	Crabapple Road	Alpharetta Street	1.29	6	3	D	38752	2	45	12.0	0.0	0.0	0	3.5	Y	С	2.0	0	100	4.0	2	4.26	D	3.49	С
130.0 A	Ros	Etris Rd	Hardscrabble	Crabapple	0.23	2	1	U	4554	3	45	14.0	2.0	0.0	0	4.5	Y	С	2.0	0	100	5.0	2	3.36	С	2.65	С
130.0 B	Ros	Etris Rd	Hardscrabble	Crabapple	0.23	2	1	U	4554	3	45	14.0	2.0	0.0	0	4.5	Y	С	2.0	0	100	5.0	2	3.36	С	2.65	С
131.0 A	Ros	Etris Rd	Hardscrabble	Сох	1.52	2	1	U	4800	3	45	11.0	0.0	0.0	0	4.0	Ν	С	2.0	0	20	5.0	2	3.87	D	3.91	D
131.0 B	Ros	Etris Rd	Hardscrabble	Сох	1.52	2	1	U	4800	3	45	11.0	0.0	0.0	0	4.0	Ν	С	2.0	0	75	5.0	2	3.87	D	3.12	С
		Georgia Highway 9	Hembree Rd	Upper Hembree Rd	0.54	4	2	LT	31950	4	45	12.2	0.0	0.0	0	3.5	Ν	С	2.0	0	94	5.0	1	4.88	E	3.79	D
		Georgia Highway 9	Hembree Rd	Upper Hembree Rd	0.54	4	2	LT	31950	4	45	12.2	0.0	0.0	0	3.5	Ν	С	2.0	0	94	5.0	1	4.88	E	3.79	D
		Hardscrabble Rd	Woodstock Road	King Road	0.79	2	1	U	16162	3	40	10.8		0.0	0	3.5	N	S	0.0	0	0	0.0	3	4.56	E	4.73	E
133.0 B	Ros	Hardscrabble Rd	Woodstock Road	King Road	0.79	2	1	U	16162	3	40	10.8	-	0.0	0	3.5	Ν	S	0.0	0	0	0.0	3	4.56	E	4.73	E
133.1 A	Ros	Hardscrabble Rd	King Road	Etris Road	1.27	2	1	U	16090	3	40	11.5			0	4.5	N	С	2.0	0	50	5.0	3	4.23	D	3.96	D
		Hardscrabble Rd	King Road	Etris Road	1.27	2	1	U	16090	3	40	11.5			0	4.5	Ν	С	2.0	0	20	5.0	3	4.23	D	4.38	D
		Hardscrabble Rd	Etris Road	Crabapple	0.39	2	1	U	23468	4	40			0.0	0	4.0	N	С	2.0	0	50	5.0	2	4.81	E	4.42	D
		Hardscrabble Rd	Etris Road	Crabapple	0.39	2	1	U	23468	4	40			0.0	0	4.0	Ν	С	2.0	0	0	5.0	2	4.81	E	5.14	E
		Hembree Rd	Crabapple Road	Houze Road	0.84	2	1	U	14344	2	35	-	1.5		0	4.0	Y	С	2.0	0	0	4.0	2	3.90	D	4.35	D
		Hembree Rd	Crabapple Road	Houze Road	0.84	2	1	U	14344	2	35			0.0	0	4.0	Y	С	2.0	0	100	4.0	2	3.90	D	3.10	С
		Hembree Rd	Houze Road	Elkins Road	0.68	2	1	U	16564	3	40		0.0		0	5.0	Ν	С	2.0	0	50	5.0	2	4.19	D	3.98	D
		Hembree Rd	Houze Road	Elkins Road	0.68	2	1	U	16564	3	40		0.0		0	5.0	Ν	С	2.0	0	50	5.0	2	4.19	D	3.98	D
		Hembree Rd	Elkins Road	Alpharetta Hwy[Hwy 9]	0.58	2	1	U	15516	3	40		0.0		0	5.0	Y	С	2.0	0	0	5.0	2	4.03	D	4.51	E
		Hembree Rd	Elkins Road	Alpharetta Hwy[Hwy 9]	0.58	2	1	U	15516	3	40			0.0	0	5.0	Y	С	2.0	0	100	5.0	2	4.03	D	3.18	С
		Hembree Rd	Alpharetta Hwy[Hwy 9]	Old Roswell	0.92	4	2	LT	13118	3	45	-		0.0	0	4.0	Y	С	2.0	0	100	4.0	1	4.21	D	3.13	С
		Hembree Rd	Alpharetta Hwy[Hwy 9]	Old Roswell	0.92	4	2	LT	13118	3	45			0.0	0	4.0	Y	С	2.0	0	100	4.0	1	4.21	D	3.13	С
		Holcomb Bridge Rd	Alpharetta Street[Hwy 9]	Hwy 400	1.52	6	3	D	47346	2	45		0.0		0	4.0	N	С	2.0	0	75	4.0	2	4.21	D	4.00	D
		Holcomb Bridge Rd	Alpharetta Street[Hwy 9]	Hwy 400	1.52	6	3	D	47346	2	45		0.0		0	4.0	N	С	2.0	0	75	4.0	2	4.21	D	4.00	D
		Holcomb Bridge Rd	Hwy 400	Old Alabama	0.40	4	2	D	65310	4	45		0.0		0	4.0	Y	С	2.0	0	100	4.0	2	5.11	E	5.16	E
		Holcomb Bridge Rd	Hwy 400	Old Alabama	0.40	4	2	D	65310	4	45	-	0.0	-	0	4.0	Y	С	2.0	0	100	4.0	2	5.11	E	5.16	E
		Holcomb Bridge Rd	Old Alabama	Calibre Creek Pkwy	0.96	4	2	LT	39886	4	45	12.2	_		0	4.5	N	С	2.0	0	75	4.0	3	4.74	E	4.45	D
		Holcomb Bridge Rd	Old Alabama	Calibre Creek Pkwy	0.96	4	2	LT	39886	4	45	-	0.0		0	4.5	N	С	2.0	0	50	4.0	3	4.74	E	4.76	E
-		Holcomb Bridge Rd	Calibre Creek Pkwy	Fouts Road	0.91	4	2	U	41236	4	45	-	0.0		0	4.0	N	С	2.0	0	75	5.0	2	4.87	E	4.43	D
		Holcomb Bridge Rd	Calibre Creek Pkwy	Fouts Road	0.91	4	2	U	41236	4	45			0.0	0	4.0	N	С	2.0	0	0	5.0	2	4.87	E	5.45	E
		Holcomb Bridge Rd	Fouts Road	Nesbit Ferry	1.60	4	2	U	38200	4	45			0.0	0	4.5	N	С	2.0	0	30	4.0	2	4.74	E	4.96	E
136.4 B	Ros	Holcomb Bridge Rd	Fouts Road	Nesbit Ferry	1.60	4	2	U	38200	4	45	12.0	0.0	0.0	0	4.5	Ν	С	2.0	0	30	4.0	2	4.74	E	4.96	E

												Width				Bike			Tree							
					Len-			_		Post.		Of		Occ.		Lane/		Buff.	Spcg.	%	Swalk	Road	Bicy		Pedes	
Segment ID ID	City	Road Name	From	То	gth (mi)	Lanes (I Th D		Roadway	Tks. (HV)	Spd. (SPp)	F Wt	avemei Wl		Park. (OSPA)	Pavecon PCt	Pavd. Shidr.	Cross	Width (BW)	in Buffer	with Sidewalk	Width (Ws)	Profile Cond	LC Score	OS Grade	LO: Value	OS Grade
					(111)	# #		ADT	(%)	mph	(ft)	(ft)	W _{ps} (ft)	(03FA) (%)	(15)	(Y/N)	Sec. (C/S)	(BVV) (ft)	(ft/ctr)	(DIR)	(VVS) (ft)	(1,2,3)	(17)	(AF)	(17)	(AF)
136.5 A	Ros	Holcomb Bridge Rd	Nesbit Ferry	Chattahoochee River County Line	1.27	4 2	2 U	48320	4	45	13.4	1.5	0.0	0	4.5	N	С	5.0	0	25	5.0	1	4.68	E	5.25	E
		Holcomb Bridge Rd	Nesbit Ferry	Chattahoochee River County Line	1.27	4 2	2 U	48320	4	45	13.4	1.5	0.0	0	4.5	N	С	5.0	0	52	5.0	1	4.68	Е	4.89	Е
		Houze Rd	Mansell	White Hall Way	0.68	2 .	I U	15832	2	35	12.0	0.0	0.0	0	3.5	Y	С	2.0	0	0	5.0	3	4.10	D	4.44	D
		Houze Rd	Mansell	White Hall Way	0.68	2 1	I U	15832	2	35	12.0	0.0	0.0	0	3.5	Y	С	2.0	0	100	5.0	3	4.10	D	3.06	С
137.1 A	Ros	Houze Rd	White Hall Way	Rucker	1.87	2 .	I U	15904	2	35	12.5	0.0	0.0	0	3.5	N	S	0.0	0	0	0.0	3	4.04	D	4.39	D
137.1 B	Ros	Houze Rd	White Hall Way	Rucker	1.87	2 1	I U	15904	2	35	12.5	0.0	0.0	0	3.5	N	S	0.0	0	0	0.0	3	4.04	D	4.39	D
137.2 A	Ros	Houze Rd	Rucker	Crabapple	0.32	2 .	I U	19982	5	35	12.0	0.0	0.0	0	3.5	N	С	2.0	0	25	5.0	2	4.87	Е	4.34	D
137.2 B	Ros	Houze Rd	Rucker	Crabapple	0.32	2 1	I U	19982	5	35	12.0	0.0	0.0	0	3.5	N	С	2.0	0	50	5.0	2	4.87	Е	4.00	D
138.0 A	Ros	King Rd	Woodstock Road	Hardscrabble	0.40	2 .	I LT	10712	2	35	12.0	0.0	0.0	0	4.5	Y	С	0.0	0	100	6.0	2	3.66	D	2.74	с
138.0 B	Ros	King Rd	Woodstock Road	Hardscrabble	0.40	2 1	I LT	10712	2	35	12.0	0.0	0.0	0	4.5	Y	С	0.0	0	100	6.0	2	3.66	D	2.74	С
138.1 A			Hardscrabble	King Circle	0.86	2 .	I U	4694	2	35	12.5	0.0	0.0	0	5.0	Y	С	2.0	0	0	4.0	1	3.11	с	3.71	D
138.1 B	Ros	King Rd	Hardscrabble	King Circle	0.86	2 1	I U	4694	2	35	12.5	0.0	0.0	0	5.0	Y	С	2.0	0	100	4.0	1	3.11	С	2.50	в
138.2 A			King Circle	Cox Road	0.94	2 '	I U	4726	3	40	11.5	0.0	0.0	0	4.0	N	S	0.0	0	0	0.0	3	3.71	D	3.97	D
138.2 B	Ros	King Rd	King Circle	Cox Road	0.94	2 1	I U	4726	3	40	11.5	0.0	0.0	0	4.0	N	S	0.0	0	0	0.0	3	3.71	D	3.97	D
139.0 A	Ros	Magnolia St	Atlanta Street	Coleman Road	0.36	2 '	I U	30560	3	35	12.5	0.0	0.0	0	4.0	Y	С	2.0	0	100	4.0	2	4.42	D	4.04	D
139.0 B	Ros	Magnolia St	Atlanta Street	Coleman Road	0.36	2 1	I U	30560	3	35	12.5	0.0	0.0	0	4.0	Y	С	2.0	0	90	4.0	2	4.42	D	4.17	D
140.0 A	Ros	Mansell Rd	Houze Road	Old Roswell	1.13	4 2	2 LT	30576	4	40	11.5	0.0	0.0	0	4.0	Y	С	2.0	0	75	4.0	2	4.69	Е	3.94	D
140.0 B	Ros	Mansell Rd	Houze Road	Old Roswell	1.13	4 2	2 LT	30576	4	40	11.5	0.0	0.0	0	4.0	Y	С	2.0	0	100	4.0	2	4.69	Е	3.62	D
141.0 A	Ros	Marietta Hwy	N Atlanta St	City Limit	2.01	4 :	2 D	21568	4	45	13.0	0.0	0.0	0	4.5	N	C/S	2.0	0	18	5.0	2	4.32	D	4.34	D
141.0 B	Ros	Marietta Hwy	N Atlanta St	City Limit	2.01	4 2	2 D	21568	4	45	13.0	0.0	0.0	0	4.5	N	C/S	2.0	0	12	5.0	2	4.32	D	4.41	D
144.0 A	Ros	Mountain Park Rd	Woodstock Road	Wildwood Spring	0.89	2	U	4912	2	35	10.0	0.0	0.0	0	3.0	N	S	10.0	0	25	5.0	3	3.92	D	3.57	D
144.0 B	Ros	Mountain Park Rd	Woodstock Road	Wildwood Spring	0.89	2 1	U	4912	2	35	10.0	0.0	0.0	0	3.0	N	S	10.0	0	0	5.0	3	3.92	D	4.01	D
144.1 A	Ros	Mountain Park Rd	Wildwood Spring	City Limit	0.55	2 '	U	4546	2	35	10.5	0.0	0.0	0	4.0	Y	С	2.0	0	50	5.0	3	3.49	С	3.18	С
144.1 B	Ros	Mountain Park Rd	Wildwood Spring	City Limit	0.55	2 1	U	4546	2	35	10.5	0.0	0.0	0	4.0	Y	С	2.0	0	100	5.0	3	3.49	С	2.44	В
145.0 A	Ros	N Atlanta St	Marietta Hwy	Magnolia St	0.63	4 2	2 U	25652	3	35	10.3	0.0	0.0	0	3.0	Y	S	0.0	0	100	5.0	3	4.71	Е	3.27	С
145.0 B	Ros	N Atlanta St	Marietta Hwy	Magnolia St	0.63	4 2	2 U	25652	3	35	10.3	0.0	0.0	0	3.0	Y	S	0.0	0	38	5.0	3	4.71	Е	4.15	D
146.0 A	Ros	Norcross St	Alpharetta Hwy	Canton St	0.06	2 .	U	2000	4	25	11.3	0.0	0.0	0	3.5	Y	С	0.0	0	67	5.0	2	2.27	В	2.54	с
146.0 B	Ros	Norcross St	Alpharetta Hwy	Canton St	0.06	2 1	U	2000	4	25	11.3	0.0	0.0	0	3.5	Y	С	0.0	0	100	5.0	2	2.27	в	2.09	в
147.0 A	Ros	Norcross St	Alpharetta Street[Hwy 9]	Grimes Bridge Road	0.92	2 .	U	13740	2	35	13.0	2.5	0.0	0	4.0	Ν	S	2.0	0	40	5.0	2	3.75	D	3.69	D
147.0 B	Ros	Norcross St	Alpharetta Street[Hwy 9]	Grimes Bridge Road	0.92	2 1	U	13740	2	35	13.0	2.5	0.0	0	4.0	Ν	S	2.0	0	90	5.0	2	3.75	D	3.04	с
148.0 A	Ros	Old Alabama Conn	Old Alabama	City Limit	0.59	2 1	U	14278	6	45	11.8	0.0	0.0	0	4.0	N	С	2.0	0	25	5.0	1	5.12	E	4.34	D
		Old Alabama Conn	Old Alabama	City Limit	0.59	2 1	U	14278	6	45	11.8	0.0	0.0	0	4.0	N	С	2.0	0	50	5.0	1	5.12	E	3.99	D
		Old Alabama Rd	Riverside Road	Market Blvd	0.72	4 2	2 U	8536	2	35	15.5	4.5	0.0	0	4.5	Y	С	2.0	0	100	5.5	3	2.05	В	2.31	В
		Old Alabama Rd	Riverside Road	Market Blvd	0.72	4 2	2 U	8536	2	35	14.8	3.5	0.0	0	4.5	Y	С	5.5	0	100	10.0	3	2.37	В	2.06	В
149.1 A	Ros	Old Alabama Rd	Market Blvd	Holcombe Bridge Road	0.45	4 ;	2 U	8554	2	35	12.8	1.6	0.0	0	4.5	Y	С	2.0	0	100	5.5	3	3.23	С	2.38	В
		Old Alabama Rd	Market Blvd	Holcombe Bridge Road	0.45	4 2	2 U	8554	2	35	12.8	1.6	0.0	0	4.5	Y	С	2.0	0	90	5.5	3	3.23	С	2.52	С
		Old Alabama Rd	Holcombe Bridge Road	Old Alabama Conn	1.77	2	LT	17244	2	40		0.0	0.0	0	3.5	Y	С	2.0	0	100	4.0	2	4.31	D	3.44	С
		Old Alabama Rd	Holcombe Bridge Road	Old Alabama Conn	1.77	2 1	LT	17244	2	40		0.0		0	3.5	Y	С	2.0	0	0	4.0	2	4.31	D	4.73	Е
		Old Alabama Rd	Old Alabama Conn	Nesbit Ferry	0.83	2 1	U	15746	2	40		0.0		0	4.5	N	С	2.0	0	75	5.0	3	3.94	D	3.56	D
		Old Alabama Rd	Old Alabama Conn	Nesbit Ferry	0.83	2 1	U	15746	2	40	12.0	0.0	0.0	0	4.5	N	С	2.0	0	25	5.0	3	3.94	D	4.25	D
		Old Roswell Rd	Commerce Pkwy	Warsaw Road	0.27	2 1	U	8026	2	35		0.0		0	3.5	Y	С	7.0	0	100	5.0	1	3.64	D	2.42	В
		Old Roswell Rd	Commerce Pkwy	Warsaw Road	0.27	2 1	U	8026	2	35	13.0	0.0	0.0	0	3.5	Y	С	7.0	0	25	5.0	1	3.64	D	3.51	D
151.1 A	Ros	Old Roswell Rd	Holcomb Bridge Road	Commerce Pkwy	0.44	2 1	U	11978	3	40	11.5	0.0	0.0	0	3.5	Y	С	3.0	0	100	4.0	1	4.34	D	3.08	С
		Old Roswell Rd	Holcomb Bridge Road	Commerce Pkwy	0.44	2 1	U	11978	3	40		0.0	0.0	0	3.5	Y	С	3.0	0	25	4.0	1	4.34	D	4.08	D
		Pine Grove Rd	County Line	High Tower	1.08	2 -	U	19082	2	35	11.7		0.0	0	3.5	N	S	2.0	0	25	5.0	3	4.24	D	4.32	D
		Pine Grove Rd	County Line	High Tower	1.08	2 1	U	19082	2	35	11.7	0.0	0.0	0	3.5	N	S	2.0	0	25	5.0	3	4.24	D	4.32	D
		Pine Grove Rd	High Tower	Lake Charles	0.43	2 1	U	12660	2	35	13.0	2.0	0.0	0	4.0	Y	С	2.0	0	100	4.0	2	3.71	D	2.96	С
		Pine Grove Rd	High Tower	Lake Charles	0.43	2 1	U	12660	2	35		2.0		0	4.0	Y	С	2.0	0	0	4.0	2	3.71	D	4.15	D
		Pine Grove Rd	Coleman Road	Lake Charles	0.74	2 1	U	12878	2	35				0	3.0	N	С	2.0	0	20	4.0	2	4.29	D	4.10	D
	-	Pine Grove Rd	Coleman Road	Lake Charles	0.74	2 1	U	12878	2	35		0.0	0.0	0	3.0	N	С	2.0	0	0	4.0	2	4.29	D	4.36	D
153.0 A	Ros	Riverside Rd	S. Atlanta	Riverside/Dogwood	1.05	2 1	U	12824	2	35	11.6	1.0	0.0	0	4.0	Ν	S	0.0	0	80	5.0	3	3.89	D	3.23	С

_	\square												Width				Bike			Tree				Г			
	Ē					Len-			_		Post.		Of		Occ.		Lane/		Buff.	Spcg.	%	Swalk	Road	Bicy		Pedes	
Segment ID ID	C	City	Road Name	From	То	-	anes (L) h Dir		Roadway	Tks. (HV)	Spd. (SPp)	Wt	Pavemer WI		Park. (OSPA)	Pavecon PCt	Pavd. Shidr.	Cross Sec.	Width (BW)	in Buffer	with Sidewalk	Width (Ws)	Profile Cond	LO	OS Grade	LO Value	OS Grade
	\square					. ,	t #		ADT	(%)	(SPP) mph	(ft)	_	W _{ps} (ft)	(%)	(15)	(Y/N)	(C/S)	(BVV) (ft)	(ft/ctr)	(DIR)	(VVS) (ft)	(1,2,3)	Score (17)	(AF)	(17)	(AF)
153.0	BF	Rive	erside Rd	S. Atlanta	Riverside/Dogwood	1.05	2 1	U	12824	2	35	11.6		0.0	0	4.0	N	s	0.0	0	0	5.0	3	3.89	D	4.29	D
		Rive		Riverside/Dogwood	Old Alabama	0.23	2 1	U	13008	2	35	14.7	3.8	0.0	0	4.5	N	S	0.0	0	0	5.0	2	2.76	с	4.02	D
			erside Rd	Riverside/Dogwood	Old Alabama	0.23	2 1	U	13008	2	35	14.7	3.8	0.0	0	4.5	N	S	0.0	0	50	5.0	2	2.76	С	3.45	С
		Ruck		Alpharetta City Limit	Hardscrabble Road	0.70	2 1	U	13888	2	35	12.0	0.0	0.0	0	4.0	Y	С	2.0	0	75	5.0	2	3.88	D	3.29	С
		Ruck		Alpharetta City Limit	Hardscrabble Road	0.70	2 1	U	13888	2	35	12.0	0.0	0.0	0	4.0	Y	С	2.0	0	100	5.0	2	3.88	D	2.95	С
		Ros S Atl		Riverside Rd	Marietta Hwy	1.15	2 1	LT	22498	3	35	12.4	0.0	0.0	0	5.0	N	С	0.0	0	53	5.0	3	4.12	D	4.12	D
		Ros S Atl		Riverside Rd	Marietta Hwy	1.15	2 1	LT	22498	3	35	12.4	0.0	0.0	0	5.0	N	С	0.0	0	0	5.0	3	4.12	D	4.79	Е
		Ros S Ma		Upper Hembree Rd	Haney Dr	0.15	1 2	LT	32826	4	45	12.4	0.0	0.0	0	3.5	N	С	2.0	0	40	5.0	2	4.87	Е	4.54	E
		Ros S Ma		Upper Hembree Rd	Haney Dr	0.15	1 2	LT	32826	4	45	12.4	0.0	0.0	0	3.5	N	С	2.0	0	33	5.0	2	4.87	Е	4.63	Е
			rossville Rd	King	Crabapple Road	1.52 (3	D	49338	2	45	12.0	0.0	0.0	0	4.0	Y	С	2.0	0	100	4.0	2	4.23	D	3.74	D
			rossville Rd	King	Crabapple Road	1.52	3 3	D	49338	2	45	12.0	0.0	0.0	0	4.0	Y	С	2.0	0	100	4.0	2	4.23	D	3.74	D
		Ros Wars		Grimes Bridge Road	Holcomb Bridge Road	0.58	2 1	U	10992	2	35	13.0	2.3	0.0	0	4.5	Y	С	0.0	0	0	4.0	2	3.54	D	4.05	D
		Ros Wars		Grimes Bridge Road	Holcomb Bridge Road	0.58	2 1	U	10992	2	35	13.0	2.3	0.0	0	4.5	Y	С	0.0	0	100	4.0	2	3.54	D	2.93	С
		Ros Wille		City Limit	Coleman Rd	0.77	2 1	U	11844	2	35	10.8	0.0	0.0	0	3.0	N	s	2.0	0	12	5.0	3	4.28	D	4.16	D
		Ros Wille		City Limit	Coleman Rd	0.77	2 1	U	11844	2	35	10.8	0.0	0.0	0	3.0	N	S	0.0	0	0	0.0	3	4.28	D	4.34	D
		Ros Wille		Coleman Rd	Marietta Hwy	0.68	2 1	U	10644	2	35	15.0	3.8	0.0	0	4.5	Y	С	2.0	0	0	5.0	1	2.60	С	3.85	D
		Ros Wille		Coleman Rd	Marietta Hwy	0.68	2 1	U	10644	2	35	15.0	3.8	0.0	0	4.5	Y	С	2.0	0	100	5.0	1	2.60	С	2.66	С
			odstock Rd	Alpharetta Street	Canton	0.32	2 1	U	17316	2	35	10.7	0.0	0.0	0	5.0	Y	С	0.0	0	100	5.0	2	3.99	D	3.28	с
			odstock Rd	Alpharetta Street	Canton	0.32	2 1	U	17316	2	35	10.7	0.0	0.0	0	5.0	Y	С	0.0	0	50	5.0	2	3.99	D	3.97	D
			odstock Rd	Canton	Roswell Area Park	0.51	2 1	U	8176	2	35	13.0	2.7	0.0	0	3.5	Y	s	1.5	0	100	4.0	2	3.65	D	2.71	с
			odstock Rd	Canton	Roswell Area Park	0.51	2 1	U	8176	2	35	13.0	2.7	0.0	0	3.5	Y	S	1.5	0	50	4.0	2	3.65	D	3.30	С
			odstock Rd	Roswell Area Park	Elizabeth Cove	0.43	2 1	U	6434	2	35	12.7	1.5	0.0	0	4.0	Y	С	2.0	0	100	5.0	2	3.42	с	2.48	в
			odstock Rd	Roswell Area Park	Elizabeth Cove	0.43	2 1	U	6434	2	35	12.7	1.5	0.0	0	4.0	Y	С	2.0	0	100	5.0	2	3.42	с	2.48	В
			odstock Rd	Elizabeth Cove	Woodstock Drive/ Crossville	1.45	2 1	U	7038	3	40	12.7	1.5	0.0	0	4.0	Y	С	2.0	0	100	5.0	2	3.76	D	2.66	с
			odstock Rd	Elizabeth Cove	Woodstock Drive/ Crossville	1.45	2 1	U	7038	3	40	12.7	1.5	0.0	0	4.0	Y	С	2.0	0	100	5.0	2	3.76	D	2.66	С
			odstock Rd	Cobb County Line	King	2.15 (3 3	D	50746	2	45	12.3	0.0	0.0	0	3.0	Y	С	2.0	0	100	4.0	2	4.54	E	3.76	D
			odstock Rd	Cobb County Line	King	2.15 6	6 3	D	50746	2	45	12.3	0.0	0.0	0	3.0	Y	С	2.0	0	100	4.0	2	4.54	Е	3.76	D
			rnathy Rd NE	Hwy 400	Mt. Vernon	0.22 6	3 3	D	54108	4	35	11.5	0.0	0.0	0	3.0	N	С	2.0	0	0	5.0	3	4.91	Е	4.83	Е
			mathy Rd NE	Hwy 400	Mt. Vernon	0.22 6	6 3	D	54108	4	35	11.5	0.0	0.0	0	3.0	N	С	2.0	0	0	5.0	3	4.91	Е	4.83	Е
			rnathy Rd NE	P. Tree Dunwoody	Mt. Vernon	0.12	1 2	D	41028	4	45	12.0	0.0	0.0	0	4.0	Y	с	2.0	0	100	5.0	2	4.87	Е	4.08	D
			rnathy Rd NE	P. Tree Dunwoody	Mt. Vernon	0.12	2	D	41028	4	45	12.0	0.0	0.0	0	4.0	Y	С	2.0	0	100	5.0	2	4.87	Е	4.08	D
			meter Center W Rd	Mt. Vernon	Ashford Dunwoody (County Line)	0.33 4	4 2	D	38466	3	35	11.5	0.0	0.0	0	3.0	N	с	1.7	0	0	5.0	3	4.78	Е	5.07	E
			meter Center W Rd	Mt. Vernon	Ashford Dunwoody (County Line)	0.33			38466	_	35		0.0		0	3.0	N	С	1.7	0	0	5.0	3	4.78	Е	5.07	E
			mathy Rd NE	Brandon Mill Road/Johnson Ferry	Roswell	0.75			16530		35		0.0		0	3.0	Y	С	2.0	0	0	4.0	N/A	4.24	D	4.42	D
			mathy Rd NE	Brandon Mill Road/Johnson Ferry	Roswell		2 1		16530		35		0.0		0	3.0	Y	С	2.0	0	100	4.0	N/A	4.24	D	3.21	С
			rnathy Rd NE	Roswell	Hwy 400	1.26	4 2		32698	4	45	11.7			0	3.5	Y	С	2.0	0	90	5.0	2	4.95	Е	3.89	D
			mathy Rd NE	Roswell	Hwy 400	1.26	4 2	-	32698	4	45	11.7		0.0	0	3.5	Y	С	2.0	0	100	5.0	2	4.95	Е	3.75	D
			ield Rd NE	Hammond	Mt. Vernon	0.71 2	2 1	LT	7416	2	35	15.0	3.8	0.0	0	5.0	Y	с	0.0	0	100	5.0	2	2.36	в	2.54	с
			ield Rd NE	Hammond	Mt. Vernon		2 1		7416		35	_	3.8		0	5.0	Y	С	0.0	0	100	5.0	2	2.36	В	2.54	С
			ield Rd NE	Mt. Vernon	Abernathy	0.34 4			7410		35		0.0		0	5.0	Y	С	2.0	0	100	6.0	1	3.35	с	2.39	в
			ield Rd NE	Mt. Vernon	Abernathy	0.34 4	_	_	7658	2	35		0.0		0	5.0	Y	С	2.0	0	100	6.0	1	3.35	С	2.39	В
			ndon Mill Rd NW	Riverside	N. Mill Road	0.82			942	2	35	10.4			0	4.0	N	C	0.0	0	0	0.0	3	1.54	В	3.02	c
			ndon Mill Rd NW	Riverside	N. Mill Road	0.82 2			942	2	35	-	0.0		0	4.0	N	C	0.0	0	0	0.0	3	1.54	В	3.02	С
			ndon Mill Rd NW	N. Mill Road	Abennathy	0.67 2			942	2	35		0.0	0.0	0	3.5	N	C	0.0	0	0	0.0	3	1.53	B	2.97	с
			ndon Mill Rd NW	N. Mill Road	Abennathy		2 1	U	942		35	_	0.0		0	3.5	N	C	0.0	0	0	0.0	3	1.53	В	2.97	c
		SSp Colq		Pitts Rd	Northridge Road	0.79 2	-	U	6540	-	35	10.8	_	0.0	0	4.0	Y	C	0.0	0	0	4.2	3	3.64	D	4.01	D
		SSp Colq		Pitts Rd	Northridge Road	0.79 2		U	6540		35	-	0.0	0.0	0	4.0	Y	C	0.0	0	100	4.2	3	3.64	D	2.73	C
			ymple Rd NE	Dalrymple Ends	Princeton Way	0.90 2		-	10272		35		0.0		0	4.0	N	S	0.0	0	0	0.0	3	3.73	D	4.18	D
			ymple Rd NE	Dalrymple Ends	Princeton Way		2 1		10272		35	_	0.0		0	4.5	N	S	0.0	0	0	0.0	3	3.73	D	4.18	D
			ymple Rd NE	Princeton Way	Roswell	0.56 2			10272		35		1.7		0	4.5	Y	C	2.0	0	100	4.0	3	3.47	c	2.87	c
			ymple Rd NE		Roswell		2 1	U	11532		35		1.7		0	4.5	Y	C	2.0	0	0	4.0	3	3.47	c	4.01	D
171.1	5 5	Sop Dany		Princeton Way	INOSWEII	5.00			11532	-	00	10.1	1	0.0	v	4.5		Ŭ	2.5	v	, v	1.5					

										T		Width				Bike			Tree				I			
			-		Len-					Post.		Of		Occ.		Lane/		Buff.	Spcg.	%	Swalk	Road		ycle	Pedes	
Segment ID ID	Ci	ity Road Name	From	То	v	.anes (L 'h Di	,	Roadway	Tks. (HV)	Spd. (SPp)	Wt	Pavemer WI		Park. (OSPA)	Pavecon PC _t	Pavd. Shidr.	Cross Sec.	Width (BW)	in Buffer	with Sidewalk	Width (Ws)	Profile Cond	Score	OS Grade	LC Value	OS Grade
					. ,	# #		ADT	(%)	mph	(ft)		(ft)	(%)	(15)	(Y/N)	(C/S)	(ft)	(ft/ctr)	(DIR)	(ft)	(1,2,3)	(17)	(AF)	(17)	(AF)
171.2	A SS	Sp Dalrymple Rd NE	Roswell Road	Spalding	0.35	2 1	U	13600	2	35	12.5	0.0	0.0	0	4.5	Y	С	6.0	0	50	5.0	1	3.72	D	3.53	D
171.2	B SS	Sp Dalrymple Rd NE	Roswell Road	Spalding	0.35	2 1	U	13600	2	35	12.5	0.0	0.0	0	4.5	Y	С	6.0	0	100	5.0	1	3.72	D	2.80	с
174.0	A SS	Sp Dunwoody Club Dr	Spalding	Ball Mill Road	1.59	2 1	U	17370	2	35	10.5	0.0	0.0	0	3.0	Ν	С	2.0	0	50	5.0	2	4.50	D	3.95	D
174.0	B SS	Sp Dunwoody Club Dr	Spalding	Ball Mill Road	1.59	2 1	U	17370	2	35	10.5	0.0	0.0	0	3.0	Ν	С	2.0	0	0	5.0	2	4.50	D	4.69	E
174.1	A SS	Sp Dunwoody Club Dr	Ball Mill Road	Jett Ferry	0.73	2 1	U	14798	2	35	10.9	0.0	0.0	0	4.0	Ν	С	0.0	0	60	5.0	2	4.04	D	3.66	D
		Sp Dunwoody Club Dr	Ball Mill Road	Jett Ferry	0.73	2 1	U	14798	2	35	10.9	0.0	0.0	0	4.0	Ν	С	0.0	0	0	5.0	2	4.04	D	4.49	D
174.2	A SS	Sp Dunwoody Club Dr	Jett Ferry	Mt. Vernon	0.16	3 2	U	14180	2	35	11.5	0.0	0.0	0	4.0	Y	С	0.0	0	100	5.0	2	3.95	D	3.05	с
174.2	B SS	Sp Dunwoody Club Dr	Jett Ferry	Mt. Vernon	0.16	3 2	U	14180	2	35	11.5	0.0	0.0	0	4.0	Y	С	0.0	0	100	5.0	2	3.95	D	3.05	С
174.3	A SS	Sp Dunwoody Club Dr	Mt. Vernon	Mt. Vernon	0.21	3 2	U	14180	2	35	12.6	0.0	0.0	0	4.0	Y	С	2.0	0	100	5.0	2	3.82	D	2.95	с
174.3	B SS	Sp Dunwoody Club Dr	Mt. Vernon	Mt. Vernon	0.21	3 2	U	14180	2	35	12.6	0.0	0.0	0	4.0	Y	С	2.0	0	100	5.0	2	3.82	D	2.95	с
174.4	A SS	Sp Dunwoody Club Dr	Happy Hallow	Mt. Vernon	1.03	2 1	U	6504	2	35	9.5	0.0	0.0	0	3.0	Y	С	0.0	0	0	5.0	3	4.10	D	4.17	D
		Sp Dunwoody Club Dr	Happy Hallow	Mt. Vernon	1.03	2 1	U	6504	2	35	9.5	0.0	0.0	0	3.0	Y	С	0.0	0	100	5.0	3	4.10	D	2.67	С
		Sp Dunwoody PINorthridge	Northridge	Roberts Drive	0.57	3 2	U	16208	2	35	14.2	0.0	0.0	0	4.0	N	С	0.0	0	0	0.0	2	3.68	D	4.26	D
		Sp Dunwoody PINorthridge	Northridge	Roberts Drive	0.57	3 2	U	16208	2	35	14.2	0.0	0.0	0	4.0	N	С	0.0	0	0	0.0	2	3.68	D	4.26	D
		Sp Dunwoody PINorthridge	Roberts Drive	Roswell	0.72	4 2	U	18350	2	35	9.6	0.0	0.0	0	4.0	Y	С	2.0	0	100	5.0	2	4.08	D	2.93	с
		Sp Dunwoody PINorthridge	Roberts Drive	Roswell	0.72	4 2	U	18350	2	35	9.6	0.0	0.0	0	4.0	Y	С	2.0	0	100	5.0	2	4.08	D	2.93	С
176.0	A SS	Sp Garmon Rd NW	Northside Dr	City Limit	0.08	2 1	U	1300	2	35	17.3	4.1	0.0	0	3.5	N	S	0.0	0	0	0.0	3	1.31	A	2.60	С
		Sp Garmon Rd NW	Northside Dr	City Limit	0.08	2 1	U	1300	2	35	17.3	4.1	0.0	0	3.5	N	S	0.0	0	0	0.0	3	1.31	A	2.60	С
		Sp Dunwoody PINorthridge	Abernathy	UPS Headquarters	0.82	4 2	U	3900	2	35	12.1	0.0	0.0	0	4.5	N	С	3.0	0	75	5.0	2	1.98	В	2.59	с
177.0	B SS	Sp Dunwoody PINorthridge	Abernathy	UPS Headquarters	0.82	4 2	U	3900	2	35	12.1	0.0	0.0	0	4.5	N	С	3.0	0	90	5.0	2	1.98	В	2.38	В
		Sp Glenlake Pkwy NE	UPS Headquarters	Glen Bridge Drive	0.17	3 2	U	2842	2	35	12.3		0.0	0	5.0	N	С	0.0	0	0	0.0	2	1.89	В	3.63	D
		Sp Glenlake Pkwy NE	UPS Headquarters	Glen Bridge Drive	0.17	3 2	U	2842	2	35	12.3	0.0	0.0	0	5.0	N	С	0.0	0	0	0.0	2	1.89	В	3.63	D
		Sp Glenridge Conn	l 285	Peach Tree Dunwoody		63	D	23978	4	45	12.0		0.0	0	3.5	N	С	0.0	0	0	0.0	2	4.49	D	4.39	D
		Sp Glenridge Conn	l 285	Peach Tree Dunwoody		63	D	23978	4	45	12.0	0.0	0.0	0	3.5	N	С	0.0	0	0	0.0	2	4.49	D	4.39	D
		Sp Glenridge Dr	Hammond	I 285	0.71	4 2		13782	2	35	11.9		0.0	0	4.0	Y	С	2.0	0	100	5.0	2	3.68	D	2.68	с
		Sp Glenridge Dr	Hammond	I 285	0.71	4 2	D	13782	2	35	11.9	0.0	0.0	0	4.0	Y	С	2.0	0	0	5.0	2	3.68	D	4.04	D
		Sp Glenridge Dr NE	Hammond	Johnsons Ferry	0.32	2 1	U	13626	2	35	15.0	0.0	0.0	0	3.5	N	S	0.0	0	0	0.0	2	3.63	D	4.03	D
		Sp Glenridge Dr NE	Hammond	Johnsons Ferry		2 1	-	13626	2	35	15.0	_	0.0	0	3.5	N	S	0.0	0	0	0.0	2	3.63	D	4.03	D
		Sp Glenridge Dr NE	Johnsons Ferry	Mt. Vernon		2 1	U	6142	2	35	12.0	_	0.0	0	5.0	Y	С	3.0	0	100	5.0	2	3.32	С	2.47	В
		Sp Glenridge Dr NE	Johnsons Ferry	Mt. Vernon		2 1		6142	2	35	12.0		0.0	0	5.0	Y	С	3.0	0	100	5.0	2	3.32	С	2.47	В
		Sp Glenridge Dr NE	Mt. Vernon	Abernathy	0.67		-	5166	2	35	13.5		0.0	0	5.0	N	С	2.0	0	25	5.0	2	3.04	с	3.34	с
		Sp Glenridge Dr NE	Mt. Vernon	Abernathy		2 1		5166		35		0.0		0	5.0	N	С	2.0	0	0	5.0	2	3.04	С	3.65	D
		Sp Glenridge Dr NE	Abernathy	Glen Lake Pkwy	0.42		-	8000	2	35	14.7	-		0	5.0	N	С	0.0	0	0	0.0	2	3.09	с	3.72	
		Sp Glenridge Dr NE	Abernathy	Glen Lake Pkwy		2 1		8000		35	_	0.0		0	5.0	N	С	0.0	0	0	0.0	2	3.09	С	3.72	D
		Sp Glenridge Dr NE	Glen Lake Pkwy	Spalding	0.63		-	7998	2	25	14.5		0.0	0	3.0	Y	С	2.0	0	100	5.0	1	3.25	с	2.29	В
		Sp Glenridge Dr NE	Glen Lake Pkwy	Spalding		2 1		7998	2	25	_	0.0		0	3.0	Y	С	2.0	0	0	5.0	1	3.25	C	3.50	C
		Sp Glenridge Dr NE	Roswell Road	Johnsons Ferry	1.02	_	-	10788	4	35	12.5	_	0.0	0	4.5	N	С	2.0	0	75	5.0	2	4.01	D	3.08	C
		Sp Glenridge Dr NE	Roswell Road	Johnsons Ferry		2 1		10788	4	35	-	0.0		0	4.5	N	С	2.0	0	25	5.0	2	4.01	D	3.75	D
		Sp Hammond Dr NW	Mt. Vernon	Sandy Spring Circle	0.41			3638	3	35	_	0.0		0	3.5	N	С	2.0	0	25	5.0	2	2.49	В	3.34	c
		Sp Hammond Dr NW	Mt. Vernon	Sandy Spring Circle		4 2		3638	3	35	-	0.0		0	3.5	N	С	2.0	0	50	5.0	2	2.49	В	2.99	c
		Sp Hammond Dr NW	Snady Spring Circle	Roswell Road		4 2		12720	2	35		0.0		0	3.5	Y	С	2.0	0	50	5.0	2	3.79	D	3.31	c
		Sp Hammond Dr NW	Snady Spring Circle	Roswell Road		4 2		12720	2	35	-	0.0		0	3.5	Y	С	2.0	0	100	5.0	2	3.79	D	2.63	C
		Sp Hammond Dr NW	Roswell	Boylston Dr	0.14		-	18000	2	35	11.5			0	4.5	N	С	0.0	0	0	0.0	2	3.97	D	4.62	E
		Sp Hammond Dr NW	Roswell	Boylston Dr		2 1		18000	2	35	_	0.0		0	4.5	N	С	0.0	0	0	0.0	2	3.97	D	4.62	E
		Sp Hammond Dr NW	Boylston Dr	Lorell Ter	0.50		-	18000	3	35	11.5		0.0	0	5.0	N	S	0.0	0	0	0.0	3	4.11	D	4.62	E
		Sp Hammond Dr NW	Boylston Dr	Lorell Ter		2 1		18000	3	35	-	0.0		0	5.0	N	S	0.0	0	0	0.0	3	4.11	D	4.62	E
		Sp Hammond Dr NW	Lorell Ter	Greenbrier Dr	0.13	_	-	18000	3	35	15.5		0.0	0	5.0	N	S	0.0	0	0	0.0	3	2.87	C C	4.25	D
		Sp Hammond Dr NW	Lorell Ter	Greenbrier Dr		2 1	-	35440		35		4.0		0	5.0	N	S	0.0	0	0	0.0	3	3.22	C	5.29	E
		Sp Hammond Dr NW	Greenbrier Dr	GA 400	0.46			25202	3	35	-	0.0		0	5.0	Y	С	2.0	0	100	5.0	2	4.09	D	3.14	C F
		Sp Hammond Dr NW	Greenbrier Dr	GA 400		4 2		25202	3	35		0.0		0	5.0	Y	C	2.0	0	0	5.0	2	4.09	D	4.55	E
186.6	A SS	Sp Hammond Dr NW	GA 400	County Line	0.59	4 2	LT	20248	3	35	11.0	0.0	0.0	0	4.5	Y	С	2.0	0	100	5.0	2	4.09	D	2.96	С

								_				Width			Bike			Tree			-				
Segment ID	Ci	ity Road Name	From	То	Len- gth La	ines (L)			Tks.	Post. Spd.	.	Of Pavement	Occ. Park.	Pavecon	Lane/ Pavd.	Cross	Buff. Width	Spcg. in	% with	Swalk Width	Road Profile	Bicy		Pedes LO	
ID				10	-	Dir	Con	Roadway	(HV)	(SPp)	Wt			Pavecon	Shidr.	Sec.	(BW)	Buffer	Sidewalk	(Ws)	Cond	Score	Grade		Grade
					#			ADT	(%)	mph	(ft)	(ft) (ft		(15)	(Y/N)	(C/S)	(ft)	(ft/ctr)	(DIR)	(ft)	(1,2,3)	(17)	(AF)	(17)	(AF)
		Sp Hammond Dr NW	GA 400	County Line	0.59 4	2	LT	20248	3	35	11.0			4.5	Y	C	2.0	0	100	5.0	2	4.09	D	2.96	c
		Sp Heards Ferry Rd NW	Northside Drive	Heards Road	0.75 2	1	U	7378	2	35	13.0			5.0	N	C	2.0	0	50	5.0	2	3.28	C	3.19	c
		Sp Heards Ferry Rd NW	Northside Drive	Heards Road	0.75 2	1	0	7378	2	35	13.0	1.0 0.0		5.0	N	C	2.0	0	25	5.0	2	3.28	C	3.51	D
		Sp Heards Ferry Rd NW	Heards Road	Mt. Vernon	1.58 2	1	U	7010	2	35	12.4	1.0 0.0		5.0	Y	C	2.0	0	0	5.0	2	3.33	c	3.86	0
		Sp Heards Ferry Rd NW	Heards Road	Mt. Vernon	1.58 2 0.99 2	1	U	7010	2	35	12.4	1.0 0.0		5.0	Y	C	2.0	0	100	5.0	2	3.33	C	2.52	C
		Sp High Point Rd NE	Windsor Pkwy	Northland	0.99 2	1	U	2944	2	35 35	15.5 15.5	0.0 0.0		3.0	Y	C C	0.0	0	100 0	5.0 5.0	3	2.25	B	2.25 3.36	B
188.0	B SS	Sp High Point Rd NE Sp High Point Rd NE	Windsor Pkwy	Northland	0.99 2	1	U	2944	2	35	13.5	0.0 0.0		3.0	Y	c	0.0	0	100	5.0	3	3.60	 D	2.65	c
		Sp High Point Rd NE	Northland	Glenridge	0.62 2	· ·	U	8478	2	35	13.5			3.5	Y	c	0.0	0	50	5.0	2	3.60	D	3.25	c
		Sp Holcomb Bridge Rd	Northland	Glenridge	0.45 4	2	LT	8478	4	45	12.0	0.0 0.0		3.5	Y	c	2.0	0	100	5.0	2	5.06	E	4.17	 D
		Sp Holcomb Bridge Rd	Chattahoochee River	Spalding Drive	0.45 4	2	LT	43364	4	45	12.0			3.5	Y	c	2.0	0	0	5.0	2	5.06	E	5.54	F
		Sp Interstate North Pkwy NW	Chattahoochee River	Spalding Drive	0.76 2	1	U	43364	3	40	16.0			3.5	Y	c	0.0	0	0	0.0	1	2.77	c	3.75	D
		Sp Interstate North Pkwy NW	City limit City limit	Northside Drive	0.76 2	1	U	7674	3	40	16.0	4.0 0.0		3.5	Y	C	0.0	0	0	0.0	1	2.77	c	3.75	D
		Sp Jett Rd NW	Mt. Paran Rd.	City Limit	0.21 2	1	U	2480	2	30	10.5			3.5	N	s	0.0	0	0	0.0	3	2.72	c	3.28	c
		Sp Jett Rd NW	Mt. Paran Rd.	City Limit	0.21 2	1	U	2480	2	30	10.5			3.5	N	S	0.0	0	0	0.0	3	2.72	c	3.28	c
		Sp Johnson Ferry Rd NE	City Limit	Peachtree Dunwoody	0.47 2	1	U	13012	2	35	11.5	0.0 0.0		4.0	Y	С	2.0	0	100	5.0	2	3.91	D	2.92	с
		Sp Johnson Ferry Rd NE	City Limit	Peachtree Dunwoody	0.47 2	1	U	13012	2	35	11.5			4.0	Y	C	2.0	0	25	5.0	2	3.91	D	3.97	D
		Sp Johnson Ferry Rd NE	Glenridge Drive	Peachtree Dunwoody	0.64 4	2	U	23882	3	35	12.0	0.0 0.0	0 0	4.5	Y	с	2.0	0	90	4.0	2	4.05	D	3.32	с
		Sp Johnson Ferry Rd NE	Glenridge Drive	Peachtree Dunwoody	0.64 4	2	U	23882	3	35	12.0	0.0 0.0	0 0	4.5	Y	С	2.0	0	100	4.0	2	4.05	D	3.20	С
		Sp Johnson Ferry Rd NE	River Valley Rd	Sandy Springs Cir	0.52 2	1	U	6958	2	35	14.8	0.0 0.0	0 0	3.5	N	С	2.0	0	46	5.0	2	3.31	с	3.09	с
		Sp Johnson Ferry Rd NE	River Valley Rd	Sandy Springs Cir	0.52 2	1	U	6958	2	35	14.8	0.0 0.0	0 0	3.5	N	С	2.0	0	67	5.0	2	3.31	С	2.84	С
		Sp Johnson Ferry Rd NE	Sandy Springs Cir	Roswell Rd	0.14 4	2	U	14068	2	35	12.0	0.0 0.0	0 0	4.0	Y	С	2.0	0	0	5.0	2	3.69	D	4.06	D
		Sp Johnson Ferry Rd NE	Sandy Springs Cir	Roswell Rd	0.14 4	2	U	14068	2	35	12.0	0.0 0.0	0 0	4.0	Y	С	2.0	0	100	5.0	2	3.69	D	2.68	С
		Sp Johnson Ferry Rd NE	Roswell Rd	Mt. Vernon Hwy	0.23 2	2	OW	9654	2	35	12.0	0.0 0.0	0 0	3.0	N	С	0.0	0	0	11.0	2	3.97	D	4.00	D
		Sp Johnson Ferry Rd NE	Roswell Rd	Mt. Vernon Hwy	0.23 2	2	OW	9654	2	35	12.0	0.0 0.0	0 0	3.0	N	С	0.0	0	56	11.0	2	3.97	D	3.09	С
195.3	A SS	Sp Johnson Ferry Rd NE	Mt. Vernon Hwy	Glenridge Dr	0.81 2	1	U	20070	2	35	13.0	0.0 0.0	0 0	4.0	N	С	2.0	0	0	5.0	2	3.95	D	4.60	Е
195.3	B SS	Sp Johnson Ferry Rd NE	Mt. Vernon Hwy	Glenridge Dr	0.81 2	1	U	20070	2	35	13.0	0.0 0.0	0 0	4.0	Ν	С	2.0	0	64	5.0	2	3.95	D	3.76	D
196.0	A SS	Sp Johnson Ferry Rd NW	City Limit	River Valley Rd	1.01 4	2	U	21100	3	Х	х	0.0 0.0	0 0		Ν	х	х	0	23	х	x		UC		UC
196.0	B SS	Sp Johnson Ferry Rd NW	City Limit	River Valley Rd	1.01 4	2	U	21100	3	Х	Х	0.0 0.0	0 0		Ν	Х	х	0	0	х	x		UC		UC
		_{Sp} Lake Forrest Dr NE	Mt. Vernon	Hammond	0.21 4	2	U	1152	2	35	12.0	0.0 0.0	0 0	3.5	N	С	0.0	0	0	0.0	2	0.80	Α	2.78	С
197.0	B SS	Sp Lake Forrest Dr NE	Mt. Vernon	Hammond	0.21 4	2	U	1152	2	35	12.0			3.5	N	С	0.0	0	0	0.0	2	0.80	Α	2.78	С
		_{Sp} Lake Forrest Dr NE	Hammond	Mt. Paran	1.72 2	_	U	4638	2	35	12.0			3.5	N	S	0.0	0	0	0.0	3	3.49	с	3.77	D
		Sp Lake Forrest Dr NE	Hammond	Mt. Paran	1.72 2	1	U	4638	2	35	12.0			3.5	N	S	0.0	0	0	0.0	3	3.49	С	3.77	D
		_{Sp} Lake Forrest Dr NE	Mt. Paran	W. Wieuca [City Limit]	1.07 2	1	U	3324	2	35		1.0 0.0		3.5	N	С	0.0	0	0	0.0	2	3.05	С	3.59	D
		_{Sp} Lake Forrest Dr NE	Mt. Paran	W. Wieuca [City Limit]	1.07 2	1	U	3324	2	35	12.0			3.5	N	С	0.0	0	0	0.0	2	3.05	С	3.59	D
		Sp Lake Hearn Dr NE	P. Tree/Dunwoody	County Line	0.28 2	_	U	12702	2	35	11.3			4.0	Y	С	0.0	0	100	5.0	1	3.92	D	2.98	С
		Sp Lake Hearn Dr NE	P. Tree/Dunwoody	County Line	0.28 2		U	12702	2	35	-	0.0 0.0		4.0	Y	C	0.0	0	0	5.0	1	3.92	D	4.33	D
		Sp Long Island Dr NE	Roswell Rd	Mt. Paran Rd	0.70 2	1	U	6378	2	35	13.0			3.5	N	S	2.0	0	49	5.0	3	3.52	D	3.14	c
		Sp Long Island Dr NE	Roswell Rd	Mt. Paran Rd	0.70 2		U	6378	2	35	-	0.0 0.0		3.5	N	S	2.0	0	49	5.0	3	3.52	D	3.14	c
		Sp Long Island Dr NW	Mt. Paran	Mt. Vernon	2.13 2 2.13 2	-	U	3100		35		0.0 0.0	_	5.0	N	S	2.0	0	18	5.0	3	2.57	c	3.41	c
		Sp Long Island Dr NW	Mt. Paran	Mt. Vernon Jett Rd		1	UU	3100	2	35 30		0.0 0.0		5.0 4.0	N	S	2.0	0	19 0	5.0	3	2.57	C	3.39	C D
		_{Sp} Mt Paran Rd NE _{Sp} Mt Paran Rd NE	Northside Dr	Jett Rd	0.29 2	_	U	16526	2	30		0.0 0.0		4.0	N N	S S	0.0	0	0	0.0	3	3.89	D	4.39 4.39	D
		_{Sp} Mt Paran Rd NE _{Sp} Mt Paran Rd NE	Northside Dr		1.30 2	1	U	16526	2	30		0.0 0.0			N	S S	2.0	0	25	5.0	3	3.89 3.88	D	4.39 3.84	
		Sp Mt Paran Rd NE	Jett Rd	Long Island Dr	1.30 2	_	U	14048	2	30		0.0 0.0		3.5	N	S	2.0	0	10	5.0	3	3.88	D	4.04	
		Sp Mt Paran Rd NE Sp Mt Paran Rd NW	Jett Rd	Long Island Dr	0.89 2	1	U	14048	2	30	12.3			3.5	N	S S	2.0	0	51	5.0	3	3.88	D	3.07	c
		Sp Mt Paran Rd NW	Long Island Tr	Roswell Rd	0.89 2		U	7344	2	30		0.0 0.0		3.0	N	S	2.0	0	0	2.0	3	3.71	D	3.07	D
		Sp Mt Vernon Hwy NE	Long Island Tr	Roswell Rd	0.89 2	1	U	7344	2	30	12.3				N	C	0.0	0	0	0.0	2	3.41	C	4.04	
		Sp Mt Vernon Hwy NE	Lake Forest	Sandy Springs Circle	0.26 2	1	U	12492	2	35		2.5 0.0	_	5.0	N	c	0.0	0	0	0.0	2	3.41	c	4.04	D
		Sp Mt Vernon Hwy NE	Lake Forest	Sandy Springs Circle	0.20 2		U	12492 5874	2	35		0.0 0.0		5.0	N	c	0.0	0	0	0.0	2	3.29	c	3.85	 D
		Sp Mt Vernon Hwy NE	Sandy Springs Circle	Roswell Road		1	U	5874 5874	2	35		0.0 0.0		5.0	N	c	0.0	0	0	0.0	2	3.29	c	3.85	D
203.1	B 88	Sh live concerning the	Sandy Springs Circle	Roswell Road	0.21 2		0	58/4	-	- 33	12.0	0.0 0.0		5.0			0.0	0	0	0.0	2	3.23	U	0.00	

													Width	1			Bike			Tree			·7			
					Len-						Post.		Of		Occ.		Lane/		Buff.	Spcg.	%	Swalk	Road	Bic		Pedestrian
Segment ID ID	Ci	ty Road Name	From	То	gth (mi)		es (L) Dir	Con	Roadway	Tks. (HV)	Spd. (SPp)	F Wt	aveme Wi	ent W _{ps}	Park. (OSPA)	Pavecon PCt	Pavd. Shidr.	Cross Sec.	Width (BW)	in Buffer	with Sidewalk	Width (Ws)	Profile Cond	LC Score	OS Grade	LOS Value Grade
					, ,	#		COIL	ADT	(%)	mph	(ft)	(ft)	(ft)	(%)	(15)	(Y/N)	(C/S)	(BVV) (ft)	(ft/ctr)	(DIR)	(vvs) (ft)	(1,2,3)	(17)	(AF)	(17) (AF)
203.2	A SS	Sp Mt Vernon Hwy NE	Roswell Road	Johnsons Ferry	0.18	2	2	OW	4386	2	35	12.0	0.0	0.0	0	4.0	N	С	0.0	0	80	5.0	2	2.52	С	2.69 C
		Sp Mt Vernon Hwy NE	Roswell Road	Johnsons Ferry	0.18	2	2	OW	4386	2	35	12.0	0.0	0.0	0	4.0	N	С	0.0	0	0	5.0	2	2.52	С	3.73 D
		Sp Mt Vernon Hwy NE	Johnson's Ferry Rd	Crestline Pkwy	1.22	2	1	U	10334	2	35	14.7	0.0	0.0	0	4.0	N	С	2.0	0	57	5.0	2	3.45	с	3.17 C
		Sp Mt Vernon Hwy NE	Johnson's Ferry Rd	Crestline Pkwy	1.22	2	1	U	10334	2	35	14.7	0.0	0.0	0	4.0	N	С	2.0	0	37	5.0	2	3.45	С	3.41 C
203.4	A SS	Sp Mt Vernon Hwy NE	Crestline Pkwy	Mt. Vernon Cir	0.58	4	2	D	9232	2	35	12.3	0.0	0.0	0	4.0	N	С	2.0	0	17	5.0	3	3.44	С	3.59 D
203.4	B SS	Sp Mt Vernon Hwy NE	Crestline Pkwy	Mt. Vernon Cir	0.58	4	2	D	9232	2	35	12.3	0.0	0.0	0	4.0	Ν	С	2.0	0	14	5.0	3	3.44	С	3.63 D
203.5	A SS	Sp Mt Vernon Hwy NE	Mt. Vernon Cir	City Limit	0.17	2	1	U	8702	2	35	15.1	0.0	0.0	0	4.0	N	С	2.0	0	12	5.0	3	3.23	С	3.59 D
203.5	B SS	Sp Mt Vernon Hwy NE	Mt. Vernon Cir	City Limit	0.17	2	1	U	8702	2	35	15.1	0.0	0.0	0	4.0	N	С	2.0	0	12	5.0	3	3.23	С	3.59 D
		Sp Mt Vernon Hwy NW	Northside Drive	Dupree/ Powers Ferry	0.71	2	1	U	4938	2	35	12.5	0.0	0.0	0	3.5	N	С	2.0	0	50	5.0	2	3.46	с	3.07 C
		Sp Mt Vernon Hwy NW	Northside Drive	Dupree/ Powers Ferry	0.71	2	1	U	4938	2	35	12.5	0.0	0.0	0	3.5	N	С	2.0	0	0	5.0	2	3.46	С	3.73 D
		Sp Mt Vernon Hwy NW	Dupree/Powers Ferry	Powers Ferry/ Mt. Vernon Pkwy	0.53	2	1	LT	11712	2	35	12.4	0.0	0.0	0	3.0	Y	С	2.0	0	75	5.0	2	4.08	D	3.14 C
		Sp Mt Vernon Hwy NW	Dupree/Powers Ferry	Powers Ferry/ Mt. Vernon Pkwy	0.53	2	1	LT	11712	2	35	12.4	0.0	0.0	0	3.0	Y	С	2.0	0	100	5.0	2	4.08	D	2.81 C
		_{Sp} Mt Vernon Hwy NW	Powers Ferry/ Mt Vernon Pkwy	Lake Forest	1.67	2	1	U	9848	2	35	12.5	1.0	0.0	0	5.0	Y	С	2.0	0	100	5.0	2	3.49	с	2.70 C
		Sp Mt Vernon Hwy NW	Powers Ferry/ Mt Vernon Pkwy	Lake Forest	1.67	2	1	U	9848	2	35	12.5	1.0	0.0	0	5.0	Y	С	2.0	0	0	5.0	2	3.49	С	4.02 D
		Sp Mt Vernon Rd	Dunwoody Club	Spalding Drive	0.66	2	1	U	9400	2	35	11.3	0.0	0.0	0	5.0	N	С	2.0	0	10	5.0	3	3.61	D	3.99 D
205.0	BISS	Sp Mt Vernon Rd	Dunwoody Club	Spalding Drive	0.66	2	1	U	9400	2	35	11.3	0.0	0.0	0	5.0	N	С	2.0	0	20	5.0	3	3.61	D	3.85 D
		Sp New Northside Dr	1 285	Northside Drive	0.29	5	3	U	11892	2	35	12.0	0.0	0.0	0	4.5	N	С	2.0	0	0	4.0	2	3.35	с	3.85 D
		Sp New Northside Dr	1 285	Northside Drive	0.29	5	3	U	11892	2	35	12.0	0.0	0.0	0	4.5	N	С	2.0	0	50	4.0	2	3.35	с	3.22 C
		Sp New Northside Dr	Northside Drive	1 285	0.31	3	3	OW	8220	2	35	11.6	0.0	0.0	0	4.5	N	С	1.5	0	25	5.0	2	2.81	с	3.48 C
		Sp New Northside Dr	Northside Drive	1 285	0.31	3	3	OW	8220	2	35	11.6	0.0	0.0	0	4.5	N	С	1.5	0	0	5.0	2	2.81	с	3.82 D
	_	Sp Northland Dr NE	Windsor Pkwy	Glen Bridge Drive	1.44	2	1	U	2554	2	35	10.0	0.0	0.0	0	3.0	Y	С	0.0	0	50	5.0	3	3.15	с	3.14 C
		Sp Northland Dr NE	Windsor Pkwy	Glen Bridge Drive	1.44	2	1	U	2554	2	35	10.0	0.0	0.0	0	3.0	Y	С	0.0	0	100	5.0	3	3.15	С	2.42 B
		Sp Northridge Rd	Roswell	Roberts Drive	0.56	4	2	U	39814	3	35	12.0	0.0	0.0	0	4.5	N	C	2.0	0	75	5.0	3	4.31	D	4.04 D
		Sp Northridge Rd	Roswell	Roberts Drive	0.56	4	2	U	39814	3	35	12.0	0.0	0.0	0	4.5	N	С	2.0	0	75	5.0	3	4.31	D	4.04 D
		Sp Northside Dr NW	Mt. Paran Rd	Garmon Rd	0.79	2	1	U	8562	2	35	16.9	3.6	0.0	0	3.0	Y	S	0.0	0	0	0.0	3	2.59	c	3.57 D
		Sp Northside Dr NW	Mt. Paran Rd	Garmon Rd	0.79	2	1	U	8562	2	35	16.9	3.6	0.0	0	3.0	Y	S	0.0	0	0	0.0	3	2.59	С	3.57 D
		Sp Northside Dr NW	Garmon Rd	Indian Trail NW	0.89	2	1	U	7866	2	35	15.3	4.6	0.0	0	4.5	Y	S	0.0	0	0	0.0	2	2.24	В	3.66 D
		Sp Northside Dr NW	Garmon Rd	Indian Trail NW	0.89	2	1	U	7866	2	35	15.3	4.6	0.0	0	4.5	Y	S	0.0	0	0	0.0	2	2.24	в	3.66 D
	_	Sp Northside Dr NW			0.54	2	1	U	426	2	35	15.1	5.2	0.0	0	4.5	Y	S	0.0	0	0	0.0	2	0.72	- A	2.66 C
		Sp Northside Dr NW	Indian Trail NW	S Mount Vernon Hwy	0.54	2	1	U		2	35	15.1	5.2	0.0	0		Y	S	0.0	0	0	0.0	2	0.72	A	2.66 C
		Sp Northside Dr NW	Indian Trail NW	S Mount Vernon Hwy New Northside Dr NW	0.47	2	1	U	426 15892	2	35	15.9	4.9	0.0	0	4.5	Y	s	0.0	0	0	0.0	2	2.40	В	4.09 D
		Sp Northside Dr NW	S Mount Vernon Hwy	New Northside Dr NW			1	U		2	35			0.0	0	4.5	Y	s	0.0	0	0	0.0	2	2.40	В	4.09 D
		Sp Northside Dr NW	S Mount Vernon Hwy New Northside Dr NW	Powers Ferry Rd NW	0.10	1	1	ow	15892	3	35		6.6		0	4.5 4.0	Y	C	2.0	0	0	5.0		1.66	В	3.99 D
		Sp Northside Dr NW	New Northside Dr NW	Powers Ferry Rd NW	0.10	1	1	OW	10076	3	35	_	6.6		0	4.0	Y	c	2.0	0	100	5.0	1	1.66	В	2.97 C
		Sp Northside Dr NW	Powers Ferry Rd NW	Interstate N Pkwy	0.28	2	2	ow	10076	2	35		0.0		0	3.5	N	c	2.0	0	0	5.0	2	2.64	c	3.74 D
		Sp Northside Dr NW	Powers Ferry Rd NW	Interstate N Pkwy	0.28	2	2	OW	4312	2	35		0.0		0	3.5	N	c	0.0	2	15	5.0	2	2.64	c	3.55 D
	_	Sp Northside Dr NW	Interstate N Pkwy		0.28	3	2	U	4312	2	35	13.3			0	3.5	N	c	0.0	0	0	0.0	3	0.93	A	3.45 C
		Sp Northside Dr NW	Interstate N Pkwy	Riveredge Pkwy	0.14	3	2	U	1532	2	35	_	0.0		0	3.5	N	c	0.0	0	0	0.0	3	0.93	A	3.45 C
	_	Sp Northside Dr NW		Riveredge Pkwy	0.14	2	1	U	1532	2	35		0.0		0	3.5	N	c	0.0	0	0	0.0	3	0.93	A	2.56 C
		Sp Northside Dr NW	Riveredge Pkwy	Wintherthur Dr	0.47	2	1	U	920	2	35			0.0	0	3.5	N	c	0.0	0	0	0.0	3	0.00	A	2.56 C
			Riveredge Pkwy	Wintherthur Dr	0.47	2	1	U	920	2	35	15.0			0		Y	c	1.0	0	100	5.0	2	3.14	C A	2.36 C
		Peachtree Dunwoody Rd NE	Windsor Pkwy	City Limit	0.45	2	1	U	5226	2	35		0.0		0	4.0	Y Y	c	1.0	0	50	5.0	2	3.14	c	3.01 C
		Peachtree Dunwoody Rd NE	Windsor Pkwy	City Limit	-	2	1	U	5226	2		-	0.0		0	4.0										1 1
		Peachtree Dunwoody Rd NE	Glenridge Conn	Windsor Pkwy	1.38 1.38	2	1	U	1348		35		0.0		0	4.0	N	C	2.0	0	50	5.0	2	0.72	A	2.76 C 2.76 C
	_	Peachtree Dunwoody Rd NE	Glenridge Conn	Windsor Pkwy		2			1348	2	35		0.0			4.0	N	C	2.0		50	5.0	2	0.72	A	1 1
		Sp Peachtree Dunwoody Rd NE	I 285	Glenridge Conn	0.79		2	U	24412	3	35	_			0	4.0	Y	C	2.0	0	100	5.0	2	4.16	D	3.09 C
		Sp Peachtree Dunwoody Rd NE	1 285	Glenridge Conn	0.79	4	2	U	24412	3	35		0.0		0	4.0	Y	C	2.0	0	100	5.0	2	4.16	D	3.09 C
		Peachtree Dunwoody Rd NE	Hammond	I 285	0.36	4	2	D	28408	3	35	11.0		0.0	0	3.5	Y	C	3.0	0	25	5.0	2	4.51	E	4.35 D
		Peachtree Dunwoody Rd NE	Hammond	I 285	0.36	4	2	D	28408	3	35		0.0		0	3.5	Y	C	3.0	0	100	5.0	2	4.51	E	3.25 C
		Sp Peachtree Dunwoody Rd NE	Mt Vernon	Hammond	0.91	4	2	D	16738	2	35		0.0		0	3.5	Y	С	2.0	0	90	5.0	2	3.96	D	2.93 C
	-	Sp Peachtree Dunwoody Rd NE	Mt Vernon	Hammond	0.91	4	2	D	16738	2	35			0.0	0	3.5	Y	С	2.0	0	100	5.0	2	3.96	D	2.79 C
213.5	A SS	Sp Peachtree Dunwoody Rd NE	Abernathy	Mt Vernon	0.13	4	2	D	11778	2	35	12.0	0.0	0.0	0	3.5	Y	С	2.0	0	100	5.0	1	3.75	D	2.59 C

I + +	1											Width			Bike			Tree						1	
			_	_	Len-	_					Post.	Of	Occ.		Lane/		Buff.	Spcg.	%	Swalk	Road	Bicy		Pedest	
Segment ID ID	City	Road Name	From	То	gth (mi)	Lanes	s (L) Dir	Con	Roadway	Tks. (HV)	Spd. (SPp)	Pavement Wt WI W _{ps}	Park. (OSPA)	Pavecon PCt	Pavd. Shidr.	Cross Sec.	Width (BW)	in Buffer	with Sidewalk	Width (Ws)	Profile Cond	LC Score	Grade	LO: Value	S Grade
					()		#		ADT	(%)	mph	(ft) (ft) (ft)	(%)	(15)	(Y/N)	(C/S)	(ft)	(ft/ctr)	(DIR)	(ft)	(1,2,3)	(17)	(AF)	(17)	(AF)
213.5 B	SSp Pe	eachtree Dunwoody Rd NE	Abernathy	Mt Vernon	0.13	4	2	D	11778	2	35	12.0 0.0 0.0	0	3.5	Y	С	2.0	0	100	5.0	1	3.75	D	2.59	С
213.6 A	SSp Pe	eachtree Dunwoody Rd NE	N. Park Place	Abernathy	0.13	2	1	D	13738	2	35	12.0 0.0 0.0	0	5.0	Y	С	2.0	0	100	5.0	2	3.72	D	2.94	С
213.6 B	SSp Pe	eachtree Dunwoody Rd NE	N. Park Place	Abernathy	0.13	2	1	D	13738	2	35	12.0 0.0 0.0	0	5.0	Y	С	2.0	0	100	5.0	2	3.72	D	2.94	С
213.7 A	SSp Pe	eachtree Dunwoody Rd NE	Glen Meadow Ct	N. Park Place	0.42	2	1	LT	13738	2	35	11.3 0.0 0.0	0	3.5	Y	С	1.5	0	100	5.0	2	4.11	D	2.99	С
213.7 B	SSp Pe	eachtree Dunwoody Rd NE	Glen Meadow Ct	N. Park Place	0.42	2	1	LT	13738	2	35	11.3 0.0 0.0	0	3.5	Y	С	1.5	0	100	5.0	2	4.11	D	2.99	С
213.8 A	SSp Pe	eachtree Dunwoody Rd NE	Spalding	Glen Meadow CT	1.20	2	1	U	8556	2	35	12.4 0.0 0.0	0	4.0	Y	С	2.0	0	100	5.0	2	3.59	D	2.61	С
213.8 B	SSp Pe	eachtree Dunwoody Rd NE	Spalding	Glen Meadow CT	1.20	2	1	U	8556	2	35	12.4 0.0 0.0	0	4.0	Y	С	2.0	0	100	5.0	2	3.59	D	2.61	С
215.0 A	SSp Pi	itts Rd	Roswell	Spalding Road	0.71	2	1	U	10248	2	35	10.5 0.0 0.0	0	4.0	Ν	С	2.0	0	80	5.0	2	3.90	D	3.08	с
215.0 B	SSp Pi	itts Rd	Roswell	Spalding Road	0.71	2	1	U	10248	2	35	10.5 0.0 0.0	0	4.0	Ν	С	2.0	0	25	5.0	2	3.90	D	3.90	D
216.0 A	SSp Po	owers Ferry Rd NW	City Limit	Mt. Paran	0.80	2	1	U	5080	2	35	12.0 0.0 0.0	0	3.5	Ν	S	0.0	0	0	0.0	3	3.54	D	3.80	D
216.0 B	SSp Po	owers Ferry Rd NW	City Limit	Mt. Paran	0.80	2	1	U	5080	2	35	12.0 0.0 0.0	0	3.5	Ν	S	0.0	0	0	0.0	3	3.54	D	3.80	D
216.1 A	SSp Po	owers Ferry Rd NW	Mt. Paran	Mt. Vernon	1.71	2	1	U	6810	2	35	9.5 0.0 0.0	0	3.0	Ν	С	0.0	0	0	0.0	3	4.12	D	4.18	D
216.1 B	SSp Po	owers Ferry Rd NW	Mt. Paran	Mt. Vernon	1.71	2	1	U	6810	2	35	9.5 0.0 0.0	0	3.0	Ν	С	0.0	0	0	0.0	3	4.12	D	4.18	D
216.2 A	SSp Po	owers Ferry Rd NW	Mt. Vernon	Heards	0.40	2	1	U	9620	2	35	12.5 0.0 0.0	0	5.0	Y	С	2.0	0	50	5.0	1	3.47	С	3.34	С
		owers Ferry Rd NW	Mt. Vernon	Heards	0.40	2	1	U	9620	2	35	12.5 0.0 0.0	0	5.0	Y	С	2.0	0	100	5.0	1	3.47	С	2.68	С
216.3 A	SSp Po	owers Ferry Rd NW	Heards	Driveway 5780	0.33	2	1	U	3246	2	35	12.5 1.0 0.0	0	5.0	Y	С	0.0	0	0	5.0	2	2.62	С	3.63	D
216.3 B	SSp Po	owers Ferry Rd NW	Heards	Driveway 5780	0.33	2	1	U	3246	2	35	12.5 1.0 0.0	0	5.0	Y	С	0.0	0	100	5.0	2	2.62	С	2.37	В
216.4 A	SSp Po	owers Ferry Rd NW	Driveway 5780	New Northside	0.89	2	1	LT	2860	2	35	11.0 0.0 0.0	0	4.5	Ν	С	2.0	0	50	5.0	2	2.71	С	3.05	С
216.4 B	SSp Po	owers Ferry Rd NW	Driveway 5780	New Northside	0.89	2	1	LT	2860	2	35	11.0 0.0 0.0	0	4.5	Ν	С	2.0	0	50	5.0	2	2.71	С	3.05	С
216.5 A	SSp Po	owers Ferry Rd NW	New Northside	City Limit	0.82	3	2	U	19316	2	35	11.2 0.0 0.0	0	4.0	Ν	С	2.0	0	50	5.0	2	4.14	D	4.01	D
216.5 B	SSp Po	owers Ferry Rd NW	New Northside	City Limit	0.82	3	2	U	19316	2	35	11.2 0.0 0.0	0	4.0	N	С	2.0	0	0	5.0	2	4.14	D	4.72	Е
218.0 A	SSp Ri	iver Valley Rd NW	Riverside Dr	Johnson Ferry Rd	1.29	2	1	U	3696	2	35	13.0 0.0 0.0	0	5.0	Ν	С	0.0	0	0	0.0	3	2.81	С	3.52	D
		iver Valley Rd NW	Riverside Dr	Johnson Ferry Rd	1.29	2	1	U	3696	2	35	13.0 0.0 0.0	0	5.0	Ν	С	0.0	0	0	0.0	3	2.81	С	3.52	D
219.0 A	SSp Ri	iverside Dr NW	Darlrymple	Bridge (out)	3.29	2	1	U	14038	2	35	12.2 1.5 0.0	0	4.5	Ν	С	0.0	0	0	0.0	2	3.76	D	4.31	D
		iverside Dr NW	Darlrymple	Bridge (out)	3.29	2	1	U	14038	2	35	12.2 1.5 0.0	0	4.5	N	С	0.0	0	0	0.0	2	3.76	D	4.31	D
220.0 A	SSp Ri	iverside Dr NW	Mt. Vernon Hwy	Coldstream Ct	0.70	2	1	U	17048	2	35	12.3 0.0 0.0	0	4.5	N	S	0.0	0	0	0.0	3	3.85	D	4.47	D
220.0 B	SSp Ri	iverside Dr NW	Mt. Vernon Hwy	Coldstream Ct	0.70	2	1	U	17048	2	35	12.3 0.0 0.0	0	4.5	N	S	0.0	0	0	0.0	3	3.85	D	4.47	D
221.0 A	SSp R	oberts Dr	Roswell	Rec.	1.47	2	1	U	5000	2	35	13.2 0.0 0.0	0	4.5	N	С	2.0	0	0	5.0	2	3.12	С	3.67	D
221.0 B	SSp R	oberts Dr	Roswell	Rec.	1.47	2	1	U	5000	2	35	13.2 0.0 0.0	0	4.5	Ν	С	2.0	0	10	5.0	2	3.12	С	3.54	D
221.1 A	SSp R	oberts Dr	Rec. Ave	Dunwoody Pl	0.74	2	1	U	5024	2	35	12.7 0.0 0.0	0	4.5	Ν	С	2.0	0	0	5.0	3	3.18	С	3.72	D
221.1 B	SSp R	oberts Dr	Rec. Ave	Dunwoody Pl	0.74	2	1	U	5024	2	35	12.7 0.0 0.0	0	4.5	N	С	2.0	0	25	5.0	3	3.18	С	3.39	С
222.0 A	SSp R	oberts Dr	City Limit	GA Hwy 400	0.90	2	1	U	18734	2	35	11.3 0.0 0.0	0	4.5	Y	С	2.0	0	40	5.0	3	4.02	D	4.12	D
222.0 B			City Limit	GA Hwy 400	0.90	2	1	U	18734	2	35	11.3 0.0 0.0	0	4.5	Y	С	2.0	0	100	5.0	3	4.02	D	3.26	С
		oswell Rd NE	City Limits (N)	Mt. Paran Raod	1.37	4	2	LT	21852	3	35	10.0 0.0 0.0	0	5.0	Y	С	0.0	0	100	6.0	2	4.17	D	3.04	С
223.0 B	SSp R	oswell Rd NE	City Limits (N)	Mt. Paran Raod	1.37	4	2	LT	21852	3	35	10.0 0.0 0.0	0	5.0	Y	С	0.0	0	100	6.0	2	4.17	D	3.04	С
223.1 A	SSp R	oswell Rd NE	Mt. Paran Raod	I 285	1.05	4	2	LT	36452	4	35	10.0 0.0 0.0	0	5.0	N	С	0.0	0	50	6.0	2	4.65	Е	4.40	D
223.1 B	SSp R	oswell Rd NE	Mt. Paran Raod	I 285	1.05	4	2	LT	36452	4	35	10.0 0.0 0.0	0	5.0	Ν	С	0.0	0	50	6.0	2	4.65	Е	4.40	D
223.2 A	SSp R	oswell Rd NE	I 285	Abernathy	1.73	4	2	LT	36618	4	35	10.0 0.0 0.0	0	3.5	Y	С	0.0	0	100	6.0	2	4.96	Е	3.62	D
223.2 B	SSp R	oswell Rd NE	I 285	Abernathy	1.73	4	2	LT	36618	4	35	10.0 0.0 0.0	0	3.5	Y	С	0.0	0	100	6.0	2	4.96	Е	3.62	D
		oswell Rd NE	Abernathy	Dalrymple	1.52	4	2	LT	32150	4	35	10.0 0.0 0.0	0	5.0	Y	С	2.0	0	100	5.0	2	4.58	Е	3.47	С
223.3 B	SSp Ro	oswell Rd NE	Abernathy	Dalrymple	1.52	4	2	LT	32150	4	35	10.0 0.0 0.0	0	5.0	Y	С	2.0	0	100	5.0	2	4.58	Е	3.47	С
223.4 A	SSp R	oswell Rd NE	Dalrymple	Northridge	2.13	4	2	LT	34792	4	45	10.0 0.0 0.0	0	4.5	Y	С	2.0	0	60	5.0	2	4.91	Е	4.50	D
223.4 B	SSp R	oswell Rd NE	Dalrymple	Northridge	2.13	4	2	LT	34792	4	45	10.0 0.0 0.0	0	4.5	Y	С	2.0	0	100	5.0	2	4.91	Е	3.89	D
		oswell Rd NE	Northridge	City Limits (N)	1.59	4	2	LT	31188	2	45	10.6 0.0 0.0	0	4.5	Y	С	2.0	0	90	5.0	2	4.32	D	3.88	D
223.5 B	SSp R	oswell Rd NE	Northridge	City Limits (N)	1.59	4	2	LT	31188	2	45	10.6 0.0 0.0	0	4.5	Y	С	2.0	0	100	5.0	2	4.32	D	3.73	D
226.0 A	SSp Sa	andy Springs Cir NE	Roswell Rd	Johnson's Ferry Rd	0.53	4	2	U	16282	2	35	12.4 0.0 0.0	0	3.5	N	С	0.0	0	30	0.0	2	3.86	D	4.09	D
		andy Springs Cir NE	Roswell Rd	Johnson's Ferry Rd	0.53	4	2	U	16282	2	35	12.5 0.0 0.0	0	3.5	N	С	0.0	2	11	5.0	2	3.85	D	3.94	D
		andy Springs Cir NE	Johnson's Ferry Rd	Hammond Dr	0.22	4	2	U	10358	2	35	12.1 0.0 0.0	0	3.5	Y	С	2.0	0	77	5.0	2	3.67	D	2.84	с
		andy Springs Cir NE	Johnson's Ferry Rd	Hammond Dr	0.22	4	2	U	10358	2	35	12.1 0.0 0.0	0	3.5	Y	С	2.0	0	100	5.0	2	3.67	D	2.53	С
227.0 A			Mt Vernon Road	Winters Chapel	1.27	2	1	U	12794	2	35	12.7 0.0 0.0	0	4.5	N	С	2.0	0	0	5.0	2	3.66	D	4.18	D
227.0 B			Mt Vernon Road	Winters Chapel	1.27	2	1	U	12794	2	35	12.7 0.0 0.0	0	4.5	N	С	2.0	0	25	5.0	2	3.66	D	3.85	D

													idth			Bike			Tree					L	I
					Len-					Post.			Df	Occ.	_	Lane/	-	Buff.	Spcg.	%	Swalk	Road		ycle	Pedestri
Segment ID	City	Road Name	From	То	ů,	Lanes (l Th Di	,	Roadway	Tks. (HV)	Spd. (SPp)	Wt		ement VI W _{ps}	Park. (OSPA)	Pavecon PCt	Pavd. Shldr.	Cross Sec.	Width (BW)	in Buffer	with Sidewalk	Width (Ws)	Profile Cond	L Score	OS Grade	LOS Value (
					· · /	# #		ADT	(%)	mph	(ft)			(%)	(15)	(Y/N)	(C/S)	(BW) (ft)	(ft/ctr)	(DIR)	(tt)	(1,2,3)	(17)	(AF)	(17)
228.0	A SSp Sp	alding Dr	River Exchange	Holcomb Bridge	0.35	3 2	2 LT	12		35	11.		.0 0.0		4.5	Ň	c	2.0	0	40	5.0	1	3.85	D	3.76
228.0			River Exchange	Holcomb Bridge	0.35	3 2	2 LT	12	-	35	12.	2 0.	.0 0.0	0	4.5	N	С	2.0	0	60	5.0	1	3.71	D	3.40
228.1	A SSp Sp		Wunters Chapel	River Exchange Drive	0.28	2 1	U	12	392 2	35	12.	0 0.	.0 0.0	0	4.5	N	С	0.0	0	0	0.0	2	3.73	D	4.24
	B SSp Sp		Wunters Chapel	River Exchange Drive	0.28	2 1	U	12	392 2	35	12.	0 0.	.0 0.0	0	4.5	N	С	0.0	0	0	0.0	2	3.73	D	4.24
	A SSp Sp		Darlrymple	Chardlee Dunwoody (City Limit)	0.76	2 1	U	13	2 2	35	11.	5 0.	.0 0.0	0	4.2	Y	С	2.0	0	90	5.0	2	3.91	D	3.12
	B SSp Sp		Darlrymple	Chardlee Dunwoody (City Limit)	0.76	2 1	U	13	900 2	35	11.	5 0.	.0 0.0	0	4.2	Y	С	2.0	0	100	5.0	2	3.91	D	2.98
229.1	-		Chardlee Dunwoody (City Limit)	Dunwoody Club/Roberts	0.55	2 1	U	12)38 2	35	11.	0 0.	.0 0.0	0	4.0	N	С	2.0	0	0	5.0	2	3.93	D	4.31
229.1	B SSp Sp	alding Dr	Chardlee Dunwoody (City Limit)	Dunwoody Club/Roberts	0.55	2 1	U	12)38 2	35	11.	0 0.	.0 0.0	0	4.0	N	С	2.0	0	0	5.0	2	3.93	D	4.31
229.2	A SSp Sp	alding Dr	Dunwoody Club Drive	Jett Ferry	3.47	2 1	U	34	194 2	35	10.	70.	.0 0.0	0	4.2	N	С	2.0	0	0	5.0	3	3.15	с	3.84
229.2	B SSp Sp	alding Dr	Dunwoody Club Drive	Jett Ferry	3.47	2 1	U	34	194 2	35	10.	7 0.	.0 0.0	0	4.2	N	С	2.0	0	15	5.0	3	3.15	с	3.62
229.3	A SSp Sp	alding Dr	Jett Ferry	Mt Vernon	0.75	2 1	U	52	234 2	35	11.	0 0.	.0 0.0	0	4.5	Ν	С	2.0	0	0	5.0	3	3.42	С	3.91
229.3	B SSp Sp	alding Dr	Jett Ferry	Mt Vernon	0.75	2 1	U	52	234 2	35	11.	0 0.	.0 0.0	0	4.5	N	С	2.0	0	25	5.0	3	3.42	с	3.55
230.0	A SSp Sp	alding Dr NE	Darlrymple	Roswell Road	1.02	2 1	U	4	518 2	35	14.	0 2.	.5 0.0	0	4.5	Y	С	2.0	0	100	4.0	2	2.98	С	2.45
230.0	B SSp Sp	alding Dr NE	Darlrymple	Roswell Road	1.02	2 1	U	4	518 2	35	14.	0 2.	.5 0.0	0	4.5	Y	С	2.0	0	0	4.0	2	2.98	С	3.58
232.0	A SSp Tro	owbridge Rd	Roswell	Darlrymple	0.56	2 1	U	9	794 2	35	12.	8 0.	.0 0.0	0	5.0	Y	С	2.0	0	100	5.0	2	3.45	С	2.68
232.0	B SSp Tro	owbridge Rd	Roswell	Darlrymple	0.56	2 1	U	9	794 2	35	12.	8 0.	.0 0.0	0	5.0	Y	С	2.0	0	75	5.0	2	3.45	С	3.01
233.0	A SSp Wi	ndsor Pkwy NE	Roswell Road	Hwy 400	0.98	2 1	U	6	L62 2	35	14.	5 0.	.0 0.0	0	5.0	Ν	С	0.0	0	0	0.0	3	2.99	С	3.63
233.0	B SSp Wi	ndsor Pkwy NE	Roswell Road	Hwy 400	0.98	2 1	U	6	162 2	35	14.	5 0.	.0 0.0	0	5.0	Ν	С	0.0	0	0	0.0	3	2.99	С	3.63
233.1	A SSp Wi	ndsor Pkwy NE	Hwy 400	Peactree/Dunwoody	0.63	2 1	U	7:	246 2	35	11.	5 0.	.0 0.0	0	5.0	Ν	С	2.0	0	50	5.0	3	3.46	С	3.28
233.1	B SSp Wi	ndsor Pkwy NE	Hwy 400	Peactree/Dunwoody	0.63	2 1	U	73	246 2	35	11.	5 0.	.0 0.0	0	5.0	Ν	С	2.0	0	50	5.0	3	3.46	С	3.28
233.2	A SSp Wi	ndsor Pkwy NE	Peactree/Dunwoody	City Limit	0.43	2 1	U	8	228 2	30	11.	5 0.	.0 0.0	0	3.0	N	С	2.0	0	25	5.0	3	3.87	D	3.55
233.2	B SSp Wi	ndsor Pkwy NE	Peactree/Dunwoody	City Limit	0.43	2 1	U	8	228 2	30	11.	5 0.	.0 0.0	0	3.0	N	С	2.0	0	25	5.0	3	3.87	D	3.55
234.0	A SSp Wi	nters Chapel Rd	City Limit	Spalding	0.60	2 1	U	12	392 2	35	11.	9 0.	.0 0.0	0	3.5	Ν	С	0.0	0	0	0.0	2	4.00	D	4.24
234.0		nters Chapel Rd	City Limit	Spalding	0.60	2 1	U	123	392 2	35	11.	9 0.	.0 0.0	0	3.5	Ν	С	0.0	0	0	0.0	2	4.00	D	4.24
301.0	A SSp He	mbree Road	Old Roswell	Westside Parkway	0.59	2 1	U	16	7 ₃₈ 2	35	11.	5 0.	.0 0.0	0	4.0	Ν	S	2.0	0	0	5.0	3	4.04	D	4.54
301.0	B SSp He	mbree Road	Old Roswell	Westside Parkway	0.59	2 1	U	16	7 ₃₈ 2	35	11.	5 0.	.0 0.0	0	4.0	Ν	S	2.0	0	50	5.0	3	4.04	D	3.84
otes:	Pedestrian Results are directional due to variations in sidewak coverage																								
	"A" Segments are for North- or East-Bound sides, "B" Segments are for South of West-Bound sides					U = Undi	vided									OW=One	Way			UC= U	nder Constru	ction at tin	ie of data	collection.	
	Estimated of	data shown in italics. Se	e Existing Facilities Report for explanation	ı.			D=Divide	d																	

APPENDIX H

Envision6 (Long Range) Projects in North Fulton





ARC	Funding	Compltn	P	roject		_	
ID	Total	Date	Group	Type General	Project Description	From	То
FN- 103B	\$6,485,600	2020	Rdwy	Purpose Roadway	Glenridge Drive (Widen 2 to 4 Lanes)	SR 9 (Roswell Road)	Johnson Ferry Road
AR- 900	\$277,000,000	2030	Transit	Fixed Guideway Transit Capital	I-285 North Bus Rapid Transit (BRT)	Cumberland/Galleri a Area in Cobb County	Perimeter Center in DeKalb County
AR-H- 300	\$1,356,192,500	2030	Rdwy	Managed Lanes (Auto/Bus)	I-285 North HOV Lanes	I-75 North in Cobb County	I-85 North in DeKalb County
FN- AR- 185	\$4,120,086	2020	Rdwy	Interchange Upgrade	I-285 North	Riverside Drive (Widen to 4 Lanes (2 through, 2 Left Turn))	
FN- AR- 203	\$209,289,000	2020	Rdwy	Interchange Capacity	I-285 North	SR 9 (Roswell Road) (Widen to 2 Left Turn Lanes in Each Direction)	
DK- AR- 219A	\$171,532,000	2020	Rdwy	Interchange Capacity	I-285 North (C-D System, Widen Ashford Dunwoody Road include additional turn lanes on bridge (2 westbound, 3 eastbound))	SR 400	N Shallowford Road - Includes Ashfd-Dunwdy Interchange
FN- 055A	\$10,240,000	2020	Rdwy	General Purpose Roadway Capacity	Peachtree-Dunwoody Road (Widen 2 to 4 lanes)	Abernathy Road/Perimeter Center West	Spalding Drive
FN- 011	\$3,500,000	2020	Rdwy	General Purpose Roadway Capacity	Dunwoody Place (Widen 2 to 4 lanes)	Northridge Road	Hightower Trail
FN- 140	\$8,600,000	2020	Rdwy	General Purpose Roadway Capacity	Mansell Road Extension (New location 4 lane roadway)	SR 92 (Crossville Road)	SR 9 (Alpharetta Street)
FN- 145	\$8,600,000	2020	Rdwy	General Purpose Roadway Capacity	Commerce Parkway Extension (New location 4 lane roadway)	Old Roswell Road	Holcomb Bridge Road
FN- 123A	\$38,921,000	2020	Rdwy	General Purpose Roadway Capacity	Old Alabama Road: Segment 1 (Widen 2 to 4 lanes)	SR 140 (Holcomb Bridge Road)	Jones Bridge Road
FN- 123B	\$42,031,000	2020	Rdwy	General Purpose Roadway Capacity	Old Alabama Road: Segment 2 (Widen 2 to 4 lanes)	Jones Bridge Road	SR 141 (Medlock Bridge Road)
FN- 031B	\$12,949,800	2020	Rdwy	General Purpose Roadway Capacity	Haynes Bridge Road (Widen 2 to 4 lanes)	Mansell Road	Old Alabama Road

FN- 126	\$66,792,000	2020	Rdwy	General Purpose Roadway Capacity	SR 140 (Houze Road/Arnold Mill Road) (Widen 2 to 4 lanes)	Mansell Road	Ranchett Road
FN- 003	\$54,896,200	2020	Rdwy	General Purpose Roadway Capacity	SR 120 (Kimball Bridge/Abbotts Bridge Road) (Widen 2 to 4 lanes)	State Bridge Road/Old Milton Parkway	Peachtree Industrial Boulevard
FN- 049A	\$23,518,320	2030	Rdwy	General Purpose Roadway Capacity	Jones Bridge Road: Segment 1 (Widen 2 to 4 lanes)	Old Alabama Road	SR 120 (Abbotts Bridge Road/Kimball Bridge Road)
FN- 049B	\$7,500,000	2030	Rdwy	General Purpose Roadway Capacity	Jones Bridge Road: Segment 2 (Widen 2 to 4 lanes)	SR 120 (Abbotts Bridge Road/Kimball Bridge Road)	Douglas Road
FN- 225	\$9,940,600	2030	Rdwy	General Purpose Roadway Capacity	State Bridge Road/Pleasant Hill Road (Widen 4 to 6 lanes)	SR 141 (Medlock Bridge Road)	Peachtree Industrial Boulevard